

BROOKLYN NAVY | YARD

Brooklyn Navy Yard Development Corporation Archives Guide to the Records of Naval Districts and Shore Establishments NARARG181

Brooklyn Navy Yard Development Corporation Archives
Building 77, 141 Flushing Avenue, Suite 801, Brooklyn, NY 11205

Finding aid produced on: March 6, 2026
Description is in English.

Title

Records of Naval Districts and Shore Establishments

Date

1784 – 2000

Description

Record Group 181: Records of Naval Districts and Shore Establishments
Series: Photographs of Ships, Small Craft, and Navy Yards, 1898 - 1922
Series: Glass Plate Negatives of the Construction and Repair of Buildings, Facilities, and Vessels at the New York Navy Yard, 1903 - 1920

Admin Notes

Select photographs from NARA Record Group 181, held by NARA Still Pictures Division in College Park, MD and NARA-NYC in New York, NY. Images downloaded from the National Archives public access catalog in 2015, or were scanned by BNYDC Archives' staff at NARA-NYC in the summer of 2008.

Call Number

NARARG181

Related Collections

BNYDC Photographs collection

Collection Contents

External collection: Records of Naval Districts and Shore Establishments, NARARG181(5531 records)

- Shore Crane Beams in Foundry Building 29, View of Column E4, 3566
- Rolling Cold Asphalt between Building Ways No. 1 and 2, 3572
- Laying brick for new guard house at new gate at Cumberland Street, 3573
- General View of Paving at New Cumberland Street Gate, 3574
- Laying new concrete floor in Building 132, 3577
- Cumberland Street Gate Improvement, 3580
- General View of Improvement to Cumberland Street Gate, 3583
- Remodeling of Motion Picture Exchange Building 213 - Breaking up Floor Slabs for Extension, 3584
- Pouring Concrete into Duct Forms on Pier C, 3588
- Removing Paving at Old Gate Entrance, Cumberland Street, 3605
- Forming for Concrete Sidewalk Slabs Leading to New Cumberland Street Gate, 3606
- Landscaping at Building 27 on Site of Previous Roadway and Entrance, Work by Yard Labor, 3618
- New Landscaping at South End of Building 29, Work by Yard Labor, 3620
- Dredging the Navy Yard Basin, Area No. 5, 3621
- Improvements to Building Ways No. 1 General View Looking Outboard, 3635
- Turret and Erection Shop Building and Accessories Test Pits at Site of New Turret and Assembly Shops, 3657
- Acid Storage Tanks at Shipways, View Showing Tank FoundationD LABOR, 3659
- 350 Ton Hammerhead Crane Foundation Near Berth 12, Looking East Showing Composite Pile Shells in Place, 3681

Foundation for New 350 Ton Hammerhead Crane Near Berth 12, View Showing Erection of Tower (Traveler) and Interior Floor of Foundation, 3690
 Turret and Erection Shops Installing Foundations for Storage of Steel Plate and Relocation of Steam Line at Ordnance Dock, Looking South, 3698
 USS Pensacola, Portside Looking Aft from Port Bow, 4240
 USS West Virginia - Removal of Plates Pile Driver and Ram Ready to Start Lower Key, 4253
 USS West Virginia Double Turret Indicator MK I MOD 2 and General View in Turret Officer's Station, 4274
 U.S. Naval Hospital - Mary Alford, complete ankylosis of elbow after fracture, 5975
 U.S. Naval Hospital - Mary Alford, result of treatment by physiotherapy, 5976
 U.S. Naval Hospital - Group of Brazilian Patients in Waiting Room, Beriberi Cases, 5977
 Monthly Progress Photo - Building 131, Additions to Motor-generator Lean-to, Substation 11, 6168
 Monthly Progress Photo - Building 131 Addition For Dry Dock 4 Latrine, Sailors' Part Looking Northwest, 6177
 Monthly Progress Photo - Building 131, Addition for Latrine at Dry Dock 4, 6181
 Building 128 Completed Exterior of Extension to Machine Shop, 6253
 Building 128 Foundation Piles for Erecting Wing Extension, Looking Southwest, 6293
 General View of Building 128 Interior, 6338
 General View of Building 128 Interior, 6348
 Liberty Loan meeting in front of Boat Shop Building 127, 6351
 Excavation for Foundation of Hydraulic Press, 6425
 Excavation for Foundation of Hydraulic Press , 6426
 Building 11 - Drop Forge Plant, Showing Steam Drop Hammers and Trimming Pressers for Hot Trim Work, 6475
 Building 11 - Drop Forge Plant, Showing Shearing Machinery, 6476
 Building 11 - Drop Forge Plant, Cold Trim Section, 6477
 Building 11 - Drop Forge Plant, Grinding Dept, 6478
 Building 11 - Monthly Progress Photo, Sidewalk on 3rd St, Looking Southwest, Yard Labor, 6501
 Building 11 - Steel Foundry, Foundations for Drop Hammers, Looking South, Yard Labor, 6582
 Building 11 - Smithery, Foundation for 500 Ton Forge Press, Looking Southwest, Yard Labor, 6583
 Building 11 - Steel Storage Racks in Courtyard, Looking South, Yard Labor, 6585
 Building 11 - Smithery, Steam Hammer Foundations Along 2nd St, Looking Northwest, Yard Labor, 6586
 Building 11 - Steel Foundry, Foundations Along 3rd St, Looking East, Yard Labor, 6587
 Building 11 - Steel Foundry, Looking South, 6588
 Building 11 - Steel Foundry, Looking West, 6589
 Building 11 - Steel Foundry Toilet Room, Looking Southwest, 6590
 Building 11 - Steel Foundry, Looking East, 6591
 Building 11 - Steel Foundry, Looking North, 6592
 Building 11 - Steel Foundry, 6593
 Building 11 - Steel Foundry, Looking Northwest, 6594
 Building 11 - Steel Foundry, Looking West, 6595
 Building 11 - Steel Foundry, Looking Southwest, 6596
 Building 11 - Steel Foundry, Looking Southeast, 6597
 Building 11 - Steel Foundry, Looking North, 6599
 Building 11 - (34) Monthly Progress Photo, New Wood Block Floor, Looking Northwest, Yard Labor, 6600
 Building 11 - (34) Monthly Progress Photo, Foundation for Wood Block Pavement, Looking Southeast, Yard Labor , 6602
 Building 11 - (34) Monthly Progress Photo, Brick Floor Relaid, SE Smithy, Looking Southwest, Yard Labor, 6603
 Building 11 - (34) Monthly Progress Photo, Jib Crane in Courtyard, Looking North, Yard Labor, 6604
 Building 11 - (34) Smokers, Lunch Hour, 6605
 Building 11 - (34) Fireboard, 6606
 Building 11 - (34) Planning Room Entrance, 6607
 Building 11 - (34) File Board in Planning Room, 6609
 Building 11 - (34) Monthly Progress Photo, Foundation for Drop Hammers & Forces, Looking Southeast, Yard Labor , 6610
 Building 11 - (34) Monthly Progress Photo, Reinforcement of Crane Runway, Looking Southeast, Yard Labor, 6611
 Building 11 - Monthly Progress Photo, Bar Shear, Looking Southwest, Yard Labor, 6612
 Building 11 - Monthly Progress Photo, Forging Press, Yard Labor, 6613
 Building 11 - Monthly Progress Photo, Foundation for Bar Shear, Looking Northeast, Yard Labor, 6614
 Building 11 - Monthly Progress Photo, Foundation Pit for Bar Shear, Looking Northeast, Yard Labor, 6615
 Building 11 - Monthly Progress Photo, Foundation for Forging Press, Looking South, Yard Labor, 6616
 Building 11 - Monthly Progress Photo, Foundation for Forging Press, Yard Labor, 6617
 Building 11 - Monthly Progress Photo, Converter Foundation, Yard Labor, 6618
 Building 11 - Monthly Progress Photo, Converter Foundation, Yard Labor, 6619
 Building 11 - Monthly Progress Photo, Converter Foundation, Yard Labor, 6620
 Building 11 - Monthly Progress Photo, Converter Foundation, Yard Labor, 6621
 Building 11 - Monthly Progress Photo, Converter Foundation, Looking North, Yard Labor, 6622
 Building 11 - Monthly Progress Photo, Excavation for Converter, Yard Labor, 6623
 Building 11 - Looking North, 6624
 Building 11 - Sabining Shop, Looking North, 6625

Building 11 - Looking North, 6626
 Building 11 - Looking East, 6627
 Building 11 - Looking East, 6628
 Building 11 - Addition Looking East, 6629
 View of the Waterfront, Looking North from the Top of Building 6, 6793
 View of Waterfront, Looking North from the Top of Building 6, 6794
 View of the Waterfront, Looking North from the Top of Building 6, 6795
 Warning signs at Flushing Avenue gate, 6806
 Locomotive caution sign on Building 20 (45) at Fourth Street, 6807
 Argentine Battleship Rivadavia in Dry Dock 4, Looking Northeast Showing Clearance between Sides of Ship and Dock, 6887
 Argentine Battleship Rivadavia, in Dry Dock 4, Looking Northeast, 6894
 Monthly Progress Photo - New Tennis Courts at Officer's Quarters, Looking Northeast, 6903
 First House Occupied by the Navy Yard Commandant 1801-1806, 6917
 Wallabout Market, 6925
 Construction of Building 234, Substation 6, Looking Northeast, 6943
 Substation 6 Under Construction, South Wall Looking Northwest, 6949
 Duct Work to Building 224, Substation 11 , 6957
 Prison, Building 215, 6976
 Excavating for Lumber Rack Foundations in Building 214, 6982
 Repairs to Dry Dock crane No. 199, 7005
 Installation of New Freight Elevator in Building 131, View on First Floor , 7058
 Installation of New Elevator in Building 131, View on Top Floor, 7059
 Penthouse on Roof of Building 131 for Installation of New Elevator, 7060
 Machine Shop Building 128 - Foundation for 60" Double Housing Planer, View Looking East, 7083
 Repairing Floor in Building 128 , 7122
 Repairs to Cornice of Building 128, 7144
 Repairs to Ventilators and Roof of Building 128, 7165
 Pumping Plant, Dry Dock 1, 7274
 Pumping Plant, Dry Dock 1, 7276
 Moving Building 121 to New Site, 7324
 Laying Building 121 on Foundation of New Site, 7325
 Building 121 Paymaster's Office Preparatory to Moving, Looking North, 7338
 Monthly Progress Photo Building 115 (26) - New Asphaltic Mastic Floor Partially Laid, Looking Southeast, 7379
 Monthly Progress Photo - Trolley Runway between Buildings 115 (26) and 116 (27), Looking Northwest, 7380
 Monthly Progress Photo Building 115 (26) - Trolley Track Out Southeast End, Looking Northeast, 7406
 Monthly Progress Photo - Changes to Northwest End of Building 115 (26) for Trolley Extension, Looking Northeast, 7408
 Transverse Crane Runway, Looking West from Morris Avenue Showing Trench for Electric Conduit through Site of Building 6, 7422
 Repairs to Exterior of Building 3, 7490
 Repairs to Exterior of Building 3, 7491
 Elevator Shaft for Building 30, 6" TC Pipe for Connecting Roof Leader, 7510
 Brick Elevator Shaftway, Pattern Shop Building 30, 7516
 New Column Footings in Boiler Shop, Building 28, 7571
 Laying Floor in Boiler Shop Building 28, 7572
 New Floor in Boiler Shop, Building 28, 7574
 Extension Demolition at Building 27, 7576
 Demolishing Building 26 on Sixth Street, 7579
 Improvement of Shop Buildings, Building 23, New Elevator Enclosure, 7589
 Improvement of Shop Buildings - Excavation for Enlarging Elevator Pit in Building 23, 7592
 Repairs to Brickwork of Building 20, 7604
 Renewing Light Sash on Roof of Building 20, 7606
 Marine Barrack Building 13, remodeling toilet and bathroom, 3rd Floor, 7633
 Interior of Building 13, Remodeled for the Marine Barracks, View of Mess Hall, 1st Floor., 7649
 Remodeling of Building 13 for the Marine Barracks, view of 1st floor, northern extremity looking south , 7665
 Excavating for Layout Slab, Building 12, 7719
 Repairs to Roof and Cornice of Building 12, 7722
 Repairs to Roof and Cornice of Building 12, 7723
 Installing Concrete for Mezzanine Floor in Building 12, 7732
 Sectional View of Steel Frame for Mezzanine Floor in Building 12, 7734
 Building 11 - Blacksmith Shop, 4500 Steam Hammer Foundation, (C&R), SAO, Yard Labor, 7742
 Building 11 - Blacksmith Shop, 4500 Steam Hammer Foundation, (C&R), SAO, Yard Labor, 7743
 Blacksmith Shop, Building 11, 4500 Lb. Steam Hammer Foundation, 7744
 Building 12 Showing Settlement of the Floor, 7745
 Building 11 - Machine Foundation, Yard Labor, 7746
 Foundation for Board Hammer in Building 11, 7747
 Building 11 - Repairs to Roof, New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7758

USS NEW MEXICO PORT BROADSIDE, 7767
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, STERN VIEW, 7768
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, STERN VIEW, 7769
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, STERN VIEW, 7770
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, BOW VIEW, 7771
USS TENNESSEE VIEW FROM BOW LOOKING STERNWARD, 7772
USS TENNESSEE VIEW FROM STERN LOOKING TOWARDS BOW, 7773
USS TENNESSEE VIEW FROM MID-SHIP ON STARBOARD SIDE LOOKING INTO HULL, 7774
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7775
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7776
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, STERN VIEW, 7777
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, STERN VIEW, 7778
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, STERN VIEW, 7779
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, STERN VIEW, 7780
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, STERN VIEW, 7781
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7782
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, STERN VIEW, 7783
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7784
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7785
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7786
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7787
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7788
USS TENNESSEE FROM FORWARD LOOKING AFT FROM BLDG 6, 7789
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7790
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7791
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7792
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7793
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, 7794
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, 7795
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, 7796
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, 7797
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, 7798
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, 7799
FYRFYTER EXTINGUISHER, ENCLOSURE A, 1618-A, 7800
FASTAC FIRE EXTINGUISHER, 1589-A, ENCLOSURE A, 7801
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7802
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7803
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7804
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7805
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7806
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7807
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7808
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD4, 7809
Submarine Chasers under Construction near Dry Dock 4, 7810
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD4, 7811
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD4, 7812
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD4, 7813
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD4, 7814
Submarine Chasers Under Construction Near Dry Dock 4, 7815
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD4, 7816
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD4, 7817
USS TENNESSEE, SECOND VIEW FROM FORWARD, 7818
GARAGE PRESS ON BOARD USS PENNSYLVANIA, 7819
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, 7820
USS TENNESSEE STARBOARD SIDE LOOKING INBOARD FROM GANTRY CRANE IN PLATELOT, 7821
USS TENNESSEE LOOKING AFT FROM BLDG 6, 7822
USS TENNESSEE PORT SIDE LOOKING FORWARD FROM PIER, 7823
USS TENNESSEE PORT SIDE LOOKING AFT FROM CANTILEVER CRANE FORWARD, 7824
USS TENNESSEE PORT SIDE LOOKING FORWARD FROM CANTILEVER CRANE AFT, 7825
USS NEW MEXICO IN DD 4 BOW VIEW, 7826
USS NEW MEXICO PORT SIDE LOOKING FORWARD DD 4, 7827
USS NEW MEXICO IN DD 4 PORT SIDE LOOKING AFT, 7828
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, STERN VIEW, 7829
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, BOW VIEW, 7830
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7831

SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, STERN VIEW, 7832
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, GENERAL VIEW, 7833
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, BOW VIEW, 7834
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, STERN VIEW, 7835
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7836
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7837
USS TENNESSEE FROM FORWARD QUARTER LOOKING STERNWARD, 7839
USS TENNESSEE FROM STERN LOOKING TOWARD BOW, 7840
USS TENNESSEE FROM PORT SIDE OF STERN LOOKING FORWARD, 7841
USS TENNESSEE FROM FORWARD PORT SIDE LOOKING AFT, 7842
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, BOW VIEW, 7843
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7844
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, STERN VIEW, 7845
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, BOW VIEW, 7846
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7847
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7848
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, STERN VIEW, 7849
Submarine Chasers under Construction Near Dry Dock 4, Stern View, 7850
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, GENERAL VIEW, 7851
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7852
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, STERN VIEW, 7853
SUBMARINE CHASERS UNDER CONSTRUCTION NEAR DD 4, BOW VIEW, 7854
MONTHLY PROGRESS PHOTO, BLDG 114 (36), TROLLEY TRACKS, LOOKING SW, YARD LABOR, 7855
MONTHLY PROGRESS PHOTO, BLDG 114 (36), NEW TROLLEY TRACKS, LOOKING SW, YARD LABOR, 7856
MONTHLY PROGRESS PHOTO, BLDG 114 (36), CRANE RUNWAYS, LOOKING SW, YARD LABOR, 7857
BLDG 45, LOOKING N, 7858
BLDG 45, LOOKING E, 7859
BLDG 45, LOOKING S, 7860
BLDG 60, LOOKING SE, 7861
BLDG 60 INTERIOR PUMPING STATION, 7862
Building 60 from Caisson in Dry Dock 2, 7863
Building 60 from Caisson in Dry Dock 3, 7864
BLDG 45, NEW FURNACE LOOKING SE, 7865
BLDG 45, LOOKING SE, 7866
SUBMARINE CHASERS UNDER CONSTRUCTION ON ATHLETIC FIELD, 7867
WALLABOUT MARKET, 7868
WALLABOUT MARKET, 7869
USS TENNESSEE PORT SIDE FORWARD LOOKING AFT FROM FORWARD CRANE, 7870
USS TENNESSEE PORT SIDE FORWARD LOOKING AFT FROM FORWARD CRANE, 7871
USS TENNESSEE PORT SIDE AFT LOOKING FORWARD FROM AFT CRANE, 7872
USS HUNTINGTON FRAME NO 38, 7873
GARBAGE PRESS, USS PENNSYLVANIA, 7874
SUPPLY STOREHOUSE BLDG 3, TURNER CONST CO CONTR, 7875
Initial Lesion of Lip, 7876
SUPPLY STOREHOUSE, BLDG 3, TURNER CONST CO CONT, 7877
PAY CAR TRAILER, 7878
BLDG 41, YARD LABOR, 7879
BLDG 41, YARD LABOR, 7880
BLDG 41, YARD LABOR, 7881
BLDG 41, 7882
POWER HOUSE, BLDG 41 FROM SW, 7883
POWER HOUSE, BLDG 41 FROM 4TH ST & WARRINGTON AVE, 7884
POWER HOUSE, BLDG 41 FROM S, 7885
GENERAL PLAN OF THE US NAVY YARD, SHOWING CONDITION OF YARD WHEN IMPROVEMENTS ARE COMPLETED AND AVAILABLE BERTHING FACILITIES, 7886
POWER HOUSE, BLDG 41 FROM S, 7887
BLDG 41, WORK ON COAL HANDLING PLANT, LOOKING N, 7888
BLDG 41, ENG ROOM LOOKING SE, 7889
BLDG 41, BOILER ROOM LOOKING NW, 7890
BLDG 41, BOILER ROOM LOOKING SE, 7891
BLDG 41, 7892
BLDG 41, 7893
DD 2, E SIDE FROM 365' TO HEAD END, EXHIBIT XXIV, 7894
DD 2, E SIDE FROM 295' TO 375', EXHIBIT XXV, 7895
DD 2, E SIDE FROM 200' TO 290', EXHIBIT XXVI, 7896

DD 2, E SIDE FROM 115' TO 200', EXHIBIT XXVII, 7897
 DD 2, E SIDE FROM 35' TO 115', EXHIBIT XXVIII, 7898
 DD 2, E SIDE FROM CL CAISSON TO 50' MARK, EXHIBIT XXIX, 7899
 DD 2, HEAD END E SIDE, EXHIBIT XXIII, 7900
 DD 2, W SIDE FROM 45' TO CL CAISSON, EXHIBIT XXII, 7901
 DD 2, W SIDE FROM 45' TO CAISSON, EXHIBIT XXI, 7902
 DD 2, W SIDE FROM 120' TO 35', EXHIBIT XX, 7903
 DD 2, W SIDE FROM 200' TO 120', EXHIBIT XIX, 7904
 DD 2, W SIDE FROM 285' TO 200', EXHIBIT XVIII, 7905
 DD 2, W SIDE FROM 360' TO 270', EXHIBIT XVII, 7906
 DD 2, W SIDE FROM HEAD END TO 360', EXHIBIT XVI, 7907
 DD 2, HEAD END W SIDE, EXHIBIT XV, 7908
 Dry Dock 2, Exhibit XIV, 7909
 Dry Dock 2, Exhibit XIII, 7910
 DD 2, E SIDE FROM CAISSON TO 40', EXHIBIT XXX, 7912
 SS WEST OIL ARMED GUARD QUARTERS, OP28754-16, OP-24-D, 7913
 Photograph of President Franklin D. Roosevelt, 7914
 NAVAL HOSP, PLASTIC OPERATION OF PENIS AND SCROTUM, 7916
 Naval Hospital, Plastic Operation of Penis and Scrotum, 7917
 NAVAL HOSP, CASE OF PSORIASIS, 7918
 NAVAL HOSP, CASE OF PSORIASIS, 7919
 MONTHLY PROGRESS PHOTO, NEW POSITION, JIB CRANE, BLDG 114 (36), LOOKING SW, YARD LABOR, 7920
 MONTHLY PROGRESS PHOTO, NEW POSITION, FOUNDATION FOR JOGGING PRESS, BLDG 114 (36), LOOKING S, YARD LABOR, 7921
 MONTHLY PROGRESS PHOTO, NEW POSITION, FOUNDATION FOR JOGGING PRESS, BLDG 114 (36), LOOKING S, YARD LABOR, 7922
 MONTHLY PROGRESS PHOTO, NEW CRANE TROLLEYS, BLDG 114 (36), LOOKING N, YARD LABOR, 7923
 MONTHLY PROGRESS PHOTO, STRUCTURAL CHANGES N END, BLDG 114 (36), LOOKING SW, YARD LABOR, 7924
 ALTERATIONS TO PNEUMATIC TUBE SYSTEM, VIEW AT 4TH ST LOOKING S, GATE ALONG LINE OF TRENCH, SHOWING PAVEMENT RESTORED, CONTRACT NOY 4708, 7925
 ALTERATIONS TO PNEUMATIC PIPE SYSTEM, VIEW SHOWING LINE OF TRENCH FROM INSIDE BLDG 14 TO BLDG 121 WITH PAVING RESTORED IN PART ACROSS 3RD ST, CONTRACT NOY 4708, 7926
 ALTERATIONS TO PNEUMATIC TUBE SYSTEM, VIEW OF UNDERGROUND INSTALLATION OF PIPE AND TUBE FROM BLDG 14, 2ND ST TO NEW MANHOLE 1, CONTRACT NOY 4708, 7927
 STEAM SERVICES, BLDG 41 TO BLDG 77, LOOKING W FROM MORRIS AVE AND 5TH ST, RNV (C&M), 17X0603-5, YARD LABOR, 7928
 STEAM SERVICES, BLDG 41 TO BLDG 77, CORNER MORRIS AVE AND 5TH ST, LOOKING S, RNV (C&M), 17X0603-5, YARD LABOR, 7929
 SHIP AT BKLYN NAVY YARD, 7930
 Improvement to Shipbuilding Area, Looking Northwest on Dock Street Showing Saltwater Line Near Second Street at Building 10 for New Fire Hydrant, 7935
 Transverse Crane Runway, Looking Northeast Showing New Access Ladder and Handrail to Cranes on the East End of the Runway, 7943
 TRANSVERSE CRANE RUNWAY, COLUMN FOOTINGS AND 12" AIR LINE ON N SIDE OF BLDG NO 4, CONTRACT NOY 4243, 7945
 Transverse Crane Runway, Looking Southeast , 7950
 Hammerhead Crane for Heavy Duty, View Looking North Showing New 6" Air Line between Piers G and H, 7952
 Transverse Crane Runway, Looking Northwest from Morris Avenue near Second Street Showing Excavating Work for Pipe Trench, 7956
 Transverse Crane Runway Pouring Concrete around Electric Ducts at Head of Buildingways No. 2, 7973
 Reconstruction of Buildingways No. 2, Looking Northeast from West of Ways Showing Intermediate Cofferdam, 7976
 Reconstruction of Buildingways No. 1 Looking Northeast from West Side of Ways Showing Inboard Cofferdam, 7977
 Enclosure in Hammerhead Crane Base Toilets and Toilet Stalls in Ground Floor Toilet Room, 7981
 Excavation for Storm and Sanitary Sewers, West Side of Building 18, 7985
 Excavation for Manhole and Electric Duct Line Beneath Plate Storage Racks, 7988
 New Transformer Outside Substation, Building 223, 7996
 Excavating for Electric Manhole between Buildings 4 and 18, West Side, 7998
 Sub-assembly Shop Improvements of Shop Buildings and Steel Storage Runways , 8005
 Reconstruction of Railroad Tract on Perry Avenue near Second Street, 8050
 Repairs to Retaining Wall and Electric Manhole at Rear of Commandant's House, 8056
 New Pavement on Perry Avenue and Second Street, 8064
 Improvements of Berths 11 and 12, View Showing Tie Rods in Place at Berth 12, 8090
 Improvements to Berths 11 and 12, Looking Southwest Showing Tie Rods in Place, Berth 12, 8092
 U.S.N. Receiving ship barracks, Bay Ridge, Brooklyn - Dispensary looking west, 8128
 U.S Naval Hospital, Navy Yard, New York - Herpes , 8145

U.S. Naval Hospital - Erecting Building E Emergency Hospital, Looking Northeast, 8163
 U.S. Naval Hospital - Erecting Building E, Emergency Hospital Looking East, 8164
 U.S. Naval Hospital Building E Looking North, 8165
 U.S. Naval Hospital - Emergency Hospital Building E, Looking North, 8169
 U.S. Naval Hospital Erecting Nurses Building, Looking North, 8174
 U.S. Naval Hospital Steam and Water Trench from Powerhouse to Nurses Quarters, 8204
 U.S. Naval Hospital Building F, 8205
 U.S. Naval Hospital Building F, 8206
 U.S. Naval Hospital Building F , 8208
 Master Mechanists office, 2nd Floor of Machine Shop, 8212
 Hard Coal Storage and Master Mechanics Office, Looking Northwest, 8215
 Oil Storage House in Foreground, Machine Shop in Background, Looking Northeast, 8216
 Interior of Blacksmith Shop, Looking Northeast, 8218
 U.S. Naval Hospital - Squad of Artificial Leg Cases Exercising Leg Each Morning, Case A, 8224
 U.S. Naval Hospital - Leg Case E after Use of Improvised Peg, 8235
 U.S. Naval Hospital - Closing of Wound Showing Progress of Wound Closure, 8236
 Gallagher - Anterior Scar with Sinus Persisting, 8239
 Sarcoma of the Foot with Abdominal Metastasi Admitted to the Hospital with a Diagnosos of an Abscess of the Foot, 8240
 U.S. Naval Hospital - Lawhorn, Empyema Up and About During Carrel-Dakin Treatment, 8263
 U.S. Naval Hospital - Guerrini - Closure following Carrel-Dakin Treatment of Osteomyelitis of the Tibia, 8264
 U.S. Naval Hospital - Physiotherapy - First plant B-1, 8267
 U.S. Naval Hospital Squad of Amputated Leg Cases - Setting Up Exercises with Artificial Limbs in Use, 8268
 U.S. Naval Hospital Physiotherapy - First Plant B-1, 8270
 U.S. Naval Hospital - Light Duty for Convalescents, 8271
 U.S. Naval Hospital - Markes Empyema, up and about during Carrel-Dakin treatment, 8275
 U.S. Naval Hospital - Physiotherapy - First Plant, 8280
 U.S. Naval Hospital - Bilateral arthritis of the knee, with extension, showing manipulation of feet to prevent foot drop , 8281
 U.S. Naval Hospital occupational therapy - a group in the sun parlor , 8282
 U.S. Naval Hospital occupational therapy - weaving, 8284
 U.S. Naval Hospital occupational therapy - working on looms, 8285
 U.S. Naval Hospital - Mental Diversion, 8286
 U.S. Naval Hospital occupational therapy - carving toy making , 8287
 U.S. Naval Hospital, Ward B-1, Surgical Admission Ward, 8288
 U.S. Naval Hospital Occupational Therapy Bead Chain - Mental Cases , 8289
 U.S. Naval Hospital - Dermatological and Urological Service, Ulcerative Glossitis Leutic , 8292
 Occupational therapy basketry at the U.S. Naval Hospital, 8295
 U.S. Naval Hospital - Arm Case, Light Duty, 8300
 U.S. Naval Hospital - Light Duty , 8301
 U. S. Naval Hospital - Light Duty , 8302
 U.S. Naval Hospital - Light Duty, Diet Kitchen SOQ, 8303
 U.S. Naval Hospital - Gustafson, Amputation Up on Permanent Artificial Limb, 8304
 U.S. Naval Hospital - Occupational Therapy, Weaving Exceptionally Beneficial for Hand, Arm and Leg Trouble, 8305
 U.S. Naval Hospital Occupational Therapy Basektry Weaving Bead Chains, 8306
 U.S. Naval Hospital - Convalescent with arthritis in both knees rug weaving, 8307
 U.S. Naval Hospital - Occupational Therapy, Making Toys and Weaving, 8308
 U.S. Naval Hospital - Light Duty, Service in Diet Kitchen, 8311
 U.S. Naval Hospital - toy-making occupational therapy , 8312
 U.S. Naval Hospital Occupational Therapy - Bead Chain, C-6 Mental Cases, 8313
 Hospital Corps Demonstration for Visiting Nurses at the U.S. Naval Hospital, 8314
 U.S. Naval Hospital - Hospital Corps Drill Showing Stretcher, 8315
 U.S. Naval Hospital - Hospital Corps Drill, 8316
 U.S. Naval Hospital - Group of Hospital Nurses, 8318
 U.S. Naval Hospital - Pemphigus, 8320
 Ulna Paralysis - Typical Clay Hand Deformity , 8333
 Alopecia of Eyebrows, 8337
 USS Arkansas in Dry Dock 4 for Repairs to Bottom , 8413
 USS Arkansas in Dry Dock 4 for Repairs to Bottom, 8414
 Inclining Experiments of USS Worden , 8424
 USS Utah – First Docking in Dry Dock 4, 8429
 USS Utah – First Docking in Dry Dock 4, 8430
 USS Utah – First Docking in Dry Dock 4, 8431
 USS Utah – First Docking in Dry Dock 4, 8432
 USS Colorado in Dry Dock 3 Pumping Out, 8437
 USS New York leaving the ways, 8449
 USS New York leaving the ways, bow view, 8450

USS New York: Breaking the Bottle, 8451
 USS New York: The President and the Secretary of the Navy at the Sponsors Stand, 8452
 USS New York stern view starboard , 8453
 USS New York from an oil painting, 8454
 Electric Manhole on Ordnance Dock Near Coal Pier, 8515
 Resurfacing Tennis Courts, 8525
 View Looking North Showing Boring No. 13 at Berth 6 , 8537
 Transverse Craneway, Looking Southeast Showing Fresh and Saltwater Lines, Air Lines, and Sewer at Intersection of Second Street and Morris Avenue, 8544
 Improvement to Distribution Systems - Renewal of Steam Heating and Return Lines, 8547
 Acid Storage Tank Trench for Distributing Pipe Line, 8550
 Acid Storage Tanks Excavation for Footing Slabs , 8551
 Cofferdam for Shipways No.2, Interior View of Box Cofferdam after Pumping Down, 8556
 Cofferdams for Shipways 2 - Inner Section of Cofferdam Bracing Assembled and Ready for Launching , 8565
 Cofferdams for Shipways No. 2, View Showing Operations for Cutting Off Piles Under Water, 8574
 Extension of Crane Runways, Shipways No. 1 and No. 2 - Crane Way Extension between Tower 24 and 25, 8575
 Improvement of Distributing Systems - Concrete Steam Trench on Fourth Street, East of Building 20, Reconstruction of Steam Lines from Building 42 to Building 131, 8582
 Extension of Crane Runways Shipways 1 and 2 - Damage to North Transverse Truss, View of Top Chord from East End , 8590
 Cofferdams for Shipways No. 2 - Pile Driving Operations on Outboard End of Cofferdam, 8600
 Extension of Crane Runways, Shipways No. 1 and 2, 8602
 General View of New Welding Shed at Seawall between Dry Docks 1 and 4, 8619
 Footings for Roller Track Weldment House Near Head of Dry Dock 2, 8628
 Improvement to Buildingways No. 1 Gantry Crane at New Welding Platform, East Side of Buildingways No. 1, 8634
 Improvements to Building Ways 1 - General View of Welding Platform Locations East Side of Building Ways, 8641
 New Stress Relieving Furnace Near Seawall between Dry Docks 2 and 3, Interior View, 8652
 Turret Annealing Plant near Seawall between Dry Docks 2 and 3, 8662
 Turret Annealing Plant near Seawall between Dry Docks 2 and 3, Looking West, 8663
 Steel Framework for Welding Shed at Seawall between Dry Docks 1 and 4, 8664
 Turret Annealing Plant Near Sea Wall between Dry Docks 2 and 3 - General View and Driving Piles , 8668
 Extension of Electric Distributing System, Looking West at Berth 6, 8673
 Steel Frame for Roller Track Weldment House Near Head End of Dry Dock 2, 8686
 Excavation Showing New Air Main, West Side of New Welding Platform, 8693
 Addition to Structural Shop Building 4, Looking North from Second Street Showing Column Framing and Bracing, 8700
 Addition of Structural Shop Building 4 and Accessories for Repairs to Retaining Wall and Buttresses, West Side of New Additions, 8710
 Addition of Structural Shop and Accessories Pavings on West Side of New Addition to Building 4, 8716
 Addition of Structural Shop and Accessories Laying Railroad Tracks on South Side of Extension of Building 4, 8717
 Addition of Structural Shop and Accessories Paving Outside of Building 4 on First Street , 8732
 Addition of Structural Shop and Accessories Laying of Railroad Track Outside New Extension, View of South Side of Building, 8756
 Extension to Building 4, View in Mold Loft Showing Finished Flooring Prepared for Sanding Operation , 8773
 Extension to Building 4, View at Southeast Corner Showing Brickwork in Progress Together with Lacing Steel Sliding Door, 8778
 Extension to Building 4 Foundation for Welding Platform, 8781
 Extension to Building 4 New Bending Slab , 8782
 Extension to Building 4, View Showing Ventilator Ducts in Mold Loft Trusses, 8790
 Extension of Building 4 - View of Mold Loft Looking East Showing Installation of Sprinkler System Piping and Electric Fittings, 8795
 Extension to Building 4, Looking Eastward Showing Erection of New Steel Work including the Triangle Building in Right Background, 8825
 Extension Painting and Repairing Window Frames and Doors of Structure Shop, Building 4, 8835
 Replacing Loos and Broken Stucco on Exterior of Building 4, 8851
 USS New Orleans commissioning ceremony, 8858
 USS New Orleans commissioning ceremony, 8859
 USS New Orleans - Captain A.B. Reed reading his orders during the commissioning ceremony, 8860
 USS New Orleans Launching and Christening Ceremony, Miss Cora S. Jahncke Sponsor, 8899
 Miss Cora Jahncke (sponsor) at launching of the USS New Orleans, 8900
 USS New Orleans - View Showing Ship Leaving the Ways, 8901
 USS New Orleans After Poppet with Tricing Line, 8907
 USS New Orleans After Most Poppet – Slings Passed around Poppet underneath for Second Grip to Rise out of Water, 8920
 USS New Orleans, Looking Forward from About Frame 69, 8925
 USS New Orleans, Looking Forward from about FR 69 , 8927
 USS New Orleans, Looking Forward from About Frame 69, 8963
 USS New Orleans Assembly Section at Head of Ways , 8970
 USS New Orleans, Looking Forward, Frame 103 to Frame 53, 9017
 USS New Orleans, Looking Aft from Frame 20 to Bulkhead 60, 9033
 USS New Orleans, Looking Forward from Bulkhead 74, 9049

USS New Orleans, Looking Aft from Bulkhead 74, 9050
 USS New Orleans Bulkhead Assemblies in Field at Building Ways, 9065
 USS New Orleans, View about Midships Looking Aft, 9067
 USS New Orleans View Looking Forward from Frame 68, 9126
 USS Louisville Showing Crack in Rudder Cross Head VED Out 1 1/2" x 5" Deep Before Welding, 9127
 USS Louisville Showing Crack in Rudder Cross Head VED Out 1 1/2" x 5" Deep Before Welding, 9128
 USS Louisville Showing Crack in Rudder Cross Head which was VED Out 1 1/2" x 5" Deep After Welding, 9141
 USS Louisville Showing Crack in Rudder Cross Head which was VED Out 1 1/2" x 5" Deep After Welding, 9142
 USS New Orleans Drilling for Tap Holes in Back Face of Armor, 9180
 USS Brooklyn (CL-40), View Looking Aft, 9259
 USS Brooklyn (CL-40) - Laying of the Keel in Buildingways No. 2, 9262
 First Rivet Driven at the Keel Laying of the USS Brooklyn, 9263
 First Rivet Driven at the Keel Laying of the USS Brooklyn, 9264
 USS Brooklyn Sponsors Party , 9403
 USS Brooklyn - Miss Hester Laning, maid of honor, Miss Kathryn Jane Lackey, sponsor, Miss Dorothea Legenhausen, maid of honor, 9404
 USS Brooklyn - Miss Kathryn Jane Lackey, Sponsor, 9406
 Christening of the USS Brooklyn - Miss Kathryn Jane Lackey, Sponsor, 9407
 USS Brooklyn (CL-40), Turret No. 5, 9431
 USS Brooklyn, 9434
 USS Brooklyn, 9435
 USS Brooklyn, 9436
 USS Brooklyn, 9437
 USS Brooklyn, 9438
 Commissioning Ceremony - USS Brooklyn, 9439
 Commissioning Ceremony USS Brooklyn, 9440
 Commissioning Ceremony USS Brooklyn, 9442
 Commissioning Ceremony USS Brooklyn, 9443
 Commissioning ceremony for the USS Brooklyn, featuring Mr. Edwin H. Thatcher, Admiral Harris Laning, and Captain William D. Brereton, Jr., 9444
 USS Brooklyn - Test of Turret Buffer , 9445
 USS Brooklyn - Test of Turret Buffer, 9446
 Dry Dock 4 - Yard Renewing Floor, View at Entrance Showing Brick Paving Under Sluice Gates, 9456
 Dry Dock 4 - Yard Labor Renewing the Floor Looking North Toward Entrance, 9457
 Dry Dock 4 - Yard Labor Renewing the Floor Looking North Toward Entrance, 9458
 Dry Dock 4 - Renewing the Floor, Looking North Toward Entrance, 9459
 Ericsson (TB-2), Port Stern Quarter, at Wharf, 14767
 USS Kearsarge (BB-5), Port Bow, at Wharf, 14768
 Massachusetts (BB-2). Starboard Bow at Wharf, 14769
 USS Iowa (BB-4), Port Bow, Entering Dry Dock, 14770
 USS Houston (AK1), formerly the SS Liebenfels Cargo Ship, Starboard Bow, at Wharf, 14771
 Dry Dock 4 Monthly Progress Photo – Durax Pavement Looking North from Building 41 (58), 9497
 Dry Dock 4 Monthly Progress Photo - Durax Pavement Looking Northwest from Building 41 (58), 9498
 Dry Dock 4 Monthly Progress Photo – Form for Bollard Foundation, EAST Side Looking West, 9501
 Dry Dock 4 Monthly Progress Photo – Grading Looking Northeast, 9552
 Dry Dock 4 Monthly Progress Photo – Pumpwell Looking East, 9559
 Dry Dock 4 Monthly Progress Photo – East Approach Wall Looking Southwest, 9560
 Dry Dock 4 Monthly Progress Photo – New Outlet for Sewer, East Side of Dry Dock, Looking Southeast, 9562
 Dry Dock 4 Monthly Progress Photo – New Outlet for Sewer East of Dry Dock, Looking Southwest, 9563
 Dry Dock 4 Monthly Progress Photo – Looking Northeast from the East End Caisson, East Approach Wall, 9564
 Dry Dock 4 Monthly Progress Photo Looking East from the East End of Caisson , 9565
 Dry Dock 4 Monthly Progress Photo – Looking Southeast from East End of Caisson, 9566
 Dry Dock 4 Monthly Progress Photo Looking South from the East End of the Caisson , 9567
 Dry Dock 4 Monthly Progress Photo Looking Northwest from West End of Caisson, 9570
 Dry Dock 4 Monthly Progress Photo – Looking Southwest from West End of Caisson , 9572
 Dry Dock 4 Monthly Progress Photo Looking East from Building 41, 9573
 Dry Dock 4 Monthly Progress Photo – Looking Northeast from Building 41, 9574
 Dry Dock 4 Monthly Progress Photo Looking North from Building 41 , 9576
 Dry Dock 4 Monthly Progress Photo – West Approach Wall Looking Southwest, 9578
 Dry Dock 4 Monthly Progress Photo – General View Looking South, 9579
 Dry Dock 4 Monthly Progress Photo – General View Looking South, 9580
 Dry Dock 4 Monthly Progress Photo – General View Looking North, USS North Dakota, 9581
 Dry Dock 4 Monthly Progress Photo – East Approach Wall, Looking Southwest, 9582
 Dry Dock 4 Monthly Progress Photo – East Approach Wall Looking East , 9583
 Dry Dock 4 Monthly Progress Photo – Pumpwell Roof Looking North , 9584

Dry Dock 4 Monthly Progress Photo – Backing West Approach Wall Looking North, 9585
 Dry Dock 4 Monthly Progress Photo – West Approach Wall Looking West, 9586
 Dry Dock 4 Monthly Progress Photo – West Approach Wall from East Side, 9587
 Dry Dock 4 Monthly Progress Photo – West Approach Wall from East Side, 9588
 Dry Dock 4 Monthly Progress Photo – East Approach Wall from West Wall, 9589
 Dry Dock 4 Monthly Progress Photo – East Approach Wall from West Wall, 9590
 Dry Dock 4 Monthly Progress Photo – General View Looking North, 9593
 Dry Dock 4 Monthly Progress Photo – East Approach Wall, Looking Southwest , 9597
 Dry Dock 4 Monthly Progress Photo – West Approach Wall, Looking West, 9598
 USS Utah - First Docking in Dry Dock 4, 9603
 Dry Dock 4, First Vessel Docked - USS Utah, 9616
 Dry Dock 4, First Vessel Docked - USS Utah, 9617
 Dry Dock 4, First Vessel Docked - USS Utah, 9618
 Dry Dock 4, First Vessel Docked - USS Utah, 9619
 Dry Dock 4, First Vessel Docked - USS Utah, 9620
 Dry Dock 4, First Vessel Docked - USS Utah, 9621
 Dry Dock 4, First Vessel Docked - USS Utah, 9622
 Dry Dock 4, First Vessel Docked - USS Utah, 9623
 Dry Dock 4, First Vessel Docked - USS Utah, 9624
 Dry Dock 4, First Vessel Docked - USS Utah, 9625
 Dry Dock 4, First Vessel Docked - USS Utah, 9626
 Dry Dock 4, First Vessel Docked - USS Utah, 9627
 Dry Dock 4, First Vessel Docked - USS Utah, 9628
 Dry Dock 4 - First vessel docked, USS Utah, 9629
 Dry Dock 4, First Vessel Docked - USS Utah, 9630
 Dry Dock 4, First Vessel Docked - USS Utah, 9631
 Dry Dock 4, First Vessel Docked - USS Utah, 9632
 Dry Dock 4, First Vessel Docked - USS Utah, 9633
 Dry Dock 4, First Vessel Docked - USS Utah, 9636
 Dry Dock 4, First Vessel Docked - USS Utah, 9637
 Dry Dock 4, First Vessel Docked - USS Utah, 9638
 Dry Dock 4, First Vessel Docked - USS Utah, 9639
 Dry Dock 4, First Vessel Docked - Blocking Ready for USS Utah, 9640
 Sub-assembly - shop improvements of shop buildings and steel storage runway, 9645
 Sub-assembly shop improvements of shop and steel storage runways, 9646
 Sub-assembly shop and improvements of shop buildings and steel storage runways , 9647
 Sub-assembly shop - improvements of shop buildings and steel runways , 9648
 Sub-assembly Shop No. 2, Building 269 - View looking west from Building 70, showing column footings, 9649
 Sub-assembly Shop No. 2, Building 269, view looking west from Building 70 showing column footings, 9650
 Sub-assembly Shop No. 2, building 269, View Looking East from Second Street and Dock Street , 9651
 Dry Dock 4 Monthly Progress Photo – Timber on Dock of Floor Looking South, 9709
 Dry Dock 4 Monthly Progress Photo – Foms for Concrete Sewer, 9710
 Dry Dock 4 Monthly Progress Photo – Water Flowing from 8" Pipe through Dock Floor, 9711
 Dry Dock 4 Monthly Progress Photo – Cofferdam from Dock Floor, 9712
 Dry Dock 4 Monthly Progress Photo – Condenser Intake Cofferdam, Looking East, 9713
 Dry Dock 4 Monthly Progress Photo – Condenser Pipes Looking North, 9714
 Dry Dock 4 Monthly Progress Photo – Elevated Duct Change Around Head, East End, 9715
 Dry Dock 4 Monthly Progress Photo – Elevated Duct Change around Head, West End Looking South. , 9716
 Dry Dock 4 Monthly Progress Photo – Caisson Condenser System Inlet, Looking West, 9719
 Dry Dock 4 Monthly Progress Photo – North End Wall, Looking South, 9720
 Dry Dock 4 Monthly Progress Photo – North End of West Wall, Looking Southwest, 9721
 Dry Dock 4 Monthly Progress Photo – North End of East Wall, Looking South, 9722
 Dry Dock 4 Monthly Progress Photo – North End of West Wall Viewed from East Wall, 9723
 Dry Dock 4 Monthly Progress Photo – South End of West Wall, Looking Northwest, 9724
 Dry Dock 4 Monthly Progress Photo – Trench for Condenser Pipes, 9725
 Dry Dock 4 Monthly Progress Photo – Cofferdam from Dock Floor, 9726
 Dry Dock 4 Monthly Progress Photo – Capstan Foundation, Head of Dock, 9727
 Dry Dock 4 Monthly Progress Photo – Junction of Old and New Sewer, Looking South, 9728
 Dry Dock 4 Monthly Progress Photo – Head of Dock Looking West, 9729
 Dry Dock 4 Monthly Progress Photo – East Wall Backing Looking North, 9730
 Dry Dock 4 Monthly Progress Photo – General View Looking North, 9731
 Dry Dock 4 Monthly Progress Photo – South End of Wall, Looking Northeast, 9732
 Dry Dock 4 Monthly Progress Photo – West Wall Backing Looking North, 9734
 Dry Dock 4 Monthly Progress Photo – West Wall Backing Head of Dock , 9735
 Dry Dock 4 Monthly Progress Photo – General view Looking North, 9747

Dry Dock 4 Monthly Progress Photo – General view Looking South, 9748
 Dry Dock 4 Monthly Progress Photo – Motor Floor, 9759
 Dry Dock 4 Monthly Progress Photo – Cofferdam, Dredging Entrance, 9760
 Dry Dock 4 Monthly Progress Photo – Dredging Entrance, 9761
 Dry Dock 4 Monthly Progress Photo – General View Looking Southwest, 9781
 Dry Dock 4 Monthly Progress Photo – Capstan in Building 41, Looking Southwest, 9785
 Dry Dock 4 Monthly Progress Photo – Addition to Building 41 Condenser System Piping , 9787
 Dry Dock 4 Monthly Progress Photo – Pumpwell Looking North over Main Gallery Floor, 9789
 Dry Dock 4 Monthly Progress Photo – Pumpwell Motor Floor, Looking North, 9790
 Dry Dock 4 Monthly Progress Photo – Pumpwell Roof Looking Northwest, 9791
 Dry Dock 4 Monthly Progress Photo – Suction Intake from Water Side, 9792
 Dry Dock 4 Monthly Progress Photo Looking Northeast from the West Side Near Abutment , 9819
 Dry Dock 4 Monthly Progress Photo – General view Looking Southwest, 9823
 Dry Dock 4 Monthly Progress Photo – Caisson, 9824
 Dry Dock 4 Monthly Progress Photo – West Entrance Wall Looking West, 9827
 Dry Dock 4 Monthly Progress Photo – Pumpwell Roof looking Northeast, 9828
 Dry Dock 4 Monthly Progress Photo – Sewer Junction Looking Northeast, 9829
 Dry Dock 4 Monthly Progress Photo – Capstan in Building 41 Looking Southeast, 9830
 Dry Dock 4 Monthly Progress Photo – Capstan in Building 41 Looking Southwest, 9831
 Dry Dock 4 Monthly Progress Photo – Suction Pipe Trench near Waterfront, 9832
 Dry Dock 4 Monthly Progress Photo – Pumpwell Looking Southeast, Showing Pump , 9833
 Dry Dock 4 Monthly Progress Photo – Pumpwell Looking Northeast, Showing Pump, 9834
 Dry Dock 4 Monthly Progress Photo – Pumpwell Main Gallery Floor Looking Northeast, 9835
 Dry Dock 4 Monthly Progress Photo – General View from Building 41, 9837
 Dry Dock 4 Monthly Progress Photo – General View from Caisson, 9838
 Dry Dock 4 Monthly Progress Photo – General view from Building 41, 9840
 Dry Dock 4 Monthly Progress Photo – East Approach Wall Looking Northeast, 9841
 Dry Dock 4 Monthly Progress Photo – West Approach Wall, Looking Northwest, 9842
 Dry Dock 4 Monthly Progress Photo – Crane Track Foundation, East Side Near Entrance Looking North East, 9845
 Dry Dock 4 Monthly Progress Photo – Pumpwell Roof Looking Southwest, 9846
 Dry Dock 4 Monthly Progress Photo – Capstan Foundation Head of Dry Dock, 9848
 Dry Dock 4 Monthly Progress Photo – Cofferdam from Dock Floor, 9849
 Dry Dock 4 Monthly Progress Photo – South End of West Wall Looking Northwest, 9851
 Dry Dock 4 Monthly Progress Photo – Pump Well Discharge Culvert Forms, 9853
 Dry Dock 4 Monthly Progress Photo – North End of East Wall, Looking South, 9854
 Dry Dock 4 Monthly Progress Photo – North End of West Wall, Looking Southwest, 9855
 Dry Dock 4 Monthly Progress Photo – Caisson Condenser System Inlet, Looking West, 9856
 Dry Dock 4 Monthly Progress Photo – Elevated Duct Change Around Head, East End, 9858
 Dry Dock 4 Monthly Progress Photo – Condenser Pipes Looking North , 9859
 Dry Dock 4 Monthly Progress Photo – Condenser Intake Cofferdam Looking East, 9860
 Dry Dock 4 Monthly Progress Photo – Cofferdam from Dock Floor, 9861
 Dry Dock 4 Monthly Progress Photo – Water Flowing from 8" Pipe through Dock Floor, 9862
 Dry Dock 4 Monthly Progress Photo – Forms for Concrete Sewer, 9863
 Dry Dock 4 Monthly Progress Photo – Timber on Dock Floor Looking South, 9864
 Dry Dock 4 Monthly Progress Photo – Head of Dock from Scaffold at Slide 8, 9865
 Dry Dock 4 Monthly Progress Photo – North End of East Wall, Looking South, 9889
 Dry Dock 4 Monthly Progress Photo – End of West Wall Looking South, 9890
 Dry Dock 4 Monthly Progress Photo – General view Looking South, 9899
 Dry Dock 4 Monthly Progress Photo – General View Looking Monthly , 9906
 Dry Dock 4 - Water Flowing from Pipe through Floor, 9909
 Dry Dock 4 - Water Flowing from 8" Pipe through Dock Floor, 9914
 Dry Dock 4 Monthly Progress Photo – Ground Water Flowing from Pipe in Floor, 9923
 Dry Dock 4 Monthly Progress Photo – Cofferdam from Dock Bottom Looking North, 9925
 Dry Dock 4 Monthly Progress Photo – Backing of East Wall, Looking North, 9926
 Dry Dock 4 Monthly Progress Photo – South End of East Wall, Looking Northeast, 9928
 Monthly progress photo - addition to Building 131 for latrine for Dry Dock 4, 10108
 Dry Dock 4 - Old Sheet Piling, Panel 31, 10113
 General View, Head End from Derrick No. 7, 10124
 Panel 33 View from Southwest, 10129
 Crates of Supplies for the USS Santa Olivia, Erie Basin Barge 95, 11040
 Crates of Supplies for the USS Santa Olivia, Erie Basin Barge 95, 11041
 Crates of Supplies for the USS Santa Olivia, Erie Basin Barge 95, 11042
 Sacks and Crates of Supplies for the USS Santa Olivia, Erie Basin Barge 95, 11043
 USS Ohion, Barge Fashion, 11044
 USS Ohion, Barge Fashion, 11045

USS Ohion, Barge Fashion, 11046
USS Ohion, Barge Fashion, 11049
Gowanus Reserve Coal Station, 11053
Office of the Inspector of Engineering Materials, 44 Court Street, Lieutenant Commander McCallister, 11162
General View Showing Broken Bearings, 11228
Dreadnaught Safety Suit - Method of Fastening Inside Bag, 11231
Dreadnaught Safety Suit Showing Entrance Bag, 11232
Dreadnaught Safety Suit Completely Donned, 11233
Dreadnaught Safety Suit Closing Entrance Bag, 11234
LAND PRODUCTS CO NEW YORK ENGINEERING DEPARTMENT, 11247
Removal of Cells from Building 88 for Installation in Building 14 , 3181
Location of New Gate and Guard House at Cumberland Street, Excavating for Foundation and Driving Tube Piling , 3196
FORMS FOR NEW TURET FOUNDATIONS AT SEA WALL BET DRY DOCKS 1 AND 4 ALLOT 7X127-1-4 YARD LABOR, 3542
WORKS PROGRESS ADMINISTRATION GENERAL VIEW OF TUNNEL EXCAVATION – SHORING AND CONCRETING OF BRICK ARCHES SUPPORTING MACHINE SHOP FLOOR BLDG 128 (NORTH END), 3543
WORKS PROGRESS ADMINISTRATION SHORING OF FOOTING WITH USE OF JACK UNDER FOOTING OF COLUMNS NO 25 AND 26 SECTION 'D' MACHINE SHOP BLDG 128 YARD PROJ 11 'B' OFFICIAL PROJ 209-2021 , 3544
WORKS PROGRESS ADMINISTRATION BRICK ARCH SUPPORTING FLOOR AT NORTH END OF MACHINE SHOP BLDG 128 YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3545
WORKS PROGRESS ADMINISTRATION NEW UNDERPINNING TO FOTINGS UNDER COLUMNS 13 AND 14 MACHINE SHOP BLDG 128, 3546
WORKS PROGRESS ADMINISTRATION EXCAVATING AND GRADING FOR CONCRETE PAVING AT WATERFRONT BETWEEN DRY DOCKS 2 AND 4 YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3547
WORKS PROGRESS ADMINISTRATION STORM SEWER BETWEEN DRY DOCKS 2 AND 4 EXPOSED IN THE EXCAVATION AND GRADING FOR REPAVING OF WATERFRONT YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3548
WORKS PROGRESS ADMINISTRATION GENERAL VIEW OF TUNNEL UNDER FLOOR OF MACHINE SHOP LOOKING FROM 5TH ST END BLDG 128 YARD PROJECT 11 'B' OFFICIAL PROJ 209 – 2021, 3549
WORKS PROGRESS ADMINISTRATION REPAIRS TO FOUNDATION EAST SIDE OF BLDG 120 SWINGING PILE OVER TO POSITION FOR DRIVING YARD PROJ 11'B' OFFICAIL PROJ 209-2021, 3550
WORKS PROGRESS ADMINISTRATION DRIVING PILE IN REPAIR TO FOUNDATION OF BLDG 120 YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3551
WORKS PROGRESS ADMINISTRATION LAYING CONCRETE PAVEMENT SLABS AT WATERFRONT BETWEEN DRY DOCSK 2 AND 4 YARD PROJ 11 'B' OFFICIAL 209-2021, 3552
WORKS PROGRESS ADMINISTRATION EXPOSED PILE IN TEST PIT UNDER COLUMNS 11 AND 12 MACHINE SHOP BLDG 128 YARD LABOR PROJ 11 'B' OFFICIAL PROJ 209-2021, 3553
WORKS PROGRESS ADMINISTRATION FOUNDATION WALL OVER PIER AT – W11 – MORRIS AVE SIDE OF BLDG 128 YARD PROJ – 11 B OFFICIAL PROJ 209-2021 (VIEW SHOWING CRACK IN WALL), 3554
WORKS PROGRESS ADMINISTRATION UPRIGHT SUPPORTING PILE CAP PIT WII MORRIS AVE SIDE OF BLDG 128 MACHINE SHOP YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3555
WORKS PROGRESS ADMINISTRATION PILE CONDITIONS AND JACKS BETWEEN CAP AND PILE CUT OFF UNDER COLUMNS 17 AND 18 YARD PROJ 11 B OFFICIAL PROJ 209-2021, 3556
WORKS PROGRESS ADMINISTRATION EXPOSED PILE UNDER FOOTING OF COLUMNS 17 AND 18 IN BLDG 128 YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3557
WORKS PROGRESS ADMINISTRATION EXPOSED PILES UNDER FOOTIN OF COLUMNS 17 AND 18 IN BLDG 128 YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3558
WORKS PROGRESS ADMINISTRATION TEST PIT UNDER CLOUMNS 17 AND 18 NO END OF BLDG 128 5TH ST SIDE YARD PROJECT 11 'B' OFFICIAL PROJ 209 – 2021, 3559
WORKS PROGRESS ADMINISTRATION VIEW SHOWING DETERIORATED PILES UNDER COLUMNS 17 AND 18 NO END OF BLDG 128 5TH ST SIDE YARD PROJ 11'B' OFFICIAL PROJ 209-2021, 3560
WORKS PROGRESS ADMINISTRATION EXPOSED PILE UNDER COLUMNS 17 AND 18 SHOWING STEEL UPRIGHTS AND JACK FROM CUT OFF TO CONCRETE CAP BLDG 128 5TH ST SIDE YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3561
WORKS PROGRESS ADMINISTRATION STEEL UPRIGHTS AND JACKS MAINTAINING FOOTING UNDER COLUMNS 17 AND 18 BLDG 128 5TH ST SIDE YARD PROJ 11 'B' OFFICIAL 209-2021, 3562
WORKS PROGRESS ADMINISTRATION TEST PIT UNDER OLD FOOTING TO COLUMNS 17 AND 18 BLDG 128 5TH SIDE YARD LABOR PROJ 11 'B' OFFICIAL PROJ 209-2021, 3563
WORKS PROGRESS ADMINISTRATION PAVING AT ENTRANCE OF NEW CUMBERLAND ST GATE YARD PROJ – 11 'B' OFFICIAL PROJ 209-2021, 3564
WORKS PROGRESS ADMINISTRATION SETTING GRANITE FOR NEW CUMBERLAND ST GATE ANCHORAGE YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3565
WORKS PROGRESS ADMINISTRATION EXCAVATION SHOWING CONDITION AT BASE OF CRANE COLUMN "E 4" MORRIS AVE SIDE OF FOUNDRY BLDG 29 YARD PROJ 11 'A' OFFICIAL PROJ 209-2021, 3567
WORKS PROGRESS ADMINISTRATION ERECTION PF STEEL TRUSSES EXTENSION TO MARINE BARRACKS BLDG 13 YARD PROJ 11 OFFICIAL PROJ 209-2021, 3568
WORKS PROGRESS GENERAL VIEW SHOWING PORCH STEEL WORK ON PERRY AVE SIDE OF BLDG NO 13 YARD PROJECT 11 OFFICIAL PROJ 209 – 2021, 3569

WORKS PROGRESS ADMINISTRATION RR TRACK IMPROVEMENTS NEAR BLDG WAYS NO 1 YARD PROJ 12 OFFICIAL PROJ 209-4019, 3571

WORKS PROGRESS ADMINISTRATION FRONT ELEVATION OF BLDG NO 50 YARD PROJ 11 OFFICIAL PROJ 209-2021, 3575 untitled, 3579

WORKS PROGRESS ADMINISTRATION CUMBERLAND ST GATE GUARD HOUSE LAYING BRICK OF GUARD HOUSE YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3581

WORKS PROGRESS ADMINISTRATION WEATHER PROTECTION IN THE CONSTRUCTION OF NEW CUMBERLAND ST GATE YARD PROJ 11 'B' OFFICIAL 209-2021, 3582

WORKS PROGRESS ADMINISTRATION RR TRACK IMPROVEMENT NEAR BLDG WAYS AND BLDG NO 4 YARD PROJ 12 OFFICIAL PROJ 209-4019, 3585

WORKS PROGRESS ADMINISTRATION RR TRACK IMPROVEMENTS NO SIDE OF BLDG NO 4 YARD PROJ NO 12 OFFICIAL PROJ 209-4019, 3586

WORKS PROGRESS ADMINISTRATION MAN HOLE FOR WATER VALVE AT NEW GUARD HOUSE CUMBERLAND ST GATE YARD PROJ 12 OFFICIAL PROJ 209-4019, 3587

WORKS PROGRESS ADMINISTRATION BRICKING UP WALLS FOR ADDITION TO MOTION PICTURE EXCHANGE BLDG NO 213 YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3589

WORKS PROGRESS ADMINISTRATION GENERAL VIEW OF NEW CUMBERLAND ST GATE YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3590

WORKS PROGRESS ADMINISTRATION OFFICE OF GARAGE MECHANIC 2ND FLOOR BLDG NO 50 YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3591

WORKS PROGRESS ADMINISTRATION SHOWER ROOM IN GARAGE BLDG NO 50 2ND FLOOR YARD PROJ 11 OFFICIAL 209-2021, 3592

WORKS PROGRESS ADMINISTRATION TOILET IN NEW GARAGE BLDG NO 50 2ND FLOOR YARD PROJ 11 OFFICIAL PROJ 209-2021, 3593

WORKS PROGRESS ADMINISTRATION WASH ROOM 2ND FLOOR GARAGE BLDG NO 50 YARD PROJ 11 OFFICIAL PROJ 209-2021, 3594

WORKS PROGRESS ADMINISTRATION GARAGE REPAIR SHOP BLDG NO 50 YARD PROJ 11 OFFICIAL PROJ 209-2021, 3595

WORKS PROGRESS ADMINISTRATION MARINE BARRACKS EXTENSION BLDG 13 PERRY AVE SIDE OF BLDG YARD PROJ NO 11 OFFICIAL PROJ 209-2021, 3596

WORKS PROGRESS ADMINISTRATION TILE FLOORING 1ST FLOOR IN EXTENSION BLDG 13 YARD PROJ 11 OFFICIAL PROJ 209-2021, 3597

WORKS PROGRESS ADMINISTRATION MEZZANINE TANK FLOOR SO EAST CORNER 1ST FLOOR BLDG 13 MARINE BARRACKS YARD PROJ 11 OFFICIAL PROJ 209-2021, 3598

WORKS PROGRESS ADMINISTRATION GENERAL VIEW OF MARINE BARRACKS 'BLDG NO 13' EXTENSION CHAUNCEY AVE SIDE YARD PROJ 11 OFFICIAL PROJ 209-2021, 3599

FOUNDRY BLDG NO 29 WORKS PROGRESS ADMINISTRATION EXCAVATING AND REMOVING OLD BRICK FOOTING UNDER COLUMN NO 2 E YARD PROJ 11 OFFICIAL PROJ 209-2021, 3600

WORKS PROGRESS ADMINISTRATION SKYLIGHT ROOF AND COPPER GUTTERS BLDG NO 11 – 3RD ST SIDE YARD PROJ 2 A SUB PROJ 1 OFFICIAL PROJ 0912 NEC 612, 3601

WORKS PROGRESS ADMINISTRATION PLUMBING INSTALLATION OF WATER FEED AND DRAIN LINES FOR TOILETS AND SHOWERS 1ST FLOOR BLDG 23 YARD PROJ 11 'B' OFFICIAL 209-2021, 3602

WORKS PROGRESS ADMINISTRATION DEMOLITION OF OLD GUARD HOUSE BLDG 138 AT 'OLD' CUMBERLAND ST GATE YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3603

Demolition of Old Guard House, Building 138 at Old Cumberland Street Gate, 3604

WORKS PROGRESS ADMINISTRATION SCREEN WALL AND LECTURE PLATFORM PROJECTION SCHOOL ADJOINING MOTION PICTURE EXCHANGE BLDG NO 213 YARD PROJ 11 'B' OFFICIAL PROJ 209-2021, 3608

WORKS PROGRESS ADMINISTRATION INTERIOR OF PROJECTION SCHOOL ADJOINING MOTION PICTURE EXCHANGE BLDG 213 YARD PROJ 11 B OFFICIAL PROJ 209-2021, 3609

FERTILIZER BINS NO SIDE OF BLDG NO 32 YARD LABOR, 3610

Repairing Scrap Metal Bins, Building 322, 3611

WORKS PROGRESS ADMINISTRATION MESS HALL UNDER CONSTRUCTION NEW EXTENSION TO MARINE BARRACKS BLDG NO 13 YARD PROJ 11 A OFFICIAL PROJ 209-2021, 3612

WORKS PROGRESS ADMINISTRATION KITCHEN SHOWING SERVICE WINDOW TO MESS HALL – TILE FLOORING AND GLAZE TILE WAINSCOATING YARD PROJ 11 OFFICIAL 209-2021, 3613

WORKS PROGRESS ADMINISTRATION TOILET WATER LINES 2ND FLOOR MARINE BARRACKS EXTENSION BLDG NO 13 YARD PROJ 11 'A' OFFICIAL PROJ 209-2021, 3614

WORKS PROGRESS ADMINISTRATION TOILET WATER LINES 2ND FLOOR MARINE BARRACKS EXTENSION BLDG NO 13 YARD PROJ 11 'A' OFFICIAL PROJ 209-2021, 3615

NEW CUMBERLAND ST ENTRANCE WITH LANDSCAPING BY YARD LABOR, 3616

WORKS PROGRESS ADMINISTRATION RIFLE RANGE ALLEY IN ATTIC OF MARINE BARRACKS EXTENSION BLDG 13 YARD PROJ 11 'A' OFFICIAL PROJ 209-2021, 3617

WORKS PROGRESS ADMINISTRATION EXTERIOR VIEW OF MARINE BARRACKS BLDG NO 13 NEW EXTENSION PERRY AVE SIDE YARD PROJ NO 11 'A' OFFICIAL PROJ 209-2021, 3619

DREDGEING [SIC] IN AREA '6' NAVY YARD BASIN CONTRACT NOY 2837, 3622

FORM WORK AND PLACING CONCRETE FOR NEW PICKLING PLANT FOUNDATIONS STEEL STORAGE YARD A LOT C AND R YARD LABOR, 3630

GENERAL VIEW OF CONSTRUCTION OF NEW PLATE RACK FOUNDATIONS VIEW LOOKING INBOARD BETWEEN LITTLE MEANY AND LITTLE ST ALLOT 7X127-3-4 YARD LABOR, 3631

GENERAL VIEW OF NEW PLATE RACK FOUNDATIONS VIEW LOOKING IN BOARD FROM LITTLE MEANY ALLOT 7X127-3-4 YARD LABOR, 3632

GENERAL VIEW OF CONSTRUCTION OF NEW PLATE RACKS VIEW LOOKING INBOARD FROM LITTLE MEANY ALLOT 7X127-3-4 YARD LABOR, 3633

IMPROVEMENTS [SIC] TO BLDG WAYS NO 1 GENERAL VIEW SHOWING KEEL BLOCK FORMS ALLOT 7X127-3-4 YARD LABOR, 3634

Improvement to Building Ways No.1 - Excavating for Extension to Working Platform, 3636

IMPROVEMENT [SIC] TO BLDG WAYS NO 1 PILE NETS EXPOSED AT HEAD OF WAYS ALLOT 7X127-3-4 YARD LABOR, 3637

IMPROVEMENT TO BLDG WAYS NO 1 POURING CONCRETE ALLOT 7X127-A-0400 (C AND R) YARD LABOR, 3638

IMPROVEMENT TO BLDG WAYS NO 1 EXCAVATION AT HEAD END FOR EXTENSION OF WAYS VIEW SHOWING OLD PILES ALLOT 7X127-3-3 YARD LABOR, 3639

IMPROVEMENT TO BLDG WAYS NO 1 FOUNDATION FOR WORKING PLATFORM (EAST SIDE) POURING CONCRETE ALLOT 7X123-3-3 YARD LABOR, 3640

GENERAL VIEW OF CONSTRUCTION OF NEW PLAT RACK FOUNDATIONS NEAR LITTLE ST ALLOT 7X127-3-4 YARD LABOR, 3641

GENERAL VIEW OF CONSTRUCTION OF PLATERACK FOUNDATIONS NEAR LITTLE ST ALLOT 7X127-3-4 YARD LABOR, 3642

RELOCATING SEWER FOR TURRET FOUNDATIONS NEAR SEAWALL BETWEEN DRY DOCKS NO 1 AND 4 ALLOT 7X127-1-4 YARD LABOR, 3643

RELOCATING SEWER FOR TURRET FOUNDATIONS NEAR SEAWALL BETWEEN DRY DOCKS NO 1 AND 4 ALLOT 7X127-1-4 YARD LABOR (GENERAL VIEW), 3644

GENERAL VIEW OF NEW STEEL SHAPE FOUNDATION NEAR LITTLE ST PIER ALLOT (LOOK INBOARD) 7X127-3-4 YARD LABOR, 3645

GENERAL VIEW OF NEW STEEL SHAPE FOUNDATONS NEAR LITTLE ST PIER ALLOT 7X127-3-4 YARD LABOR VIEW LOOKING INBOARD, 3646

GENERAL VIEW OF NEW STEEL SHAPE FOUNDATIONS NEAR LITTLE ST PIER ALLOT 7X127-3-4 YARD LABOR VIEW LOOKING INBOARD, 3647

DRIVING PILES AND FORM WORK FOR NEW TURRET FOUNDATIONS AT SEA WALL BETWEEN DRY DOCKS NO 1 AND 4 ALLOT 7X127-1-4, 3648

IMPROVEMENT TO BLDG WAYS NO 1 GENERAL VIEW AT HEAD OF WAYS SHOWNG REINFORCEMENT STEEL IN PLACE ALLOT 7X127-3-3 YARD LABOR, 3649

IMPROVEMENT TO BLDG WAYS NO 1 WELDING PLATFORM FOUNDATIONS EAST SIDE OF WAYS LOOKING AFT ALLOT 7X127-3-3 YARD LABOR, 3650

GENERAL VIEW OF NEW STEEL SHAPE FOUNDATIONS NEAR LITTLE ST PIER ALLOT 7X127-3-4 YARD LABOR (COMPLEATE [SIC], 3651

GENERAL VIEW OF NEW STEEL SHAPE FOUNDATIONS NEAR LITTLE ST PIER ALLOT 7X127-3-4 YARD LABOR, 3652

IMPROVEMENT TO BLDG WAYS NO 1 WIDEING [SIC] OF WORKING PLATFORM EAST SIDE OF WAYS ALLOT 7X127-3-3 YARD LABOR, 3653

IMPROVEMENT TO BLDGWAYS GENERAL VIEW OF WELDING PLATFORM LOCATION EAST SIDE OF BLDG WAYS NO 1 ALLOT 7X127-1-8 YARD LABOR, 3654

TURRET AND ERECTIONS SHOP BUILDING AND ACCESSORIES TEST PITS AT SITE OF NEW TURRET AND ASSEMBLY SHOPS ALLOT 7X218 – 42 – 1 YRD [SIC] LABOR, 3656

ACID STORAGE TANKS AT SHIPWAYS VIEW SHOWING TRENCH FOR ACID DISTRIBUTING LINES APPN RNV (C AND M) YARD LABOR, 3658

IMPROVEMENT OF DISTRIBUTING SYSTEMS – INSTALLATION NEW SALTWATER HYDRANT NORTH BUILDING NO 214 ALLOT 7X218 – 35 YARD LABOR, 3660

COFFERDAMS FOR SHIPWAYS NO 2 INTERIOR VIEW OF BOX COFFERDAM SHOWING REINFORCING STEEL FOR E GROUNDWAYS CONTRACT NOY 3352_, 3661

COFFERDAMS FOR SHIPWAYS NO 2 INTERIOR VIEW OF BOX COFFERDAM SHOWING FORMS FOR W GROUNDWAYS CONTRACT NOY 3352, 3662

COFFERDAMS FOR SHIPWAYS 2 GENERAL VIEW FROM EAST SIDE OF BUILDING WAYS 2 CONTRACT NOY 3352, 3663

SULPHURIC ACID STORAGE TANKS – VIEW LOOKING WEST SHOWING TANKS IN PLACE ALLOT APPN RNV C AND M JO 012 – 127 H/X1140 YARD LABOR, 3664

"TURRET AND ERECTION SHOPS" INSTALLATION FOUNDATIONS FOR STORAGE OF STEEL PLATE AT ORDNANCE DOCK VIEW LOOKIN EAST ALLOT 7X218 – 42 – 1 YARD LABOR, 3665

TURRET AND ERECTION SHOPS GRADING SITE FOR STORAGE OF STEEL PLATE AT ORDNANCE DOCK VIEW LOOKING EAST SHOWING INSTALLATION OF NEW TRACK ALLOT 7X218 – 42 0 1 YARD LABOR, 3666

TURRET AND ERECTION SHOPS INSTALLATION FOUNDATIONS FOR STORAGE OF STEEL PLATE AND RELOCATING STEAM LINE AT ORDNANCE DOCK VIEW LOOKING SOUTH ALLOT 7X218 – 42 – 1 YARD LABOR, 3667

IMPROVEMENT OF DISTRIBUTING SYSTEM RECONSTRUCTION OF STEAM AND RETURN LINES ON PAULDING AVE EAST OF BLDG 5 VIEW LOOKING WEST ALLOT 7X218 – 35 – 1 YARD LABOR, 3668

COFFERDAMS FOR SHIPWAYS NO 2 GENERAL VIEW OF W FACE OF W GROUNDWAYS TUNNELS 1 – TO – 7 CONTRACT NOY 3352, 3669

COFFERDAMS FOR SHIPWAYS NO 2 W FACE OF W GROUNDWAYS TUNNEL 4 TO 7 CONTRACT NOY 3352, 3670

GROUND WAYS CORNER AND INTERIOR OF 5TH TUNNEL CONTRACT NOY 3352, 3671

COFFERDAMS FOR SHIPWAYS NO 2 W – FACE OF W – GROUNDWAYS SO OF 1ST TUNNEL CONTRACT NOY 3352, 3672

COFFERDAMS FOR SHIPWAYS NO 2 GENERAL VIEW OF E FACE OF W – GROUNDWAYS CONTRACT NOY 3352, 3673

COFFERDAMS FOR SHIPWAYS 2 W – GROUNDWAYS INSIDE OF 1ST TUNNEL CONTRACT NOY 3352, 3674

COFFERDAMS FOR SHIPWAYS 2 E – FACE OF W – GROUNDWAYS BETWEEN 1 – AND – 2 TUNNEL CONTRACT NOY 3352, 3675

COFFERDAMS FOR SHIPWAYS 2 FACE OF W – GROUNDWAYS 5TH TUNNEL CONTRACT NOY 3352, 3676

COFFERDAMS FOR SHIPWAYS NO 2 FACE OF W – GROUNDWAYS BETWEEN 3 AND 5 TUNNEL CONTRACT NOY 3352, 3677

COFFERDAMS FOR SHIPWAYS NO 2 FACE OF W GROUNDWAYS AT 6TH TUNNEL CONTRACT NOY 3352, 3678

350 TON HAMMERHEAD CRANE NEAR BERTH 12 VIEW SHOWING REINFORCEING [SIC] AND FORMS CONTRACT NOY 3462, 3679

350 TON HAMMERHEAD CRANE FOUNDATION NEAR BERTH 12 VIEW LOOKING WEST SHOWING ALIGNMENT OF WALL AT BERTH 12 CONTRACT NOY 3462, 3682

350 TON HAMMERHEAD CRANE FOUNDATION NEAR BERTH 12 VIEW LOOKING WEST SHOWING COMPOSITE PILE SHELLS REINFORCEING [SIC] AND FORMS CONTRACT NOY 3462, 3683

350 TON HAMMERHEAD CRANE FOUNDATION NEAR BERTH 12 VIEW SHOWING REINFORCING AND FORMS WEST SIDE CONTRACT NOY 3462, 3684

350 TON HAMMERHEAD CRANE FOUNDATION NEAR BERTH 12 VIEW LOOKING EAST SHOWING FORMS AND COMPOSITE PILES CONTRACT NOY 3462, 3685

FOUNDATION FOR NEW 350 TON HAMMERHEAD CRANE NEAR BERTH 12 VIEW LOOKING EAST SHOWING INSERTS IN PLACE CONTRACT NOY 3462, 3686

FOUNDATION FOR NEW 350 TON HAMMER HEAD CRANE NEAR BERTH 12 VIEW LOOKING SOUTH SHOWING INSERTS IN PLACE CONTRACT NOY 3462, 3687

FOUNDATION FOR NEW 350 TON HAMMER HEAD CRANE NEAR BERTH 12 VIEW SHOWING INSERTS IN PLACE AND STEEL CONTRACT NOY 3462, 3688

FOUNDATION FOR NEW 350 TON HAMMERHEAD CRANE NEAR BERTH 12 VIEW SHOWING ANCHOR BOLTS (BILLET PLATES NOT GROUTED) CONTRACT NOY 3462, 3689

COFFERDAMS SHIPWAYS NO 2 PULLING SHEETING BETWEEN CENTER AND BOX COFFERDAM CONTRACT NOY 3352, 3692

COFFERDAMS SHIPWAYS NO 2 GENERAL VIEW OF CENTER AND BOX COFFERDAM EAST SIDE CONTRACT NOY 3352, 3693

COFFERDAMS FOR SHIPWAYS NO 2 PLACING CONCRETE IN 'W' WING OF FOUNDATION SLAB 11 + 37 TO 11 + 88 CONTRACT NOY 3352, 3694

COFFERDAMS FOR SHIPWAYS NO 2 VIEW FROM W SIDE OF CENTER COFFER DAM SHOWING BURNED OFF SHEETING AT 11 + 88 AND DROP OFF WALL IN LEFT FOREGROUND CONTRACT NOY 3352, 3695

COFFERDAMS FOR SHIPWAYS NO 2 PILE FOUND FOR CENTER SLAB 11 + 37 TO 11 + 88 VIEWED FROM EAST SIDE CONTRACT NOY 335, 3696

TURRET AND ERECTION SHOPS INSTALLING FOUNDATIONS FOR STORAGE OF STEEL PLATE AT ORDNANCE DOCK VIEW LOOKING WEST ALLOT 7X218 – 42 – 1 YARD LABOR, 3697

IMPROVEMENT OF DISTRIBUTION SYSTEM RECONSTRUCTION OF STEAM AND RETURN LINES ON PAULDING AVE EAST OF BLDG 5 VIEW LOOKING WEST ALLOT 7X218 – 35 – 1 YARD LABOR, 3699

IMPROVEMENTS OF DISTRIBUTING SYSTEM RECONSTRUCTION OF STEAM AND RETURN LINES ON PAULDING AVE E OF BLDG 5 VIEW LOOKING EAST ALLOT 7X218 – 35 – 1 YARD LABOR, 3700

IMPROVEMENTS TO DISTRIBUTING SYSTEM RELOCATING FIRE HYDRANT NEAR HEAD END OF BLDG WAYS NO 1 ALLOT 7X218 – 35 – 1 YARD LABOR, 3701

COFFERDAMS FOR SHIPWAYS NO 2 INTERIOR VIEW OF BOX COFFERDAM LOOKING INBOARD W GROUND WAYS TO RIGHT CONTRACT NOY 3352, 3702

COFFERDAMS FOR SHIPWAYS NO 2 VIEW AT STATION 11 + 88 LOOKING INBOARD SHOWING CONSTRUCTION OF GROUNDWAYS CONTRACT NOY 3352, 3703

COFFERDAMS FOR SHIPWAYS NO 2 GENERAL VIEW FROM EAST SIDE OF WAYS CONTRACT NOY 3352, 3704

350 TON HAMMER HEAD CRANE NEAR BERTH 12 VIEW SHOWING ERECTION OF TOWER CONTRACT NOY 3341, 3705

EXTENSION OF FOUNDATIONS FOR CRANE RUNWAYS BLDG WYAS NO 2 INBOARD END 7X218 – 38 – 4 YARD LABOR, 3706

EXTENSION OF FOUNDATIONS FOR CRANE RUNWAYS BLDG WAYS NO 2 INBOARD END ALLOT 7X218 – 38 – 4 YARD LABOR, 3707

IMPROVEMENTS OF DISTRIBUTING SYSTEM RECONSTRUCTION OF STEAM AND RETURN LINES EAST SIDE OF BLDG 4 ALLOT 7X218 – 35 – 1 YARD LABOR, 3708

IMPROVEMENTS OF DISTRIBUTING SYSTEM RECONSTRUCTION OF STEAM AND RETURN LINES EAST SIDE OF BLDG 4 ALLOT 7X218 – 35 – 1 YARD LABOR, 3709

IMPROVEMENTS TO DISTRIBUTING SYSTEM RECONSTRUCTION OF STEAM AND RETURN LINES ON PAULDING AVE EAST OF BLDG 5 VIEW LOOKING WET ALLOT 7X218-35-1 YARD LABOR, 3710

NEW STEEL STORAGE YARD AT OLD ORDNANCE DOCK RELOCATED FROM SITE OF NEW TURRET AND ERECTION SHOP ALLOT 7X218-42-1 YARD LABOR, 3711

NEW STEEL STORAGE YARD AT OLD ORDNANCE DOCK RELOCATED FROM SITE OF NEW TURRET AND ERECTION SHOP ALLOT 7X218-42-1 YARD LABOR, 3712

NEW LUMBER STORAGE RACKS STEEL RAIL ON CONCRETE BEARERS IN BLDG 14 ALLOT 70201-8 YARD LABOR, 3713

COFFERDAMS SHIPWAYS NO 2 VIEW OF WELL POINTS AND 'E' SIDE OF 'E' GROUNDWAYS LOOK OUTBOARD FROM STA 12 + 00 CONTRACT NOY 3352 (COMPLETE), 3714

COFFERDAMS SHIPWAYS NO 2 VIEW OF WELL POINTS AND 'W' SIDE OF 'W' GROUNDWAYS LOOK OUTBOARD FROM STA 11 + 90 CONTRACT NOY 3352 (COMPLETE), 3715

COFFERDAMS SHIPWAYS NO 2 VIEW LOOKING OUTBOARD FROM AT STA 11 + 37 SHOWING SLAB AND W SIDE OF 'E' GROUNDWAYS CONTRACT NOY 3352 COMPLETE, 3716

COFFERDAMS SHIPWAYS NO 2 VIEW LOOKING INBOARD FROM AT STA 12 + 70 SHOWING SIDE VIEWS OF GROUNDWAYS AND BRACING FOR OUTBOARD END OF COFFERDAM CONTRACT NOY 3352 COMPLETE, 3717

COFFERDAMS SHIPWAYS NO 2 VIEW FROM AT STA 11 + 37 LOOKING OUTBOARD SHOWING SLAB AND 'E' SIDE OF 'W' GROUNDWAYS CONTRACT NOY 3352 (COMPLETE), 3718

COFFERDAMS SHIPWAYS NO 2 VIEW ON LOOKING OUTBOARD FROM STA 12 + 00 SHOWING E AND W GROUNDWAYS AND BRACING FOR OUTBOARD END OF COFFERDAM CONTRACT NOY 3352 (COMPLETE), 3719

COFFERDAMS SHIPWAYS NO 2 VIEW SHOWING WELL POINTS – PUMPS AND OUTBOARD END OF 'E' GROUNDWAYS LOOKING EAST AT STA 12 + 85 CONTRACT NOY 3352 COMPLETE, 3720

COFFERDAMS SHIPWAYS NO 2 EAST GROUNDWAYS LOOKING INBOARD FROM OUTBOARD END AT STA 12 + 82 CONTRACT NOY 3352, 3721

COFFERDAMS SHIPWAYS NO 2 VIEW OF SLAB AND W SIDE OF W GROUNDWAYS LOOKING OUTBOARD FROM STA 11 + 37 CONTRACT NOY 3352 COMPLETE, 3722

COFFERDAMS SHIPWAYS NO 2 GENERAL VIEW OF CENTER AND BOX COFFERDAMS LOOKING OUTBOARD FROM ABOVE ON EAST SIDE CONTRACT NOY 3352 (COMPLETE), 3723

COFFERDAMS SHIPWAYS NO 2 GENERAL VIEW OF INBOARD END OF CENTER COFFERDAM TAKEN FROM ABOVE FROM EAST SIDE CONTRACT NOY 3352, 3724

COFFERDAMS SHIPWAYS NO 2 INTERIOR VIEW OF CENTER COFFERDAM LOOKING INBOARD FROM STA 11 + 37 CONTRACT NOY 3352 COMPLETE, 3726

COFFERDAMS SHIPWAYS NO 2 VIEW OF W GROUNDWAYS LOOKING INBOARD FROM STA 12 + 75 CONTRACT NOY 3352, 3727

CRANE RUNWAYS EXTENSIONS SHIPWAYS 1 AND 2 MECHANICS PLACING BRACKETS FOR RELOCATION OF STEAM LINES BETWEEN TOWER 27 & 28 CONTRACT NOY 3590, 3728

CRANE RUNWAYS EXTENSIONS SHIPWAYS 1 & 2 VIEW LOOKING SO FROM WAYS NO 1 SHOWING ONE TRUSS OF BRIDGE CRANE AE 18 BEING LOWERED & LOADED ON TRUCKS CONTRACT NOY 3590, 3729

CRANE RUNWAYS EXTENSIONS SHIPWAYS 1 & 2 VIEW LOOKING SO SHOWING BRIDGE CRANE AE 18 PRIOR TO REMOVAL CONTRACT NOY 3590, 3731

DEMOLITION OF BUILDINGS INSIDE OF NEW PROPERTY LINE - VIEW SOUTH OF EVANS STREET CONTRACT NOY 3666, 3732

DEMOLITION OF BUILDINGS INSIDE OF NEW PROPERTY LINE - VIEW SHOWING BLDGS DEMOLISHED EAST OF LITTLE STREET CONTRACT NOY 3666, 3733

DEMOLITION OF BUILDINGS INSIDE OF NEW PROPERTY LINE VIEW LOOKING WEST FROM TOP OF BUILDING WAYS CONTRACT NOY 3666, 3734

NEW 350 TOM HAMMER HEAD CRANE NEAR BERTH 12 VIEW LOOKING SO WEST CONTRACT NOY 3341, 3735

IMPROVEMENTS FOR SHIPWAYS NO 2 PILE DRIVING ON 'E' SIDE WAYS AT APPROX STATION 10+50 CONTRACT NOY 3643 (LOOK IN BOARD), 3736

IMPROVEMENT TO BLDG WAYS NO 2 EXCAVATING AND REMOVING OLD PILES ON 'E' SIDE OF WAYS IN CENTER COFFERDAM CONTRACT NOY 3643, 3737

TURRET AND ERECTION SHOP FOUNDATIONS FOR STEEL STORAGE RACKS ORDNANCE DOCK ALLOT 7X218-42-1 YARD LABOR, 3738

FOUNDATIONS FOR NEW RETAINING WALL AND BUTTRESSES SO SIDE OF BLDG WAYS NO 2 ALLOT 7X218-31-2 YARD LABOR, 3739

TURRET AND ERECTION SHOP AND ACCESSORIES CLEARING SITE FOR NEW BUILDING AT SO SIDE OF WAYS NO 2 ALLOT 7X218-42-1 YARD LABOR, 3740

TURRET AND ERECTION SHOP ACCESSORIES) FOUNDATIONS FOR NEW STEEL STORAGE RACKS AT ORDNANCE DOCK ALLOT 7X218-42-1 YARD LABOR, 3741

ADDITIONAL LUMBER STORAGE FACILITIES SECTION OF LUMBER RACK IN BLDG 214 ALLOT 70201-8 YARD LABOR, 3742

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES DRAINS AND CATCH BASINS OUTSIDE BLDG 4 ALLOT 7X218-31-2 YARD LABOR, 3743

ADDITION OF STRUCTURAL SHOP DRAIN LINES AND CATCH BASINS OUTSIDE OF BLDG NO 4 ALLOT 7X218-31-2 YARD LABOR, 3744

ADDITION OF STRUCTURAL SHO AND ACCESSORIES DRAIN LINES AND CATCH BASINS OUTSID [SIC] OF NEW EXTENSION OF BLDG 4 ALLOT 7X218-31-2 YARD LABOR, 3745

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES TRACK WORK OUTSIDE OF BLDG 4 NEAR BLDG 15 ALLOT 7X218-31-2 YARD LABOR, 3746

IMPROVEMENTS TO SHIPWAYS NO 2 GENERAL VIEW OF SITE OF TOWER FOUNDATION NO 40 SHOWING PILES TO BE REMOVED CONTRACT NOY 3643, 3747

IMPROVEMENTS TO SHIPWAYS NO 2 VIEW LOOKING 'E' FROM WAYS NO 2 SHOWING PILE DRIVING FOR EXTENSION TO PIERS ON EITHER SIDE OF WAYS NO 1 CONTRACT NOY 3643, 3748

IMPROVEMENTS TO SHIPWAYS NO 2 GENERAL VIEW OF WORK IN CENTER COFFERDAM FROM EAST SIDE CONTRACT NOY 3643, 3749

IMPROVEMENTS TO SHIPWAYS NO 2 VIEW LOOKING OUTBOARD FROM STA 9 + 50 SHOWING OLD WOOD SHEETING ON EAST SIDE CONTRACT NOY 3643, 3750

CRANE RUNWAYS EXTENSION SHIPWAYS 1 AND 2 ERECTION OF TOWER NO 28 LOOK NORTH CONTRACT NOY 3590, 3751

CRANE RUNWAYS EXTENSIONS SHIPWAYS 1 AND 2 SHOWING ERECTION OF TOWER NO 28 VIEW LOOKING NORTH CONTRACT NOY 3590, 3752

CRANE RUNWAYS EXTENSIONS SHIPWAYS NO 1 AND 2 VIEW LOOKING EAST SHOWING 40 TON TRUSS BEING BOLTED INTO PLACE BETWEEN TOWERS 27 AND 28, 3755

CRANE RUNWAYS EXTENSION SHIPWAYS 1 AND 2 VIEW LOOKING EAST SHOWING ERECTION OF TOWER 29 CONTRACT NOY 3590, 3756

TURRET AND ERECTION SHOP AND ACCESSORIES NEW STEEL RACKS AND BEARES AT OLD ORDANANCE DOCK ALLOT 7X218 – 42 – 1 YARD LABOR, 3757

NEW 350 TON HAMMERHEAD CRANE UNDER CONTRUCTION NEAR BERTH 12 GENERAL VIEW CONTRACT NOY 3341, 3758

EXTENSION OF ELECTRIC LINES TO WATERFRONT VIEW BETWEEN BLDG NO 43 AND DD 3 ALLOT 7X218 – 32 - 3, 3759

NEW 350 TON HAMMERHEAD CRANE LOCATED NEAR BERTH 12 SLEWING MECHANISM FOR 350 TON BRIDGE CONTRACT NOY 3341, 3760

350 TON HAMMERHEAD CRANE LOCATED NEAR BERTH 12 – 2 – 175 TON HOISTING ENGINE DRUMS CONTRACT NOY 3341, 3761

IMPROVEMENTS OF SHIPWAYS NO 2 VIEW LOOKING SOUTH FRON 11 & 37 SHOWING PILES AND REINFORCING STEEL IN CENTER COFFERDAM CONTRACT NOY 3643, 3762

IMPROVEMENTS TO SHIPWAYS NO 2 VIEW SHOWING PILE DRIVING FOR EXTENSION OF PIER ON EAST SIDE OF WAYS NO 1 CONTRACT NOY 3643, 3763

IMPROVEMENTS TO SHIPWAYS NO 2 VIEW FROM EAST SIDE OF WAYS NO 2 LOOKING NO WEST SHOWING PILES – CONCRETE FORMS AND PROTECTION FOR CONCRETE CONTRAT NOY 3643, 3764

EXTENSION OF SHIPWAYS NO 2 VIEW LOOKING SOUTH SHOWING THE TRANVERSE TRUSS OVER WAYS NO 2 BEING RAISED INTO POSTION CONTRACT NOY 3590, 3765

EXTENSION TO SHIPWAYS NO 2 VIEW LOOKING SOUTH VIEWING THE TRANSVERSE TRUSS, OVER WAYS NO 2 IN FINAL POSITION CONTRACT NOY 3590, 3766

EXTENSION TO SHIPWAYS NO 2 VIEW LOOKING NO EAST SHOWING THE TRANSVERSE AND LONGITUDINAL TRUSSES WAYS NO 2 IN PLACE CONTRACT NOY 3590_, 3767

IMPROVEMENTS OF BERTHS NO 11 AND 12 VIEW SHOWING EXCAVATION BEHIND SEAWALL CONTRACT NOY 3742, 3768

IMPROVEMENTS TO BERTHS NO 11 AND 12 VIEW LOOKING NO WEST SHOWING EXCAVATION NEAR BERTH 12 CONTRACT NOY 3742, 3769

IMPROVEMENTS TO BERTHS NO 11 AND 12 VIEW LOOKING NO WEST SHOWING EXCAVATION NEAR BERTH 12 CONTRACT NOY 3742, 3770

Subassembly Shop Improvements of Shop Buildings and Steel Storage Runways , 3791

Subassembly Shop - Improvements of Shop Buildings and Steel Storage Runaways, Looking East on Chauncey Avenue at Site of Building 63, 3792

Subassembly Shop - Improvements of Shop Buildings and Steel Storage Runaways, Looking East on Chauncey Avenue Showing Excavation Work for Footings of Building 63 , 3797

Building 63 Looking Northwest from Chauncey Avenue and Fourth Street Showing Excavation Work, 3798

Building 63, Looking Northwest from Chauncey Avenue and Fourth Street Showing Column Footings, 3799

Building 63 Looking North at Third Street and Chauncey Avenue Showing Preparing of Track for Paving, 3800

BUILDING NO 126, 3916

Test Submarine Section, Interior View No. 2, 4005

Laying Pneumatic Messenger Tube System on Warrington Avenue, North of Third Street, 4012

Excavation for Foundation of New Cumberland Street Gate and Guard House, 4057

Pit Excavation for Foundation for New Cumberland Street Gate and Guard House , 4058

General View of New Gate and Guard House at Cumberland Street Gate, 4062

Works Progress Administration View Showing Machines Crowded Close to Columns Beings Underpinned in Building 128, 4068

Works Progress Administration Pouring Concrete into Tube Piling at Cumberland Street Gate , 4077

Marine Barracks extension of Building 13 - bricking up extension walls and setting steel with use of speed crane, 4102

View of Proposed Location of New Cumberland Street Gate before Work Started, 4106

Cumberland Street Gate before New Construction, 4107

Bricking up the Extension Wall on Perry Avenue, Marine Barracks Building 13, 4109

Improvements to Marine Barracks, Chauncey Avenue Elevation, Building 13, 4110

Extension to Building 244 between Ways No. 1 and 2, 4129

350 Ton Hammerhead Crane Near Berths 11 and 12, 4137

Pemphigus, 4155
BLDG 1 CONTR 3892 TYPICAL WARD FIRST FLOOR, 4157
BLDG "F" NAVAL HOSPITAL BREAD MIXER AND MEAT CHOPPER MAIN GALLEY, 4158
BLDG "F" NAVAL HOSPITAL VEGETABLE WASHER MAIN GALLEY 2ND FLOOR, 4159
BLDG "F" NAVAL HOSPITAL DISHWASHING STATION, MAIN MESS ROOM 2ND FOOR, 4160
US NAVAL HOSPITAL PHYSIOTHERAPY DEPT ABDOMINAL TREATMENT POST OP CASE WITH MORSE MACHINE, 4164
USS PENSACOLA_GENERAL VIEW LOOKING AFT, 4189
USS PENSACOLA MAIN DECK MIDSHIP LOOKING FORWARD, 4190
USS PENSACOLA MAIN DECK MIDSHIP LOOKING AFT, 4191
USS PENSACOLA_MAIN DECK VIEW LOOKING AFT FROM FRAME 52, 4192
USS PENSACOLA MAIN DECK VIEW LOOKING FORWARD FROM FRAME 77, 4193
USS PENSACOLA FROM ABOUT FRAME 55 OVERHEAD LOOKING FORWARD, 4194
USS PENSACOLA FROM FRAME 90 OVERHEAD LOOKING FORWARD, 4195
USS PENSACOLA FROM FORECASTLE LOOKING AFT, 4196
USS PENSACOLA FROM ABOUT FRAME "55" OVERHEAD LOOKING AFT, 4197
USS PENSACOLA FROM BRIDGE LOOKING AFT, 4198
USS PENSACOLA FROM FRAME 73 LOOKING FORWARD, 4199
USS PENSACOLA MIDSHIP LOOKING FORWARD, 4200
USS PENSACOLA MIDSHIP LOOKING AFT, 4201
USS PENSACOLA STERN LOOKING FORWARD, 4202
USS PENSACOLA STARBOARD SIDE LOOKING FORWARD, 4203
NAVY YARD NY USS PENSACOLA, 4204
USS PENSACOLA STARBOARD QUARTER, 4205
USS PENSACOLA BOW VIEW SHOWING PORE POPPET, 4206
USS PENSACOLA HYDRAULIC JACKS & SOLE PLATE PORT SIDE, 4207
USS PENSACOLA HYDRAULIC JACKS & SOLE PLATE PORT SIDE, 4208
USS PENSACOLA BOW VIEW, 4209
USS PENSACOLA REPRODUCTION OF WIDE WORLD PHOTO, 4210
USS PENSACOLA REPRODUCTION OF WIDE WORLD PHOTO, 4211
USS PENSACOLA REPRODUCTION OF ACME NEWS PICTURES, 4212
USS PENSACOLA REPRODUCTION OF INTERNATIONAL NEWS REEL PHOTO, 4213
USS PENSACOLA IMMEDIATELY AFTER LAUNCHING REPRODUCTION OF PACIFIC & ATLANTIC PHOTO, 4214
USS PENSACOLA PORT BROADSIDE, 4215
USS PENSACOLAREPRODUCTION OF EDWIN LEVICK STUDIO PHOTO, 4216
USS PENSACOLA AFT STARBOARD, 4217
USS PENSACOLA MID SHIPS STARBOARD , 4218
USS PENSACOLA STARBOARD BOW, 4219
USS PENSACOLA VIEW OFF PORT BEAM, 4220
USS PENSACOLA VIEW OFF PORT BOW, 4221
USS PENSACOLA STARBOARD SIDE FROM MIDSHIPS AFT, 4222
USS PENSACOLA STARBOARD SIDE FROM MIDSHIPS FORWARD, 4223
USS PENSACOLA VIEW MAIN DECK AFT SHOWING PARTIAL ARRANGEMENT OF MINE TRACKS, 4224
AFTER DIRECTOR TRAIN TRANSMITTER SWITCH PENSACOLA MAIN BATTERY SWITCHBOARD IN ORIGINAL CONDITION, 4225
AFTER DIRECTOR TRAIN TRANSMITTER SWITCH PENSACOLA MAIN BATTERY SWITCHBOARD IN ORIGINAL CONDITION, 4226
AFTER DIRECTOR TRAIN TRANSMITTER SWITCH PENSACOLA MAIN BATTERY SWITCHBOARD AFTER RECONNECTING, 4227
AFTER DIRECTOR TRAIN TRANSMITTER SWITCH MAIN BATTERY SWITCHBOARD AFTER RECONNECTING, 4228
USS PENSACOLA MAIN BATTERY FIRE CONTROL SWITCHBOARD AFTER REWIRING, 4229
USS PENSACOLA BATTERY FIRE CONTROL SWITCHBOARD AFTER REWIRING CLOSE UP VIEW, 4230
USS PENSACOLA MAIN BATTERY FIRE CONTROL SWITCHBOARD AFTER REWIRING, 4231
USS PENSACOLA MAIN BATTERY FIRE CONTROL SWITCHBOARD AFTER REWIRING, 4232
USS PENSACOLA BROADSIDE VIEW STARBOARD SIDE FROM STERN TO AFTER TURRET, 4233
USS PENSACOLA, 4234
USS PENSACOLA EXHIBIT "B", 4235
USS PENSACOLA BROADSIDE VIEW STARBOARD SIDE FROM STERN TO AFTER TURRET, 4236
USS PENSACOLA BROADSIDE VIEW OF PORT SIDE, 4237
USS PENSACOLA EXHIBIT "C", 4238
USS PENSACOLA STARBOARD SIDE LOOKING AFT FROM MIDSHIP, 4239
USS WEst Virginia Ships Bearing Indicator MK XIII MOD 5, 4272
USS WVA RANGE AND DEFLECTION INDICATOR MK IX MOD 1, 4276
USS WVA RANGE & DEFLECTION TRANSMITTER MKX MOD 1, 4277
GENERAL VIEW OF FORM WORK AND PLACING CONCRETE FOR NEW PICKLING PLANT FOUNDATIONS STEEL STORAGE YARD C AN R ALLOT YARD LABOR, 4622

Demolition of Interior Wall Building 12 in the Consolidaiton of Shops, 5890
 Interior Demolition Operations Building 10, View from South End of Building, 5892
 Temporary Machine Shop, Building 11 - Miscellaneous Work and General Equipment, 5895
 Construction of New Transformer Room to Building 41 at Fifth Street and Morris Avenue, 5914
 Repairs to Standard Gauge Track and Paving at Stringham and Paulding Avenues, 5916
 Resetting and Grouting Old Granite Block Paving on Chauncey Avenue between Second and Third Streets, 5920
 Standard Gauge Railroad Track, Work on Morris Avenue between First and Second Streets, 5921
 General Interior View of Building 10 , 5923
 Improvement to Sidewalk and Street on Morris Avenue, Looking towards Second Street , 5924
 Office and field employees, Time Keeping Department, Building 6, 3rd Floor, 5929
 US NAVAL HOSPITAL, NY, NEW BAND STAND UNDER CONSTRUCTION, 5943
 US NAVAL HOSPITAL, NY, ROADWAY, CURB AND SIDEWALKS BETWEEN BUILDINGS E AND F, LOOKING WEST, 5944
 US NAVAL HOSPITAL, NY, ROADWAY, CURBS AND RAMP WEST OF POWER HOUSE, LOOKING NW, 5945
 US NAVAL HOSPITAL, NY, ROADWAY AND SIDEWALK BETWEEN BLDGS C AND E, LOOKING N, 5946
 US NAVAL HOSPITAL, NY, ROADWAY CURB EAST OF BLDG E, LOOKING N, 5947
 US NAVAL HOSPITAL, NY, SIDEWALK EAST OF BLDG F, LOOKING N, 5948
 US NAVAL HOSPITAL, NY, CONCRETE ROADWAY WEST OF POWER HOUSE, LOOKING N, 5949
 REPAIRING WALL BOARD CEILING, UNIT #3, 5950
 LOOKING E THROUGH HALL, UNIT #3, 5951
 UNIT #1 SOUTH BEDROOM, 5952
 UNIT #1 LOOKING EAST THROUGH HALL, 5953
 UNIT #1 KITCHEN, 5954
 UNIT #1 LIVING ROOM AND DINING ROOM, 5955
 UNIT #1 BATHROOM, 5956
 UNIT #2 LOOKING WEST THROUGH HALL, 5957
 NAVAL HOSP, CORRIDOR BLDG E, REPAIR KEMPOLITE FLOOR, GROUND FL LOOKING W, 5963
 NAVAL HOSP, CORRIDOR NURSES QUARTERS, REPAIR KEMPOLITE FLOOR, GROUND FL LOOKING W, 5964
 NAVAL HOSP, WEST CORRIDOR NURSES QUARTERS, REPAIR KEMPOLITE FLOOR, GROUND FL LOOKING W, 5965
 US NAVAL HOSP, PHYSIOTHERAPY DEPT, JOHN GEIER, NON UNION FRACTURE OF FEMUR INTESTINAL STASIS, 5966
 US NAVAL HOSP, PHYSIOTHERAPY DEPT, HIP JOINT PRACTICALLY FIXED BY ABSCESS, SENT IN AS TUBERCULAR HIP, ABSCESS EXTRA ARTICULAR, OPENED, CURETTED, PHYSIOTHERAPY, RESULT SHOWN, 5967
 US NAVAL HOSP, PHYSIOTHERAPY DEPT, STATIC FOR CHRONIC EAR DISEASE, 5968
 US NAVAL HOSP, WHIPPO, SHOT IN FRANCE 191 , CONSERVATION TREATMENT IN ALMOST HOPELESS ATTEMPT TO SAVE RIGHT LEG, MANY OPERATIONS, RESULT SHOWN, BONE REFORMED, PICTURE SHOWS SIZE OF BONE LEFT AFTER OPERATIONS, (ROD) MEASURE INDICATES SIZE OF REFORMED TIBIT, NO BONE GRAFTING, 5969
 US NAVAL HOSP, REFER TO F920N3065A, 5970
 US NAVAL HOSP, REFER TO F920N3065A, 5971
 US NAVAL HOSP, REFER TO F920N3065A, THIS PICTURE SHOWS APPARATUS USED TO SAFE-GUARD LEG WHILE BONE IS STILL WEAK, 5972
 US NAVAL HOSP, REFER TO F920N3065A, 5973
 US NAVAL HOSP, REFER TO F920N3065A, 5974
 US NAVAL HOSP, ALPINE LIGHT, FORM OF ULTRA VIOLET TREATMENT, 5978
 US NAVAL HOSP, LEVIN, BEFORE TREATMENT, 5979
 CASE OF TJD, WARD R2, SHOWING LESIONS ON OUTER ASPECT OF RIGHT LEG AND LENER ASPECT, LEFT LEG, THREE SMALL LESIONS ON LEFT ARM, ONE ON OUTER SIDE RIGHT ARM, AND ONE (SWELLING) LOBE OF RIGHT EAR, 5980
 US NAVAL HOSP, CASE OF TJD, WARD R2, SHOWING ULCERATIVE LESIONS, INNER & POSTERIOR ASPECT OF RIGHT LEG AND THIGH, 5981
 US NAVAL HOSP, CASE OF TJD, WARD R2, LESIONS, INNER SURFACE OF RIGHT AND OUTER SURFACE OF LEFT LEG AND THIGH, 5982
 US NAVAL HOSP, VOILETT, AE SEA ACUE, FACE, BEFORE TREATMENT, 5983
 US NAVAL HOSP, COSGROVE, SAME AS F920N3090A, 5985
 US NAVAL HOSP, NY, CONCRETE ROAD WORK LOOKING W BETWEEN BLDGS E & F, 5986
 NAVAL HOSP, NY, CONCRETE ROAD WORK LOOKING N, NE CORNER BLDG E, 5987
 NAVAL HOSP, NY, CONCRETE ROAD WORK LOOKING S, NE CORNER BLDG E, 5988
 NAVAL HOSP, NY, FOUNDATION FOR BAND STAND, SE OF BLDG F, LOOKING E, 5989
 NAVAL HOSP, NY, BLDG F, GENERAL VIEW OF PIPE TUNNEL, 5990
 NAVAL HOSP, NY, BLDG F, GENERAL VIEW OF REFRIGERATORS, SHOWING OVERHEAD TRACKS, 5991
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT ARM EXERCISES, 5993
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, ABSCESS OF AXILLA, SINUS BEING TREATED BY KROMAYER LIGHT, 5994
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, AFTER SIX MONTHS OF PHYSIOTHERAPEUTIC TREATMENT, EXTENSIVE SCAR, CAUSING ANKYLOSIS OF KNEE, RESULT, NORMAL FUNCTION, 5995
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, ATITIS MEDIA BEING TREATED WITH KROMAYER LAMP, 5996
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, XRAY SHADOW BOX IN EXAMINING ROOM, 5997
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, AFTER FIVE MONTHS TREATMENT IN PHYSIOTHERAPY DEPT SHOWING

INCREASE OF FLEXION OF ANKLES, 5998
 NAVAL HOSP, NY, REST ROOM, CONNECTED WITH HDROTHERAPY DEPT, 5999
 NAVAL HOSP, NY, CABINET BATH TREATMENT (BUIDICK), 6000
 NAVAL HOSP, NY, WHIRLPOOL BATHS, 6001
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, ABDOMINAL TREATMENT, POST OP, CASE WITH MORSE MACHINE, 6002
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, ABDOMINAL TREATMENT, POST OP, CASE WITH MORSE MACHINE, 6003
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, BEFORE TREATMENT, EXTENSIVE SCAR, CAUSING ANKYLOSIS OF KNEE, 6004
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, DEEP THERAPEUTIC LIGHT, 6005
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, JOHN CURTIS, WAR WOUNDED NOV 9, 1918, SIX OPERATIONS BEFORE CLOSURE, PHYSIOTHERAPY, 1 YR SUTURE SCIATIC NERVE TO ROOT AT CORD PHYSIOTHERAPY CONTINUING, 6006
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, SHOWING CAST IN CASE OF BONE GRAFT FOR NON UNION OF HUMERUS, PHYSIOTHERAPY GOING ON, 6007
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, EXTRA ARTICULAR TUBERCULAR ABSCESS OF THIGH AND BUTTOCKS, SCAR BEING TREATED AND WOUND CLOSED BY BURDICK ULTRA VIOLET, 6008
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, DION, KNEE BAING CENT, FRACTURE WITH TRACTORS TO OVERCOME OVER-RIDING, ABSOLUTELY STIFF, SHOWING RESULT AFTER 5 WEEKS TREATMENT IN PHYS TER. ETHRIDGE, ARTHRITIS, ABSOLUTELY STIFF, 4 WEEKS, 10 DEGREES MOTION OBTAINED, 6009
 NAVAL HOSP, NY, PHYSIOTHERAPY DEPT, PYORRHEA ALVEOLUS BEING TREATED WITH KROMAIER LAMP, 6010
 NAVAL HOSP, NY, BLDG "F", SLOP SINK, MAIN GALLEY, 6011
 NAVAL HOSP, NY, BLDG "F", BREAD MIXER AND MEAT CHOPPER, MAIN GALLEY, 6012
 NAVAL HOSP, NY, BLDG "F", VEGETABLE WASHER, MAIN GALLEY, 2ND FL, 6013
 NAVAL HOSP, NY, BLDG "F", DISHWASHING STATION, MAIN MESS ROOM, 2ND FL, 6014
 NAVAL HOSP, NY, AW SHELBY, SEAMAN 2ND CLASS, ANKYLOSIS OF KNEE, 6015
 NAVAL HOSP, NY, AW SHELBY, SEAMAN 2ND CLASS, ANKYLOSIS OF KNEE, 6016
 NAVAL HOSP, NY, AW SHELBY, SEAMAN 2ND CLASS, ANKYLOSIS OF KNEE, 6017
 NAVAL HOSP, LUETIC GLOSITIS, 6018
 NAVAL HOSP, LUETIC GLOSITIS, 6019
 NAVAL HOSP, ULCER OF LEG (LUETIC), 6020
 NAVAL HOSP, RESULT OF OPERATION OF PROLAPSE RECTUM, 6021
 NAVAL HOSP, OPERATION FOR PROLAPSE ANUS SHOWING APPLICATION OF SPECIAL CLAMP, 6022
 NAVAL HOSP, BLDG "F", GENERAL VIEW, NEW GALLEY, LOOKING S, 6023
 NAVAL HOSP, BLDG "F", GENERAL VIEW, SERVICE STATION, MAIN MESS HALL, 2ND FL, 6024
 NAVAL HOSP, BLDG "F", GENERAL VIEW, REFRIGERATORS, BASEMENT, LOOKING N, 6025
 NAVAL HOSP, BLDG "F", ICE CREAM FREEZER AND ICE CRUSHER, BASEMENT, 6026
 NAVAL HOSP, BLDG "F", STEAM TABLES, SERVICE STATION, 2ND FL, 6027
 NAVAL HOSP, BLDG "F", SERVICE STATION, MAIN MESS ROOM, 2ND FL, 6028
 NAVAL HOSP, BLDG "F", BASEMENT TOILET, 6029
 NAVAL HOSP, BLDG "F", LOOKING S, CONNECTION OF OLD KITCHEN & W WING, 6030
 NAVAL HOSP, BLDG "F", LOOKING W ALONG ST BETWEEN "F" AND "E" BLDGS, 6031
 NAVAL HOSP, BLDG "F", VENTILATING DUCTS AND PANEL BOX IN ATTIC, 6032
 NAVAL HOSP, BLDG "F", LADDER TO ATTIC, 6033
 NAVAL HOSP, BLDG "F", VENTILATING MOTOR STARTER IN ATTIC, 6034
 NAVAL HOSP, BLDG "F", GROUND FL, SCULLERY, STAIRWAY AND CONNECTION WITH "A" ANNEX, 6035
 BLDG 4, GENERAL VIEW OF BULL RIVETING MACHINE, 6036
 BLDG 4, PLATE PUNCHING MACHINE WITH PLATE HANDLING EQUIPMENT, 6037
 NAVAL HOSP, STRAIGHT CLAMPS AND ALLISAN CLAMP USED IN CONJUNCTION WITH SPECIAL CLAMPS IN REMOVING QUADRANT OF RECTAL PROTRUSION, 6038
 NAVAL HOSP, SPECIAL CLAMPS USED TO REMOVE QUADRANT OF RECTAL PROTRUSION, 6039
 NAVAL HOSP, SPECIAL CLAMPS (CURVED), STRAIGHT CLAMP AND ALLISON CLAMP USED IN REMOVAL OF QUADRANT OF RECTAL PROTRUSION, 6040
 NAVAL HOSP, OPERATION FOR PROLAPSE ANI: OPERATION COMPLETE, 6041
 NAVAL HOSP, OPERATION FOR PROLAPSE ANI: DILATATION COMPLETE, 6042
 NAVAL HOSP, OPERATION FOR PROLAPSE ANI: DILATATION PARTIAL, 6043
 NAVAL HOSP, OPERATION FOR PROLAPSE ANI: SHOWING SPHINCTER MUSCLE UPPER ANGLE, 6044
 F920N2083, 6045
 NAVAL HOSP, ALOPECIA LUETIC, AFTER TREATMENT, 6046
 NAVAL HOSP, ALOPECIA, EYEBROWS AFTER TREATMENT, 6047
 NAVAL HOSP, PSORIASIS UNDERGOING TREATMENT, 6049
 NAVAL HOSP, BLDG "F", NORTH SIDE, CONNECTION WITH "A" ANNEX, 6050
 NAVAL HOSP, BLDG "F", SOUTH ENT OF NEW TUNNEL, LOOKING NORTH, 6051
 NAVAL HOSP, BLDG "F", GROUND FL, MESS HALL, LOOKING WEST, 6052
 NAVAL HOSP, BLDG "F", SOUTH AND EAST VIEW OF BLDG, 6053
 NAVAL HOSP, BLDG "E", LOOKING SOUTH, 6054
 NAVAL HOSP, BLDG "E", LOOKING SOUTH AT EAST WING, 6055

NAVAL HOSP, BLDG "F", BOILER ROOM & OPENING INTO NEW TUNNEL, 6056
 NAVAL HOSP, BLDG "F", BASEMENT, LOOKING SOUTH EAST, STOREROOM, 6057
 NAVAL HOSP, LOOKING WEST ALONG UNPAVED STREET BETWEEN BLDGS "F" & "E", 6058
 NAVAL HOSP, BLDG "F", BASEMENT, RECEIVING WARD, LOOKING SOUTH EAST, 6059
 NAVAL HOSP, BLDG "F", GROUND FL, WASHROOM & TOILET, NORTH WING, 6060
 NAVAL HOSP, BLDG "F", BASEMENT, LOOKING NORTH, CORRIDOR INTO "A" ANNEX, 6061
 NAVAL HOSP, BLDG "F", LOOKING NORTH, FRONT OF ISSUING ROOM, 6062
 NAVAL HOSP, BLDG "F", LOOKING NORTH, SITE OF BASEMENT REFRIGERATORS, 6063
 NAVAL HOSP, BLDG "F", ATTIC, LOOKING INTO THE ELEVATOR SHAFT, 6064
 NAVAL HOSP, BLDG "F", SECOND FL, EAST WARD, LOOKING SOUTH, 6065
 NAVAL HOSP, BLDG "F", FIRST FL, DIET KITCHEN, 6066
 NAVAL HOSP, BLDG "F", SECOND FL, RECOVERY ROOM, 6067
 NAVAL HOSP, BLDG "F", FIRST FL, EAST WING TOILET, 6068
 NAVAL HOSP, BLDG "F", FIRST FL, LOOKING INTO OLD PAYMASTER'S OFFICE, 6069
 NAVAL HOSP, BLDG "F", FIRST FL, EAR, NOSE & THROAT EXAM ROOM, 6070
 NAVAL HOSP, BLDG "F", FIRST FL, OPTICIANS EXAM ROOM (DARK ROOM AT LEFT), 6071
 NAVAL HOSP, BLDG "F", GROUND FL, GALLEY, LOOKING SOUTH, 6072
 NAVAL HOSP, BLDG "F", SECOND FL, WEST WARD, LOOKING WEST, 6073
 NAVAL HOSP, BLDG "F", FIRST FL, QUIET ROOMS, 6074
 NAVAL HOSP, BLDG "F", FIRST FL, NURSE'S TOILET, 6075
 NAVAL HOSP, BLDG "F", GROUND FL, EAST WING TOILET, 6076
 NAVAL HOSP, BLDG "F", GROUND FL, CONNECTION TO OLD GALLEY, 6077
 NAVAL HOSP, BLDG "F", THIRD FL, PASSAGE TO OPERATING ROOM OF MAIN BLDG, 6078
 NAVAL HOSP, BLDG "F", FIRST FL, EAR, NOSE & THROAT OPERATING ROOM, 6079
 NAVAL HOSP, BLDG "F", EAST WING, LOOKING SOUTH, 6080
 NAVAL HOSP, BLDG "F", GROUND FL, ERECTING CANOPY IN GALLEY, DUMB-WAITER AT RIGHT, 6081
 NAVAL HOSP, BLDG "F", FIRST FL, CORRIDOR INTO "A" ANNEX, 6082
 NAVAL HOSP, ULCERATED SYPHILIDE HEALED AFTER 8 DOSES OF SALVARSAN ("A" SAME AS B), 6083
 NAVAL HOSP, ULCERATED SYPHILIDE HEALED AFTER 8 DOSES OF SALVARSAN ("B" SAME AS A), 6084
 NAVAL HOSP, TINEA CRURALIS, 6085
 NAVAL HOSP, END RESULT OF PHAGEDINIC DUCREY, DETAIL VIEW, 6086
 NAVAL HOSP, END RESULT OF PHAGEDINIC DUCREY, GENERAL VIEW, 6087
 NAVAL HOSP, BLDG "F", PAYMASTER'S OFFICE, 6088
 NAVAL HOSP, BLDG "F", GENERAL VIEW, 6090
 NAVAL HOSP, SMALL PAPULAR SYPHILIDE, 6092
 NAVAL HOSP, ULCERATIVE LUETIC ADENITIS OF GROIN, 6093
 NAVAL HOSP, ULCERATIVE LUETIC ADENITIS OF NECK, 6094
 NAVAL HOSP, HARCOT JOINT, 6095
 NAVAL HOSP, HARCOT JOINT, 6096
 NAVAL HOSP, GENERAL VIEW OF BLDG "F", LOOKING WEST, 6097
 NAVAL HOSP, GENERAL VIEW OPERATING ROOM, 6098
 BLDG 131, FIRST FL, JOINER, WEST BAY, LOOKING SOUTH, 6099
 BLDG 131, SECOND FL, BLOCK SHOP, 6100
 BLDG 131, SECOND FL, SAW FILING AND FITTING DEPT, 6101
 BLDG 131, SECOND FL, FLAG PAINTING DEPT, 6102
 BLDG 131, THIRD FL, SPECIAL MACHINERY, LOOKING SOUTH, 6103
 BLDG 131, THIRD FL, JOINER ASSEMBLY AND BENCH DEPT, LOOKING NORTH, 6104
 BLDG 131, THIRD FL, SPECIAL MACHINERY MILL, LOOKING NORTH, 6105
 BLDG 131, THIRD FL, JOINER ASSEMBLY AND BENCH DEPT, LOOKING SOUTH, 6106
 BLDG 131, FIRST FL, JOINER MILL, WEST BAY LOOKING NORTH, 6107
 BLDG 131, SERVING LATHE, WORMING, 6108
 BLDG 131, SERVING LATHE, PARCELLING, 6109
 BLDG 131, SERVING LATHE, SERVING, 6110
 BLDG 131 AT NEW 5 TON TRAVELLING CRANE, LOOKING NE, EXETER MACHINE, WKS CONTR (HULL DIV WORK),
 MONTHLY PROGRESS PHOTO, 6111
 BLDG 131 (47) JIB CRANE AT NE END, LOOKING SOUTH, YARD LABOR, MONTHLY PROGRESS PHOTO, 6112
 BLDG 131 (47) JIB CRANE FOUNDATION AT NE END, LOOKING SE, YARD LABOR, MONTHLY PROGRESS PHOTO, 6113
 BLDG 131 (47) JIB CRANE, YARD LABOR, MONTHLY PROGRESS PHOTO, 6114
 BLDG 131 (47) JIB CRANE, YARD LABOR, MONTHLY PROGRESS PHOTO, 6115
 BLDG 130 LOOKING NE, 6116
 BLDG 130 LOOKING E, 6117
 BLDG 130 LOOKING E, 6118
 BLDG 130 LOOKING NE, 6119
 BLDG 130 LOOKING E, 6120
 BLDG 130 LOOKING NE, 6121

BLDG 130 LOOKING N, 6122
BLDG 130 LOOKING NE, 6123
BLDG 130 LOOKING E, 6124
BLDG 130, 6125
BLDG 130, 6126
BLDG 130, 6127
BLDG 130, 6128
BLDG 129 (80), I-BEAM TROLLEY TRACK FOR COALING CHUTES, LOOKING NW, MONTHLY PROGRESS PHOTO, YARD LABOR, 6129
BLDG 129 (80), I-BEAM TROLLEY TRACK FOR COALING CHUTES, LOOKING SW, MONTHLY PROGRESS PHOTO, YARD LABOR, 6130
BLDG 129 (80), I-BEAM TROLLEY FOR OUTBOARD CHUTES, LOOKING SE, MONTHLY PROGRESS PHOTO, YARD LABOR, 6131
BLDG 129 (80), COAL PLANT, CHUTE RUNWAY & COAL HOIST FOUNDATION, LOOKING NW, MONTHLY PROGRESS PHOTO, YARD LABOR, 6132
BLDG 129 (80), COAL PLANT, TOWER LOCKING DEVICE, W SIDE, LOOKING NW, MONTHLY PROGRESS PHOTO, YARD LABOR, 6133
BLDG 129 (80), COAL PLANT, TOWER LOCKING DEVICE, E SIDE, LOOKING NE, MONTHLY PROGRESS PHOTO, YARD LABOR, 6134
BLDG 129 (80), COAL PLANT, TOWER LOCKING DEVICE ON E SIDE, LOOKING NE, MONTHLY PROGRESS PHOTO, YARD LABOR, 6135
BLDG 129 (80), COAL PLANT, TOWER W SIDE, CHANNEL REPLACED, LOOKING SW, MONTHLY PROGRESS PHOTO, YARD LABOR, 6136
BLDG 129 (80), COAL PLANT, TOWER W SIDE, CHANNEL REPLACED, LOOKING NW, MONTHLY PROGRESS PHOTO, YARD LABOR, 6137
BLDG 129 (80), COAL PLANT, LOOKING N FROM COB DOCK, 6138
BLDG 129 (80), COAL PLANT, LOOKING NW FROM PIER E, 6139
BLDG 129 (80), COAL PLANT, SE END, LOOKING NW, 6140
BLDG 129 (80), COAL PLANT, NE SIDE, LOOKING W, 6141
BLDG 129 (80), COAL PLANT, OUTER END, NE SIDE, LOOKING W, 6143
BLDG 129 (80), TESTING PLANT, 6144
BLDG 129 (80), COAL PLANT, LOOKING NW, 6145
BLDG 129 (80), COAL PLANT, VIEW OF CAR, 6146
BLDG 129 (80), COAL PLANT, LOOKING N, 6147
BLDG 129 (80), COAL PLANT, LOOKING N, 6148
BLDG 129 (80), COAL PLANT, LOOKING NW, 6149
BLDG 129 (80), COAL PLANT, INTERIOR LOOKING NW, 6150
BLDG 129 (80), COAL PLANT, LOOKING NE, 6151
BLDG 129 (80), COAL PLANT, LOOKING NE, 6152
BLDG 129 (80), COAL PLANT, LOOKING NW, 6153
BLDG 129 (80), COAL PLANT, LOOKING N, 6154
BLDG 129 (80), COAL PLANT, LOOKING N, 6155
BLDG 129 (80), COAL PLANT, LOOKING NE, 6156
BLDG 129 (80), COAL PLANT, LOOKING N, 6157
BLDG 129 (80), COAL PLANT, LOOKING N, 6158
BLDG 129 (80), COAL PLANT, LOOKING NW, 6159
BLDG 129 (80), COAL PLANT, LOOKING N, 6160
BLDG 129 (80), COAL PLANT, LOOKING N, 6161
BLDG 129 (80), COAL PLANT, LOOKING NE, 6162
BLDG 129 (80), COAL PLANT, LOOKING N, 6163
BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET, 500 LBS OUTLET, 75 LBS, 6164
BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET, 500 LBS OUTLET, 25 LBS, 6165
BLDG 131, SERVING LATHE, 6166
BLDG 131, SERVING LATHE, 6167
BLDG 131 FOR DD 4, LATRINE, LOOKING NE IN OFFICERS' PART, MONTHLY PROGRESS PHOTO, YARD LABOR, 6169
BLDG 131 FOR DD 4, LATRINE, LOOKING SW IN OFFICERS' PART, MONTHLY PROGRESS PHOTO, YARD LABOR, 6170
BLDG 131 FOR DD 4, LATRINE, LOOKING S IN SAILORS' PART, MONTHLY PROGRESS PHOTO, YARD LABOR, 6171
BLDG 131 FOR DD 4, LATRINE, LOOKING N IN SAILORS' PART, MONTHLY PROGRESS PHOTO, YARD LABOR, 6172
BLDG 131 FOR DD 4, LATRINE, LOOKING W IN SAILORS' PART, MONTHLY PROGRESS PHOTO, YARD LABOR, 6173
BLDG 131 FOR DD 4, LATRINE, LOOKING E IN WORKMENS' PART, MONTHLY PROGRESS PHOTO, YARD LABOR, 6174
BLDG 131 FOR DD 4, LATRINE, LOOKING W IN WORKMENS' PART, MONTHLY PROGRESS PHOTO, YARD LABOR, 6175
BLDG 131, SUBSTATION 11, ADDITION TO LEAN-TO, LOOKING SE, MONTHLY PROGRESS PHOTO, YARD LABOR, 6176
BLDG 131, ADDITION FOR LATRINE DD 4, WORKMENS' PART, LOOKING W, MONTHLY PROGRESS PHOTO, YARD LABOR, 6178
BLDG 131, ADDITION FOR LATRINE DD 4, LOOKING NW, MONTHLY PROGRESS PHOTO, YARD LABOR, 6179

BLDG 131, ADDITION FOR LATRINE DD 4, MONTHLY PROGRESS PHOTO, YARD LABOR, 6180
 BLDG 131, ADDITION FOR LATRINE DD 4, MONTHLY PROGRESS PHOTO, YARD LABOR, 6182
 BLDG 131, FOUNDATION PILES, LEAN-TO FOR LATRINE, DD 4, MONTHLY PROGRESS PHOTO, YARD LABOR, 6183
 BLDG 131, FOUNDATION FOR LATRINE, DD 4, MONTHLY PROGRESS PHOTO, YARD LABOR, 6184
 BLDG 131, SITE OF NEW LEAN-TO, 6185
 BLDG 131, LOOKING N, 6186
 BLDG 131, 6215
 BLDG 130, ORDNANCE BLDG, EXTERIOR, VIEW OF PARAVANE STOWING, LOOKING E, 6219
 BLDG 130, ORDNANCE BLDG, EXTERIOR, N SIDE, (SECT VIEW OF COALING PLANT AT RIGHT), VIEW OF PARAVANE STOWAGE, LOOKING W, 6220
 BLDG 130, ORDNANCE BLDG, DETAIL VIEW OF PARAVANE, 6221
 BLDG 130, 2ND FL, LOOKING W, 6222
 BLDG 130, EXTERIOR, 6223
 BLDG 130, 1ST FL LOOKING W, 6224
 BLDG 130, 1ST FL LOOKING W, 6225
 BLDG 130, 1ST FL LOOKING E, 6226
 BLDG 130, 2ND FL LOOKING W, 6227
 BLDG 130, INTERIOR, 6228
 BLDG 130, INTERIOR, 6229
 BLDG 130, EXTERIOR LOOKING E, 6230
 BLDG 130, EXTERIOR, 6231
 BLDG 129, EXTERIOR, 6233
 BLDG 129, EXTERIOR, 6234
 BLDG 129, EXTERIOR, 6235
 BLDG 129, EXTERIOR, 6236
 BLDG 128, 1200 HP EX-GERMAN SUBMARINE DEISEL ENGINE VIEW FROM INBOARD SIDE SHOWING CAM SHAFT AND LEVERS, 6237
 BLDG 128, 1750 HP EX-GERMAN SUBMARINE DEISEL ENGINE, GENERAL VIEW FROM ABOVE LOOKING AFT, 6238
 BLDG 128, 3000 HP EX-GERMAN SUBMARINE DEISEL ENGINE, FRONT VIEW SHOWING FUEL PUMP, 6239
 BLDG 128, 300 HP EX-GERMAN SUBMARINE DEISEL ENGINE, TOP VIEW LOOKING FORWARD, 6240
 BLDG 128, 300 HP EX-GERMAN SUBMARINE DEISEL ENGINE, INBOARD SIDE QUARTERING VIEW, 6241
 BLDG 128, 1200 HP EX-GERMAN SUBMARINE DEISEL ENGINE (U164), FRONT ELEVATION SHOWING OPERATING GEAR, 6242
 BLDG 128, 1750 HP EX-GERMAN SUBMARINE DEISEL ENGINE, OUTBOARD SIDE, 6243
 BLDG 128, 1750 HP EX-GERMAN SUBMARINE DEISEL ENGINE, OUTBOARD SIDE, 6244
 BLDG 128, 1750 HP EX-GERMAN SUBMARINE DEISEL ENGINE, QUARTER ELEVATION INBOARD SIDE, 6245
 BLDG 128, 40 TON CRANE VIEW OF TROLLEY AND CONTROL BASKET, 6246
 BLDG 128, 40 TON CRANE, GENERAL VIEW, 6247
 BLDG 128, INSTALLATION OF 40 TON BROWNING CRANE, 6248
 BLDG 128, INTERIOR OF MACHINE SHOP EXTENSION (LAYING PAVEMENT), 6249
 BLDG 128, INTERIOR OF MACHINE SHOP EXTENSION (LAYING GROUND), 6250
 BLDG 128, BALCONY INTERIOR EXTENSION MACHINE SHOP, 6251
 BLDG 128, BALCONY INTERIOR EXTENSION MACHINE SHOP LAYING GROUND, 6252
 BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET 500 LBS OUTLET 100 LBS, 6254
 BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET 500 LBS OUTLET 50 LBS, 6255
 BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET 1000 LBS OUTLET 400 LBS, 6256
 BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET 1000 LBS OUTLET 300 LBS, 6257
 BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET 1000 LBS OUTLET 500 LBS, 6258
 BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET 1000 LBS OUTLET 500 LBS, 6259
 BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET 1000 LBS OUTLET 200 LBS, 6260
 BLDG 128, FISHER EXP SPRAY VALVE NEEDLE 2 THIRDS PER 1 INLET 1000 LBS OUTLET 600 LBS, 6261
 BLDG 128, USS 0-2 STARBOARD ENGINE & MAIN MOTORS, 6262
 BLDG 128, USS 0-2 STARBOARD ENGINE INBOARD SIDE, 6263
 BLDG 128, USS 0-2 STARBOARD ENGINE LOOKING FORWARD, 6264
 BLDG 128, USS 0-2 STARBOARD ENGINE OUTBOARD SIDE, 6265
 BLDG 128, O BOAT ENGINE'S ERECTING AND TESTING CREW, 6266
 BLDG 128, EXP SPRAY VALVE – NEEDLE 2 THIRDS PER 1 – INLET 1000 LBS OUTLET 400 LBS, 6267
 BLDG 128, EXP SPRAY VALVE – NEEDLE 2 THIRDS PER 1 – INLET 900 LBS OUTLET 500 LBS, 6268
 BLDG 128, EXP SPRAY VALVE – NEEDLE 2 THIRDS PER 1 – INLET 1200 LBS OUTLET 500 LBS, 6269
 BLDG 128, EXP SPRAY VALVE – NEEDLE 2 THIRDS PER 1 – INLET 800 LBS OUTLET 500 LBS, 6270
 BLDG 128, EXP SPRAY VALVE – NEEDLE 2 THIRDS PER 1 – INLET 1000 LBS OUTLET 450 LBS, 6271
 BLDG 128, EXP SPRAY VALVE – NEEDLE 2 THIRDS PER 1 – INLET 1200 LBS OUTLET 500 LBS, 6272
 BLDG 128, EXP SPRAY VALVE – NEEDLE 2 THIRDS PER 1 – INLET 1000 LBS OUTLET 350 LBS, 6273
 BLDG 128, EXP SPRAY VALVE – NEEDLE 2 THIRDS PER 1 – INLET 1000 LBS OUTLET 500 LBS, 6274
 EXTENSION TO BLDG 128, 6275

EXTENSION TO BLDG 128, LOOKING W, 6276
BUILDING EXTENSION TO BLDG 128, LOOKING W, 6277
EXTENSION TO BLDG 128, 6278
AMERICAN BRIDGE CO GOOSENECK ERECT CRANE, 6279
AMERICAN BRIDGE CO GOOSENECK ERECT CRANE, 6280
AMERICAN BRIDGE CO GOOSENECK ERECT CRANE, 6281
AMERICAN BRIDGE CO GOOSENECK ERECT CRANE, 6282
AMERICAN BRIDGE CO GOOSENECK ERECT CRANE AT EXTENT OF BLDG 128, 6283
AMERICAN BRIDGE CO GOOSENECK ERECT CRANE, 6284
AMERICAN BRIDGE CO GOOSENECK TYPE AT BLDG 128, 6285
CONSTRUCTION OF EXTENSION TO BLDG 128, LOOKING W, 6286
FOUNDATION FOR EXTENSION OF BLDG 128, LOOKING NW, 6288
BLDG 128 ROTTED FOUNDATION PILES UNDER SW CORNER, 6289
3 1/2" X 12" PLUNGER PUMP – SUPLEX BELT DRIVER GEARED – 1750 LBS PER INCH FOR ACCUMULATOR FOR MACHINE AND STRUCTURAL SHOPS, 6290
HYDRAULIC ACCUMULATOR PUMP FOR MACHINE AND STRUCTURAL SHOPS, 6291
HYDRAULIC ACCUMULATOR FOR MACHINE AND STRUCTURAL SHOPS, 6292
BLDG 128 EXTENSION ANCHOR ROD PLAN, 6294
EXTENSION TO BLDG 128, LOOKING N, 6295
BLDG 128 SHOWING CONDITION OF FOUNDATION PILES AT S CORNER OF ERECTING WING, 6296
BLDG 128 ERECTING WING, EXCAVATION FOR FOUNDATION FOR MILLING MACHINE, LOOKING NW, YARD LABOR, 6297
TABLET ON SW CORNER OF BLDG 128, 6298
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) GALLERY IN LEAN TO, LOOKING S, YARD LABOR, 6299
MACHINE SHOP, BLDG 128 (63-A) SHOWING CONGESTION, LOOKING NW, 6300
BLDG 128 (63-C) STEEL DELIVERED FOR LEAN-TO GALLERY, ERECTION BY YARD LABOR, 6304
BLDG 128 (63-A) SKYLIGHT GLASS WITH WIRE SCREEN UNDERNEATH, 6305
BLDG 128 (63-A) SKYLIGHT GLASS WITH WIRE SCREEN UNDERNEATH, 6306
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) LEAN-TO, LOOKING W, YARD LABOR, 6307
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) LEAN-TO, LOOKING S, YARD LABOR, 6308
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) LEAN-TO, LOOKING W, YARD LABOR, 6309
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) LEAN-TO, LOOKING S, YARD LABOR, 6310
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) LEAN-TO AT NW CORNER, LOOKING W, YARD LABOR, 6311
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) BORING MILL FOUNDATION, LOOKING W, YARD LABOR, 6312
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) BORING MILL FOUNDATION, LOOKING SW, YARD LABOR, 6313
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION, SE END, LOOKING W, YARD LABOR, 6314
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION, W END, LOOKING NW, YARD LABOR, 6315
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) EXCAVATION FOR LEAN-TO, LOOKING W, YARD LABOR, 6316
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) BORING MILL FOUNDATION, LOOKING NW, YARD LABOR, 6317
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) BORING MILL FOUNDATION, LOOKING NW, YARD LABOR, 6318
MONTHLY PROGRESS PHOTO, BLDG 128 (63-C) BORING MILL FOUNDATION, UNDERPINNING COLUMN, LOOKING N, YARD LABOR, 6319
MONTHLY PROGRESS PHOTO, BLDG 128 CONNECTION OIL ENGINE FOUNDATION TO SEWER ON MORRIS AVE, LOOKING SE, YARD LABOR, 6320
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION TO SEWER ON MORRIS AVE, LOOKING NW, YARD LABOR, 6321
BLDG 128 STARBOARD ENGINE S-10 ASSEMBLING VERTICAL SHAFT, 6322
BLDG 128 PORT ENGINE S-10 UNDER CONSTRUCTION ASSEMBLING OPERATING GEAR, 6323
BLDG 128 PORT ENGINE S-10 UNDER CONSTRUCTION GENERAL VIEW (QUARTER) INBOARD SIDE, 6324
BLDG 128 STARBOARD ENGINE S-10 UNDER CONSTRUCTION, 6325
BLDG 128 PORT ENGINE S-10 UNDER CONSTRUCTION, QUARTER VIEW INBOARD, 6326
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION, LOOKING N, YARD LABOR, 6327
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION, LOOKING N, YARD LABOR, 6328
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION, LOOKING SE, YARD LABOR, 6329
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) SEWER CONNECTION TO OIL ENGINE FOUNDATION, LOOKING SE, YARD LABOR, 6330
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION, LOOKING E, YARD LABOR, 6331
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION, LOOKING SE, YARD LABOR, 6332
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION, LOOKING SE, YARD LABOR, 6333
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION EXCAVATION, LOOKING NW, YARD LABOR, 6334
MONTHLY PROGRESS PHOTO, BLDG 128 (63-A) OIL ENGINE FOUNDATION EXCAVATION, LOOKING NW, YARD LABOR, 6335
MONTHLY PROGRESS PHOTO, BLDG 128, FOUNDATION FOR 14'-0" PLANER, YARD LABOR, 6336
MONTHLY PROGRESS PHOTO, BLDG 128, FOUNDATION FOR 14'-0" PLANER, YARD LABOR, 6337
BLDG 128, ROOF TEST ROOM, LOOKING W, 6339

BLDG 128, 6340
BLDG 128, WINDOWS, 6341
BLDG 128, WINDOWS, 6342
BLDG 128, OVERVIEW, 6343
BLDG 128, WINDOWS, 6344
BLDG 128, OVERVIEW, 6345
EXTENSION TO BLDG 128, MACHINERY DIV, INTERIOR VIEW OF N SIDE, LOOKING W FROM S PLATFORM, 6346
EXTENSION TO BLDG 128, MACHINERY DIV, INTERIOR VIEW, E SIDE OF SHOP, LOOKING NE, 6347
BLDG 128, MACHINERY DIV, EXTENSION TO BLDG 128, INTERIOR VIEW W SIDE OF SHOP, LOOKING NE, 6349
BLDG 128, OVERVIEW, 6350
36' AMBULANCE BOAT NO 6448 FOR USS HAVANA, 6352
36' AMBULANCE BOAT NO 6448 FOR USS HAVANA, 6353
36' AMBULANCE BOAT NO 6448 FOR USS HAVANA, 6354
36' AMBULANCE BOAT NO 6448 FOR USS HAVANA, 6355
36' AMBULANCE BOAT NO 6448 FOR USS HAVANA, 6356
BLDG 127, BOAT SHOP ENLARGED DOORWAY AT MORRIS AVE & 4TH ST CORNER, LOOKING NW, YARD LABOR, 6357
BLDG 127, BOAT SHOP ENLARGEMENT OF DOORWAY, MORRIS AVE & 4TH ST CORNER, LOOKING NW, YARD LABOR, 6358
BLDG 127, BOAT SHOP ENLARGING DOORWAY, MORRIS AVE & 4TH ST CORNER, LOOKING NW, YARD LABOR, 6359
MONTHLY PROGRESS PHOTO, BLDG 127 (44), TRANSFORMER STA, REBUILT TO LET CRANE CAGE PASS, LOOKING E, YARD LABOR, 6360
MONTHLY PROGRESS PHOTO, BLDG 127 (44), NEW RUNWAY, YARD LABOR & CRANES, EXETER MACH WKS IN SW BAY, LOOKING SE, 6361
MONTHLY PROGRESS PHOTO, BLDG 127 (44), NEW CRANE ON QUAY WALL, EXETER MACH WKS CONTR, 6362
MONTHLY PROGRESS PHOTO, BLDG 127 (44), NEW CRANE RUNWAY ON SW SIDE, LOOKING NW, YARD LABOR, 6363
MONTHLY PROGRESS PHOTO, BLDG 127 (44), NEW STEEL DOOR IN SW CORNER, LOOKING NW, YARD LABOR, 6364
MONTHLY PROGRESS PHOTO, BLDG 127 (44), ENLARGED DOORWAY IN S CORNER, LOOKING NW, YARD LABOR, 6365
MONTHLY PROGRESS PHOTO, BLDG 127 (44), ENLARGED HATCHWAY & DOORWAY IN S CORNER, LOOKING NW, YARD LABOR, 6366
MONTHLY PROGRESS PHOTO, BLDG 127 (44), ENLARGING HATCHWAY IN S CORNER, LOOKING SE, YARD LABOR, 6367
MONTHLY PROGRESS PHOTO, BLDG 127 (44), ENLARGEMENT OF DOORWAY IN S CORNER, LOOKING NW, YARD LABOR, 6368
MONTHLY PROGRESS PHOTO, BLDG 127 (44), CTR COLS CRANE RUNWAY, SW SIDE, LOOKING SE, YARD LABOR, 6369
MONTHLY PROGRESS PHOTO, BLDG 127 (44), SIDE COLS NEW CRANE RUNWAY, SW SIDE, LOOKING SE, YARD LABOR, 6370
MONTHLY PROGRESS PHOTO, BLDG 127 (44), NEW CRANE RUNWAY 1ST FL, W SIDE, LOOKING S, YARD LABOR, 6371
MONTHLY PROGRESS PHOTO, BLDG 127 (44), NEW CRANE RUNWAY 1ST FL, W SIDE, LOOKING S, YARD LABOR, 6372
MONTHLY PROGRESS PHOTO, BLDG 127 (44), NEW CRANE RUNWAY 1ST FL, W SIDE, LOOKING SE, YARD LABOR, 6373
MONTHLY PROGRESS PHOTO, BLDG 127 (44), NEW CRANE RUNWAY 1ST FL, W SIDE, LOOKING SE, YARD LABOR, 6374
MONTHLY PROGRESS PHOTO, BLDG 127 (44), ENLARGING SW HOISTWAY, YARD LABOR, 6375
BLDG 127, 3RD FL OFFICES, 6376
BLDG 127, SIDEWALK, 6377
BLDG 127, 3RD FL, LOOKING N, 6378
BLDG 127, ELEVATOR IN NE CORNER, 6379
BLDG 127, N END, BLDGS 22, 23, 24 & 127, 6380
BLDG 127, 1ST FL, LOOKING NW, 6381
BLDG 127, INTERIOR, 6382
BLDG 127, INTERIOR, 6383
BLDG 127, EXTERIOR, 6384
BLDG 127, EXTERIOR, 6385
BLDG 127, EXTERIOR, 6386
BLDG 127, EXTERIOR, 6387
BLDG 127, EXTERIOR, 6388
BLDG 127, INTERIOR, 6389
BLDG 127, EXTERIOR, 6390
BLDG 127, EXTERIOR, 6391
BLDG 127, EXTERIOR, 6392
BLDG 127, EXTERIOR, 6393
BLDG 127, EXTERIOR, 6394
BLDG 127, EXTERIOR, 6395
BLDG 127, EXTERIOR, 6396
BLDG 127, EXTERIOR, 6397
BLDG 127, EXTERIOR, 6398
BLDG 127, EXTERIOR, 6399
BLDG 127, EXTERIOR, 6400

BLDG 127, EXTERIOR, 6401
BLDG 127, EXTERIOR, 6402
BLDG 127, EXTERIOR, 6403
BLDG 127, EXTERIOR, 6404
BLDG 127, EXTERIOR, 6405
BLDG 127, EXTERIOR, 6406
BLDG 127, EXTERIOR, 6407
BLDG 127, EXTERIOR, 6408
BLDG 127, EXTERIOR, 6409
BLDG 127, EXTERIOR, 6410
BLDG 127, EXTERIOR, 6411
BLDG 127, EXTERIOR, 6412
BLDG 127, EXTERIOR, 6413
ALTERATIONS TO 5TH FL BLDG 5 FOR RADIO STATION AND ETC, ALLOT 7.03/5640.2-3335 PROJECT 4, YARD LABOR, 6414
ALTERATIONS TO 5TH FL BLDG 5 FOR RADIO STATION AND ETC, STEAM LINE OVERHAUL, ALLOT 75201-16, YARD LABOR, FED PW PROJECT 4, 6415
ALTERATIONS TO 5TH FL BLDG 5 FOR RADIO STATION AND ETC, ALLOT 7.03/5640.2-3335 PROJECT 4, YARD LABOR, 6416
ALTERATIONS TO 5TH FL BLDG 5 FOR RADIO STATION AND ETC, ALLOT 7.03/5640.2-3335 PROJECT 4, YARD LABOR, 6417
ALTERATIONS TO 5TH FL BLDG 5 FOR RADIO STATION AND ETC, ALLOT 7.03/5640.2-3335 PROJECT 4, YARD LABOR, 6418
REPAIRS TO EXTERIOR OF BLDG 5, ALLOT 73201-6, YARD LABOR, 6419
LIGHT MACHINE SHOP BLDG 5, 6420
PAINTING WINDOW FRAMES EXTERIOR BLDG 4, ALLOT 77 201-20, YARD LABOR, 6421
PAINTING AND REPAIRING DOORS AND WINDOW FRAMES EXTERIOR OF BLDG 4, ALLOT 77 201-20, YARD LABOR, 6422
NEW HYDRAULIC PRESS IN BLDG 4, BUREAU OF C AND R, 6423
NEW HYDRAULIC PRESS IN BLDG 4, BUREAU OF C AND R, 6424
FOUNDATION FOR NEW PLANER IN STRUCTURAL SHOP BLDG 4, 6427
REMOVING LOOSE CEMENT FROM FACE OF BLDG 4, ALLOT 76201-1 YARD LABOR, 6428
REPAIRS TO ROLLING STEEL DOORS BLDG 4, EXTERIOR VIEW OF DOORS E & F CONTRACT NOY 2514, 6429
REPAIRS TO ROLLING STEEL DOORS BLDG 4, EXTERIOR VIEW OF DOOR K CONTRACT NOY 2514, 6430
BENDING SLAAB BLDG 4, ALLOT 7.03/5640.1-33-5, YARD LABOR, 6431
EXTENSION TO BLDG 4, COMPLETED W ELEVATION, CONTRACT NOY 1905, 6432
EXTENSION TO BLDG 4, E ELEVATION, CONTRACT NOY 1905 COMPLETED, 6433
EXTENSION TO BLDG 4, N ELEVATION, CONTRACT NOY 1905 COMPLETED, 6434
EXTENSION TO BLDG 4, 5 TON ELECTRIC TRAVELING CRANE, CONTRACT NOY 1905, 6435
EXTENSION TO BLDG 4, STEEL SUPPORTING MEMBERS FOR BENDING SLAB ALLOT 7.03/5640.1-33-5, YARD LABOR, 6436
EXTENSION TO BLDG 4, GENERAL VIEW INTERIOR FROM E ENTRY DOOR LOOK W, CONTRACT NOY 1905, 6437
EXTENSION TO BLDG 4, CHAIN IDLER ARRANGEMENT (MONITOR SASH) SASH OPERATING DEVICE, CONTRACT NOY 1905, 6438
EXTENSION TO BLDG 4, STEEL CHANNELS SUPPORTING OPERATING MECHANISM FOR STEEL SHUTTER DOOR, CONTRACT NOY 1905, 6439
EXTENSION TO BLDG 4, STEEL SHUTTER DOOR RELOCATED, CONTRACT NOY 1905, 6440
EXTENSION TO BLDG 4, W ELEVATION INTERIOR VIEW SASH OPERATING DEVICES, CONTRACT NOY 1905, 6441
EXTENSION TO BLDG 4, REINFORCING COLUMN WEB SASH OPERATING DEVICE SHAFTINGS THROUGH SAME, CONTRACT NOY 1905, 6442
EXTENSION TO BLDG 4, CONTRACT NOY 1905, 6443
EXTENSION TO BLDG 4, CONTRACT NOY 1905, 6444
STORM DOORS TO BLDG 4, ALLOT 74201-1, YARD LABOR, 6445
EXTENSION TO BLDG 4, VIEW SHOWING STEEL ERECTING OPERATIONS, CONTRACT NOY 1905, 6446
PLACING COLUMN FOOTINGS FOR EXTENSION TO BLDG 4, ALLOT 7-03/5640.1-51-1, YARD LABOR, 6447
REPAIRS AND PAINTING BLDG 4, CONTRACT NOY 1543, VIEW NW CORNER, 6448
REPAIRS AND PAINTING BLDG 4, CONTRACT NOY 1543, COMPLETED, S SIDE, 6449
REPAIRS AND PAINTING BLDG 4, VIEW OF N SIDE, CONTRACT NOY 1543, COMPLETED, 6450
REPAIRS AND PAINTING BLDG 4, VIEW OF E END, CONTRACT NOY 1543, COMPLETED, 6451
PAINTING SW CORNER OF BLDG 4, CONTRACT NOY 1543, 6452
PAINTING S SIDE OF BLDG 4, CONTRACT NOY 1543, 6453
PAINTING WINDOW SASH OF BLDG 3, ALLOT 76201-17A, YARD LABOR, 6454
PAINTING WINDOW SASH OF BLDG 3, ALLOT 76201-17A, YARD LABOR, 6455
PAINTING WINDOW SASH OF BLDG 3, ALLOT 76201-17A, 6456
REPAIRS TO STEEL SASH BLDG 3, CONTRACT NOY 1926, 6457
REPAIRS TO STEEL SASH BLDG 3, CONTRACT NOY 1926, 6458
REPAIRS TO ELEVATORS BLDG 3, VIEW SHOWING EXCAVATION OF PIT, ALLOT 72201-56, YARD LABOR, 6459

REPAIRS TO ELEVATORS BLDG 3, VIEW OF MOTOR CONTROL PANEL AND BRAKE CONTRACT NOY 1518, 6460
VIEW OF COVERING ON STEAM PIPES IN POLICE OFFICE BLDG 3, ALLOT 73201-24, YARD LABOR, 6461
BLDG 3, ROUNDHOUSE, 6462
BLDG 2, STOREHOUSE, WOODEN ADDITION ON WARRINGTON AVE SIDE, LOOKING N, YARD LABOR, 6463
BLDG 2, STOREHOUSE, 6464
BLDG 2, STOREHOUSE, 6465
BLDG 2, STOREHOUSE, BOATSWAIN JOHNSON'S OFFICE, 6466
BLDG 2, STOREHOUSE, LOOKING SE, 6467
BLDG 2, STOREHOUSE, 6468
BLDG 2, STOREHOUSE, 6469
BLDG 1, LOOKING NE, POST OFFICE NAVY YARD STATION, 6470
Building 11 - Steel Foundry, Foundations for Drop Hammers, Looking South, Yard Labor, 6471
Building 11 - 1500 Ton Forge Press in Smithery, Looking West, Foundation, Yard Labor, 6472
Building 11 - Steel Foundry, Foundations for Drop Hammers, Looking South, Yard Labor, 6473
BLDG 12, 6479
BLDG 12, TYPE SAFETY DEVICES- NO 10, 6480
BLDG 5, LIGHT MACHINE SHOP, INTERIOR VIEW THIRD FL, LOOKING W, 6481
MONTHLY PROGRESS PHOTO, PAVING & NEW RR TRACK BACK OF BLDG 41 (58), LOOKING NW, YARD LABOR, 6482
MONTHLY PROGRESS PHOTO, NEW PAVING BETWEEN 5TH & 6TH STS, BLDGS 28 & 128 & 123, LOOKING NW, YARD
LABOR, 6483
MONTHLY PROGRESS PHOTO, NEW PAVING & RR TRACKS BEHIND BLDG 41 (58), LOOKING NW, YARD LABOR, BLDG 43,
ACCOUNTING DEPT, BLDG 55, 6484
MONTHLY PROGRESS PHOTO, NEW WOOD BLOCK PAVING FIRST ST, LOOKING NE, MACK BROTHERS CONTRACTOR,
6485
MONTHLY PROGRESS PHOTO, NEW WOOD BLOCK PAVING PARK AVE, LOOKING N, MACK BROTHERS CONTRACTOR,
6486
MONTHLY PROGRESS PHOTO, PAVING MORRIS AVE BETWEEN 4TH & 3RD STS, BLDG 20, LOOKING NW, MACK
BROTHERS CONTRACTOR, 6487
MONTHLY PROGRESS PHOTO, WOODBLOCK PAVING 3RD ST NEAR MORRIS AVE, LOOKING NE, MACK BROTHERS
CONTRACTOR, 6488
MONTHLY PROGRESS PHOTO, GRANITE BLOCK PAVING MORRIS AVE, LOOKING SE FROM 3RD ST, MACK BROTHERS
CONTRACTOR, 6489
MONTHLY PROGRESS PHOTO, WOOD BLOCK PAVING WARRINGTON AVE, LOOKING SE FROM 3RD ST, MACK
BROTHERS CONTRACTOR, 6490
MONTHLY PROGRESS PHOTO, WOOD BLOCK PAVING WARRINGTON AVE & 4TH ST, LOOKING NE, MACK BROTHERS
CONTRACTOR, 6491
MONTHLY PROGRESS PHOTO, WOOD BLOCK PAVING ON 1ST ST, LOOKING NE FROM PARK AVE, MACK BROTHERS
CONTRACTOR, 6492
MONTHLY PROGRESS PHOTO, WOOD BLOCK PAVING ON 1ST ST, LOOKING NE FROM WARRINGTON AVE, MACK
BROTHERS CONTRACTOR, 6493
MONTHLY PROGRESS PHOTO, WOOD BLOCK PAVING ON PARK AVE, LOOKING S FROM 1ST ST, MACK BROTHERS
CONTRACTOR, 6494
MONTHLY PROGRESS PHOTO, WOOD BLOCK PAVING ALONG RR TRACK ON 1ST ST BTWN WARRINGTON & PARK
AVES, LOOKING NE, MACK BROTHERS CONTRACTOR, 6495
MONTHLY PROGRESS PHOTO, WOOD BLOCK PAVEMENT ALONG RR TRACKS ON 1ST ST BTWN WARRINGTON & PARK
AVES, LOOKING SW, MACK BROTHERS CONTRACTOR, 6496
MONTHLY PROGRESS PHOTO, NEW WOOD BLOCK PAVING 3RD ST NEAR MORRIS AVE, LOOKING NE, MACK BROTHERS
CONTRACTOR, 6497
MONTHLY PROGRESS PHOTO, NEW WOOD BLOCK PAVING WARRINGTON AVE BTWN 3RD & 4TH STS, LOOKING SE,
MACK BROTHERS CONTRACTOR, 6498
MONTHLY PROGRESS PHOTO, NEW WOOD BLOCK PAVING WARRINGTON AVE & 4TH ST, LOOKING NE, MACK
BROTHERS CONTRACTOR, 6499
MONTHLY PROGRESS PHOTO, NEW GRANITE BLOCK PAVEMENT, MORRIS AVE, LOOKING SE FROM 3RD ST, MACK
BROTHERS CONTRACTOR, 6500
MONTHLY PROGRESS PHOTO, 5TH ST PAVING, LOOKING NE FROM CHAUNCEY AVE, YARD LABOR, 6502
MONTHLY PROGRESS PHOTO, 5TH ST REPAVING COMPLETED, LOOKING NE FROM CHAUNCEY AVE, YARD LABOR,
6503
MONTHLY PROGRESS PHOTO, NEW SIDEWALK ON MORRIS AVE ALONGSIDE BLDG 29, LOOKING NW, YARD LABOR,
6504
MONTHLY PROGRESS PHOTO, REPAIRS TO WATERFRONT STREET BTWN PIERS D&C, LOOKING NW, YARD LABOR,
6505
MONTHLY PROGRESS PHOTO, REPAIRS TO WATERFRONT STREET APPROACHING PIER C, LOOKING SE, YARD LABOR,
6506
CONCRETE PAVING WATERFRONT BTWN PIERS C&D, YARD LABOR, 6507
MONTHLY PROGRESS PHOTO, REPAIRS TO WATERFRONT STREET APPROACHING PIER C, LOOKING W, YARD LABOR,

6508

CONCRETE PAVING WATERFRONT BTWN PIERS C&D, YARD LABOR, 6509
CONCRETE PAVING WATERFRONT BTWN PIERS C&D, YARD LABOR, 6510
CONCRETE PAVING WATERFRONT BTWN PIERS C&D, YARD LABOR, 6511
CONCRETE PAVING WATERFRONT BTWN PIERS C&D, YARD LABOR, 6512
MONTHLY PROGRESS PHOTO, CONCRETE PAVING AT PIER D APPROACH, LOOKING W, YARD LABOR, 6513
MONTHLY PROGRESS PHOTO, CONCRETE PAVING WATERFRONT BTWN PIERS C&D, LOOKING NW, YARD LABOR, 6514
MONTHLY PROGRESS PHOTO, NEW PAVING WATERFRONT BTWN PIERS C&D, LOOKING NW, YARD LABOR, 6515
REBUILDING DRIVEWAY, NAVAL HOSPITAL, LOOKING SE FROM IN FRONT OF QUARTERS 4, YARD LABOR, 6516
DRIVEWAY & WALK TO CONTAGIOUS DISEASES UNITS, NAVAL HOSPITAL, YARD LABOR, 6517
REBUILDING DRIVEWAY, NAVAL HOSPITAL, LOOKING N FROM NEAR MEDICAL SUPPLY DEPOT, YARD LABOR, 6518
REBUILDING DRIVEWAY, NAVAL HOSPITAL, LOOKING W FROM NEAR CEMETARY ENTRANCE, YARD LABOR, 6519
Concrete Roadway between Piers C&D Damaged by Oxy-Acetylene Flame, 6520
Concrete Roadway between Piers C&D Damaged by Oxy-Acetylene Flame, 6521
CONCRETE DRIVEWAY BTWN PIERS C&D DAMAGED BY OXY-ACETYLENE FLAME, 6522
CONCRETE DRIVEWAY BTWN PIERS C&D DAMAGED BY OXY-ACETYLENE FLAME, 6523
NAVAL HOSPITAL ROAD REPAIRS, LOOKING NW TOWARD QUARTERS 4, YARD LABOR, 6524
NAVAL HOSPITAL ROAD REPAIRS, LOOKING NE OVER CIRCLE NEAR QUARTERS 4, YARD LABOR, 6525
NAVAL HOSPITAL ROAD REPAIRS, LOOKING W FROM NEAR CEMETARY, YARD LABOR, 6526
NAVAL HOSPITAL ROAD REPAIRS, LOOKING SW FROM NEAR FEMALE NURSES QUARTERS, YARD LABOR, 6528
NAVAL HOSPITAL ROAD REPAIRS, LOOKING N FROM NEAR BOILER ROOM, YARD LABOR, 6529
REPAVING AT HOSPITAL, LOOKING SW FROM NEAR FEMALE NURSES QUARTERS, YARD LABOR, 6530
REPAVING AT HOSPITAL, LOOKING NE FROM NEAR BOILER ROOM, YARD LABOR, 6531
REPAIRS TO 2ND ST, LOOKING NE FROM CHAUNCEY AVE, 6532
REPAIRS TO 2ND ST, LOOKING NE FROM DOCK ST, 6533
NEW PAVEMENT 3RD ST, BTWN DOCK ST & MORRIS AVE, LOOKING N FROM NEAR MORRIS AVE, FRANKLIN CONTG CO CTR, 6534
NEW PAVING 3RD ST, BTWN DOCK ST & MORRIS AVE, LOOKING SW FROM DOCK ST, BASE, YARD LABOR, TOP, FRANKLIN CONTG CO CTR, 6535
NEW PAVEMENT ON 2ND ST, LOOKING NE FROM WARRINGTON AVE, FRANKLIN CONTG CO CTR, 6536
BLDG 7, ARCHITECTURE DRAWINGS, FIRST, SECOND & THIRD FLOORS, 6537
CONTROL REGULATOR IN AIR CONDITION ROOM, CONTRACT NOY 2348, 6538
SECTION OF AIR SUPPLY DUCT AND RETURN GRILLE IN AIR CONDITIONED ROOM, 2ND FL, BLDG 5, CONTRACT NOY 2348, 6539
AIR INTAKE DUCTS AND WEATHER MAKER FOR AIR CONDITIONED ROOM, 2ND FL, BLDG 5, CONTRACT NOY 2348, 6540
REMODELING 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC, (BLUE PRINTING DEPT), ALLOT, 7.03/5640.2.3335, FED, PW PROJECT NO 4, 6541
REMODELING 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC, (ENLISTED PERSONNEL QUARTERS), ALLOT, 7.03/5640.2.3335, FED, PW PROJECT NO 4, 6542
REMODELING 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC, (RADIO LABORATORY), ALLOT, 7.03/5640.2.3335, YARD LABOR, FED, PW PROJECT NO 4, 6543
REMODELING 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC, (GENERATOR ROOM), ALLOT, 7.03/5640.2.3335, YARD LABOR, FED, PW PROJECT NO 4, 6544
AIR INTAKE DUCTS AND WEATHER MAKER FOR AIR CONDITIONED ROOM, 2ND FL, BLDG 5, CONTRACT NOY 2348, 6545
REMODELING 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC (VIEW OF US NAVAL RADIO STATION), ALLOT 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 6546
REMODELING 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC (OFFICER IN CHARGE OFFICE), ALLOT 7.03/5640.2-3335, FED, PW PROJECT NO 4, 6547
REMODELING 6TH FL OF BLDG 5, ALLOT 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 6548
REMODELING 6TH FL OF BLDG 5, ALLOT 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 6549
REPLACEMENT OF STEEL SASH BLDG 5, 6TH FL, VIEW OF S SIDE OF BLDG, CONTRACT NOY 2265, 6550
ALTERATIONS TO 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC, ALLOT, 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 6551
ALTERATIONS TO 5TH FL BATHROOM OF BLDG 5 FOR RADIO STATION AND ETC, ALLOT, 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 6552
ALTERATIONS TO 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC, ALLOT, 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 6553
ALTERATIONS TO 5TH FL OF BLDG 5 COVERING STEAM PIPES, ALLOT, 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 6554
ALTERATIONS TO 6TH FL OF BLDG 5 LAYING NEW FLOORING, ALLOT, 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 6555
ALTERATIONS TO 5TH FL OF BLDG 5 STEAM LINE OVERHAUL 6TH ST SIDE OF BLDG 5, 6556
ALTERATIONS TO 6TH FL OF BLDG 5 FOR DRAFTING DEPT, ALLOT, 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 6557
ALTERATIONS TO 5TH FL BATHROOM OF BLDG 5 FOR RADIO STATION AND ETC, ALLOT, 7.03/5640.2-3335, YARD LABOR,

PROJECT NO 4, 6558
 ALTERATIONS TO 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC, ALLOT, 7.03/5640.2-3335, YARD LABOR, PROJECT NO 4, 6559
 ALTERATIONS TO 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC, ALLOT, 7.03/5640.2-3335, YARD LABOR, FED PW PROJECT NO 4, 6560
 REPAIRS TO QUARTERS K AND L, WORK BEING DONE BY CWA WORKERS, 6561
 NEW KITCHEN IN QUARTERS A, ALLOT, 75201-12, YARD LABOR, 6562
 NEW KITCHEN IN QUARTERS A, ALLOT, 75201-12, YARD LABOR, 6563
 ALTERATIONS AND REPAIRS TO QUARTERS G, VIEW OF NEW BATHROOM IN BASEMENT, ALLOT 74201-48, YARD LABOR, 6564
 ALTERATIONS AND REPAIRS TO QUARTERS G, VIEW OF 1ST FL, ALLOT 74201-48, YARD LABOR, 6565
 ALTERATIONS AND REPAIRS TO QUARTERS G, VIEW IN BASEMENT, ALLOT 74201-48, YARD LABOR, 6566
 ALTERATIONS AND REPAIRS TO QUARTERS G, VIEW OF EAST SIDE, ALLOT 74201-48, YARD LABOR, 6567
 ALTERATIONS AND REPAIRS TO QUARTERS G, VIEW OF NEW REAR STAIRS, ALLOT 74201-48, YARD LABOR, 6568
 ALTERATIONS AND REPAIRS TO QUARTERS G, VIEW OF EAST SIDE, ALLOT 74201-48, YARD LABOR, 6569
 ALTERATIONS AND REPAIRS TO QUARTERS G, ALLOT 74201-48, YARD LABOR, 6570
 ALTERATIONS AND REPAIRS TO QUARTERS G, ALLOT 74201-48, YARD LABOR, 6571
 QUARTERS A, 6572
 WPA CONSTRUCTION OF CONSERVATORY AT QUARTERS A COMPLETE, YARD PROJ 10, SUBPROJ 10, OFFICIAL PROJ 09-46, NEC 657, 6573
 WPA CONSTRUCTION OF CONSERVATORY AT QUARTERS A COMPLETE, YARD PROJ 10, SUBPROJ 10, OFFICIAL PROJ 09-46, NEC 657, 6574
 NEW OAK FLOORING ON COMPLETION OF CONTRACT NOY 2559 IN QUARTERS A, 6575
 NEW OAK FLOORING, QUARTERS A (1/4 OAK, WHITE, CLEAR) PRIOR TO FINISHING WORK START, VIEW LOOKING INTO HALL, 6576
 OAK FLOORING, QUARTERS A, VIEW FROM MAIN HALL, CONTRACT NOY 2559, 6577
 OAK FLOORING, QUARTERS A, CONDITION OF EXISTING FLOOR PRIOR TO CONTRACT START, CONTRACT NOY 2559, 6578
 OAK FLOORING, QUARTERS A, CONDITION OF EXISTING FLOOR PRIOR TO CONTRACT START, CONTRACT NOY 2559, 6579
 ALTERATIONS AND REPAIRS TO QUARTERS G, ALLOT 74201-48, YARD LABOR, 6580
 REPAIRS TO QUARTERS G, ALLOT 74201-48, YARD LABOR, 6581
 Building 11 - Smithery, Foundation for Small Forge Presses, Looking Northeast, Yard Labor, 6584
 Building 11 - Steel Foundry, Looking Southeast, 6598
 Building 11 - (34) Monthly Progress Photo, Foundation, Etc, Preliminary to Laying Wood Block Pavement, Looking West, Yard Labor, 6601
 Building 11 - (34) Case in Planning Room, 6608
 Building 10 - Monthly Progress Photo, Lean-to, New Floor, Looking East, Yard Labor, 6630
 TYPE SAFETY DEVICES- NO 7, 6631
 TYPE SAFETY DEVICES- NO 6, 6632
 TYPE SAFETY DEVICES- NO 5, 6633
 TYPE SAFETY DEVICES- NO 4, 6634
 Building 10 - Addition Looking Southeast, 6635
 Building 10 - Lean-to Addition Looking North, 6636
 Building 10 - Lean-to Addition Looking North, 6637
 Building 10 - Looking North, 6638
 Building 10 - Addition, Looking North, 6639
 Building 10 - Looking North, 6640
 Building 10 - Looking North, 6641
 Building 10, 6642
 REPAIRS TO ROOF AND RAMP BLDG 9, ALLOT 7X218-23-1, YARD LABOR, 6643
 ALTERATIONS TO N WALL, BLDG 9, LOOKING E FROM BLDG 15, YARD LABOR, 223G 13/X153, 6644
 SHORING & REMOVAL 1ST STORY NW WALL, EXTRA WORK, BLDG 9, LOOKING SE, 6645
 SHORING & REMOVAL 1ST STORY NW WALL, EXTRA WORK, BLDG 9, LOOKING S, 6646
 LOOKING SE IN BLDG 9, 1ST FL, 6647
 MONTHLY PROGRESS PHOTO, BLDG 9, CRANE RUNWAY EXTENDED TO END OF BLDG, LOOKING SE, YARD LABOR, 6648
 BLDG 8, LOOKING E, 6649
 BLDG 8, LOOKING W, 6650
 FILING CABINET FOR YARD SURVEY SHEETS, 6651
 VAULT FILING CABINET FOR YARD SURVEY SHEETS, LIBRARY BUREAU, CONTRACTOR, 6652
 PUBLIC WORKS DEPT VAULT NEGATIVE FILE CASES, 6653
 PUBLIC WORKS DEPT, "TICKLER" CABINET, 6654
 PUBLIC WORKS DEPT, CARD FILES FOR ALLOTMENTS, ETC, 6655
 PUBLIC WORKS DEPT, CARD FILES FOR ALLOTMENTS, ETC, 6656

PUBLIC WORKS DEPT, DRAFTING ROOM, 6657
PUBLIC WORKS DEPT, VAULT – NEGATIVE FILE, 6658
PUBLIC WORKS DEPT, DRAFTING ROOM, 6659
PUBLIC WORKS DEPT, BLUEPRINT ROOM, 6660
PUBLIC WORKS DEPT, VAULT – PLAN FILE, 6661
PUBLIC WORKS DEPT, BLUEPRINT ROOM, 6662
PUBLIC WORKS DEPT, BLUEPRINT ROOM, 6663
PUBLIC WORKS DEPT, BLUEPRINT FILE RACK, 6664
PUBLIC WORKS DEPT, BLUEPRINT FILE RACK, 6665
PUBLIC WORKS DEPT, RECORD BOARD IN FOREMEN'S OFFICE, 6666
PUBLIC WORKS DEPT, RECORD BOARD IN FOREMEN'S OFFICE, 6667
PUBLIC WORKS DEPT, RECORD BOARD IN FOREMEN'S OFFICE, 6668
PUBLIC WORKS DEPT, RECORD BOARD IN FOREMEN'S OFFICE, 6669
DRAFTING ROOM BLDG 7, 6670
DRAFTING ROOM BLDG 7, 6671
DRAFTING ROOM BLDG 7, 6672
ADDITION TO SW CORNER OF BLDG 6, LOOKING E, CONTR 3399, 6673
PAINTING DOORS – WINDOW FRAMES AND SASH OF BLDG 5, S SIDE OF BLDG, ALLOT, 76201-17A, YARD LABOR, 6674
NEW VAULT 5TH FL, BLDG 5, ALLOT, 77201-8, YARD LABOR, 6675
NEW VAULT 5TH FL, BLDG 5, ALLOT, 77201-8, YARD LABOR, 6676
PAINTING DOORS, WINDOW FRAMES, AND SASH, BLDG 5, N SIDE, ALLOT, 76201-17A, YARD LABOR, 6677
PAINTING DOORS, WINDOW FRAMES, AND SASH, BLDG 5, S SIDE OF BLDG, ALLOT, 76201-17A, YARD LABOR, 6678
PAINTING WINDOW FRAMES, AND SASH OF BLDG 5, ALLOT, 76201-17A, YARD LABOR, 6679
ENCLOSURE OF AIR CONDITIONING SYSTEM AND EQUIPMENT, CONTRACT NOY 2348, 6680
ENCLOSURE OF AIR CONDITIONING SYSTEM AND EQUIPMENT, CONTRACT NOY 2348, 6681
WEATHERMAKER, SUPPLY DUCTS AND REFRIGERATOR OUTSIDE OF AIR CONDITIONED ROOM, CONTRACT NOY 2348, 6682
WEATHERMAKER, SUPPLY DUCTS AND REFRIGERATOR OUTSIDE OF AIR CONDITIONED ROOM, CONTRACT NOY 2348, 6683
WALLABOUT MARKET, 6684
"IN THE TROUGH OF THE SEA", USS ADAMS IN TOW OF USS YORKTOWN, 6685
LEASED STEAM LIGHTER "DANA" PORT QUARTER, PROV & CLO DEPOT, 6692
LEASED STEAM LIGHTER "DANA" STARBOARD BOW, PROV & CLO DEPOT, 6693
PHOTO FOR PERMANENT BOARD OF INVESTIGATION, 6694
CLINTON AVE STOREHOUSES LOOKING N, CHAS MEADS & CO, CONTRACTOR, 6696
INTERIOR OF BARRACKS BLDG, CITY PARK CAMP, 6697
LINING UP DIRECTOR SCOPE, 6700
LINING UP DIRECTOR SCOPE, 6701
LINING UP DIRECTOR SCOPE, 6702
CLINTON AVE STOREHOUSE, LOOKING CHAS MEADS & CO, CONTRACTOR, 6703
BLDG 115, MOULD LOFT- 2ND FL, 6705
SCRAP LUMBER E SIDE OF SAW MILL, 6706
CITY PARK FROM NW CORNER, S OF PAVILLION, 6708
CITY PARK FROM SE CORNER, E OF PAVILLION, 6709
CITY PARK FROM NW CORNER, N OF PAVILLION, 6710
CITY PARK FROM SE CORNER, W OF PAVILLION, 6711
CITY PARK PERGOLA & COMFORT STATION FROM ST EDWARDS PLACE, 6712
CITY PARK PAVILLION, 6713
CITY PARK COMFORT STATION FROM S, 6714
CLINTON AVE STOREHOUSE, LOOKING N, CHAS MEADS & CO, CONTRACTOR, 6715
CLINTON AVE STOREHOUSE, LOOKING S, CHAS MEADS & CO, CONTRACTOR, 6716
MACHINERY DETAIL, 6717
MACHINERY DETAIL, 6718
MACHINERY DETAIL, 6719
MACHINERY DETAIL, 6720
MACHINERY DETAIL, 6721
SPRUCE, WHITE PINE AND THICK MAPLE IN LUMBER SHED, 6722
SPRUCE INSIDE LUMBER SHED, 6723
OAK LUMBER ON 2ND FL OF LUMBER SHED, 6724
OAK BOAT LUMBER, 6725
ASH MESS BENCHES, 6726
TEAK SHED, 6727
TIMBER PILES SE OF TEAK SHED, 6728
VIEW INSIDE JOINER SHOP, 6729
LUMBER SHED S OF MAIN GATE, 6730

DRY KILN IN JOINER SHOP, 6731
POPLAR DRAWING BOARDS, 6732
TEMP STORAGE SHED, CHAUNCEY AVE BET 3 & 2 STS, LOOKING NW FROM CHAUNCEY NEAR 3RD, CHAS MEADS & CO,
CONTR, 6733
TEMP STORAGE SHED, CHAUNCEY AVE BET 4 & 3 STS, LOOKING NW FROM SW SIDE LOCO SHED, CHAS MEADS & CO,
CONTR, 6734
MACHINERY DETAIL, 6737
MACHINERY DETAIL, 6738
DIRECTOR SCOPE, 6739
DIRECTOR SCOPE, 6740
FINE TAILORING LETTER, 45 SANDS ST, 6741
STEEL RACK W OF DD1 REINFORCED CONCRETE WORK BY PUB WKS, LOOKING N, YARD LABOR, 6742
LOOKING S FROM PAULDING AVE, W OF BLDG 120, 6743
SCRAP HEAP W OF BLDG 120, LOOKING NW, 6744
LOOKING N FROM E OF REAR OF BLDG 120, 6745
LOOKING SE AT PARK & PERRY AVES, 6746
LOOKING SE FROM BET BLDGS 87 & 215, 6747
EXPERIMENTAL FLOOR NO 10, 6748
EXPERIMENTAL FLOOR NO 10, INCLUDING DESCRIPTION OF PHOTOGRAPH, 6749
MONTHLY PROGRESS PHOTO, OIL STORAGE SHED IN REAR OF BLDG 120, LOOKING E, YARD LABOR, 6751
GENERAL ROUTING OF PLATES AND BARS, MANUFACTURING DERF, HULL DIV, 6752
SCALES FOR EXPERIMENTAL PURPOSES ABOARD SHIP WEIGHING POSITION, 6753
SCALES FOR EXPERIMENTAL PURPOSES ABOARD SHIP LOADING POSITION, 6754
MONTHLY PROGRESS PHOTO, OIL STORAGE SHED IN REAR OF BLDG 120, LOOKING E, YARD LABOR, 6755
TEST SUBMARINE SECTION, INTERIOR VIEW NO 3, 6756
TEST SUBMARINE SECTION, INTERIOR VIEW NO 2, 6757
TEST SUBMARINE SECTION, INTERIOR VIEW NO 1, 6758
TEST SUBMARINE SECTION, EXTERIOR VIEW, 6759
WATERFRONT FROM S SIDE, PIER F, LOOKING SW, 6760
WATERFRONT LOOKING S FROM S SIDE, PIER F, 6761
WATERFRONT LOOKING SE FROM S SIDE, PIER F, 6762
WATERFRONT LOOKING NE FROM S SIDE, PIER F, 6763
WATERFRONT LOOKING NW FROM TOP FWD MAST USS FLORIDA LYING ALONG S SIDE OF PIER F, 6764
WATERFRONT LOOKING W FROM OUT END COAL PLANT, 6765
WATERFRONT LOOKING SW FROM OUT END COAL PLANT, 6766
WATERFRONT LOOKING S FROM OUT END COAL PLANT, 6767
WATERFRONT LOOKING SE FROM OUT END COAL PLANT, 6768
WATERFRONT LOOKING SE FROM INNER END COAL PLANT, 6769
WATERFRONT LOOKING NE FROM INNER END OF COAL PLANT, 6770
WATERFRONT LOOKING N FROM INSHORE END OF COAL PLANT, 6771
WATERFRONT LOOKING S FROM OUT END CANTILEVER CRANE TRACK, 6772
WATERFRONT LOOKING SE FROM OUT END CANTILEVER CRANE TRACK, 6773
WATERFRONT LOOKING E FROM OUT END CANTILEVER CRANE TRACK, 6774
WATERFRONT LOOKING NE FROM OUT END CANTILEVER CRANE TRACK, 6775
WATERFRONT LOOKING NW FROM OUTER END OF CANTILEVER CRANE TRACK, 6776
MONTHLY PROGRESS PHOTO, FOUNDATION FOR PROPELLER SHAFTS, MCD AVE NEAR BLDG 6 (25), YARD LABOR,
6777
HULL DIV, OIL BURNING BAKE OEN FOR PEARL HARBOR, 6778
MONTHLY PROGRESS PHOTO, FOUNDATION FOR PROPELLER SHAFTS, MCDONOUGH AVE NEAR BLDG 2 (18), YARD
LABOR, 6779
METHOD OF TESTING BULKHEAD STIFFENER BRACKET, 6780
OIL BURNING RANGES IN CREW'S GALLEY OF USS FULTON, 6781
HULL DIV TEST AIR TANK, TANK NO 27, 6782
CARGO MAT, HULL DIV, 6783
CARGO MAT, HULL DIV, 6784
CARGO MAT, HULL DIV, 6785
VIEW OF WATERFRONT, LOOKING SE FROM CANTILEVER CRANE TRACK, 6786
VIEW OF WATERFRONT, LOOKING E FROM CANTILEVER CRANE TRACK, 6787
VIEW OF WATERFRONT, LOOKING NE FROM CANTILEVER CRANE TRACK, 6788
VIEW OF WATERFRONT, LOOKING N FROM CANTILEVER CRANE TRACK, 6789
VIEW OF WATERFRONT, LOOKING NW FROM CANTILEVER CRANE TRACK, 6790
VIEW OF WATERFRONT, LOOKING E FROM TOP OF BLDG 6, 6791
VIEW OF WATERFRONT, LOOKING NE FROM TOP OF BLDG 6, 6792
ONE TON TROLLY HOIST, 6796
ONE TON TROLLY HOIST, WITH HOIST REMOVED, 6797

ONE TON TROLLY HOIST, 6798
ROPE FENDER FOR HULL DIV, 6799
MONTHLY PROGRESS PHOTO, LAUNCHING WAYS FOR HYDROPLANE, LOOKING S, YARD LABOR, 6800
MONTHLY PROGRESS PHOTO, JIB CRANE AND FENCE AT PICKLING TANK, LOOKING NW, YARD LABOR, 6801
CD THURBER, CE, USN, 6802
CD THURBER, CE, USN, 6803
MONTHLY PROGRESS PHOTO, FENCE & CRANE FOUNDATION AT PICKLING TANKS, LOOKING W, YARD LABOR, 6804
FRAME FOR PILE CUTTING SAW, 6805
DRINKING FOUNTAIN, 6809
COALING ORION BY CONVEYOR FROM BARGE ALONG SIDE, 6810
COALING ORION BY CONVEYOR FROM BARGE ALONG SIDE, 6811
COALING ORION BY CONVEYOR FROM BARGE ALONG SIDE, 6812
COMMANDANT'S DAUGHTERS ABOARD LAUNCH SPRAY, 6813
COMMANDANT'S LAUNCH SPRAY, 6814
COMMANDANT'S LAUNCH SPRAY, 6815
COMMANDANT'S LAUNCH SPRAY, 6816
COMMANDANT'S LAUNCH SPRAY, 6817
COMMANDANT'S LAUNCH SPRAY, 6818
COMMANDANT'S LAUNCH SPRAY, 6819
COMMANDANT'S LAUNCH SPRAY, 6820
DENT MADE IN PORT SIDE HAMBURG AMERICAN SS CLEVELAND OFF QUARANTINE 04-20-1914, BY PORTO RICO
STEAMER CAROLINA, PHOTO MADE AFTER WATER PUMPED DOWN, 6821
DENT ON PORT SIDE HAMBURG AMERICAN SS CLEVELAND MKADE 4-20-1914 OFF QUARANTINE, BY PORTO RICO
STEAMER CAROLINA, PHOTO TAKEN WHILE VESSEL STILL AFLOAT, 6822
HAMBURG AMERICAN SS CLEVELAND IN DD 4, 6823
HAMBURG AMERICAN SS CLEVELAND IN DD 4, 6824
STEAM SHOVEL BROUGHT UP FROM PANAMA, SIDE & BACK VIEW, 6825
STEAM SHOVEL BROUGHT UP FROM PANAMA, SIDE & FRONT VIEW, 6826
LOOKING SE FROM 180 FT MARK, W SIDE DRY DOCK 4, 6827
LOOKING N FROM SANDS ST GATE, 6828
LOOKING SE ALONG MORRIS AVE FROM 5TH ST, 6829
LOOKING NW ALONG WARRINGTON AVE FROM 3RD ST, 6830
SNOW ALONG WATERFRONT BET 2ND & 3RD STS, LOOKING NW, 6831
SNOW IN DOCK ST, LOOKING SE FROM 1ST ST, 6832
SNOW IN CHAUNCEY AVE, LOOKING NW FROM 3RD ST, 6833
SNOW IN MAIN ST, LOOKING SW FROM DOCK ST, 6834
SNOW IN 5TH ST, LOOKING SW FROM NEAR MORRIS AVE, 6835
SNOW IN 4TH ST, LOOKING SW FROM WARRINGTON AVE, 6836
SNOW IN 3RD ST, LOOKING SW FROM NEAR CHAUNCEY AVE, 6837
SNOW IN 1ST ST, LOOKING SW FROM NEAR WARRINGTON AVE, 6838
SNOW, LOOKING SE FROM PARK AVE AT SANDS ST GATE, 6839
SNOW, LOOKING NE FROM PARK AVE AT SANDS ST GATE, 6840
SNOW, LOOKING N FROM PARK AVE AT SANDS ST GATE, 6841
SNOW, LOOKING SE FROM HOUSE A (10), 6842
SNOW, LOOKING NE FROM HOUSE A (10), 6843
SNOW AROUND HOUSE A (10), LOOKING N FROM MAIN ST NEAR PERRY AVE, 6844
SNOW AROUND HOUSE A (10), LOOKING W FROM MAIN ST OPPOSITE BLDG 2 (18), 6845
E WATERFRONT LOOKING E FROM W SIDE COMMANDANT'S SLIP, 6853
ELECTRICAL CLASS, STEAM & INTERNAL COMBUSTION ENGINE LABORATORY, 6855
ELECTRICAL CLASS, ENGINE ROOM, 6856
ELECTRICAL CLASS, ENGINE SECTION, 6857
ELECTRICAL CLASS, SMITHERY SECTION, 6858
ELECTRICAL CLASS, ARMATURE WINDING SECTION, 6859
ELECTRICAL CLASS, RADIO SECTION, 6860
ELECTRICAL CLASS, MECHANICAL SECTION, 6861
WATERFRONT NEAR ENTRANCES TO DDS 2 & 3, LOOKING E, 6862
WATERFRONT FROM DD 3 ENTRANCE TO S SIDE PIER E, LOOKING NE, 6863
WATERFRONT ALONG CAUSEWAY, SHOWING END OF PIER E, LOOKING NE, 6864
WATERFRONT SW SIDE ORDNANCE DOCK, SHOWING END OF PIER F, LOOKING N, 6865
USS NEW YORK & USS WYOMING AT PIER D, LOOKING W FROM PIER E, 6866
WATERFRONT AT PIER D AND MAINLAND, LOOKING N, 6867
FROM PHOTO OF SS CARPATHIA IN DD 4 AT ERIE BASIN, BROOKLYN, NY, 6868
E WATERFRONT OF NAVY YARD, LOOKING E FROM NEAR COMMANDANT'S SLIP, 6869
WATERFRONT SW SIDE OF ORDNANCE DOCK, LOOKING N FROM W SIDE ENTRANCE DD 4, 6870
VESSELS ALONGSIDE PIER D, LOOKING SW FROM PIER E, 6871

LOOKING NW ALONG CAUSEWAY, SHOWING VESSELS AT PIERS E & F, 6872
 VESSELS ALONGSIDE PIER F, LOOKING NW, 6873
 ATHLETIC FIELD, LOOKING N, SHOWING N GOAL, SPECTATOR'S STANDS, TENNIS COURT & RECEIVING SHIP WASHINGTON, 6874
 Athletic field, looking northeast, showing north goal, spectator's stands, tennis courts, 6875
 MONTHLY PROGRESS PHOTO, PICKLING TANKS NEAR LAUNCHING WAYS, LOOKING E, YARD LABOR, 6876
 VESSELS E SIDE WHITNEY BASIN, LOOKING NE FROM W OF DD 1 ENTRANCE, 6877
 MONTHLY PROGRESS PHOTO, PICKLING TANK NEAR LAUNCHING WAYS, LOOKING N, YARD LABOR, 6878
 PHOTO OF PLATE 130, STANDARD BOATS OF THE US NAVY, 1900 ED, 6879
 PHOTO OF FRONTISPIECE, STANDARD BOATS OF THE US NAVY, 1900 ED, 6880
 FLEET TROPHY, 6881
 FLEET TROPHY, 6882
 FLEET TROPHY, 6883
 FLEET TROPHY, 6884
 FLEET TROPHIES, 6885
 FLEET TROPHIES, 6886
 ARGENTINE BATTLESHIP RIVADAVIA, IN DD 4, LOOKING SW, 6888
 ARGENTINE BATTLESHIP RIVADAVIA, IN DD 4, LOOKING SW, 6889
 ARGENTINE BATTLESHIP RIVADAVIA, IN DD 4, LOOKING SW, 6890
 ARGENTINE BATTLESHIP RIVADAVIA, IN DD 4, LOOKING SW, 6891
 ARGENTINE BATTLESHIP RIVADAVIA, IN DD 4, LOOKING N, 6892
 ARGENTINE BATTLESHIP RIVADAVIA, IN DD 4, LOOKING NE, 6893
 ARGENTINE BATTLESHIP RIVADAVIA, JUST ABOUT TO ENTER DD 4, LOOKING N, 6895
 ARGENTINE BATTLESHIP RIVADAVIA, IN WHITNEY BASIN, JUST BEFORE ENTERING DD 4, LOOKING N, 6896
 ARGENTINE BATTLESHIP RIVADAVIA, ENTERING WHITNEY BASIN, ON WAY TO DD 4, LOOKING NW, 6897
 MONTHLY PROGRESS PHOTO, SITE OF TENNIS COURT ON ORDNANCE DOCK, LOOKING E, YARD LABOR, 6898
 MONTHLY PROGRESS PHOTO, PAINTING YARD BLDGS, BLDG 12 (33), LOOKING S, YARD LABOR, 6899
 S SIDE ORDNANCE DOCK, LOOKING E FROM COAL PLANT, 6900
 Monthly progress photo - New tennis court on ordnance dock, looking northeast, 6901
 MONTHLY PROGRESS PHOTO, NEW TENNIS COURTS AT OFFICERS' QUARTERS, LOOKING NE, YARD LABOR, 6902
 OLD ANCHOR EXCAVATED NEAR BLDG 225 (19-3), LOOKING SE, 6904
 OLD ANCHOR EXCAVATED NEAR BLDG 225 (19-3), LOOKING SW, 6905
 OLD ANCHOR EXCAVATED NEAR BLDG 225 (19-3), LOOKING N, 6906
 OLD ANCHOR EXCAVATED NEAR BLDG 225 (19-3), LOOKING NE, 6907
 OLD ANCHOR EXCAVATED NEAR BLDG 225 (19-3), LOOKING NW, 6908
 OLD ANCHOR EXCAVATED NEAR BLDG 225 (19-3), LOOKING SW, 6909
 SHOWS SODA AND ACID APPARATUS ON LEFT & US NAVY FOAM EXTINGUISHER ON RIGHT, 6910
 FOAM FIRE EXTINGUISHER, LIQUIDS USED A AND B, RESULTANT VOLUME C, 6911
 FOAM FIRE EXTINGUISHER, EXTINGUISHER STILL WORKING 1 ¼ MINUTES LATER SHOWING USE OVERHEAD, NOTE ADHERING FOAM, 6912
 FOAM FIRE EXTINGUISHER, 15 SECONDS LATER, FIRE EXTINGUISHED, 6913
 FOAM FIRE EXTINGUISHER, OPERATING ON FUEL OIL AND GASOLINE, FIRE AT START, 6914
 PHOTOGRAPH OF A PHOTOGRAPH, THE OLD PROVOST MANSION, E SIDE CUMBERLAND ST BET PARK AVE AND FLUSHING AVE, BUILT ABOUT 1715, 6915
 PHOTOGRAPH OF A PHOTOGRAPH, THE OLD PROVOST MANSION, E SIDE CUMBERLAND ST BET PARK AVE AND FLUSHING AVE, BUILT ABOUT 1715, 6916
 PHOTOGRAPH OF A PHOTOGRAPH, THE 1ST HOUSE OCCUPIED BY COMMANDANT OF NAVY YARD, NY IN 1801 TO 1806 WHEN PRESENT HOUSE WAS COMPLETED, SITUATED SE CORNER EVANS ST NO 22 CLOSE TO NAVY YARD WALL AND TO THE N AND W OF THE CHIMNEY OF PRESENT (1897) BLDG OF SUPPLIES AND ACCOUNTS, 6918
 THE HALF MOON, 6919
 THE HALF MOON, 6920
 THE HALF MOON, HENRY HUDSON, 6921
 SEAMANS REG HAT, 6922
 WALLABOUT MARKET, 6923
 WALLABOUT MARKET, 6924
 VIEW LOOKING N FROM 2ND ST SHOWING FOUNDATIONS FOR ADDITION TO BLDG 234, SUB-STN 6, CONTACT NOY 4243, 6927
 REMODELLING BLDG 234, SUB-STN 6, ALLOT 7X218-8-5, YARD LABOR, 6928
 REMODELLING BLDG 234, SUB-STN 6, INTERIOR VIEW LOOK NW, ALLOT 7X218-8-5, YARD LABOR, 6929
 REMODELLING BLDG 234, SUB-STN 6, INTERIOR VIEW, ALLOT 7X218-8-5, YARD LABOR, 6930
 REMODELLING BLDG 234, SUB-STN 6, INTERIOR VIEW, ALLOT 7X218-8-5, YARD LABOR, 6931
 REMODELLING BLDG 234, SUB-STN 6, EXTERIOR VIEW, ALLOT 7X218-8-5, YARD LABOR, 6932
 REMODELED BLDG 234, SUB-STN 6, INTERIOR VIEW LOOK NW, ALLOT 7X218-8-5, YARD LABO, 6933
 REMODELED BLDG 234, SUB-STN 6, INTERIOR VIEW LOOK SW, ALLOT 7X218-8-5, YARD LABOR, 6934
 REMODELED BLDG 234, SUB-STN 6, INTERIOR VIEW LOOK SW, ALLOT 7X218-8-5, YARD LABOR, 6935

CONSTRUCTION OF BLDG 234, SUB-STN 6, INTERIOR VIEW, ALLOT 7X218-8-5, YARD LABOR, 6936
CONSTRUCTION OF BLDG 234, SUB-STN 6, FRONT VIEW LOOK NW, ALLOT 7X218-8-5, YARD LABOR, 6937
CONSTRUCTION OF BLDG 234, SUB-STN 6, INTERIOR INSIDE VIEW, ALLOT 7X218-8-8, YARD LABOR, 6938
CONSTRUCTION OF BLDG 234, SUB-STN 6, LOOK NW, ALLOT 7X218-8-8, YARD LABOR, 6939
CONSTRUCTION OF BLDG 234, SUB-STN 6, LOOK NE, ALLOT 7X218-8-8, YARD LABOR, 6940
CONSTRUCTION OF BLDG 234, SUB-STN 6, LOOK NE, ALLOT 7X218-8-8, YARD LABOR, 6941
CONSTRUCTION OF BLDG 234, SUB-STN 6, LOOK SW, ALLOT 7X218-8-8, YARD LABOR, 6942
CONSTRUCTING BLDG 234, SUB-STN 6, LOOKING SW, ALLOT 7X218-8-5, YARD LABOR, 6944
CONSTRUCTION OF BLDG 234, SUB-STN 6, LOOKING N, ALLOT 7X218-8-6, YARD LABOR, 6945
CONSTRUCTION OF BLDG 234, SUB-STN 6, LOOKING NW, ALLOT 7X218-8-6, YARD LABOR, 6946
SUBSTN 6 UNDER CONSTRUCTION, VIEW LOOKING N, ALLOT 7X218-8-6, YARD LABOR, 6947
SUBSTN 6 UNDER CONSTRUCTION, FRONT VIEW LOOKING SW, ALLOT 7X218-8-6, YARD LABOR, 6948
FOUNDATION FLOOR FOR SUBSTN 6, ALLOT 7X218-8-6, YARD LABOR, 6950
FIBRE DUCT & MANHOLE SUBSTN 6, ALLOT 7X218-8-9, YARD LABOR, 6951
FOUNDATION & FLOOR FOR SUBSTN 6, LOOKING W, ALLOT 7X218-8-6, YARD LABOR, 6952
FOUNDATION FOR SUBSTN 6, ALLOT 7X218-8-6, YARD LABOR, 6954
FOUNDATION FORM FOR SUBSTN 6, ALLOT 7X218-8-6, YARD LABOR, 6955
SUBSTN 6, 6956
ALTERATIONS TO SUBSTN 11, VIEW OF INTERIOR, ALLOT 7X218-8-1, YARD LABOR, 6958
ALTERATIONS TO SUBSTN 11, VIEW OF EXTERIOR, ALLOT 7X218-8-1, YARD LABOR, 6959
SUBSTN 11, VIEW OF EXTERIOR, ALLOT 7X218-8-1, YARD LABOR, 6960
SUBSTN 11, 6961
SUBSTN 13, 6962
VIEW SHOWING FLOOR, SUBSTN 12, ALLOT 7X218-8-1, YARD LABOR, 6963
SUBSTN 12, 6964
SUBSTN 12, 6965
REPAIRED ROOF OF CEMENT SHED BLDG 221, DAMAGED BY WIND 10/10/1925, 6966
ALTERATIONS TO BLDG 220 FOR QUARTERS CONSTRUCTION OF PROPOSED STAIRS TO 2ND FL, ALLOT 72201-9, YARD LABOR, 6967
ALTERATIONS TO BLDG 220 FOR QUARTERS, ALLOT 72201-9, YARD LABOR, 6968
ALTERATIONS TO BLDG 220 FOR QUARTERS, ALLOT 72201-9, YARD LABOR, 6969
ELECTRIC DUCTS AND MANHOLES IN BLDG 217, ALLOT 7X218-36-2, YARD LABOR, 6970
ELECTRIC DUCTS AND MANHOLES IN BLDG 217, ALLOT 7X218-36-2, YARD LABOR, 6971
ELECTRIC DUCTS AND MANHOLES IN BLDG 217, ALLOT 7X218-36-2, YARD LABOR, 6972
FIRE ESCAPE ERECTED ON N SIDE OF PRISON, BLDG 215, CONTRACT 479, 6974
FIRE ESCAPE ERECTED ON N SIDE OF PRISON, BLDG 215, CONTRACT 479, 6975
ADDITIONAL LUMBER STORAGE FACILITIES IN BLDG 214, ALLOT 70201-8, YARD LABOR, 6977
ADDITIONAL LUMBER STORAGE FACILITIES IN BLDG 214, ALLOT 70201-8, YARD LABOR, 6978
FORMS FOR LUMBER STORAGE RACKS IN BLDG 214, VIEW LOOKING NW, ALLOT 70218-8, YARD LABOR, 6980
ADDITIONAL LUMBER STORAGE FACILITIES IN BLDG 214, EXCAVATION FOR FOUNDATIONS, ALLOT 70201-8, YARD LABOR, 6981
MOVING PICTURE FILMS, US NAVY MOTION PICTURE EXCHANGE, BLDG 213, 6983
MOVING PICTURE FILMS, US NAVY MOTION PICTURE EXCHANGE, BLDG 213, 6984
REMODELING LATRINE BLDG 212, NEAR PIER C, ALLOT 711201-1, YARD LABOR, 6985
REMODELING LATRINE BLDG 212, NEAR HEAD OF PIER C, ALLOT 711201-1, YARD LABOR, 6986
REMODELING LATRINE BLDG 212, NEAR HEAD OF PIER C, ALLOT 7X218-38-6, YARD LABOR, 6987
REPAIRS TO LATRINE, BLDG 212, INTERIOR GENERAL VIEW, ALLOT 7X218-38-6, YARD LABOR, 6988
REMODELING LATRINE, BLDG 212, NEAR WELDING PLATFORM, ALLOT 7X218-38-6, YARD LABOR, 6989
REMODELING LATRINE, BLDG 212, NEAR WELDING PLATFORM, ALLOT 7X218-38-6, YARD LABOR, 6990
REPAIRS TO LATRINE BLDG 202, DAMAGED BY FIRE 12/11/1928, COMPLETED, ALLOT 79203-2, YARD LABOR, 6991
REPAIRING LATRINE BLDG 202, DAMAGED BY FIRE 12/11/1928, ALLOT 79203-2, YARD LABOR, 6992
MANUFACTURE & INSTALLATION OF NEW BOOM ON DD CRANE NO 22, ALLOT 7X0003, YARD LABOR, 6993
E SIDE OF LATRINE BLDG 202, DAMAGED BY FIRE, 6994
N END OF LATRINE BLDG 202, DAMAGED BY FIRE, 6995
VIEW OF W SIDE OF LATRINE BLDG 202, DAMAGED BY FIRE, 6996
INSIDE VIEW OF LATRINE BLDG 202, CREWS SECTION DAMAGED BY FIRE, 6997
INSIDE VIEW OF LATRINE BLDG 202, DAMAGED BY FIRE, 6998
NEW LABOR BOARD BLDG, NEW ADDITION TO BLDG 200 AT SAND ST ENTRANCE, 6999
REPAIRING AND PAINTING DD CRANE NO 199, ALLOT, 77201-1, YARD LABOR, 7000
REPAIRING DD CRANE NO 199, ALLOT, 77201-1, YARD LABOR, 7001
REPAIRS TO DD CRANE NO 199, ALLOT, 76201-16, YARD LABOR, 7002
REPAIRS TO DD CRANE NO 199, ALLOT, 76201-16, YARD LABOR, 7003
REPAIRS TO DD CRANE NO 199, ALLOT, 76201-16, YARD LABOR, 7004
REPAIRS TO DD CRANE NO 199, ALLOT, 76201-10, YARD LABOR, 7006
REPAIRS TO DD CRANE NO 199, ALLOT, 76201-2, YARD LABOR, 7007

REPAIRING DD CRANE NO 198, ALLOT, 77201-1, YARD LABOR, 7008
REPAIRS TO DD CRANE NO 198, ALLOT, 75201-28, YARD LABOR, 7009
REPAIRS TO DD CRANE NO 198, ALLOT, 73201-15, YARD LABOR, 7010
REPAIRS TO DD CRANE NO 198, ALLOT, 73201-15, YARD LABOR, 7011
REPAIRS TO DD CRANE NO 198, ALLOT 72201-10, YARD LABOR, 7012
TESTING CRANE NO 198 AFTER REPAIRS, ALLOT 79201-9, YARD LABOR, 7013
REPAIRS TO DD CRANE NO 198, ALLOT 79201-9, YARD LABOR, 7014
REPAIRS TO DD CRANE NO 197, ALLOT 73201-15, YARD LABOR, 7015
REPAIRS TO DD CRANE NO 197, ALLOT 70201-2, YARD LABOR, 7016
REPAIRS TO DD CRANE NO 197, ALLOT 70201-2A, YARD LABOR, 7017
REPAIRS TO DD CRANE NO 195, ALLOT 73201-15, YARD LABOR, 7018
REPAIRS TO DD CRANE NO 195, ALLOT 201-11, YARD LABOR, 7019
REPAIRS TO DD CRANE NO 195, ALLOT 201-11, YARD LABOR, 7020
REPAIRS TO DD CRANE NO 195, ALLOT 201-11, YARD LABOR, 7021
REPAIRS TO DD CRANE NO 195, ALLOT 201-11, YARD LABOR, 7022
REPAIRS TO DD CRANE NO 195, ALLOT 201-11, YARD LABOR, 7023
EXPOSED GEAR ON DD CRANE NO 195, 7024
REPAIRING ROOF OF BLDG 189, ALLOT, 7X218-23-1, 7025
REPAIRS TO ROOF OF BLDG 189, ALLOT, 7X218-23-1, 7026
REPAIRING DD CRANE 179, ALLOT, YARD LABOR, 7027
RECONSTRUCTION OF RR TRACK ON 5TH ST BET MORRIS AVE AND DD2, LOOKING NW FROM DD END, 7028
OIL PUMP HOUSE, BLDG 158, GENERAL VIEW LOOKING N FROM 5TH ST, CONTRACT NOY 4243, 7029
OIL PUMP HOUSE, BLDG 158, VIEW LOOKING NW FROM 6TH ST, SHOWING THE BLDG AND PIPE TRENCH CARRYING
STEAM & OIL PIPES TO BLDG 128, CONTRACT NOY 4243, 7030
IMPROVEMENT TO PIER G OUTBOARD END LOOKING SW SHOWING CLAMPS AND PART OF TENONS, CONTRACT NOY
366, 7031
CHEMICAL LABORATORY BLDG 152, MATERIALS (STONE) FOR FUME HOOD, CONTRACT NOY 2533, 7032
CHEMICAL LABORATORY BLDG 152, PIPE STAND MATERIALS, CONTRACT NOY 2533, 7033
CHEMICAL LABORATORY BLDG 152, DOUBLE FUME HOOD ANGLE FRAME, CONTRACT NOY 2533, 7034
CHEMICAL LABORATORY BLDG 152, PLACING CASEWORK REINSTALLED WALL TABLE, CONTRACT NOY 2533, 7035
BLDG 150, FIRE OF 02/09/1927, 7036
BLDG 150, FIRE OF 02/09/1927, 7037
BLDG 150, FIRE OF 02/09/1927, 7038
BLDG 150, FIRE OF 02/09/1927, 7039
BLDG 150, FIRE OF 02/09/1927, 7040
BLDG 495, FIRE OF 02/09/1927, 7041
BLDG 150, FIRE OF 02/09/1927, 7042
BLDG 150, SHOWING THE SETTLEMENT OF FLOOR, 7043
BLDG 150, SHOWING THE SETTLEMENT OF FLOOR, 7044
BLDG 150, FIRE OF 02/09/1927, 7045
BLDG 150, FIRE OF 02/09/1927, 7046
BLDG 150, SHOWING SETTLEMENT OF FLOOR, 7047
PAINTING WINDOW SASH AND DOORS OF BLDG 132, ALLOT 7.03/5640.1-51-1, YARD LABOR, 7048
REPAIRS TO ROOF & CORNICE BLDG 132, ALLOT, 7X218-23-1, YARD LABOR, 7049
REPAIRS TO ROOF & CORNICE BLDG 132, ALLOT, 7X218-23-1, YARD LABOR, 7050
NAVY YARD TRAILER, 7051
GASOLINE STORAGE IN VICINITY OF YARDMASTER'S OFFICE INSTALLED BY YARD LABOR, 7052
GASOLINE STORAGE IN VICINITY OF YARDMASTER'S OFFICE INSTALLED BY YARD LABOR, 7053
INSTALLATION OF NEW ELEVATOR IN BLDG 131, VIEW IN PENTHOUSE, CONTRACT NOY 2870, SHAFT CONSTRUCTION
BY YARD LABOR, ALLOT 79201-9, 7054
INSTALLATION OF NEW ELEVATOR IN BLDG 131, VIEW OF INTERIOR OF ELEVATOR, CONTRACT NOY 2879, SHAFT
CONSTRUCTION BY YARD LABOR, ALLOT 79201-9, 7055
INSTALLATION OF NEW ELEVATOR IN BLDG 131, VIEW OF NEW FIRE PROOF DOORS, CONTRACT NOY 2870, SHAFT
CONSTRUCTION BY YARD LABOR, ALLOT 79201-9, 7056
INSTALLATION OF NEW FREIGHT ELEVATOR IN BLDG 131, VIEW IN PENTHOUSE, ELEVATOR CONSTRUCTION
CONTRACT NOY 2870, SHAFT CONSTRUCTION BY YARD LABOR, ALLOT 79201-9, 7057
REPAIRS TO DOORS BLDG 131, YARD LABOR, 7061
REPAIRS TO ROOF BLDG 131, ALLOT, 79201-2, YARD LABOR, 7062
REPAIRS TO ROOF BLDG 131, ALLOT, 79201-2, YARD LABOR, 7063
REPAIRS TO ROOF BLDG 131, ALLOT, 79201-2, YARD LABOR, 7064
REPAIRS TO ROOF BLDG 131, ALLOT, 79201-2, YARD LABOR, 7065
REPAIRS TO ROOF BLDG 131, ALLOT, 79201-2, YARD LABOR, 7066
ROOF REPAIRS BLDG 131, ALLOT, 79201-2, YARD LABOR, 7067
GEAR STORAGE BINS INSTALLED ON 2ND FL E END OF BLDG 131, YARD LABOR, 7068
YACHT CANNON WITH MOUNT COMPLETE FROM YACHT MOMA 1917, 7069

BLDG 130, 7070
 VIEW OF 2ND FL, BLDG 130 LOOK W, 7071
 REPAIRS TO ROOF OF BLDG 130, PATTERN SHOP, VIEW FROM ROOF OF BLDG 27, YARD LABOR, ALLOT 7201-6, 7072
 VIEW OF 1ST FL BLDG 130 LOOK E, 7073
 REPAIRS TO ROOF OF BLDG 130 PATTERN SHOP, VIEW FROM ROOF OF BLDG 27, YARD LABOR, ALLOT 7201-6, 7074
 VIEW OF 1ST FL BLDG 130, LOOK W, 7075
 REPAIRS TO ROOF OF BLDG 130, PATTERN SHOP, VIEW FROM ROOF OF BLDG 27, YARD LABOR, ALLOT 7201-6, 7076
 VIEW OF 1ST FL BLDG 130, LOOKING NW, 7077
 FOUNDATION FOR BORING AND MILLING MACHINE BLDG 128, RNV (C&M), ALLOT 7X131H, YARD LABOR, 7078
 VIEW LOOKING SOUTH SHOWING EXTENSION NO2 TO BLDG 128, CONTRACT NOY 4243, 7079
 VIEW LOOKING NW SHOWING START OF BRICKWORK ON EXTENSION NO2, BLDG 128, CONTRACT NOY 4243, 7080
 60" DOUBLE HOUSING PLANER FOUNDATION, BLDG 128, RNV (C&M), ALLOT 7X131H381/X316-575, YARD LABOR, 7081
 IMPROVEMENT OF ELECTRIC POWER FACILITIES SUB-STN NO 9, BLDG 128, RNV (C&M) 17X0603, YARD LABOR, 7082
 LOCATION INSIDE BLDG 128 FROM WHICH OIL TANKS WERE REMOVED AND REUSED OUTSIDE NEW OIL PUMP HOUSE
 ON 5TH ST, CONTRACT NOY 4243, 7084
 LOOKING NW FROM 6TH ST SHOWING EXTENSION NO1 TO BLDG 128, CONTRACT 4243, 7085
 RNV (C&M), VIEW SHOWING CONCRETE IN PLACE FOR FOUNDATION OF 11'6" PLANER IN MACHINE SHOP, BLDG 128,
 ALLOT SAO, YARD LABOR, 7086
 RNV (C&M), 11'6" PLANER FOUNDATION, BLDG 128, VIEW OF EXCAVATION AND PILES, ALLOT SAO, YARD LABOR, 7087
 CHANGING CURRENT ON MEZZANINE FLOOR, OF BLDG 128, ALLOT 7X218-36-2, YARD LABOR, 7089
 FOUNDATION FOR 48 FT ENGINE LATHE IN MACHINE SHOP, BLDG 128, YARD LABOR, 7090
 FOUNDATION FOR 48 FT ENGINE LATHE IN MACHINE SHOP, BLDG 128, LOOKING N, YARD LABOR, 7091
 NEW FOUNDATION FOR BLANCHARD GRINDER, BLDG 128, YARD LABOR, 7092
 NEW FOUNDATION FOR NEW BLANCHARD GRINDER, BLDG 128, APPROPRIATION C AND R 1939, YARD LABOR, 7093
 NEW TEST BOILER IN BLDG 128 FOUNDATION ROOF MODIFICATION AND CHANGES IN HEATING DUCT BY YARD LABOR,
 APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M, BOILER CONSTRUCTION BY CONTRACT 57897, 7094
 STACK FOR NEW TEST BOILER IN BLDG 128 FOUNDATION ROOF MODIFICATION AND CHANGES IN HEATING DUCT BY
 YARD LABOR, APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M, BOILER CONSTRUCTION BY CONTRACT 57897
 (COMPLETED), 7095
 STACK FOR NEW TEST BOILER IN BLDG 128 FOUNDATION ROOF MODIFICATION AND CHANGES IN HEATING DUCT BY
 YARD LABOR, APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M, BOILER CONSTRUCTION BY CONTRACT 57897,
 7096
 NEW TEST BOILER IN BLDG 128 FOUNDATION ROOF MODIFICATION AND CHANGES IN HEATING DUCT BY YARD LABOR,
 APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M, BOILER CONSTRUCTION BY CONTRACT 57897, 7097
 NEW TEST BOILER IN BLDG 128 FOUNDATION ROOF MODIFICATION AND CHANGES IN HEATING DUCT BY YARD LABOR,
 APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M, BOILER CONSTRUCTION BY CONTRACT 57897, 7098
 NEW TEST BOILER IN BLDG 128 FOUNDATION ROOF MODIFICATION AND CHANGES IN HEATING DUCT BY YARD LABOR,
 APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M, BOILER CONSTRUCTION BY CONTRACT 57897, 7099
 NEW TEST BOILER IN BLDG 128 FOUNDATION ROOF MODIFICATION AND CHANGES IN HEATING DUCT BY YARD LABOR,
 APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M, BOILER CONSTRUCTION BY CONTRACT 57897, 7100
 VERTICAL BORING MACHINE IN BLDG 128, WORK COMPLETED, PRODUCTION DIVISION, 7101
 NEW TEST BOILER IN BLDG 128 FOUNDATION ROOF MODIFICATIONS AND CHANGES IN HEATING DUCT BY YARD
 LABOR APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M, BOILER CONSTRUCTION BY CONTRACT 57897, 7102
 ENLARGING DOOR ON BLDG 128 N END FOR ROLLER TRACK, ALLOT 7X127-4-10, YARD LABOR, 7103
 NEW TEST BOILER BLDG 128, FOUNDATION, ROOF MODIFICATIONS AND CHANGES IN HEATING DUCT BY YARD LABOR,
 APPN 7X127 REPLACEMENT NACAL VESSELS C AND M, BOILER CONSTRUCTION BY CONTRACT 57897, 7104
 FOUNDATION HORIZONTAL BORING MACHINE IN BLDG 128 FOR PRODUCTION DIVISION, YARD LABOR, 7105
 FOUNDATION AND SUPPORT FOR TEST BOILER BLDG 128 FOR PRODUCTION DIVISION, YARD LABOR, 7106
 ENLARGING DOOR OF BLDG 128, N END FOR ROLLER TRACK ALLOT, 7X127-4-10, YARD LABOR, 7107
 ENLARGING DOORWAY AT N END OF MACHINE SHOP, BLDG 128 FOR ROLLER TRACK, ALLOT, 7X127, YARD LABOR,
 7108
 LIMITED STRAIN DEVICE FOR STANDARD WRENCH, 7109
 PAINTING INTERIOR OF BLDG 128, ALLOT 7.03/5640.1-51-1, YARD LABOR, 7110
 PAINTING INTERIOR OF MACHINE SHOP BLDG 128, ALLOT 7.03/5640.1-51-1, YARD LABOR, 7111
 PAINTING INTERIOR OF MACHINE SHOP BLDG 128, ALLOT 7.03/5640.1-51-1, YARD LABOR, 7112
 PAINTING BLDG 128, ALLOT 7.03/5640.1-51-1, YARD LABOR, 7113
 PAINTING COVERED COURT OF BLDG 128, BY CWA PAINTERS, 7114
 F128C390_PAINTING BLDG 128, ALLOT, 7.03/5640.1-51-1, YARD LABOR_01/30/1934_GRID J06/07/08, K06/07_BOX 15, 7115
 PAINTING INTERIOR OF MACHINE SHOP, BLDG 128, ALLOT, 7.03/5640.1-51-1, YARD LABOR, 7116
 PAINTING INTERIOR OF MACHINE SHOP, BLDG 128, ALLOT, 7.03/5640.1-51-1, YARD LABOR, 7117
 PAINTING INTERIOR OF MACHINE SHOP, BLDG 128, ALLOT, 7.03/5640.1-51-1, YARD LABOR, 7118
 PAINTING INTERIOR OF MACHINE SHOP, BLDG 128, ALLOT, 7.03/5640.1-51-1, YARD LABOR, 7119
 PAINTING INTERIOR OF MACHINE SHOP, BLDG 128, ALLOT, 7.03/5640.1-51-1, YARD LABOR, 7120
 REPAIRING FLOOR IN BLDG 128, ALLOT, 7.03/5640.1-51-1, YARD LABOR, 7121
 PAINTING INTERIOR OF MACHINE SHOP BLDG 128, ALLOT, 74201-7, YARD LABOR, 7123

PAINTING INTERIOR OF MACHINE SHOP BLDG 128, ALLOT, 74201-7, YARD LABOR, 7124
PAINTING INTERIOR OF MACHINE SHOP BLDG 128, ALLOT, 74201-7, YARD LABOR, 7125
PAINTING METAL WORK OF MACHINE SHOP BLDG 128, ALLOT, 73201-7, YARD LABOR, 7126
NAVY YARD, NY, 7127
NAVY YARD, NY, 7128
REPAIRS TO EXTERIOR OF BLDG 128 ALLOT 73210-7, YARD LABOR, 7129
REPAIRS TO EXTERIOR METALWORK OF BLDG 128 ALLOT 73210-7, YARD LABOR, 7130
REPAIRS TO CORNICE, GUTTERS AND ETC OF BLDG 128, VIEW ON 6TH ST, ALLOT 73201-7, YARD LABOR, 7131
REPAIRS TO CORNICE, GUTTERS AND ETC OF BLDG 128, VIEW IN COURTYARD, ALLOT 73201-7, YARD LABOR, 7132
REPAIRS TO CORNICE, GUTTERS AND ETC, MORRIS AVE, SIDE OF BLDG 128, ALLOT 73201-7, YARD LABOR, 7133
REPAIRS TO CORNICE, GUTTERS AND ETC, 6TH ST SIDE, BLDG 128, ALLOT 73201-7, YARD LABOR, 7134
REPAIRS TO CORNICE, GUTTERS AND ETC, MORRIS AVE, BLDG 128, ALLOT 73201-7, YARD LABOR, 7135
REPAIRS TO ROOF OF BLDG 128, ALLOT 72201-20, YARD LABOR, 7136
REPAIRS TO CORNICE AND GUTTERS OF BLDG 128, ALLOT 73201-7, YARD LABOR, 7137
REPAIRS TO CORNICE AND GUTTERS OF BLDG 128, ALLOT 73201-7, YARD LABOR, 7138
REPAIRS TO ROOF, BLDG 128, ALLOT 72201-20, YARD LABOR, 7139
REPAIRING CORNICE, GUTTERS AND ETC ON BLDG 128, VIEW ON 6TH ST SIDE, ALLOT 73201-7, YARD LABOR, 7140
REPAIRS TO CORNICE, GUTTERS AND ETC ON BLDG 128, VIEW ON 6TH ST SIDE, ALLOT 73201-7, YARD LABOR, 7141
REPAIRS TO CORNICE, GUTTERS AND ETC ON BLDG 128, VIEW ON 6TH ST SIDE, ALLOT 73201-7, YARD LABOR, 7142
REPAIRS TO CORNICE, GUTTERS AND ETC ON BLDG 128, VIEW OF DOOR ON MORRIS AVE SIDE, ALLOT 73201-7, YARD LABOR, 7143
REPAIRS TO ROOF OF BLDG 128, ALLOT 72201-20, YARD LABOR, 7145
REPAIRS TO ROOF OF BLDG 128, ALLOT 72201-20, YARD LABOR, 7146
REPAIRS TO ROOF OF BLDG 128, ALLOT 72201-20, YARD LABOR, 7147
REPAIRS TO ROOF OF BLDG 128, ALLOT 72201-20, YARD LABOR, 7148
REPAIRS TO FLOOR IN BLDG 128, SW SIDE, COMPLETED, ALLOT 72201-31, YARD LABOR, 7149
REPAIRS TO FLOOR SW SIDE OF BLDG 128, ALLOT 72201-31, YARD LABOR, 7150
REPAIRS TO FLOOR SW SIDE OF BLDG 128, ALLOT 72201-31, YARD LABOR, 7151
REPAIRS TO ROOF OF BLDG 128, ALLOT 72201-20, YARD LABOR, 7152
NAVY YARD, NY, OUTBOARD, 7153
NAVY YARD, NY, INBOARD, 7154
SHOWING CONDITION OF SHEET METAL WORK, BLDG 128, VIEW ON MORRIS AVE, 7155
SHOWING CONDITION OF SHEET METAL WORK, BLDG 128, VIEW ON 6TH ST, 7156
REWIRING BLDG 128 FOR 3 PHASE 60 CYCLE 220V NEW 3-150 KVA TRANSFORMERS WITH TEMPORARY CONNECTIONS ALLOT, 72201-4, YARD LABOR, 7157
REPAIRS TO ROOF BLDG 128, YARD LABOR, 7158
USS DOLPHIN V7, MAIN ENGINE LH, 7159
MACHINE SHOP, 7160
USS DOLPHIN, STARBOARD MAIN ENGINE 6-A-20 7/8-R 1750 BHP AT 380 RPM, READY FOR SHIPMENT, 7161
USS DOLPHIN, STARBOARD MAIN ENGINE 6-A-20 7/8-R 1750 BHP AT 380 RPM, READY FOR SHIPMENT, 7162
USS DOLPHIN, STARBOARD MAIN ENGINE 6-A-20 7/8-R 1750 BHP AT 380 RPM, READY FOR SHIPMENT, 7163
USS DOLPHIN, STARBOARD MAIN ENGINE 6-A-20 7/8-R 1750 BHP AT 380 RPM, READY FOR SHIPMENT, 7164
MACHINERY DIVISION, LEAD COATING INVESTIGATION, 42 DAYS, CORROSION TEST, 7166
USS DOLPHIN, V-7, LH GEN ENG, 7167
USS DOLPHIN, V-7, LH GEN ENG, 7168
F128C208_VIEW SHOWING SKYLIGHT PROPPED UP, BLDG 128_03/11/1931_GRID J06/07/08, K06/07_BOX 15, 7169
TOOL ROOM, BLDG 128, 7170
4TH GENERATOR ENGINE V-5-6 RH IN THE COURSE OF ERECTING, BLDG 128, 7171
TOOL ROOM, WOODRUFF KEYWAY CUTTERS, BLDG 128, 7172
PORT V-6 MAIN ENGINE ON TEST STAND IN THE COURSE OF ERECTING, PROVISION IS MADE TO RUN THIS LAST ENGINE HOOK UP TO MAIN MOTOR & ALSO TO EXPERIMENTAL ASYNCHRONIZER SHAFTING, 7173
TOOL ROOM BLDG 128, 7174
3RD GENERATOR ENGINE V-5-6 RH BEING FAST TRIALED AFTER FINISHED SHOP TEST, 7175
TOOL ROOM BLDG 128, 7176
STB V5 MAIN ENGINE FAST TRIALED READY FOR CRATING & SHIPMENT NOTE 3 LIFTING PADS AT TOP OF ENGINE FOR HANDLING PURPOSE, 7177
TOOL ROOM BLDG 128, 7178
TOOL ROOM BLDG 128, CLASS X GROUND TAPS NATIONAL FINE THREAD SERIES, 7179
TOOL ROOM BLDG 128, CLASS X GROUND TAPS NATIONAL FINE THREAD SERIES, 7180
PIPE, 7181
PIPE, 7182
EQUIPMENT, 7183
EQUIPMENT, 7184
TOOL ROOM, BLDG 128, 7185
BLDG 128, 7186

SET UP FOR TESTING BY HYDROSTATIALLY TO DISTRUCTION IN TENTION ON 'S' TYPE WORKING CYLINDER REBORED AND FITTED WITH SKIN LINER (REF, BU, LETTER) SS155/S41 (10-740) 10/9/29, 7187
SET UP OF FIG 1 AFTER FAILURE AT 3400 INTERN PRESSURE EQUIVALENT TO R TOTAL LOAD OF 486.673, 7188
'FIG 3' VIEW OF FRACTURE, 7189
PLAN VIEW, 7190
ELEVATION VIEW, 7191
SUB V6 ENG ASYNCHRONIZER FOR TWISTING TESTS, 7192
SUB V6 PORT ENG ASYNCHRONIZER RIG FOR TWISTING TESTS, 7193
EQUIPMENT, 7194
EQUIPMENT, 7195
SANDER VIBRATION DE-ENERGIZER MOUNTED ON CAMSHAFT OF V6 PORT ENGINE, 7196
CLOSE UP VIEW OF BROKEN TOOTH IN CAMSHAFT GEAR, 7197
CHAIN DRIVEN ATTACHED CIRCULATING WATER PUMPS AS SETUP ON V6 PORT ENGINE, 7198
LINER UNDER WATER SOUND APPARATUS PLAN "6800 AD" DEVICE FOR REPRODUCING WARPED SURFACE TO CONFORM TO SHELL OF SHIP, 7199
UPPER VERTICAL SHAFT GEAR (MINUS HUB) SHOWING NATURE OF FRACTURE OF RIM AND WEBB, 7200
CAM SHAFT GEAR SHOWING BROKEN TOOTH, 7201
DIESEL ENGINE INDICATOR BEING USED TO RECORD SPRING VIBRATIONS, 7202
UPPER VERTICAL SHAFT GEAR UPON REMOVAL OF CASING, 7203
APPEARANCE OF GEARS ON REMOVAL OF CRANK CASE (PORT ENGINE V5), 7204
DIESEL ENGINE INDICATOR BEING USED TO RECORD SPRING VIBRATIONS, 7205
EQUIPMENT, 7206
HUB OF VERTICAL SHAFT GEAR, 7207
OVERSPEED GOVERNOR AS INSTALLED ON V6 RH GENERATOR ENGINE, 7208
OVERSPEED GOVERNOR AS INSTALLED ON V6 RH GENERATOR ENGINE, 7209
OVERSPEED GOVERNOR AS INSTALLED ON V6 RH GENERATOR ENGINE, 7210
V5&6 INDEPENDENT AIR WATER & LUB OIL PUMP TEST, 7211
TO ACCOMPANY REPORT ON ROOF, COVERING FEB 1927, 7212
REPAIRS TO ROOF OF BLDG 128, LOOKING AT SW EXTREMITY, YARD LABOR, ALLOT 76201-37, 7213
ALTERATIONS TO LEAN-TO AT BLDG 128 FOR BABBIT SHOP, YARD LABOR, ALLOT 6201-12, 7214
ALTERATIONS TO LEAN-TO AT BLDG 128 FOR BABBIT SHOP, YARD LABOR, ALLOT 6201-12, 7215
CONCRETE FLOOR IN LEAN-TO OF BLDG 128, ALLOT 6201-12, 7216
BLDG 128, REPAIRING SLATE BROKEN BY SKYLIGHT, WORK UNDER CONTRACT 4857, 7217
BLDG 128, REPAIRING SLATE BROKEN BY SKYLIGHT, WORK UNDER CONTRACT 4857, 7218
6TH ST SIDE OF BLDG 128, LOOKING NW FROM 3RD FL OF BLDG 5, AFTER GLAZING, 7220
6TH ST SIDE OF BLDG 128, LOOKING NW FROM 3RD FL OF BLDG 5, AFTER GLAZING, 7221
6TH ST SIDE OF BLDG 128, LOOKING W FROM 5TH FL OF BLDG 5, AFTER GLAZING, 7222
ROOF OF BLDG 28 LOOKING NW FROM COURTYARD, ROOF BLDG 128, AFTER GLAZING, 7223
BLDG 28 LOOKING NW FROM ROOF OF COURTYARD BLDG 128, AFTER GLAZING, 7224
6TH ST SIDE OF BLDG 128 LOOKING NE FROM WINDOW IN BLDG 27, AFTER GLAZING, 7225
BLDG 28 LOOKING NE FROM COURTYARD ROOF OF BLDG 128, BEFORE STARTING WORK ON THIS AREA, 7226
LOOKING SW ALONG LOWER EAVE OF ERECTING WING BLDG 128, COURTYARD SIDE AFTER GLAZING, 7227
BLDG 28, LOOKING NW FROM ROOF OF COURTYARD BLDG 128, BEFORE STARTING WORK ON THIS AREA, 7228
6TH ST SIDE OF BLDG 128 LOOKING NW FROM BLDG 27, GOVT EMPLOYEES REPLACING SLATE, AFTER GLAZING BY CONTRACTORS, 7229
BLDG 128 ERECTING WING LOOKING S FROM COURTYARD ROOF OF BLDG 128 AFTER GLAZING, 7230
BLDG 128 LOOKING NE FROM ROOF OF COURTYARD BLDG 128, BEFORE STARTING WORK ON THIS AREA, 7231
LOWER LEVEL ROOF OF BLDG 128 ERECTING WING LOOKING NE ALONG EAVE, COURTYARD SIDE AFTER GLAZING, 7232
CONT 4672, NEW LATRINE BEING ERECTED IN BLDG 128, PIPING INSTALLED BY YARD LABOR, 7234
CONT 4672, NEW LATRINE BLDG 128, PIPING INSTALLED BY YARD LABOR, 7235
LOWER LEVEL COURTYARD SIDE BLDG 128 (ERECTING WING) LOOKING SW ALONG EAVE AFTER GLAZING, 7236
6TH ST SIDE OF BLDG 128 LOOKING W FROM 5TH FL BLDG 5 AFTER GLAZING, 7238
BLDG 126 (17), 7256
BLDG 125, PUMPING PLANT DDS 2 & 3, 7257
BLDG 126, 7258
BLDG 126, 7259
PUMPWELL 125, BET DDS 2&3, LOOKING E, 7260
PUMPWELL 125, BET DDS 2&3, LOOKING W, 7261
PUMPWELL 125, BET DDS 2&3, LOOKING NW, 7262
BLDG 125 FROM STAIRWAY, 7263
BLDG 125 BACK OF MOTOR, 7264
BLDG 125 MOTOR, 7265
TOP OF PUMPING PLANT DDS 2&3, 7266
DDS 2&3, PUMPING PLANT, 7267

PUMPING PLANT DRY DOCKS 2 & 3, 7268
DDS 2&3, PUMPING PLANT, 7269
PUMPING PLANT, DD 1, 7270
PUMPING PLANT, DD 1, 7271
PUMPING PLANT, DD 1, 7272
PUMPING PLANT, DD 1, 7273
PUMPING PLANT DRY DOCK 1, 7275
BLDG 123, COPPER SHOP, LOWER FL, SHOWING IMPROVED CONDITIONS, 7277
BLDG 123, SHOWING IMPROVED SPACE AND WORKING CONDITIONS IN COPPER SHOP, 2ND FL, 7278
CONSTRUCT A FENCE OF 1 1/2" PIPING & WIRE MESH ON THE NW SIDE OF BLDG 123 FOR STORAGE OF COPPER TUBIN
AS SHOWN ON SKETCH 11G23/X534, 7279
BLDG 123, INTERIOR VIEW OF RECONSTRUCTION FOR COPPERSMITH, 7280
INTERIOR BLDG 123, CHANGES FOR COPPERSMITH, 7281
EXTERIOR BLDG 123, CHANGES LOOKING SE, 7282
BLDG 123, REBUILDING OF INTERIORS FOR COPPERSMITHS, LOOKING NE, 7283
BLDG 123, REMOVAL OF BOILERS FROM MONTHLY PROG PHOTO, CONT, THE BABCOX AND WILCOX CO
CONTRACTORS, LOOKING NE, 7284
BLDG 123, REMOVAL OF BOILERS TO BLDG 41, FROM MONTHLY PROG PHOTO, CONT, THE BABCOX AND WILCOX CO
CONTRACTORS, LOOKING NE, 7285
BLDG 123, INTERIOR LOOKING NE, 7286
BLDG 123, EXTERIOR VIEW, 7287
BLDG 123, EXTERIOR VIEW, 7288
BLDG 123, EXTERIOR VIEW, 7289
BLDG 122 ON NEW SITE (DISPENSARY), 7290
BLDG 122 DISPENSARY MOVED TO NEW SITE, LOOKING N, 7291
MOVING BLDG 122 DISPENSARY TO NEW SITE LOOKING N, DEGNON CONT CO CONTRACTOR, 7292
BLDG 122, DISPENSARY, MOVING TO NEW SITE. NEW SITE IN FOREGROUND, LOOKING NW, 7293
BLDG 122, DISPENSARY, MOVING TO NEW SITE, LOOKING S IN 2ND ST, DEGNON CONTRACTING CO, CONTRACTOR,
7294
BLDG 122, DISPENSARY, IN 2ND ST, MOVING TO NEW SITE, LOOKING N, DEGNON CONTRACTING CO, CONTRACTOR,
7295
BLDG 122, DISPENSARY, MOVING TO NEW SITE, SHOWING BLOCKING ROLLS, ETC, LOOKING NE, DEGNON
CONTRACTING CO, CONTRACTOR, 7296
BLDG 122, DISPENSARY, MOVING TO NEW SITE, GENERAL VIEW IN 2ND ST, LOOKING N, DEGNON CONTRACTING CO,
CONTRACTOR, 7297
BLDG 122, DISPENSARY, BLDG 122, LOADED PREPARATORY TO MOVING, DETAILS OF BLOCKING & ROLLERS, LOOKING
W, DEGNON CONTRACTING CO, CONTRACTOR, 7298
BLDG 122, DISPENSARY, LOADED PREPARATORY TO MOVING TO NEW SITE, LOOKING E, DEGNON CONTRACTING CO,
CONTRACTOR, 7299
BLDG 122, YARD DISPENSARY, LOADED PREPARATORY TO MOVING TO NEW SITE, LOOKING NE, DEGNON
CONTRACTING CO, CONTRACTOR, 7300
BLDG 122, YARD DISPENSARY, LOADED PREPARATORY TO MOVING TO NEW SITE, LOOKING W, DEGNON
CONTRACTING CO, CONTRACTOR, 7301
BLDG 122, YARD DISPENSARY, CONSTRUCTION OF NEW FOUNDATION, LOOKING NW, YARD LABOR, 7302
BLDG 122, YARD DISPENSARY, PREPARATORY TO MOVING, LOOKING SE, DEGNON CONTRACTING CO, CONTRACTOR,
7303
BLDG 122, YARD DISPENSARY, PREPARATORY TO MOVING, LOOKING N, DEGNON CONTRACTING CO, CONTRACTOR,
7304
NEW LOCATION FOR BLDG 122, YARD DISPENSARY, LOOKING NW, YARD LABOR, 7305
MONTHLY PROGRESS PHOTO, DISPENSARY BLDG 122, CLOTHESLINE ENCLOSURE LOOKING SE, YARD LABOR, 7306
MONTHLY PROGRESS PHOTO, DISPENSARY BLDG 122, INTERIOR LOOKING S, YARD LABOR, 7307
MONTHLY PROGRESS PHOTO, ADDITION TO DISPENSARY BLDG 122, LOOKING S, YARD LABOR, 7308
MONTHLY PROGRESS PHOTO, ADDITION TO DISPENSARY BLDG 122, YARD LABOR, 7309
MONTHLY PROGRESS PHOTO, DISPENSARY BLDG 122, LOOKING S, YARD LABOR, 7310
MONTHLY PROGRESS PHOTO, DISPENSARY BLDG 122, ADDITION, 7311
MONTHLY PROGRESS PHOTO, YARD LABOR, FOUNDATION PILES, ADDITION TO DISPENSARY BLDG 122, LOOKING N,
7312
BLDG 122, 7313
BLDG 122, INTERIOR, 7314
BLDG 122, INTERIOR, 7315
BLDG 122, INTERIOR, 7316
BLDG 122, EXTERIOR, 7317
VIEW OF PAY CAR TRAILER, 7319
VIEW OF PAY CAR TRAILER, 7320
VIEW OF PAY CAR TRAILER, 7321

MOVING BLDG 121 TO NEW SITE LOOKING N, 7322
SETTING BLDG 121, PAYMASTER'S ON FOUNDATION AT NEW SITE, 7323
MOVING BLDG 121 TO NEW SITE IN FOREGROUND LOOKING E, 7326
BLDG 121, PAYMASTER, MOVE TO NEW SITE LOOKING E, 7327
BLDG 121, PAYMASTER, MOVE TO NEW SITE LOOKING N, 7328
BLDG 121, PAYMASTER, MOVE TO NEW SITE LOOKING N, 7329
BLDG 121, MOVED TO NEW SITE, 7330
BLDG 121, PREPARATORY TO MOVING TO NEW SITE LOOKING NE, 7331
NEW SITE OF BLDG 121, LOOKING S, 7332
BLDG 121, PREPARATORY TO MOVING TO NEW SITE, 7333
NEW SITE OF BLDG 121, PAY OFFICE LOOKING S, YARD LABOR, 7334
PAY OFFICE PREPARATORY TO MOVING, LOOKING NW, DEGNON CONT CO CONTRACTOR, 7335
BLDG 121, PAYMASTER'S OFFICE CONSTRUCTION OF NEW FOUNDATION, LOOKING E, YARD LABOR, 7336
BLDG 121, PAYMASTER'S OFFICE PREPARATORY TO MOVING, LOOKING SW, DEGNON CONT CO CONTRACTOR, 7337
SITE FOR RELOCATION OF BLDG 121, PAYMASTER'S OFFICE, LOOKING S, YARD LABOR, 7339
SITE FOR RELOCATION FOR BLDG 121, PAYMASTER'S OFFICE, LOOKING W, 7340
BLDG 121, 7341
BLDG 121, 7342
BLDG 120, CONT 4347, NEW ROOF, OIL STOREHOUSE, 7343
BLDG 120, CONT 4347, REPAIRS TO ROOF OF BLDG 120, PAINT & OIL HOUSE, 7344
BLDG 120, PAINT & OIL HOUSE, INTERIOR VIEW 2ND FL E SIDE LOOKING S, SHOWING STOWAGE OF VARNISHES, ALCOHOL ETC, 7346
BLDG 120, PAINT & OIL HOUSE, INTERIOR VIEW 2ND FL W SIDE LOOKING N, SHOWING STOWAGE OF PAINTS & VARNISHES, 7347
LOOKING SE ON 2ND FL BLDG 120, N END, 7348
BLDG 120, INTERIOR LOOKING N, 7349
BLDG 120, INTERIOR LOOKING SE, 7350
BLDG 120, INTERIOR LOOKING N, 7351
BLDG 120, 7352
MONTHLY PROGRESS PHOTO, BLDG 117 (19) E FOUNDATION FOR DRILL, LOOKING N, YARD LABOR, 7353
MONTHLY PROGRESS PHOTO, BLDG 117 (19) W FOUNDATION FOR DRILL, LOOKING N, YARD LABOR, 7354
MONTHLY PROGRESS PHOTO, BLDG 117 (19) CTR BAY NEW CRANE & REINFORCED RUNWAY, LOOKING NW, YARD LABOR, 7355
MONTHLY PROGRESS PHOTO, BLDG 117 (19) EXCAVATION FOR FOUNDATION FOR DRILL, LOOKING NW, YARD LABOR, 7356
MONTHLY PROGRESS PHOTO, BLDG 117 (19) CRANES IN NE BAY TO BE REPLACED, LOOKING NW, YARD LABOR, 7358
MONTHLY PROGRESS PHOTO, BLDG 117 (19) REINFORCING CTR CRANE RUNWAY, LOOKING SE, YARD LABOR, 7359
BLDG 117, 7360
MONTHLY PROGRESS PHOTO, BLDG 116, LOOKING N SHOWING NEW CONCRETE BASE BELOW CORRUGATED METAL, YARD LABOR, 7361
MONTHLY PROGRESS PHOTO, BLDG 116 (27), NEW CORNICE ON W SIDE, LOOKING NE, YARD LABOR, 7362
MONTHLY PROGRESS PHOTO, BLDG 116 (27), REBUILDING CORNICE ON E SIDE, LOOKING N, YARD LABOR, 7363
MONTHLY PROGRESS PHOTO, BLDG 116 (27), NEW CORNICE ON E SIDE, LOOKING N, YARD LABOR, 7364
MONTHLY PROGRESS PHOTO, BLDG 116 (27), REBUILDING CORNICE ON W SIDE, LOOKING NE, YARD LABOR, 7365
MONTHLY PROGRESS PHOTO, BLDG 116 (27), NEW CORNICE, LOOKING NE, YARD LABOR, 7366
GENERATOR SWITCHBOARD SUB-STATION 6, CONTRACT 1838, 7367
MONTHLY PROGRESS PHOTO, BLDG 116 (27), TROLLEY RUNWAY TO BLDG 115 (26), LOOKING N, YARD LABOR, 7369
MONTHLY PROGRESS PHOTO, BLDG 116 (27), JIB CRANE TRACKS, SE SIDE, LOOKING NE, YARD LABOR, 7370
MONTHLY PROGRESS PHOTO, BLDG 116 (27), EXCAVATING FOR FOUNDATIONS FOR JIB CRANES, LOOKING E, YARD LABOR, 7372
MONTHLY PROGRESS PHOTO, BLDG 116 (27), STRUCTURAL CHANGES, LOOKING SW, YARD LABOR, 7373
BLDG 116 (27), 7375
BLDG 116 (27), 7376
BLDG 116 (27), 7377
MONTHLY PROGRESS PHOTO, BLDG 115 (26), NEW ASPHALTIC MASTIC FLOOR COMPLETED, LOOKING SE, DJ SKELTON, CONTR, 7378
BLDG 115 (26), SCARFING MACHINE BEFORE REBUILDING, 7382
BLDG 115 (26), SCARFING MACHINE BEFORE REBUILDING, 7383
BLDG 115 (26), SCARFING MACHINE BEFORE REBUILDING, 7384
BLDG 115 (26), SCARFING MACHINE BEFORE REBUILDING, 7385
BLDG 115 (26), SCARFING MACHINE BEFORE REBUILDING, 7386
BLDG 115 (26), SCARFING MACHINE BEFORE REBUILDING, 7387
MONTHLY PROGRESS PHOTO, BLDG 115 (26) TROLLEY RUNWAY EXTENSION, LOOKING NW, YARD LABOR, 7390
BLDG 115 (26), WASHROOM & TOILET ENCLOSURE IN N CORNER, 7394
MONTHLY PROGRESS PHOTO, BLDG 115 (26), NEW JIB CRANE ON NE SIDE, LOOKING SW, YARD LABOR, 7395

MONTHLY PROGRESS PHOTO, BLDG 115 (26), TROLLEY RUNWAY TO BLDG 116 (27), LOOKING W, YARD LABOR, 7396
MONTHLY PROGRESS PHOTO, BLDG 115 (26), TROLLEY TO BLDG 116 (27), LOOKING SW, YARD LABOR, 7397
MONTHLY PROGRESS PHOTO, BLDG 115 (26), JIB CRANE ON NE SIDE, LOOKING SW, YARD LABOR, 7398
MONTHLY PROGRESS PHOTO, BLDG 115 (26), PAINTING YARD BLDGS, LOOKING N, YARD LABOR, 7399
MONTHLY PROGRESS PHOTO, BLDG 115 (26), JIB CRANE ON NE SIDE, LOOKING SW, YARD LABOR, 7400
MONTHLY PROGRESS PHOTO, BLDG 115 (26), CRANE RUNWAY NE BAY, LOOKING NW, YARD LABOR, 7402
MONTHLY PROGRESS PHOTO, BLDG 115 (26), CRANE RUNWAY IN NE AISLE, LOOKING NW, YARD LABOR, 7403
MONTHLY PROGRESS PHOTO, EXTENSION OF TROLLEY TRACK OUT NW END BLDG 115 (26), LOOKING SE, YARD LABOR, 7404
MONTHLY PROGRESS PHOTO, BLDG 115 (26), TROLLEY TRACK OUT NW END, LOOKING E, YARD LABOR, 7405
Building 10 - Monthly Progress Photo, Pockets in Building 10 (35) for Support of Trolley from Building 115 (26), Looking East, Yard Labor, 7407
BLDG 115 (26) BALL TABLE, 7409
BLDG 115 (26) BALL TABLE, 7410
BLDG 115 (26) ROLLER TABLE, 7411
MONTHLY PROGRESS PHOTO, PLATE CARRIERS & TRACKS FOR PUNCH IN BLDG 115 (26), LOOKING SE, 7412
BLDG 115 (26), TYPE SAFETY DEVICES- NO.3, 7413
BLDG 115 (26), TYPE SAFETY DEVICES- NO.2, 7414
BLDG 115 (26), TYPE SAFETY DEVICES- NO.1, 7415
BLDG 115 (26), BRIDGE BETWEEN BLDGS 115 & 117, YARD LABOR, 7416
HYDROGEN GASOMETER CONTRACT # NOY 257 COMPLETED, 7417
Building 10 - Foundation for Gas Holder, Allot #7X218-5-3, 7418
REPAIRS TO ROOF AND RAMP BLDG 9, ALLOT 7X218-23-1, YARD LABOR, 7419
VIEW OF BLDG 9, 7420
VIEW OF BLDG 9, 7421
TRANSVERSE CRANE RUNWAY, SITE OF BLDG 6 AFTER DEMOLITION, STEAM PIPES TO BE LATER REPLACED IN TRENCH, CONTRACT NOY 4243, 7423
DEMOLISHING BLDG 6, CONTRACT NOY 4243, 7424
TRANSVERSE CRANE RUNWAY DEMOLITION OF BLDG 6, CONTRACT 4243, 7425
DEMOLISHING FRAME ADDITION TO BLDG 6, VIEW LOOKING N, W ON 2ND ST, YARD LABOR, 7426
DEMOLISHING FRAME ADDITION TO BLDG 6, VIEW ON 2ND ST, YARD LABOR, 7427
BLDG 6, 7428
VIEW SHOWING FRAME ANNEX TO BLDG 6, 7429
IMPROVE PLANNING DIV, FACILITIES BLDG 5, NEW PARTITIONS, 5TH FL, ALLOT 7X127-1, YARD LABOR, 7430
VENTILATING DUCTWORK DRAFTING ROOM, 5TH FL, BLDG 5, ALLOT 7X127-1, YARD LABOR, 7431
INSTALLING NEW VENTILATING SYSTEM ON 5TH FL, BLDG 5, ALLOT 7X127-1, YARD LABOR, 7432
INSTALLING NEW VENTILATING SYSTEM ON 6TH FL, BLDG 5, ALLOT 7X127-1, YARD LABOR, 7433
IMPROVEMENT OF PLANNING DIVISION FACILITIES, NEW DRAFTING ROOMS, 5TH FL, BLDG 5, ALLOT 7X127-1, YARD LABOR, 7434
IMPROVEMENT OF PLANNING DIVISION FACILITIES, NEW DRAFTING ROOMS, 5TH FL, BLDG 5, ALLOT 7X127-1, YARD LABOR, 7435
ALTERATIONS ON 5TH FL OF BLDG 5 FOR NEW DRAFTING ROOM, ALLOT 7X127-1, YARD LABOR, 7436
NEW DRAFTING ROOM, 5TH FL, BLDG 5, ALLOT 7X127-1, YARD LABOR, 7437
NEW CAFETERIA 3RD FL, BLDG 5, ALLOT 7X127-1, YARD LABOR, 7438
NEW CAFETERIA 3RD FL, BLDG 5, ALLOT 7X127-1, YARD LABOR, 7439
IMPROVE PLANNING FACILITIES, BLDG 5, NEW PARTITIONS 3RD FL, ALLOT 7X127-1, YARD LABOR, 7440
IMPROVE PLANNING DIV FACILITIES, BLDG 5, NEW PARTITIONS 5TH FL, ALLOT 7X127-1, YARD LABOR, 7441
IMPROVE PLANNING DIV FACILITIES, BLDG 5, NEW PARTITIONS 3RD FL, ALLOT 7X127-1, YARD LABOR, 7442
NEW VENTILATING UNITS INSTALLED ON 6TH FL OF BLDG 5, EXTERIOR VIEW OF EXHAUST, S WALL, CONTRACT NOY 2994, 7443
NEW VENTILATING UNITS INSTALLED ON 6TH FL OF BLDG 5, INTERIOR VIEW OF EXHAUST FAN, S WALL, CONTRACT NOY 2994, 7444
CONTROL REGULATOR IN AIR CONDITION ROOM, CONTRACT NOY 2348, 7445
REMODELING OF 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC (ENLISTED PERSONNEL QUARTERS) ALLOT, 7.03/5640.2-3335 FED PW PROJECT NO 4, 7446
REMODELING OF 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC (GENERATOR ROOM) ALLOT, 7.03/5640.2-3335 YARD LABOR, FED PW PROJECT NO 4, 7447
AIR INTAKE DUCTS AND WEATHER MAKER FOR AIR CONDITIONED ROOM 2ND FL BLDG 5 CONTRACT NOY 2348, 7448
REMODELING 5TH FL OF BLDG 5 FOR RADIO STATION AND ETC, (VIEW OF US NAVAL RADIO STATION), ALLOT 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 7449
ALTERATIONS TO 5TH FL, BLDG 5, FOR RADIO STATION AND ETC, ALLOT 7.03/5640.2-3335, YARD LABOR, FED, PW PROJECT NO 4, 7450
ALTERATIONS TO 5TH FL, BLDG 5, FOR RADIO STATION AND ETC, STEAM LINE OVERHAUL ALLOT 75201-16, YARD LABOR, FED, PW PROJECT NO 4, 7451
REPAIRS TO EXTERIOR OF BLDG 5, ALLOT 73201-6, YARD LABOR, 7452

FOUNDATION AND PIT FOR IMPREGNATING APPARATUS BLDG 5, ENG, 1930, 7453
 PAINTING STEEL DOORS AND WINDOW FRAMES BLDG 5, ALLOT, 0201-5, YARD LABOR, 7454
 REPAIRS TO EXTERIOR OF BLDG 5, ALLOT 73201-6, YARD LABOR, 7455
 REPAIRS TO ROOF OF BLDG 5, ALLOT 79201-2, YARD LABOR, 7456
 REPAIRS TO ROOF OF BLDG 5, ALLOT 79201-2, YARD LABOR, 7457
 SHORT ANTENNA FROM ROOF OF BLDG 3 TO BLDG 5 FOR RADIO TRANSMITTING ROOM, 7458
 RADIO RECEIVING ROOM CONSTRUCTED ON TOP FLOOR OF BLDG 5, INTERIOR VIEW, ALLOT 79601-18, YARD LABOR, 7459
 RADIO RECEIVING ROOM TOP FLOOR BLDG 5, SHOWING MACHINES IN PLACE, 7460
 RADIO RECEIVING ROOM CONSTRUCTED ON TOP FLOOR OF BLDG 5, EXTERIOR VIEW ALLOT 79601-18, YARD LABOR, 7461
 ELECTRIC DISTRIBUTING PANELS FRONT VIEW, ALLOT 218-8-4, YARD LABOR, 7462
 ELECTRIC DISTRIBUTING PANELS FRONT VIEW, ALLOT 218-8-4, YARD LABOR, 7463
 ELECTRIC DISTRIBUTING PANELS BACK VIEW, ALLOT 218-8-4, YARD LABOR, 7464
 ELECTRIC DISTRIBUTING PANEL BACK VIEW, ALLOT 218-8-4, YARD LABOR, 7465
 PRESENT OLD ELECTRIC ELEVATOR EQUIPMENT FOR PASSENGER ELEVATOR IN BLDG 5, CONT BU Y&D #5138, 7466
 MAINTENANCE BUREAU OF SHIPS, VIEW LOOKING SE SHOWING FOUNDATION AND ASSEMBLY OF STEEL FOR RADIO LABORATORY ON ROOF OF BLDG 3, ALLOT 1710601-8, YARD LABOR, 7467
 RADIO LABORATORY ON ROOF OF BLDG 3, VIEW LOOKING E SHOWING FOUNDATION PIERS OVER COLUMNS, MAINTENANCE BUREAU OF SHIPS, ALLOT 1710601-8, YARD LABOR, 7468
 FIRE (AT ABOUT 12:35 PM) IN CONNECTOR BOX ON THE CILING OF CENTER SECTION, 10TH FL, BLDG 3, VIEW LOOKING SW, 7469
 Maintenance Bureau of Ships (BuShips) Looking North Showing Erection of Store Room for Construction Materials for the New Radio Laboratory on the Roof of Building 3, 7470
 REPAIRS TO ELEVATORS BLDG 3, VIEW SHOWING EXCAVATION OF PIT, ALLOT, 72201-56, YARD LABOR, 7471
 VIEW OF COVERING ON STEAM PIPES IN POLICE OFFICE BLDG 3, ALLOT, 73201-24, YARD LABOR, 7472
 NEW SAFETY DEVICE FOR CLOSING ELEVATOR GATES BLDG 3, "GATE SWITCH" CLOSED, CONTRACT NOY 1473, 7473
 NEW SAFETY DEVICE FOR CLOSING ELEVATOR GATES BLDG 3, "GATE SWITCH" OPEN, CONTRACT NOY 1473, 7474
 NEW SAFETY DEVICE FOR CLOSING ELEVATOR GATES BLDG 3, CONTRACT NOY 1473, 7475
 TIMBER PLATFORM BLDG 3, GENERAL VIEW OF PLATFORM, 7476
 TIMBER PLATFORM BLDG 3, NEAR FOOT OF W CHUTE, 7477
 TIMBER PLATFORM BLDG 3, W END OF PLATFORM, 7478
 TIMBER PLATFORM BLDG 3, FOOT OF W CHUTE, 7479
 TIMBER PLATFORM BLDG 3, FOOT OF E CHUTE, 7480
 TIMBER PLATFORM BLDG 3, W END OF PLATFORM UNSAFE BARRICADED OFF, 7481
 DEFECTIVE SASH BLDG 3, FRAME SPRUNG SWING SASH DO NOT CLOSE, 7482
 DEFECTIVE SASH BLDG 3, FRAME SPRUNG SWING SASH DO NOT CLOSE, 7483
 DEFECTIVE SASH BLDG 3, FRAMES SPRUNG SWING SASH DO NOT CLOSE, 7484
 DEFECTIVE SASH BLDG 3, FRAMES SPRUNG SWING SASH DO NOT CLOSE, 7485
 ACOUSTICAL TILE ON CEILING OF CORRESPONDENCE SECTION 11TH FL, BLDG 3, CONTRACT NOY 993, 7487
 ACOUSTICAL TILE ON CEILING OF CORRESPONDENCE SECTION 11TH FL, BLDG 3, CONTRACT NOY 993, 7488
 IMPROVED LIGHTING SYSTEM CORRESPONDENCE SECTION 11TH FL, BLDG 3, ALLOT 71201-7, YARD LABOR, 7489
 NEW LIGHTING SYSTEM CORRESPONDENCE SECTION 11TH FL, BLDG 3, ALLOT 7X161-18, YARD LABOR, 7492
 OLD LIGHTING SYSTEM E SECTION TOP FL, BLDG 3, ALLOT 7X161-18, YARD LABOR, 7493
 NEW LIGHTING SYSTEM DRAFTING DEPT TOP FL, BLDG 3, ALLOT 7X161-18, YARD LABOR, 7494
 REPAIR OF CRACKS DUE TO SETTLEMENT BLDG 3, GENERAL STOREHOUSE, VIEW OF 9TH FL SHOWING GENERAL LOCATION, 7495
 REPAIR OF CRACKS DUE TO SETTLEMENT BLDG 3, GENERAL STOREHOUSE, VIEW OF 9TH FL SHOWING GENERAL EXTENT OF REPAIRS, 7496
 REPAIR OF CRACKS DUE TO SETTLEMENT BLDG 3, GENERAL STOREHOUSE, VIEW OF 9TH FL SHOWING DETAILS, 7497
 CRACKS IN BLDG 3 2ND FL LOOKING W- COL 104 IN FOREGROUND- CRACKS W OF CONSTRUCTION JOINT NOT CUT OUT, DEPTH OF CRACKS FROM 2" TO 6" AND FROM 1" TO 2 1/2" IN WIDTH, 7498
 CRACKS IN BLDG 3 2ND FL LOOKING E- COL 103 IN FOREGROUND- DEPTH OF CRACKS FROM 2" TO 6" AND FROM 1" TO 2 1/2" IN WIDTH, 7499
 ALTERATIONS TO QUARTERS K AND L WORK BEING DONE BY CWA LABOR, 7500
 ALTERATIONS TO QUARTERS K AND L WORK BEING DONE BY CWA LABOR, 7501
 ALTERATIONS TO QUARTERS K AND L, VIEW OF REAR STAIRS, WORK BEING DONE BY CWA LABOR, 7502
 ALTERATIONS TO QUARTERS K AND L, WORK BEING DONE BY CWA LABOR, 7503
 REPAIRS TO QUARTERS K AND L, WORK BEING DONE BY CWA LABOR, 7504
 PAINTING PATTERN SHOP, BLDG 30, WORK BEING DONE BY CWA LABOR, 7505
 PAINTING PATTERN SHOP, BLDG 30, WORK BEING DONE BY CWA LABOR, 7506
 ELEVATOR SHAFT FOR BLDG 30, FRONT ELEVATION SHOWING DOOR INSTALLED, CONTRACT NOY 1793, 7507
 NEW ELECTRIC FREIGHT ELEVATOR FOR BLDG 30, CONTRACT NOY 1815, 7508
 ELEVATOR SHAFT FOR BLDG 30, CONTRACT NOY 1793, INSTALLATION OF ELEVATOR IN SHAFTWAY VIEW SHOWING PIT, CONTRACT NOY 1815, 7509

ELECTRIC FREIGHT ELEVATOR BLDG 30, VIEW OF MACHINERY ROOM, CONTRACT NOY 1815, 7511
ELECTRIC FREIGHT ELEVATOR BLDG 30, PARTIAL INSTALLATION OF ELEVATOR, CONTRACT NOY 1815, 7512
ELEVATOR SHAFT FOR BLDG 30, W SIDE ELEVATION, CONTRACT NOY 1793, 7513
ELEVATOR SHAFT FOR BLDG 30, FRONT ELEVATION, CONTRACT NOY 1793, 7514
ELEVATOR SHAFT FOR BLDG 30, W SIDE ELEVATION, CONTRACT NOY 1793, 7515
POURING CONCRETE FOR ELEVATOR FOUNDATION BLDG 30, CONTRACT NOY 1793, 7517
ELECTRIC FREIGHT ELEVATOR BLDG 30, PLACING COUNTER WEIGHT GUIDE RAILS, CONTRACT NOY 1815, 7518
IMPROVEMENT OF SHOP LIGHTING, BLDG 29, VIEW OF NEW TRANSFORMER INSTALLATION AT S END OF BLDG, ALLOT 7X218-36-2, YARD LABOR, 7519
IMPROVEMENT OF SHOP LIGHTING, BLDG 29, VIEW AT S END SHOWING 3 NEWLY INSTALLED 50 KVA 23001 2501 115 V POWER TRANSFORMERS AND FOUNDATION, ALLOT 7X218-36-2, YARD LABOR, 7520
REPAIRS TO WALL OF FOUNDRY BLDG 29, ALLOT 7.03/56401-51-1, YARD LABOR, 7521
REPAIRS TO WALL OF FOUNDRY BLDG 29, ALLOT 7.03/56401-51-1, YARD LABOR, 7522
REPAIRS TO WALL OF FOUNDRY BLDG 29, ALLOT 7.03/5640.1-51-1A, YARD LABOR, 7523
VIEW OF INTERIOR OF CORE OVEN IN FOUNDRY, SHOWING TRENCH HG RATING AND DAMPERS, 7524
VIEW OF A BURNER AND CONNECTIONS TO CORE OVEN, 7525
VIEW SHOWING PASSAGE BETWEEN BURNER END OF OVEN AND DIVIDING WALL, 7526
DETAIL VIEW, 7527
FLOORING OVER FOUNDATION AND MACHINE INSTALLED IN FOUNDRY, YARD LABOR, ENGINEERING, 7528
MACHINE FOUNDATION IN FOUNDRY BLDG 29, YARD LABOR, ENGINEERING, 7529
FOUNDATION FOR MOULDING MACHINE IN FOUNDRY BLDG 29, YARD LABOR, ENGINEERING, 7530
CONT 4677, INSTALLATION OF STEEL DOORS IN BLDG 29 ON MORRIS AVE, SIDE NEAR ST, 7531
CONT 4677, INSTALLATION OF STEEL DOOR IN BLDG 29 ON 5TH ST, SIDE NEAR MORRIS AVE, 7532
CONT 4677, INSTALLATION OF STEEL DOORS ON BLDG 29 ON MORRIS AVE, SIDE NEAR 6TH ST, 7533
EXTENSION TO BLDG 28 GENERAL INTERIOR VIEW FROM E END SHOWING LEAD POT ENCLOSURE ON LEFT AND OFFICES ON RIGHT, CONTRACT NOY 4243, 7534
EXTENSION TO BLDG 28 VIEW LOOKING SW FROM 5TH ST, CONTRACT NOY 4243, 7535
EXTENSION TO BLDG 28, BOILER SHOP, VIEW OF E CORNER OF INTERIOR SHOWING LEAD POT ENCLOSURE, CONTRACT NOY 4243, 7536
EXTENSION TO BLDG 28, BOILER SHOP, SECTION OF BLDG BETWEEN BLDG 128 ON THE LEFT AND BLDG 123 ON THE RIGHT, VIEW LOOKING N, CONTRACT NOY 4243, 7537
EXTENSION TO BLDG 28, BOILER SHOP, VIEW OF E END OF BLDG STACK TO LEAD POT AT THE LEFT, NEW STEEL BEING PLACED FOR RAILROAD SPUR, CONTRACT NOY 4243, 7538
EXTENSION TO BLDG 28, BOILER SHOP, MASTER'S OFFICE IN THE NE CORNER OF BLDG, CONTRACT NOY 4243, 7539
EXTENSION TO BLDG 28, BOILER SHOP, VIEW LOOKING S FROM 5TH ST, SHOWING THE PLACING OF GLASS AND SASH, CONTRACT NOY 4243, 7540
EXTENSION TO BLDG 28, BOILER SHOP, NEW BRICK WALL BETWEEN BOILER SHOP AND CENTRAL TOOL SHOP, BLDG 128, CONTRACT NOY 4243, 7541
LOOKING SW FROM 5TH ST, SHOWING EXTENSION TO BLDG 128, CONTRACT NOY 4243, 7542
EXTENSION TO BOILER SHOP, BLDG 28, GENERAL VIEW LOOKING SW FROM 5TH ST, CONTRACT NOY 4243, 7543
EXTENSION TO BOILER SHOP, BLDG 28, REMOVING A SECTION OF THE NE WALL OF BLDG 28, CONTRACT NOY 4243, 7544
EXTENSION TO BOILER SHOP, BLDG 28, VIEW LOOKING E FROM 5TH ST, SHOWING COLUMN FOOTINGS, CONTRACT NOY 4243, 7545
EXTENSION TO BOILER SHOP, BLDG 28, VIEW LOOKING E, SHOWING COLUMN FOOTINGS AND ANCHOR BOLTS, CONTRACT NOY 4243, 7546
EXTENSION TO BOILER SHOP, BLDG 28, GENERAL VIEW LOOKING E, SHOWING COLUMN FOOTINGS AND PILE DRIVING OPERATIONS, CONTRACT NOY 4243, 7547
EXTENSION TO BOILER SHOP, BLDG 28, DRIVING PILES ON N SIDE OF BLDG 128, TEMPORARY ENCLOSURE FOR LEAD POTS AT LEFT, CONTRACT NOY 4243, 7548
REPAIRING ROOF OF BLDG 28, ALLOT, 7X218-23-1, YARD LABOR, 7549
NEW 10 TON CRANE IN BOILER SHOP, BLDG 28, CONTRACT NOY 1462, 7550
NEW CRANE RUNWAY IN BOILER SHOP, BLDG 28, COMPLETE, CONTRACT NOY 1421, 7551
NEW CRANE RUNWAY IN BOILER SHOP, BLDG 28, COMPLETE, CONTRACT NOY 1421, 7552
NEW CRANE RUNWAY IN BOILER SHOP, BLDG 28, COMPLETE, CONTRACT NOY 1421, 7553
NEW CRANE RUNWAY IN BOILER SHOP, BLDG 28, COMPLETED CONTRACT NOY 1421, 7554
NEW CRANE RUNWAY IN BOILER SHOP, BLDG 28, COMPLETED CONTRACT NOY 1421, 7555
REPAIRS TO BLDG 28, VIEW SHOWING REMOVAL OF DEBRIS AFTER DEMOLITION OF BRICK WALL IN BLDG 28, CONTRACT NOY 1421, 7556
REPAIRS TO BLDG 28, VIEW SHOWING REMOVAL OF DEBRIS AFTER DEMOLITION OF BRICK WALL IN BLDG 28, CONTRACT NOY 1421, 7557
REPAIRS TO BLDG 28, VIEW SHOWING REMOVAL OF DEBRIS AFTER DEMOLITION OF BRICK WALL IN BLDG 28, CONTRACT NOY 1421, 7558
REPAIRS TO BLDG 28, VIEW SHOWING ERECTION OF STEEL RUNWAY GIRDERS FOR 40 TON CRANE, CONTRACT NOY 1421, 7559

CRANE RUNWAY IN BLDG 28, VIEW SHOWING "A" FRAME IN PLACE, CONTRACT NOY 1421, 7560
NEW STEEL ON W SIDE OF BLDG 28 FOR NEW CRANE RUNWAY, CONTRACT NOY 1421, 7561
FALSE WORK SUPPORTING OLD STEEL W SIDE, NEW CRANE RUNWAY BLDG 28, CONTRACT NOY 1421, 7562
E SIDE OF NEW CRANE RUNWAY BLDG 28, CONTRACT NOY 1421, 7563
VIEW OF CROSS SECTION OF PARTING WALL AND SCAFFOLDING BLDG 28, CONTRACT NOY 1421, 7564
CLOSE-UP VIEW OF CROSS SECTION OF PARTING WALL BLDG 28, CONTRACT NOY 1421, 7565
CLOSE-UP VIEW OF CROSS SECTION AND SCAFFOLDING BLDG 28, CONTRACT NOY 1421, 7566
VIEW OF CROSS SECTION OF PARTING WALL AND SCAFFOLDING BLDG 28, CONTRACT NOY 1421, 7567
VIEW OF PARTING WALL AND SCAFFOLDING BLDG 28, CONTRACT NOY 1421, 7568
VIEW OF E WALL FROM INSIDE SHOWING CRANE RUNWAY BEARING BLDG 28, CONTRACT NOY 1421, 7569
NEW FLOOR AND CRANE RAIL FOOTINGS BLDG 128, ALLOT, 7X218-18-1, YARD LABOR, 7570
OLD COLUMN FOOTINGS IN BOILER SHOP BLDG 28 UNCOVERED, ALLOT, 7X218-18-1, YARD LABOR, 7573
EXTENSION DEMOLITION AT BLDG 27, COMPLETE ALLOT, 77201-1B, YARD LABOR, 7575
EXTENSION DEMOLITION AT BLDG 27, ALLOT, 77201-1B, YARD LABOR, 7577
PAINTING WINDOW SASH, CORNICE, AND ETC OF BLDG 27, ALLOT 7.03/5604.1-43-1, 7578
PAINTING EXTERIOR OF BLDG 25, ALLOT 73201-1, YARD LABOR, 7580
NEW ELEVATOR BLDG 24, BU, Y&D CONTRACT 1241, SPEC 6569, VIEW ON 1ST FL, 7581
NEW ELEVATOR BLDG 24, VIEW OF NEW CAR AND OVERHEAD SUPPORTS BUREAU, Y&D CONTRACT 1241, SPEC 6569,
HAUGHTON ELEVATOR & MACHINE CO, 7582
NEW ELEVATOR BLDG 24, VIEW OF WINDING PLANT, ELEVATOR PIT AND COUNTER WEIGHTS, BUREAU Y&D
CONTRACT 1241, SPEC 6569, HAUGHTON ELEVATOR & MACHINE CO, 7583
NEW ELEVATOR BLDG 24, BUREAU Y&D CONTRACT 1241, SPEC 6569, VIEW OF CAR & OVEWRHEAD STRUCTURE, 7584
BLDG 24 SHOWING THE SETTLEMENT OF FLOOR, 7585
IMPROVEMENT OF SHOP BLDGS, BLDG 23, DOORS FOR NEW ELEVATOR, ALLOT 17X1218.046-1, YARD LABOR, 7586
IMPROVEMENTS TO SHOP BLDGS, BLDG 23, DOORS FOR NEW ELEVATOR, ALLOT 17X1218.046-1, YARD LABOR, 7587
IMPROVEMENT OF SHOP BLDGS, BLDG 23, SHAFT FOR NEW ELEVATOR IN SE CORNER, ALLOT 17X1218.046-1, YARD
LABOR, 7588
IMPROVEMENT OF SHOP BLDGS, TEMPORARY PENTHOUSE ENCLOSURE, BLDG 23 ELEVATOR, ALLOT 17X1218.046-1,
YARD LABOR, 7590
IMPROVEMENT OF SHOP BLDGS, VIEW OF STEEL FRAMING AND PIT OF ELEVATOR SHAFT IN SE CORNER OF BLDG 23,
ALLOT 17X1218.046-1, YARD LABOR, 7591
NEW PASSENGER ELEVATOR IN BLDG 23, COMPLETE, CONTRACT NOY 2751, 7593
BUILDING NEW PASSENGER ELEVATOR IN BLDG 23, COMPLETE, CONTRACT NOY 2751, 7594
BUILDING NEW PASSENGER ELEVATOR IN BLDG 23, CONTRACT NOY 2751, 7595
SUPER STRUCTURE OF ELEVATOR SHAFT, BLDG 23, ALLOT 77201-11, YARD LABOR, 7596
SUPER STRUCTURE OF ELEVATOR SHAFT, BLDG 23, ALLOT 77201-11, YARD LABOR, 7597
REPAIRS TO ROOF, BLDG 23, ALLOT 77201-22, YARD LABOR, 7598
REPAIRS TO ROOF, BLDG 23, ALLOT 71201-22, YARD LABOR, 7599
NEW WINDOWS, 2ND FL, SE CORNER, YARD LABOR, 7600
REPAIRS TO BRICK WORK OF BLDG 20, ALLOT 73201-64, YARD LABOR, 7601
REPAIRS TO BRICK WORK OF BLDG 20, ALLOT 73201-64, YARD LABOR, 7602
REPAIRS TO ROOF OF BLDG 20, ALLOT 7X218-23-1, YARD LABOR, 7603
REPAIRS TO ROOF OF BLDG 20, ALLOT 7X218-23-1, YARD LABOR, 7605
CONSTRUCTION OF REFRIGERATOR IN COMMISSARY STORE, BLDG 15, CONTRACT NOY 370 COMPLETED, 7608
CONSTRUCTION OF REFRIGERATOR AND COUNTER IN COMMISSARY STORE, BLDG 15, CONTRACT NOY 370, 7609
REFRIGERATING MACHINE 1ST FL COMMISSARY STORE, BLDG 15, CONTRACT NOY 370, 7610
CONSTRUCTING REFRIGERATOR IN COMMISSARY STORE, BLDG 15, CONTRACT NOY 370, 7611
BREAKING UP OLD FLOOR PRIOR TO LAYING NEW CONCRETE, GROUND FL, BLDG 14, RNV (C&M), ALLOT 17X0603,
YARD LABOR, 7612
REPAIRS TO ROOF OF BLDG 14, ALLOT 7X218-23-1, YARD LABOR, 7613
BLDG 14, 7614
COMPLETED ALTERATIONS TO BLDG 14, NORTHERN EXTREMITY MARINE BRIG, CONT 4970, 7615
INSTALLATION OF BRIG IN BLDG 14, OF INTERIOR OF MARINE BRIG, CONT 4970, 7616
REMODELING OF BLDG 14 FOR MARINE BRIG, EXTERIOR VIEW OF N EXTREMITY OF BLDG 14, LOOKING S, CONT 4970,
7617
REPAIRING FLOOR IN YARD RESTAURANT BLDG 14, ALLOT 70201-1, YARD LABOR, 7618
REMODELING BLDG 14 FOR MARINE BRIG, EXTERIOR VIEW OF NORTHERN EXTREMITY OF BLDG 14, LOOKING S, CONT
4970, 7619
NEW FLOOR LAID IN YARD RESTAURANT, BLDG 14, ALLOT, 70201-1, YARD LABOR, 7620
REMODELING BLDG 14 FOR MARINE BRIG, INTERIOR VIEW SHOWING INSTALLATION OF CELLS, CONT 4970, 7621
REMODELING BLDG 14 FOR NEW BRIG OF MARINE BARRACKS, EXTERIOR VIEW OF NORTHERN EXTREMITY, LOOKING
S, CONT 4970, 7622
REMODELING BLDG 14 FOR NEW BRIG OF MARINE BARRACKS, INTERIOR VIEW OF NORTHERN EXTREMITY OF BLDG,
LOOKING N, 7623
REMODELING BLDG 14 FOR NEW BRIG OF MARINE CORPS, INTERIOR VIEW OF NORTHERN EXTREMITY, LOOKING N,

CONT 4970, 7624
REMODELING BLDG 14 FOR NEW BRIG OF MARINE CORPS, INTERIOR VIEW OF NORTHERN EXTREMITY, LOOKING SE, CONT 4970, 7625
REMODELING BLDG 14 FOR NEW BRIG OF MARINE CORPS, EXTERIOR VIEW OF NORTHERN EXTREMITY, LOOKING S, CONT 4970, 7626
YARD GARAGE ENTRANCE LOOKING N, YARD LABOR, 7627
BLDG 14, CHANGES IN SE END FOR YARD GARAGE, YARD LABOR, 7628
BLDG 14, CHANGES FOR YARD GARAGE, YARD LABOR, 7629
BLDG 14, CHANGES TO BE MADE IN THIS END FOR YARD GARAGE, LOOKING NW, YARD LABOR, 7630
RECONSTRUCTION OF TOILET AND WASHROOMS 2ND & 3RD FLS, MARINE BARRACKS BLDG 13, ALLOT 79902-7, YARD LABOR, 7631
MARINE BARRACKS BLDG 13, REMODELING TOILET AND BATHROOM, 2ND FL, ALLOT 79902-7, YARD LABOR, 7632
IMPROVEMENTS TO TOILETS, MARINE BARRACKS, BLDG 131, WATERPROOFING AND ROUGHING IN 3RD FL, ALLOT 79902-7, YARD LABOR, 7634
REMODELING OF TOILET 3RD FL BLDG 13, MARINE BARRACKS, ALLOT 79902-7, YARD LABOR, 7635
REMODELING OF TOILET 2ND FL BLDG 13, MARINE BARRACKS, ALLOT 79902-7, YARD LABOR, 7636
IMPROVEMENTS TO TOILETS MARINE BARRACKS BLDG 13, WATERPROOFING AND ROUGHING IN 2ND FL, ALLOT 79902-7, YARD LABOR, 7637
SE END OF BLDG 13, LOOKING W, 7638
SE END OF BLDG 13, LOOKING N, 7639
REPAIRS TO ROOF OF USS MARINE CORPS BARRACKS, 7640
INTERIOR OF BLDG 13, REMODELED FOR MARINE BARRACKS, VIEW OF APPROACH TO OFFICERS' OFFICES ON 1ST FL, CONT 4970, 7641
INTERIOR OF BLDG 13, REMODELED FOR MARINE BARRACKS, VIEW OF QUARTERS ON 3RD FL, CONT 4970, 7642
INTERIOR OF BLDG 13, REMODELED FOR MARINE BARRACKS, VIEW OF QUARTERS ON 2ND FL, CONT 4970, 7643
INTERIOR OF BLDG 13, REMODELED FOR MARINE BARRACKS, VIEW OF GYMNASIUM ON 3RD FL, CONT 4970, 7644
INTERIOR OF BLDG 13, REMODELED FOR MARINE BARRACKS, VIEW OF WASHROOM ON 3RD FL, CONT 4970, 7645
INTERIOR OF BLDG 13, REMODELED FOR MARINE BARRACKS, VIEW OF QUARTERS ON 2ND FL, CONT 4970, 7646
INTERIOR OF BLDG 13, REMODELED FOR MARINE BARRACKS, VIEW OF QUARTERS ON 2ND FL, CONT 4970, 7647
INTERIOR OF QUARTERS ON 2ND FL OF BLDG 13, REMODELED FOR MARINE BARRACKS, CONT 4970, 7648
INTERIOR VIEW OF BLDG 13, REMODELED FOR MARINE BARRACKS, GENERAL VIEW OF GALLEY, 1ST FL, CONT 4970, 7650
EXTERIOR OF BLDG 13, REMODELED FOR MARINE BARRACKS, VIEW LOOKING NE, CONT 4970, 7651
EXTERIOR VIEW OF BLDG 13, REMODELED FOR MARINE BARRACKS, LOOKING NW, CONT 4970, 7652
REMODELING OF BLDG 13 FOR MARINE BARRACKS, GENERAL VIEW OF WASHROOM AND LATRINE AT SOUTHERN EXTREME OF 3RD FL, LOOKING S, CONT 4970, 7653
REMODELING OF BLDG 13 FOR MARINE BARRACKS, GENERAL VIEW OF WASHROOM AND LATRINE OF 2ND FL, CONT 4970, 7654
REMODELING OF BLDG 13 FOR MARINE BARRACKS, VIEW OF SOUTHERN EXTREMITY OF 3RD FL, LOOKING S, CONT 4970, 7655
REMODELING OF BLDG 13 FOR MARINE BARRACKS, GENERAL VIEW OF NORTHERN EXTREMITY OF 2ND FL, CONT 4970, 7656
REMODELING OF BLDG 13 FOR MARINE BARRACKS, GENERAL VIEW OF SOUTHERN EXTREMITY OF 1ST FL LOOKING E, CONT 4970, 7657
REMODELING OF BLDG 13 FOR MARINE BARRACKS, EXTERIOR VIEW LOOKING N, CONT 4970, 7658
REMODELING OF BLDG 13 FOR MARINE BARRACKS, EXTERIOR VIEW LOOKING N, CONT 4970, 7659
REMODELING OF BLDG 13 FOR MARINE BARRACKS, EXTERIOR VIEW LOOKING NW, CONT 4970, 7660
REMODELING OF BLDG 13, EXTERIOR VIEW LOOKING N AT PORCH, CONT 4970, 7661
REMODELING OF BLDG 13 FOR MARINE BARRACKS, CENTRAL VIEW OF 1ST FL OF BLDG, LOOKING N, CONT 4970, 7662
REMODELING OF BLDG 13 FOR MARINE BARRACKS, EXTERIOR VIEW OF E SIDE, VIEW LOOKING NW, CONT 4970, 7663
REMODELING OF BLDG 13 FOR MARINE BARRACKS, EXTERIOR VIEW OF W SIDE, VIEW LOOKING NE, CONT 4970, 7664
REMODELING OF BLDG 13 FOR MARINE BARRACKS, VIEW OF 1ST FL, CONT 4970, 7666
REMODELING OF BLDG 13 FOR MARINE BARRACKS, INTERIOR VIEW OF 2ND FL, CONT 4970, 7667
REMODELING OF BLDG 13 FOR MARINE BARRACKS, INTERIOR VIEW ON 3RD FL SHOWING PLUMBING, CONT 4970, 7668
REMODELING OF BLDG 13 FOR MARINE BARRACKS, INTERIOR VIEW OF SOUTHERN EXTREMITY OF 3RD FL LOOKING S, CONT 4970, 7669
REMODELING OF BLDG 13 FOR MARINE BARRACKS, INTERIOR VIEW OF SOUTHERN EXTREMITY OF 3RD FL LOOKING S, CONT 4970, 7670
REMODELING OF BLDG 13 FOR MARINE BARRACKS, INTERIOR VIEW OF 3RD FL SHOWING PLUMBING, CONT 4970, 7671
REMODELING OF BLDG 13 FOR MARINE BARRACKS, INTERIOR VIEW OF 2ND FL SHOWING PLUMBING, CONT 4970, 7672
REMODELING OF BLDG 13 FOR MARINE BARRACKS, INTERIOR VIEW OF SOUTHERN EXTREMITY OF 2ND FL, CONT 4970, 7673
REMODELING OF BLDG 13 FOR MARINE BARRACKS, INTERIOR VIEW OF NW EXTREMITY, LOOKING S, CONT 4970, 7674
REMODELING OF BLDG 13 FOR MARINE BARRACKS, INTERIOR VIEW OF CENTRAL SECTION 1ST FL, LOOKING NW, CONT 4970, 7675

REMODELING OF BLDG 13 FOR MARINE BARRACKS, EXTERIOR VIEW LOOKING NE, CONT 4970, 7676
REMODELING BLDG 13 FOR MARINE BARRACKS, EXTERIOR VIEW OF BLDG SHOWING DETAILS OF PORCH, CONT 4970, 7677
REMODELING BLDG 13 FOR MARINE BARRACKS, EXTERIOR VIEW OF BLDG LOOKING N, SHOWING DETAILS OF PORCH, CONT 4970, 7678
REMODELING BLDG 13 VIEW OF 3RD FL SOUTHERN EXTREMITY LOOKING NE, CONT 4970, 7679
REMODELING BLDG 13 VIEW OF NORTHERN EXTREMITY OF 3RD FL LOOKING N, CONT 4970, 7680
REMODELING BLDG 13 VIEW OF 3RD FL SHOWING PLUMBING WORK LOOKING N, CONT 4970, 7681
REMODELING OF BLDG 13 VIEW OF SOUTHERN EXTREMITY LOOKING E, CONT 4970, 7682
REMODELING OF BLDG 13 VIEW OF PLUMBING WORK ON 2ND FL LOOKING SW, CONT 4970, 7683
REMODELING OF BLDG 13 VIEW OF 1ST FL NORTHERN EXTREMITY LOOKING S, CONT 4970, 7684
REMODELING OF BLDG 13 EXTERIOR VIEW LOOKING NW AT PORCH, CONT 4970, 7685
REMODELING OF BLDG 13 EXTERIOR VIEW LOOKING NW, CONT 4970, 7686
REMODELING OF BLDG 13 EXTERIOR VIEW LOOKING NE, CONT 4970, 7687
REMODELING OF BLDG 13 1ST FL VIEW OF S END LOOKING SE, CONT 4970, 7688
REMODELING OF BLDG 13 1ST FL VIEW OF N END OF BLDG LOOKING N, CONT 4970, 7689
REMODELING OF BLDG 13 1ST FL LOOKING S, CONT 4970, 7690
REMODELING OF BLDG 13 2ND FL VIEW OF NORTHERN EXTREMITY LOOKING N, CONT 4970, 7691
REMODELING OF BLDG 13 2ND FL VIEW OF SOUTHERN EXTREMITY LOOKING S, CONT 4970, 7692
REMODELING OF BLDG 13 2ND FL VIEW SHOWING PLUMBING WORK, CONT 4970, 7693
REMODELING OF BLDG 13 3RD FL VIEW OF PLUMBING WORK, CONT 4970, 7694
REMODELING OF BLDG 13 EXTERIOR VIEW LOOKING N, CONT 4970, 7695
REMODELING OF BLDG 13 EXTERIOR VIEW LOOKING NW, CONT 4970, 7696
REMODELING OF BLDG 13 EXTERIOR VIEW LOOKING NW, CONT 4970, 7697
REMODELING OF BLDG 13 EXTERIOR VIEW LOOKING NE, CONT 4970, 7698
REMODELING OF BLDG 13 INTERIOR VIEW, CONT 4970, 7699
REMODELING OF BLDG 13 1ST FL, VIEW LOOKING N, CONT 4970, 7700
REMODELING OF BLDG 13 1ST FL, SOUTHERN EXTREMITY, LOOKING E, CONT 4970, 7701
REMODELING OF BLDG 13 2ND FL, SOUTHERN EXTREMITY, LOOKING SW, CONT 4970, 7702
REMODELING OF BLDG 13 3RD FL, VIEW OF PLUMBING WORK, LOOKING E, CONT 4970, 7703
REMODELING OF BLDG 13, 2ND FL, NORTHERN EXTREMITY, LOOKING NE, CONT 4970, 7704
REMODELING OF BLDG 13, 2ND FL, SOUTHERN EXTREMITY, LOOKING SW, CONT 4970, 7705
REMODELING OF BLDG 13, 3rd FL, SOUTHERN EXTREMITY, LOOKING SW, CONT 4970, 7706
REMODELING OF BLDG 13, 1ST FL, LOOKING E, CONT 4970, 7707
REMODELING OF BLDG 13, MARINE BARRACKS, INTERIOR VIEW OF S END, LAYING OF NEW FLOOR, LOOKING N, CONT 4970, 7708
REMODELING OF BLDG 13, MARINE BARRACKS, EXTERIOR VIEW, LOOKING NE, CONT 4970, 7709
REMODELING OF BLDG 13, EXTERIOR VIEW, LOOKING NW, CONT 4970, 7710
REMODELING OF BLDG 13, INTERIOR VIEW OF 1ST FL, LOOKING N, CONT 4970, 7711
REMODELING OF BLDG 13, 1ST FL, LOOKING N, CONT 4970, 7712
REMODELING OF BLDG 13, VIEW OF 2ND FL, SOUTHERN EXTREMITY LOOKING SE, CONT 4970, 7713
REMODELING OF BLDG 13, 3RD FL, LOOKING N, CONT 4970, 7714
REMODELING OF BLDG 13, 2ND FL, LOOKING N, CONT 4970, 7715
REMODELING OF BLDG 13, 3RD FL, LOOKING N, CONT 4970, 7716
REMODELING OF BLDG 13, 1ST FL, LOOKING N, CONT 4970, 7717
NEW VENTILATING SKYLIGHT, BLDG 12, ALLOT, 7X218-23-1, YARD LABOR, 7720
REPAIRS TO ROOF AND CORNICE OF BLDG 12, FRAME FOR VENTILATING SKYLIGHT, ALLOT, 7X218-23-1, YARD LABOR, 7721
REPAIRS TO ROOF AND GUTTERS OF BLDG 12, ALLOT, 7X218-23-1, YARD LABOR, 7724
VIEW OF TROLLEY RUNWAY SWITCH UNDER MEZZANINE, BLDG 12, CONTRACT NOY 1417, 7725
VIEW OF STAIRWAY AT N END OF MEZZANINE, BLDG 12, CONTRACT NOY 1417, 7726
STAIRWAY AT S END OF MEZZANINE COMPLETE, BLDG 12, CONTRACT NOY 1417, 7727
GENERAL VIEW OF TROLLEY RUNWAY UNDER MEZZANINE FLOOR IN BLDG 12, CONTRACT NOY 1417, 7728
GENERAL VIEW OF MEZZANINE FLOOR IN BLDG 12, ALLOT, 72201-12, YARD LABOR, 7729
VIEW OF STAIRS AT S END OF MEZZANINE FLOOR IN BLDG 12, CONTRACT NOY 1417, 7730
VIEW OF STAIRS AT N END OF MEZZANINE FLOOR IN BLDG 12, CONTRACT NOY 1417, 7731
MEZZANINE UNDER CONSTRUCTION IN BLDG 12, ALLOT, 72201-12, YARD LABOR, 7733
GRILLAGE AND ANCHOR OF STEEL TO WALL FOR MEZZANINE FLOOR, BLDG 12, CONTRACT NOY 1348, 7735
GENERAL VIEW OF STEEL FRAMEWORK FOR MEZZANINE FLOOR, BLDG 12, CONTRACT NOY 1348, 7736
CUTTING HOLES FOR BED PLATES OF TRUSSES FOR MEZZANINE FLOOR, BLDG 12, ALLOT 72201-12, YARD LABOR, 7737
HOLES FOR BED PLATES OF TRUSSES FOR MEZZANINE FLOOR, BLDG 12, CONTRACT NOY 1348, 7738
HOLES FOR BED PLATES OF TRUSSES FOR MEZZANINE FLOOR, BLDG 12, CONTRACT NOY 1348, 7739
CUTTING OUT OLD WINDOWS AND DOOR FOR NEW MEZZANINE FLOOR, BLDG 12, ALLOT 72201-12, YARD LABOR, 7740
BLDG 12, SHOWING THE SETTLEMENT OF FLOOR, 7741

Building 11 - Repairs to Roof, and New Monitor Sash, View on 2nd St Side, Allot 7x218-13-1, Yard Labor, 7748
Building 11 - Repairs to Roof, Allso New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7749
Building 11 - Repairs to Roof, Allso New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7750
Building 11 - Repairs to Roof, and New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7751
Building 11 - Repairs to Roof, and New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7752
Building 11 - Repairs to Roof, and New Monitor Sash, Allot 7x218-13-1, Yard Labor , 7753
Building 11 - Repairs to Roof, and New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7754
Building 11 - Repairs to Roof, and New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7755
Building 11 - Repairs to Roof, and New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7756
Building 11 - Repairs to Roof, and New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7757
Building 11 - Repairs to Roof, and New Monitor Sash, Allot 7x218-13-1, Yard Labor, 7759
Building 11 - Trial Skylight Roof, Allot 7x218-13-1, Yard Labor, 7760
Building 11 - Installation of Steam Lines, Blacksmith Shop, Allot 7201-23, Yard Labor, 7761
Repairing Fire Damage to Building 10, 7762
Building 10 - Repairing Fire Damage, Allot 79203-1, 7763
Building 10 - Interior of Building Damaged by Fire 07/07/1928, 7764
Building 10 - Windows Broken by Fire, 7765
Building 10 - Exterior View of Lean-to Attached to Building, Used for Garage by Coast Guard Guttred by Fire 06/07/1928, 7766
RESURFACING TENNIS COURTS, RNV (C&M), ALLOT 17X0603, YARD LABOR, 7931
LOOKING NW FROM BLDG 18 SHOWING STEEL STORAGE YARD, T&E SHOP BLDG & ACC, ALLOT 17X1218-42-21, YARD LABOR, 7932
CONSTRUCTION OF DRYDOCKS NOS 5 & 6, WASHINGTON AVE SEWER, VIEW LOOKING S SHOWING SHEETING, BRACING AND PILING, CONTRACT NOY 4720, 7933
GENERAL VIEW LOOKING NW FROM BLDG 4 SHOWING TRANSVERSE CRANE RUNWAY AND COVERING OF STEEL STORAGE RACKS, CONTRACT 4243, 7934
IMPROVEMENT TO SHIPBUILDING AREA, LOOKING NW FROM BLDG 18 SHOWING FOUNDATIONS FOR ANGLE RACKS, ALLOT 17X1218-42-41, YARD LABOR, 7936
VIEW LOOKING N SHOWING THE COVERING OF STEEL STORAGE RACKS ON THE W SIDE OF SHIPWAYS 2, CONTRACT NOY 4243, 7937
VIEW LOOKING NE SHOWING THE COVERING OF STEEL STORAGE RACKS ON THE W SIDE OF SHIPWAYS 2, CONTRACT NOY 4243, 7938
RECONSTRUCTION OF SHIPWAYS 1 INSTALLING FRESH AND SALT WATER LINES AND AIR LINE ON E SIDE OF WAYS, VIEW LOOKING S, CONTRACT NOY 4206, 7940
TRANSVERSE CRANE RUNWAY VIEW LOOKING NE SHOWING NEW ACCESS LADDER AND HAND RAIL TO CRANES ON THE E END OF THE RUNWAY, CONTRACT NOY 4243, 7942
VIEW LOOKING W SHOWING BORING NO 16 NEAR BLDG 43, CONTRACT NOY 4445, 7944
TRANSVERSE CRANE RUNWAY, STEAM LINE TO SERVE PICKLING TANKS, N SIDE OF BLDG NO 4 IN BACKGROUND, CONTRACT NOY 4243, 7946
TRANSVERSE CRANE RUNWAY, VIEW LOOKING N FROM BLDG NO 4 SHOWING TUNNEL FOR WATER, AIR AND STEAM LINES ON THE W SIDE OF THE TRANSVERSE CRANE RUNWAY, CONTRACT NOY 4243, 7947
REINFORCEMENT FOR TOP OF VALVE MANHOLE AT THE SE CORNER OF BLDG NO 18, CONTRACT NOY 4243, 7948
TRANSVERSE CRANE RUNWAY DRAINAGE LINE UNDER STEAM STORAGE RACKS ON THE N SIDE OF TRANSFER CRANE RUNWAY, CONTRACT NOY 4243, 7949
VIEW LOOKING W FROM DD 1, SHOWING JIB CRANE ERECTED, ALLOT SAO, YARD LABOR, 7951
RECONSTRUCTION OF BLDGWAYS NO 1, VIEW OF TOP SLAB AT CENTER OF WAYS LOOKING N, TRIGGER PIT IN IMMEDIATE BACKGROUND, CONTRACT NOY 4206, 7953
RECONSTRUCTION OF BLDGWAYS NO 1, VIEW OF TOP SLAB AT INSHORE END OF BLDGWAYS AS SEEN LOOKING S FROM W SIDE OF WAYS, CONTRACT NOY 4206, 7954
RECONSTRUCTION OF BLDGWAYS NO 1, VIEW LOOKING NW FROM W SIDE OF WAYS, SHOWING POURING OPERATIONS ON OUTBOARD END OF INTERMEDIATE COFFERDAM, CONTRACT NOY 4206, 7955
RECONSTRUCTION OF BUILDINGWAYS NO 1, VIEW OF W SIDE TOP SLAB, LOOKING NE FROM W SIDE CENTER OF WAYS, CONTRACT NOY 4206, 7958
RECONSTRUCTION OF BUILDINGWAYS NO 1, VIEW OF E SIDE BENTS, LOOKING TOWARD THE SW INBOARD END FROM E SIDE CENTER OF WAYS, CONTRACT NOY 4206, 7959
IMPROVEMENT TO SHIPWAYS NO 2, VIEW SHOWING INSTALLATION OF NEW POWER CABLES TO 50 TON CRANES, ALLOT 7X218-38-7, YARD LABOR, 7960
TRANSVERSE CRANE RUNWAY VIEW LOOKING W SHOWING THE BLDG OF FORMS FOR WATER AND AIR VALVE MANHOLE ON E SIDE OF THE INBOARD END OF SHIPWAYS NO 1, CONTRACT NOY 4243, 7961
TRANSVERSE CRANE RUNWAY VIEW LOOKING SW SHOWING THE DRIVING OF SHELLS FOR CONCRETE PILES IN COLUMN FOOTING AT INBOARD END OF SHIPWAYS NO 2, CONTRACT NOY 4243, 7962
TRANSVERSE CRANE RUNWAY VIEW LOOKING NE SHOWING THE PLACING OF REINFORCING STEEL IN COLUMN FOOTING AT S END OF WELDING PLATFORM AND DOCK ST, CONTRACT NOY 4243, 7963
TRANSVERSE CRANE RUNWAY VIEW LOOKING N SHOWING COLUMN FOOTING AT 1ST AND DOCK STS, CONTRACT NOY 4243, 7964
TRANSVERSE CRANE RUNWAY VIEW LOOKING S TOWARD BLDG 4, SHOWING FRESH AND SALT WATER PIPES IN

CONCRETE TRENCH ON W SIDE OF TRANSVERSE CRANE RUNWAY BETWEEN BLDGS 4 AND 18, CONTRACT NOY 4243, 7965
C&R, VIEW LOOKING NE FROM BLDG NO 201 SHOWING EXCAVATION FOR JIB CRANE FOUNDATIONS AND DUCT LINES AT BLDG 71, ALLOT SAO, YARD LABOR, 7966
Improvement of Services in Shipbuilding Area, View Looking Northwest on Morris Avenue from Third St Showing Excavation for So Way 4" Fibre Duct Line at Building 1, Allot 17x1218.054-1, Yard Labor , 7967
HAMMERHEAD CRANE FOR HEABY DUTY, VIEW OF ELECTRICAL INSTALLATION ON GROUND FLOOR, ALLOT 7X218-33-1, YARD LABOR, 7968
RECONSTRUCTION OF BLDG WAYS NO 1, VIEW LOOKING S OF SERVICE PIPING ALONG E SIDE OF WAY NO 1, CONTRACT NOY 4206, 7969
COMPLETION OF SHIPWAYS NO 2, GENERAL OVERHAUL OF CRANES AE 14 AND AE 15, ALLOT NO 17X1218.038-8, YARD LABOR, 7970
TRANSVERSE CRANE RUNWAY ELECTRIC CONDUIT LINES ON N SIDE OF BLDG NO 4, CONTRACT NOY 4243, 7971
TRANSVERSE CRANE RUNWAY TRENCH FOR ELECTRIC CONDUIT ON N SIDE OF CRANE RUNWAY AT HEAD OF BLDGWAYS NO 1, VIEW LOOKING E, CONTRACT NOY 4243, 7972
CRANE RUNWAY EXTENSION SHIPWAYS NO 1 AND 2, GENERAL VIEW OF CRANEWAY STRUCTURE AT OUTSHORE END, CONTRACT NOY 3500, 7978
ENCLOSURE IN HAMMERHEAD CRANE BASE GENERAL VIEW OF EXTERIOR OF ENCLOSURE LOOKING E FROM PIER G, CONTRACT NOY 4235, 7979
ENCLOSURE OF HAMMERHEAD CRANE BASE GENERAL VIEW LOOKING N OF EXTERIOR OF ENCLOSURE, CONTRACT NOY 4235, 7980
ENCLOSURE IN HAMMERHEAD CRANE BASE VIEW ON SECOND FLOOR SHOWING SHEET METAL AND HOLLOW METAL PARTITIONS IN OFFICE ROOM, CONTRACT NOY 4235, 7982
RECONSTRUCTION OF BLDGWAYS NO 1, VIEW LOOKING SE SHOWING W SIDE OF WAYS, CONTRACT NOY 4206, 7983
VIEW SHOWING BOULDER UNEARTHED IN EXCAVATION FOR STORM AND SANITARY SEWERS, W SIDE OF BLDG 18, ALLOT 7X218-42-21, YARD LABOR, 7984
IMPROVEMENT OF SHOP LIGHTING TRANSFORMER FOUNDATION SE CORNER OF FOUNDRY, BLDG NO 29, ALLOT 7X218-31-2, YARD LABOR, 7986
MANHOLES FOR ELECTRIC AND TELEPHONE LINES AT SE CORNER OF BLDG 18, ALLOT 7X218-42-21, YARD LABOR, 7987
IMPROVEMENT OF BERTHS 11 AND 12 VIEW OF FENDER SYSTEM, WORK BEING DONE UNDER CHANGE ORDER BY EW FOLEY INC, BERTH 11, CONTRACT NOY 3742, 7989
ENCLOSURE OF HAMMERHEAD CRANE BASE VIEW LOOKING N SHOWING FRAMEWORK OF WASHROOM, WINDOW SASH AND RADIATORS IN PLACE ON UPPER FLOOR, CONTRACT NOY 4243, 7990
RECONSTRUCTION OF BLDGWAYS NO 1, W SIDE LOOKING E AT S END OF WAYS, CONTRACT NOY 4206, 7991
RECONSTRUCTION OF BLDGWAYS NO 1, E SIDE OF WAYS LOOKING NW FROM CENTER, CONTRACT NOY 4206, 7992
RECONSTRUCTION OF BLDGWAYS NO 1, VIEW LOOKING NE, SHOWING OUTBOARD END, CONTRACT NOY 4206, 7993
CRANEWAY EXTENSION SHIPWAYS 1 AND 2, OUTBOARD END AS VIEWED LOOKING SE FROM PIER AT TOWER NO 42, CONTRACT NOY 3590, 7994
REPAIRS TO CRANE RAILS BLDGWAYS NO 2, ALLOT, 7X218-34-4, YARD LABOR, 7995
EXTENSION TO BLDG NO 71 NEAR WELDING PLATFORM, BU C AND R, 7999
ELECTRIC DUCT AND MANHOLE BETWEEN BLDGWAYS 1 AND 2, ALLOT 7X218-34-4, YARD LABOR, 8000
CRANE RUNWAY EXTENSION SHIPWAYS NO 1 AND 2, OUTBOARD END OF SHIPWAYS AS SEEN LOOKING S SHOWING NEW STEEL WORK AT TOWERS 40-41, CONTRACT NOY 3590, 8001
CRANE RUNWAY EXTENSION SHIPWAYS NO 1 AND 2, NEW STEEL ERECTION FOR TOWER NO 42, SHIPWAYS NO 1, CONTRACT NOY 3590, 8002
ENCLOSURE OF HH CRANE BASE REINFORCEMENT STEEL AND FORM FOR UPPER FLOOR IN PLACE, CONTRACT NOY 4235, 8003
F659C1917_ENCLOSURE OF HH CRANE BASE UPPER FLOOR FORM AND REINFORCEMENT STEEL IN PLACE, CONTRACT NOY 4235_09/05/1940_GRID D07 D08 E07 E08_BOX 57, 8004
ENCLOSURE OF HAMMERHEAD CRANE BASE VIEW SHOWING STEEL FOR SIDING AND UNDERSIDE OF FORMS FOR FLOOR SLAB, CONTRACT NOY 4235, 8006
ENCLOSURE IN HAMMERHEAD CRANE BASE GROUND FLOOR SHOWING STEEL FOR SIDING, CONTRACT NOY 4235, 8007
RECONSTRUCTION OF BLDGWAYS NO 1 W SIDE STATION 8 AND 13, LOOKING S, CONTRACT NOY 4206, 8009
RECONSTRUCTION OF BLDGWAYS NO 1 NW CORNER OF INBOARD COFFERDAM STATION 10 AND 58, CONTRACT NOY 4206, 8010
RECONSTRUCTION OF BLDGWAYS NO 1, E SIDE OF WAYS LOOKING DOWN ON CENTER OF WAYS, STATION 5 AND 80, CONTRACT NOY 4206, 8011
RECONSTRUCTION OF BLDGWAYS NO 1, W SIDE LOOKING E AT S END OF BLDG WAYS, CONTRACT NOY 4206, 8012
IMPROVEMENT OF SHIPWAYS NO 2, VIEW FROM ABOVE SHOWING COMPLETED OUTBOARD SECTION OF WORKING PLATFORM, CONTRACT NOY 3643, 8013
IMPROVEMENT OF SHIPWAYS NO 2, VIEW LOOKING S SHOWING COMPLETED OUTBOARD SECTION OF WORKING PLATFORM, CONTRACT NOY 3643, 8014
CRANE RUNWAY EXTENSION SHIPWAYS 1 AND 2, ERECTING NEW STEEL TOWER AT OUTBOARD END, CONTRACT NOY

3590, 8015

INSTALLATION OF NEW 8 IN AIR LINE W OF BLDGWAYS NO 2, ALLOT 7X127-4-11, YARD LABOR, 8016
RECONSTRUCTION OF SHIP BLDGWAYS NO 1 SW END, VIEW LOOKING W, CONTRACT NOY 4206, 8018
RECONSTRUCTION OF SHIP BLDGWAYS NO 1 CENTER LOOKING NE, CONTRACT NOY 4206, 8019
RECONSTRUCTION OF SHIPWAYS NO 1 N END LOOKING NW, CONTRACT NOY 4206, 8021
IMPROVEMENT OF SHOPS, ETC, FIELD OFFICE, WALTER KIDDE CONTRACT NOY 4243, NEAR DD 2, 8022
IMPROVEMENT OF BERTHS NO 11 AND 12, RENEWING FENDER SYSTEM BERTH NO 11, CONTRACT NOY 3742, 8023
CRANE RUNWAY EXTENSION SHIPWAYS NO 1 AND 2, ERECTING STEELWORK, OUTBOARD END FOR TOWER 41,
CONTRACT NOY 3590, 8024
CRANE RUNWAY EXTENSION SHIPWAYS NO 1 AND 2, ERECTING STEELWORK, OUTBOARD END NEW TOWER 40 AND
WIND TRUSS FOR 40 TON CRANEWAY SHIPWAYS NO 2, CONTRACT NOY 3590, 8025
IMPROVEMENT OF BERTHS 11 AND 12 PLACING OF BANK OF 20 – 4" FIBRE DUCT LINE TO 350 TON HAMMERHEAD
CRANE AND TO SHORE OUTLET BOXES AT BERTH 12, VIEW LOOKING NE, CONTRACT NOY 3742, 8026
350 TON HAMMERHEAD CRANE CONSTRUCTED NEAR BERTH 12, FRONT VIEW OF MAIN AUTOMATIC OPERATING
SWITCH PANEL, CONTRACT NOY 3341, 8027
IMPROVEMENT TO SHIPWAYS NO 2, VIEW OF PIER 41, FROM OLD PIER LOOKING OUTBOARD SHOWING CONCRETE
QUAY WALL AND CREOSOTED TIMBER ERECTED, CONTRACT NOY 3643, 8028
IMPROVEMENT TO SHIPWAYS NO 2, VIEW TAKEN FROM PIER 41, LOOKING E SHOWING FORM WORK ERECTED FOR
TOWER 42 AND CONCRETE QUAY WALL PIER 42, CONTRACT NOY 3643, 8029
ELECTRIC SERVICE TO 350 TON HAMMERHEAD CRANE VIEW AT BOTTOM OF CRANE, ALLOT 7X218-33-1, YARD LABOR,
8030
ELECTRIC SERVICE TO 350 TON HAMMERHEAD CRANE VIEW AT BOTTOM OF CRANE, ALLOT 7X218-33-1, YARD LABOR,
8031
EXTENSION TO BLDG NO 71, NEAR WELDING PLATFORM, BU, C AND R, 8032
ELECTRIC DUCTS AND MANHOLE AT HEAD OF PIER G, NEAR HAMMERHEAD CRANE, ALLOT 7X218-41-4, YARD LABOR,
8033
NEW TRANSFORMER AND ELECTRIC MANHOLE OUTSIDE BLDG NO 43, ALLOT 7X218-32-3, YARD LABOR, 8034
350 TON HAMMERHEAD CRANE WITH TEST LOAD AND 15 TON CRANE IN POSITION AT REAR END RUNWAY, CONTRACT
NOY 3341, 8035
EXCAVATION FOR TELEPHONE DUCT, NEAR SEAWALL AT BERTHS 11 AND 12, ALLOT 7X218-33-17, YARD LABOR, 8036
EXTENSION TO BLDG NO 71, BU, C AND R, 8037
FOUNDATION FOR PLANER IN BLDG 4, ALLOT, 7X218-31-2, 8038
EXCAVATION FOR TELEPHONE DUCT NEAR SEAWALL AT BERTHS 11 AND 12, ALLOT, 7X218-33-17, YARD LABOR, 8039
ELECTRIC SERVICE TO NEW 350 TON HAMMERHEAD CRANE GENERAL VIEW AT BOTTOM OF CRANE, ALLOT, 7X218-33-
1, YARD LABOR, 8041
NEW TRANSFORMER AND MANHOLE OUTSIDE OF BLDG 43, ALLOT, 7X218-32-3, YARD LABOR, 8042
IMPROVEMENT OF BERTHS 11 AND 12 CUTTING CONCRETE SEAWALL IN ERODED SECTION OF BERTH 11, CONTRACT
NOY 3742, 8043
IMPROVEMENT OF SHIPWAYS NO 2, VIEW OF PIER 41 TAKEN FROM OLD PIER LOOKING N SHOWING TRACK AND
TOWER PEDESTALS, CONTRACT NOY 3643, 8044
IMPROVEMENT OF SHIPWAYS NO 2, VIEW OF OUTBOARD END OF WORKING PLATFORM TAKEN FROM PIER 40
LOOKING INBOARD, CONTRACT NOY 3643, 8045
IMPROVEMENT OF SHIPWAYS NO 2, VIEW OF TOWER 40, TAKEN FROM OUTBOARD END OF SHIPWAYS 2 LOOKING W
SHOWING CONCRETE FORM WORK, CONTRACT NOY 3643, 8046
IMPROVEMENT OF SHIPWAYS NO 2, VIEW OF PIER 42 TAKEN FROM OLD PIER LOOKING N SHOWING TRACK AND
TOWER PEDESTALS, CONTRACT NOY 3643, 8047
IMPROVEMENT OF SHIPWAYS NO 2, VIEW TAKEN FROM PIER 42 LOOKING W SHOWING COMPLETED CONCRETE QUAY
WALL, CONTRACT NOY 3643, 8048
IMPROVEMENT OF SHIPWAYS NO 2, VIEW SHOWING CRANE PULLING SHEET PILE FROM E SIDE OPEN COFFERDAM,
CONTRACT NOY 3643, 8049
IMPROVEMENT TO SHIPWAYS NO 2 VIEW TAKEN FROM S END OF PIER 42, LOOKING N SHOWING CONCRETE QUAY
WALLS PIER 42 AND CREOSOTED TRACK TIMBER ERECTED, CONTRACT NOY 3643, 8051
IMPROVEMENT TO SHIPWAYS NO 2 DAMAGED SHEET PILING FROM OPEN COFFERDAM, CONTRACT NOY 3643, 8052
NEW 350 TON HAMMERHEAD CRANE ERECTED NEAR BERTH 12, GENERAL VIEW, CONTRACT NO 3341, 8053
NEW TRANSFORMER AND MANHOLE OUTSIDE OF BLDG NO 43, ALLOT, 7X218-32-3, YARD LABOR, 8054
COMBINED STAGING AND WELDING TOWER AT SHIPWAYS NO 2, ALLOT, 7X218-38-6, YARD LABOR, 8055
350 TON HAMMERHEAD CRANE CONSTRUCTED NEAR BERTH 12, VIEW OF DRUMS AND SWITCHBOARD, CONTRACT
NOY 3341, 8057
350 TON HAMMERHEAD CRANE CONSTRUCTED NEAR BERTH 12, VIEW OF 175 TON TROLLEY, CONTRACT NOY 3341,
8058
350 TON HAMMERHEAD CRANE CONSTRUCTED NEAR BERTH 12, AFTERNOON TEST, OVERLOAD 437 ½ TONS,
MAXIMUM REACH, CONTRACT NOY 3341, 8059
IMPROVEMENT TO SHIPWAYS NO 2 VIEW OF E SIDE OF PIER 41, TAKEN FROM PIER 42, SHOWING CONCRETE FORM
WORK ERECTED, CONTRACT NOY 3643, 8060
TURRET AND ERECTION SHOPS BLDG 18, IMPROVEMENT OF SHIPWAYS 2, WORKING PLATFORM IN COFFERDAM

LOOKING INBOARD FROM STATION 18 AND 17, CONTRACT NOY 3643, 8062
RECONSTRUCTION OF RR TRACK ON 2ND ST, NEAR PERRY AVE, ALLOT, 7X218-31-2, YARD LABOR, 8063
IMPROVEMENTS TO BERTHS NO 11 AND 12, GENERAL VIEW, BERTH 12, SHOWING CONCRETE ENVELOPES AROUND TIE RODS, CONTRACT NOY 3742, 8065
IMPROVEMENTS TO BERTHS NO 11 AND 12, GENERAL VIEW, BERTH 12, SHOWING ELECTRICAL MANHOLE AND CONCRETE ENVELOPES AROUND TIE RODS, CONTRACT NOY 3742, 8066
IMPROVEMENTS TO BERTHS NO 11 AND 12, GENERAL VIEW, BERTH 11, SHOWING STEEL SHEET PILING PARTLY DRIVEN, CONTRACT NOY 3742, 8067
350 TON HAMMERHEAD CRANE NEAR BERTH 12, GENERAL VIEW, CONTRACT NOY 3341, 8068
NEW TRANSFORMER AND MANHOLE OUTSIDE OF BLDG NO 43, ALLOT, 7X218-32-3, YARD LABOR, 8069
TELEPHONE CABLE REPAIRS AT PERRY AVE AND 2ND ST, 8070
SEAWALLS AND SLIPS BLDG NO 18, VIEW OF BKLYN EDISON WALL ADJACENT TO LITTLE ST PIER SHOWING CRACKS BEFORE BEGINNING OF CONTRACT WORK NEARBY, CONTRACT NOY 3739, 8071
SEAWALLS AND SLIPS BLDG NO 18, VIEW OF BKLYN EDISON WALL ADJACENT TO LITTLE ST PIER SHOWING CRACKS BEFORE BEGINNING OF CONTRACT WORK NEARBY, CONTRACT NOY 3739, 8072
SEAWALLS AND SLIPS BLDG NO 18, VIEW OF BKLYN EDISON WALL ADJACENT TO LITTLE ST PIER SHOWING CRACKS BEFORE BEGINNING OF CONTRACT WORK NEARBY, CONTRACT NOY 3739, 8073
SEAWALLS AND SLIPS BLDG NO 18, VIEW OF BKLYN EDISON WALL ADJACENT TO LITTLE ST PIER SHOWING CRACKS BEFORE BEGINNING OF CONTRACT WORK NEARBY, CONTRACT NOY 373, 8074
SEAWALLS AND SLIPS BLDG NO 18, VIEW OF BKLYN EDISON WALL ADJACENT TO LITTLE ST PIER SHOWING CRACKS BEFORE BEGINNING OF CONTRACT WORK NEARBY, CONTRACT NOY 3739, 8075
SEAWALLS AND SLIPS BLDG NO 18, VIEW OF BKLYN EDISON WALL ADJACENT TO LITTLE ST PIER SHOWING CRACKS BEFORE BEGINNING OF CONTRACT WORK NEARBY, CONTRACT NOY 3739, 8076
SEAWALLS AND SLIPS BLDG NO 18, VIEW OF BKLYN EDISON WALL ADJACENT TO LITTLE ST PIER SHOWING CRACKS BEFORE BEGINNING OF CONTRACT WORK NEARBY, CONTRACT NOY 3739, 8077
SEAWALLS AND SLIPS BLDG NO 18, PILE DRIVING AT END OF EXTENSION TO LITTLE MEANY PIER (VIEW LOOKING E), CONTRACT NOY 3739, 8078
SEAWALLS AND SLIPS BLDG NO 18, PILE DRIVING AT END OF EXTENSION TO LITTLE MEANY PIER (VIEW LOOKING E), CONTRACT NOY 3739, 8079
EXTENSION OF BLDGWAYS NO 2, GENERAL VIEW OF NEW ADDITION AND CATWALKS, CONTRACT NOY 3590, 8080
EXTENSION OF BLDGWAYS NO 2, VIEW SHOWING NEW CATWALKS, CONTRACT NOY 3590, 8081
SEAWALLS AND PIERS (BLDG NO 18) VIEW LOOKING N, OF NEW SEWER CONSTRUCTION INBOARD FROM SEAWALL, CONTRACT NOY 3739, 8084
SEAWALLS AND SLIPS (BLDG NO 18) VIEW LOOKING W, SHOWING NEW PILES FOR EXTENSION OF LITTLE MEANY PIER, CONTRACT NOY 3739, 8085
IMPROVEMENTS TO SHIPWAYS NO 2, VIEW LOOKING N, SHOWING EXTENSION OF PIER ON E SIDE OF WAYS NO 1, CONTRACT NOY 3643, 8086
NEW TRANSFORMER AND MANHOLE OUTSIDE OF BLDG NO 43, ALLOT, 7X218-32-3, 8087
SOUNDING FOR NEW BLDG SITE NEAR BLDG NO 88, CONTRACT NOY 3884, 8088
IMPROVEMENTS TO BERTHS 11 AND 12 VIEW LOOKING NW SHOWING DIVER ABOUT TO DESCEND FOR EXPLORATION AT BERTH NO 11, CONTRACT NOY 3742, 8089
350 TON HAMMERHEAD CRANE VIEW SHOWING EQUALIZING BEAM FOR 350 TON LOADS, CONTRACT NOY 3341, 8091
TAKING BORINGS FOR SITE OF NEW BLDG IN SCRAPYARD, CONTRACT NOY 3884, 8093
TAKING BORINGS FOR NEW BLDG SITE, NEAR BLDG NO 425, CONTRACT NOY 3884, 8094
IMPROVEMENT TO SHIPWAYS NO 2 VIEW LOOKING INBOARD FROM STA 11 AND 40 SHOWING GROUNDWAY CONSTRUCTION IN CENTER COFFERDAM, CONTRACT NOY 3643, 8095
IMPROVEMENT TO SHIPWAYS NO 2 VIEW LOOKING INBOARD IN BOX COFFERDAM SHOWING OUTBOARD END OF NEW WORKING PLATFORM, CONTRACT NOY 3643, 8096
IMPROVEMENT TO SHIPWAYS NO 2 VIEW LOOKING SE FROM END OF BIG MEANY PIER SHOWING BOX COFFERDAM AND PILE DRIVING FOR PIER EXTENSION, CONTRACT NOY 3643, 8097
IMPROVEMENT TO SHIPWAYS NO 2 VIEW OF EXTENSION OF PIER E OF WAYS NO 1, CONTRACT NOY 3643, 8098
IMPROVEMENT TO SHIPWAYS NO 2 PILE DRIVING FOR EXTENSION OF PIER E OF WAYS NO 2, CONTRACT NOY 3643, 8099
SEAWALLS AND SLIPS, BLDG NO 18, EXCAVATION FOR NEW SEWER, PILES SHOWN ARE PART OF PRESENT SEAWALL CONSTRUCTION, CONTRACT NOY 3739, 8100
SEAWALLS AND SLIPS, BLDG NO 18, VIEW LOOKING W FROM BIG MEANY PIER SHOWING PILE DRIVING ON SITE OF LITTLE MEANY PIER, CONTRACT NOY 3739, 8101
IMPROVEMENT OF BERTHS 11 AND 12, VIEW SHOWING STEEL SHEET PILING BERTH NO 11, LOOKING OUTBOARD, CONTRACT NOY 3742, 8102
IMPROVEMENT OF BERTHS 11 AND 12, VIEW SHOWING STEEL SHEET PILING BERTH NO 12, LOOKING INBOARD, CONTRACT NOY 3742, 8103
350 TON HAMMERHEAD CRANE NEAR BERTH 12, VIEW IN MACHINE HOUSE SHOWING DRUMS OF HAMMERHEAD CRANE, CONTRACT NOY 3341, 8104
350 TON HAMMERHEAD CRANE NEAR BERTH 12, VIEW IN MACHINE HOUSE SHOWING SWITCHBOARD, CONTRACT NOY 3341, 8105

350 TON HAMMERHEAD CRANE NEAR BERTH 12, VIEW SHOWING SWITCHBOARD AND DRUMS, CONTRACT NOY 3341, 8106
350 TON HAMMERHEAD CRANE NEAR BERTH 12, GENERAL VIEW OF CRANE, CONTRACT NOY 3341, 8107
EXTENSION OF BLDGWAYS NO 2, VIEW SHOWING COMPLETED WORK AND CATWALKS, CONTRACT NOY 3590, 8108
350 TON HAMMERHEAD CRANE SHOWING LEAKAGE OF SNOW AROUND WINDOWS AND COLUMNS, CONTRACT NOY 3341, 8109
350 TON HAMMERHEAD CRANE SHOWING LEAKAGE OF SNOW AROUND WINDOWS AND COLUMNS, CONTRACT NOY 3341, 8110
POWER HOUSE INSTALLATION OF BOILERS CONT. 2590 HEINE SAFETY BOILER CO, 8112
POWER HOUSE U.S. NAVAL HOSPITAL, 8113
POWER HOUSE INSTALLATION OF BOILERS & STOKERS CONT. 2590 & 2585 HEINE SAFETY BOILER CO & MARBLE ARCH CO, 8114
EMERGENCY HOSPITAL ROOM 303 NURSES' ROOM U.S. NAVAL HOSPITAL, 8115
EMERGENCY HOSPITAL TOILET URINALS. U.S. NAVAL HOSPITAL, 8116
EMERGENCY HOSPITAL DIET KITCHEN U.S. NAVAL HOSPITAL, 8117
EMERGENCY HOSPITAL ROOM 303 NURSES' ROOM U.S. NAVAL HOSPITAL, 8118
EMERGENCY HOSPITAL TOILET AND BATH U.S. NAVAL HOSPITAL, 8119
EMERGENCY HOSPITAL DIET KITCHEN U.S. NAVAL HOSPITAL, 8120
EMERGENCY HOSPITAL ROOM 302 WARD WEST WING U.S. NAVAL HOSPITAL, 8121
POWER HOUSE U.S. NAVAL HOSPITAL GROUNDS, 8122
POWER HOUSE U.S. NAVAL HOSPITAL GROUNDS, 8123
U.S. NAVAL HOSPITAL POWER HOUSE INSTALLATION OF BOILER EXTRA ON CONT. 2590, 8124
U.S. NAVAL HOSPITAL POWER HOUSE, 8125
U.S. NAVAL HOSPITAL POWER HOUSE, 8126
U.S.N. HOSP. POWER HOUSE, 8127
U.S.N. RECEIVING SHIP BARRACKS – BAY RIDGE – BKLYN – NORTHERN EXTREMITY LOOK N. POST & MC CONT 3147, 8129
U.S.N. RECEIVING SHIP BARRACKS – BAY RIDGE – BKLYN – GEN. VIEW OF DISPENSAR – BARRACKS & MESS HALL – LOOK N. POST & MC CONT 3147, 8130
U.S.N. RECEIVING SHIP BARRACKS – BAY RIDGE – BKLYN – EXCAVATING FOR BLDs. POST & MC CONT 3147, 8131
U.S.N. RECEIVING SHIP BARRACKS – BAY RIDGE – BKLYN – EXCAVATING FOR BLDs. POST & MC CONT 3147, 8132
U.S.N. RECEIVING SHIP BARRACKS – BAY RIDGE – BKLYN – 1ST TIER OF BARRACKS WITH MESS HALL IN BACK GROUND POST & MC CONT 3147, 8133
U.S.N. RECEIVING SHIP BARRACKS – BAY RIDGE – BKLYN – MESS HALL LOOK N. POST & MC CONT 3147, 8134
U.S.N. RECEIVING SHIP BARRACKS – BAY RIDGE – BKLYN – MESS HALL LOOK S. POST & MC CONT 3147, 8135
U.S.N. HOSP. POWER HOUSE, 8136
U.S.N. SHIP BARRACKS BAY RIDGE BKLYN VIC. 71 ST. LOOK N. POST & MC CONT 3147, 8137
U.S.N. RECEIVING BARRACKS BAYRIDGE BKLYN VIC. OF 73 ST. LOOK S. POST & MC CONT 3147, 8138
INTERIOR OF EMERG. HOSPITAL, 8140
INTERIOR OF EMERG. HOSPITAL, 8141
INTERIOR OF EMERG. HOSPITAL, 8142
U.S NAVAL HOSPITAL. NAVY YARD, NEW YORK. TYPICAL PSORIASIS, 8144
U.S NAVAL HOSPITAL. NAVY YARD, NEW YORK. PAPULO CRUSTAGEOUS SYPHILIDE OF FACE, 8146
U.S NAVAL HOSPITAL. NAVY YARD, NEW YORK. PAPULO CRUSTAGEOUS SYPHILIDE OF ARMS AND BACK, 8147
NAVAL HOSPITAL POWER HOUSE, 8148
NAVAL HOSPITAL EMERGENCY WARD – LOOK N BUILDING E, 8149
NAVAL HOSPITAL EMERGENCY WARD – LOOK N BUILDING E, 8152
NAVAL HOSPITAL EMERGENCY, 8153
U.S. NAVAL HOSPITAL GROUNDS, 8154
FILLING IN GROUND AT NAVAL HOSPITAL GROUNDS, 8155
NAVAL HOSP. EXCAVATING FOR BLDG E EMERGENCY HOSPITAL LOOK SW, 8156
NAVAL HOSPITAL ERECTING BLDG E EMERGENCY HOSPITAL, 8157
NAVAL HOSPITAL ERECTING BLDG E EMERGENCY HOSPITAL, 8158
U.S. NAVAL HOSPITAL NURSES QUARTERS, 8160
U.S. NAVAL HOSPITAL ERECTING BLDG E EMERGENCY HOSPITAL LOOK SE, 8161
U.S. NAVAL HOSPITAL ERECTING BLDG E EMERGENCY HOSPITAL LOOK NE, 8162
U.S. NAVAL HOSPITAL NURSES BUILDING LOOK N, 8166
U.S. NAVAL HOSPITAL ERECTING BUILDING E LOOK E, 8167
U.S. NAVAL HOSPITAL NURSES BUILDING LOOK N, 8168
U.S. NAVAL HOSPITAL EMERGENCY HOSPITAL BUILDING E LOOKING NE, 8170
U.S. NAVAL HOSPITAL ERECTING EMERGENCY HOSPITAL BUILDING E LOOKING N, 8171
U.S. NAVAL HOSPITAL NURSES BUILDING LOOKING NORTH EAST, 8172
U.S. NAVAL HOSPITAL ERECTING EMERGENCY HOSPITAL BUILDING E LOOKING EAST, 8173
U.S. NAVAL HOSPITAL ERECTING EMERGENCY HOSPITAL BUILDING E LOOKING NORTH, 8175
U.S. NAVAL HOSPITAL ERECTING EMERGENCY HOSPITAL BUILDING E LOOKING SOUTH, 8176

U.S. NAVAL HOSPITAL ERECTING NURSES BUILDING LOOKING SE, 8177
 U.S. NAVAL HOSPITAL ERECTING EMERGENCY HOSPITAL BUILDING E LOOKING N, 8178
 U.S. NAVAL HOSPITAL ERECTING EMERGENCY HOSPITAL BUILDING E , 8179
 U.S. NAVAL HOSPITAL ERECTING NURSES QUARTERS, 8180
 U.S. NAVAL HOSPITAL COMPLETING EMERGENCY HOSPITAL BUILDING E LOOKING NE, 8181
 U.S. NAVAL HOSPITAL COMPLETING EMERGENCY HOSPITAL BUILDING E LOOKING E, 8182
 U.S. NAVAL HOSPITAL ERECTING NURSES BUILDING LOOK NE, 8183
 U.S. NAVAL HOSPITAL COMPLETING EMERGENCY HOSPITAL BUILDING E LOOKING E, 8184
 U.S. NAVAL HOSPITAL COMPLETING EMERGENCY HOSPITAL BUILDING E LOOKING NE, 8185
 U.S. NAVAL HOSPITAL COMPLETING NURSES BUILDING LOOKING E, 8186
 NAVAL HOSPITAL CONT 3892 OLD PAYMASTER'S OFFICE RECONSTRUCTED TO SERVE AS CONNECTING PASSAGE BETWEEN BLD F AND MAIN BLDG, 8187
 U. S. NAVAL HOSPITAL ERECTING EMERGENCY HOSPITAL BLDG E LOOK E, 8188
 U. S. NAVAL HOSPITAL ERECTING EMERGENCY HOSPITAL BLDG E LOOK NE , 8189
 U. S. NAVAL HOSPITAL ERECTING NURSES QUARTERS LOOK N, 8190
 U. S. NAVAL HOSPITAL ERECTING NURSES QUARTERS LOOK E, 8191
 U. S. NAVAL HOSPITAL NURSES QUARTERS, 8192
 U. S. NAVAL HOSPITAL NURSES QUARTERS, 8193
 U. S. NAVAL HOSPITAL NURSES QUARTERS COURT YARD, 8194
 U. S. NAVAL HOSPITAL ERECT EMERG HOSP BLDG E LOOK E, 8195
 U. S. NAVAL HOSPITAL ERECT EMERG HOSP BLDG E LOOK NE, 8196
 U. S. NAVAL HOSPITAL NURSES QUARTERS, 8197
 U. S. NAVAL HOSPITAL NURSES QUARTERS, 8198
 U. S. NAVAL HOSPITAL EMERGENCY WARD LOOK E, 8199
 U. S. NAVAL HOSPITAL EMERGENCY WARD LOOK NE, 8200
 U. S. NAVAL HOSPITAL EMERGENCY WARD LOOK E, 8201
 U. S. NAVAL HOSPITAL BLDG F CONT 3692, 8202
 U. S. NAVAL HOSPITAL ERECT EMERG HOSP LOOK E, 8203
 U. S. NAVAL HOSPITAL EMERG WARD LOOK N, 8207
 STORE ROOM ON 2ND FLOOR OF MACHINE SHOP SHOWING MATERIAL RACKS, 8209
 INTERIOR OF GALLEY AT WEST END OF BARRACKS BUILDING FIRST FLOOR, 8210
 GENERAL VIEW LOOKING E SHOWING MACHINE SHOP OILHOUSE TANK AND PUMP HOUSE, 8211
 FIRE FIGHTING EQUIPMENT AND HOSE HOUSE, 8213
 INTERIOR OF OIL STORAGE HOUSE, 8214
 LOCOMOTIVE CRANES, 8217
 GARAGES FOR PASSENGER CAR AND TRUCKS LOOK E, 8219
 EXTERIOR OF MACHINE SHOP AND ENGINE HOUSE LOOK NW, 8220
 VIEW FROM TOP OF TRESTLE LOOKING WEST BETWEEN STORAGE NOS 2 AND 3, 8221
 EXTERIOR OF SAND DRYING HOUSE LOOK NE, 8222
 INTERIOR OF SAND DRYING HOUSE, 8223
 U. S. NAVAL HOSPITAL EMERGENCY WARD BUILDING F LOOKING NW CONTRACT 3892, 8225
 U. S. NAVAL HOSPITAL OLD SHELL INJURY – WOUND CLOSED AFTER CARREL – DAKIN TREATMENT REVERDIN SKIN GRAFTS OVER SCAR THAT WAS REMOVED CASE “D”, 8226
 U. S. NAVAL HOSPITAL EMERGENCY WARD BUILDING F, 8227
 U. S. NAVAL HOSPITAL OLD SHELL INJURY OSTEOMYELITIS WOUND READY FOR CLOSURE CASE “F”, 8228
 U. S. NAVAL HOSPITAL ERECTING EMERGENCY WARD BUILDING F CONT 3892, 8229
 U. S. NAVAL HOSPITAL HIGH EXPLOSIVE BULLET WOUND WOUND CAUSING OSTEOMYELITIS OF ULNA RAPIDLY CLOSING UNDER CARREL – DAKIN TREATMENT AFTER DEAD BONE HAS BEEN REMOVED CASE “B”, 8230
 U. S. NAVAL HOSPITAL EMPYAEMIA CAVITY BEING TREATED BY THE CARREL – DAKIN TECHNIQUE CASE “C”_, 8231
 U. S. NAVAL HOSPITAL CASE “F” WITH CARREL – DAKIN TUBES IN POSITION, 8232
 U. S. NAVAL HOSPITAL CASE “E” AFTER USING IMPROVISED PEG - LEG, 8233
 U. S. NAVAL HOSPITAL AMPUTATION STUMP HEALED IN TEN DAYS AND JUST RPIOR TO STARTING THE USE OF AN IMPROVISER PEG – LEG MADE OF PLASTER TO BE IMMEDIATELY WORN IN OVER TO OBVIATE A PAINLESS STUMP CASE “E”, 8234
 GALLAGHER I BONE SINUS OF FEMUR GUNSHOT WOUND JULY 19 1918 OPERATIONS 3 POSTERIOR INCISION CLOSED SOME DEAD BONE WITH SMALL ANTERIOR SINUS BEACH TREATMENT (PASTE) FURTHER OPERATION NOT ADVISABLE LARGE VESSELS ALL ENCASED IN SCARS MAY HEAL BUT BETTER NOT OPERATE AND FACE LOSS OF LEG, 8238
 NEUHEDE STUMP THREE WEEKS AFTER AMPUTATION, 8241
 MIDSHIPMAN KNIGHT R. N. CLOSING OF WOUND SHOWING PROGRESS OF WOUND CLOSURE, 8242
 U. S. NAVAL HOSPITAL ERECTING EMERG WARD BLDG F LOOK N CONT 3892 NUGENT CONSTN CORP, 8243
 U. S. NAVAL HOSPITAL ERECTING EMERG WARD BLDG F CONT 3892 NUGENT CONSTN CORP, 8244
 U. S. NAVAL HOSPITAL BLDG F LOOK W CONT 3892, 8245
 U. S. NAVAL HOSPITAL ERECTING EMERG WARD BLDG F LOOK S W CONT 3892 NUGENT CONSTN CORP, 8246
 U. S. NAVAL HOSPITAL ERECTING EMERG WARD BLDG F LOOK S W CONT 3892 NUGENT CONSTN CORP, 8247
 U. S. NAVAL HOSPITAL ERECTING EMERG WARD BLDG F LOOK N CONT 3892 NUGENT CONSTN CORP, 8248

U. S. NAVAL HOSPITAL ERECTING EMERG WARD BLDG F LOOK N CONT 3892 NUGENT CONSTN CORP, 8249
 U. S. NAVAL HOSPITAL ERECTING EMERG WARD BLDG F LOOK SW CONT 3892 NUGENT CONSTN CORP, 8250
 U. S. NAVAL HOSPITAL GENERAL VIEW OF EMERG WARD BLD F CONT 3892 LOOK N, 8253
 U. S. NAVAL HOSPITAL GENERAL VIEW OF EMERG WARD BLD F CONT 3892, 8256
 U. S. NAVAL HOSPITAL BLD F CONT 3892 SHOWING BRICK WALL OF GROUND FLOOR LOOK N E, 8257
 U. S. NAVAL HOSPITAL BLD F CONT 3892 SHOWING WALL FOR BASEMENT & GROUND FLOOR EAST ELEVATION, 8258
 U. S. NAVAL HOSPITAL BLD F CONT 3892 SHOWING MIXING PLANT, 8259
 U. S. NAVAL HOSPITAL GENERAL VIEW OF EMERG WARD BLD F CONT 3892, 8260
 U. S. NAVAL HOSPITAL 1 REILY SKIN GRAFT FOLLOWING CARREL – DAKIN TREATMENT OF EXTENSIVE CARBUNCLE, 8261
 U. S. NAVAL HOSPITAL CERTAIN GAMES DEVELOPE THE POWER OF BALANCE AND AID THE AMPUTATED TO GET USED TO ARTIFICIAL LIMBS, 8262
 U. S. NAVAL HOSPITAL 1 HORTON – SARCOMA OF FOOT WITH METASTASIS IN POPLITEAL SPACE AND ABDOMEN, 8265
 U. S. NAVAL HOSPITAL 1 HORTON – SARCOMA OF FOOT WITH METASTASIS IN POPLITEAL SPACE AND ABDOMEN, 8266
 U. S. NAVAL HOSPITAL 3 SQUAD OF AMPUTATED LEG CASES – SETTING UP EXERCISES, 8269
 U. S. NAVAL HOSPITAL 1 ANDERSON SPONTANEOUS CLOSURE FOLLOWING CARRELL – DAKIN TREATMENT OF COMPOUND FRACTURE OF JAW, 8272
 U. S. NAVAL HOSPITAL 1 KEIZERSTIEN CLOSURE FOLLOWING CARREL – DAKIN TREATMENT FOR COMPOUND FRACTURE OF FEMUR, 8273
 U. S. NAVAL HOSPITAL SQUAD OF AMPUTATED LEG CASES READY TO ADJUST ARTIFICIAL LIMBS, 8274
 U. S. NAVAL HOSPITAL BED CASES MASSAGE AND BAKING IN THE WARD, 8276
 U. S. NAVAL HOSPITAL 5 PHYSIO – THERAPY – FIRST PLANT – B - 1, 8277
 U. S. NAVAL HOSPITAL 3 HORTON SARCOMA OF FOOT WITH METASTASIS IN THE GLANDS ABOVE AND BELOW POUPARTS LIGAMENT, 8278
 U. S. NAVAL HOSPITAL 1 HAY POPLITEAL ABSCESS – READY FOR CLOSURE HAVING BEEN DAKINIZED FOR 8 DAYS, 8279
 U. S. NAVAL HOSPITAL OCCUPATIONAL THERAPY REHABILITATES MIND AND BODY AND ALSO A DIRECT ECONOMIC VALUE, 8283
 U. S. NAVAL HOSPITAL DERMATOLOGICAL AND UROLOGICAL SERVICE SECONDARY LUETIC RASH, 8290
 U. S. NAVAL HOSPITAL DERMATOLOGICAL AND UROLOGICAL SERVICE CICATRICES OF SKIN IN CONVALESCENT DERMATITIS EXFOLIATIVE FOLLOWING SALVARSAN, 8291
 U. S. NAVAL HOSPITAL DERMATOLOGICAL AND UROLOGICAL SERVICE PAPULAR SYPHILIDES OF THE ARMS, 8293
 U. S. NAVAL HOSPITAL DERMATOLOGICAL AND UROLOGICAL SERVICE TERTIARY TUBERCULO SQUAMOUS SYPHILIDE, 8294
 U. S. NAVAL HOSPITAL 3 LIGHT DUTY, 8296
 U. S. NAVAL HOSPITAL OCCUPATIONAL THERAPY METAL WORK, 8297
 U. S. NAVAL HOSPITAL MAKING GAUZE PADS, 8298
 U. S. NAVAL HOSPITAL MAKING DRESSINGS B-2 DRESSING ROOM, 8299
 U. S. NAVAL HOSPITAL OCCUPATIONAL THERAPY SOME OF LEAST IMPORTANT PRODUCTS OF WORKS, 8309
 U. S. NAVAL HOSPITAL OCCUPATIONAL THERAPY CAMOFLAGING SUIT CASE LESSON IN COLORS, 8310
 U.S. Naval Hospital Reception of Visiting Nurses in Sun Parlor, 8317
 U. S. NAVAL HOSPITAL PEMPHIGUS, 8319
 U. S. NAVAL HOSPITAL PEMPHIGUS, 8321
 U. S. NAVAL HOSPITAL PEMPHIGUS, 8322
 U. S. NAVAL HOSPITAL PEMPHIGUS, 8323
 U. S. NAVAL HOSPITAL PEMPHIGUS, 8324
 NAVAL HOSPITAL BLDG F CONT 3892 DINNING ROOM GROUND FLOOR, 8325
 NAVAL HOSPITAL CONTR 3892 PASSAGE WAY CONNECTING OPERATING ROOM MAIN BLDG AND SECOND, 8326
 NAVAL HOSPITAL BLDG F CONT 3892 VIEW LOOKING AT NORTH END, 8327
 NAVAL HOSPITAL CONTR 3892 EXAMINATION ROOM FIRST FLOOR, 8328
 NAVAL HOSPITAL CONTR 3853 TUNNEL LOOKING BETWEEN BLDG C AND F LOOKING NORTH, 8329
 NAVAL HOSPITAL BLDG F CONTR 3892 MACHANICAL FACILITIES ROOM, 8330
 NAVAL HOSPITAL BLDG F KITCHEN GROUND FLOOR, 8331
 NAVAL HOSPITAL BLDG F CONTR 3892 TIPICAL WARD FIRST FLOOR, 8332
 ULNA PARALYSIS TYPICAL CLAW HAND DEFORMITY, 8334
 ULNA PARALYSIS TYPICAL CLAW HAND DEFORMITY, 8335
 ALOPECIA – LEUTIC, 8336
 NAVAL HOSPITAL CONT 3892 PAYMASTER’S ROOM CONNECTING BLD F WITH MAIN BLDG, 8338
 NAVAL HOSPITAL CONT 3892 PAYMASTER’S ROOM CONNECTING BLD F WITH MAIN BLDG, 8339
 NAVAL HOSPITAL CONT 3892 INTERIOR BLDG F SHOWING FLOOR, 8340
 NAVAL HOSPITAL CONT 3892 RETAINING WALL AT POWER HOUSE, 8341
 NAVAL HOSPITAL CONT 3892 EXTERIOR VIEW BLDG F LOOK N, 8342
 NAVAL HOSPITAL CONT 3892 INTERIOR VIEW BLDG F SHOWING FLOOR, 8343
 NAVAL HOSPITAL REPAIRS TO QTRS 4 LOOKING E, 8346
 NAVAL HOSPITAL REPAIRS TO QTRS 4 LOOKING NW, 8347

RAISING ROOF OF QUARTERS 4 AT HOSPITAL LOOKING N, 8348
DETAIL OF HOOD FOR MEDICAL SUPPLY LABORATORY – TO AC - COMPANY REQUISITION, 8349
REPAIRS TO QUARTERS 4 NAVAL HOSPITAL LOOKING NW, 8350
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT B LOOKING E FROM W END OF
WARD RIVERSIDE CONTRACTING CO CONTRACTOR, 8351
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A WARD TOILET LOOKING E
RIVERSIDE CONTRACTING CO CONTRACTOR, 8352
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A QUIET ROOM LOOKING E
RIVERSIDE CONTRACTING CO CONTRACTOR, 8353
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A LOOKING E FROM W SIDE OF W
WARD RIVERSIDE CONTRACTING CO CONTRACTOR, 8354
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A LOOKING E FROM WEST SIDE
OF E WARD RIVERSIDE CONTRACTING CO CONTRACTOR, 8355
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A DOCTORS ROOM TOILET &
HALL TO NURSES ROOM LOOKING NW RIVERSIDE CONTRACTING CO CONTRACTOR, 8356
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A NURSES ROOM LOOKING NW
RIVERSIDE CONTRACTING CO CONTRACTOR, 8357
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A S SIDE LOOKING NE RIVERSIDE
CONTRACTING CO CONTRACTOR, 8358
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A N SIDE LOOKING SE RIVERSIDE
CONTRACTING CO CONTRACTOR, 8359
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A B & C W ENDS LOOKING NE
RIVERSIDE CONTRACTING CO CONTRACTOR, 8360
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A B & C FRONT E SIDE LOOKING
W RIVERSIDE CONTRACTING CO CONTRACTOR, 8362
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS GENERAL VIEW LOOKING SW
RIVERSIDE CONTRACTING CO CTR, 8363
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT B BATHRM LOOKING E
RIVERSIDE CONTRG CO CTR, 8364
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT C LOOKING E RIVERSIDE
CONTRACTING CO CONTRACTOR, 8365
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A BATHROOM RIVERSIDE
CONTRACTING CO CTR, 8366
MONTHLY PROGRESS PHOTO MARINE HOSPITAL CONTAGIOUS DISEASES UNITS GENERAL BACK VIEW & SHOWING
DOOR CUT IN S SIDE LOOKING NE RIVERSIDE CONTRACTING CO CONTRACTOR, 8367
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT A LOOKING E RIVERSIDE
CONTRACTING CO CONTRACTOR, 8368
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS INTERIOR OF UNIT "C" LOOKING SE
RIVERSIDE CONTRACTING CO CTR, 8369
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS GENERAL VIEW LOOKING SW
RIVERSIDE CONTRACTING CO CTR, 8370
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS INTERIOR OF UNIT "A" LOOKING SE
RIVERSIDE CONTRACTING CO CONTRACTOR, 8371
MONTHLY PROGRESS PHOTO MARINE HOSPITAL CONTAGIOUS DISEASES UNITS INTERIOR OF UNIT "B" LOOKING SE
RIVERSIDE CONTRACTING CO CONTRACTOR, 8372
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS LOOKING N ALONG DITCH FOR STEAM
HEATING PIPES YARD LABOR, 8373
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS GENERAL VIEW BACKSIDE OF UNITS
LOOKING NE RIVERSIDE CONTRACTING CO CONTRACTOR, 8374
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "A" LOOKING SW RIVERSIDE
CONTRACTING CO CONTRACTOR, 8375
MONTHLY PROGRESS PHOTO MARINE HOSPITAL CONTAGIOUS DISEASES UNITS GENERAL VIEW OF FRONT OF UNITS
LOOKING NW RIVERSIDE CONTRACTING CO CONTRACTOR, 8376
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "C" LOOKING SW RIVERSIDE CTG
CO CTR, 8377
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "B" LOOKING SW RIVERSIDE CTG
CO CONTR, 8378
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "B" LOOKING NE RIVERSIDE
CONTRACTING CO CONTRACTOR, 8379
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "C" LOOKING NE RIVERSIDE
CONTRACTING CO CONTRACTOR, 8380
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "C" INTERIOR LOOKING SE
RIVERSIDE CTG CO CONTRACTOR, 8381
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "A" LOOKING NE RIVERSIDE CTG
CO CONTRACTOR, 8382

MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "A" INTERIOR LOOKING E RIVERSIDE CONTRACTING CO CONTRACTOR, 8383
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "B" INTERIOR LOOKING E RIVERSIDE CONTRACTING CO CONTRACTOR, 8384
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "B" LOOKING SE RIVERSIDE CTG CO CONTR, 8385
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "C" LOOKING NW RIVERSIDE CTG CO CTR, 8386
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "A" LOOKING NW RIVERSIDE CONTRACTING CO CONTRACTOR, 8387
MONTHLY PROGRESS PHOTO NAVAL HOSPITAL CONTAGIOUS DISEASES UNITS UNIT "B" LOOKING NW RIVERSIDE CONTRACTING CO CONTRACTOR, 8388
US NAVAL HOSPITAL CONTAGIOUS WARD E SIDE S END LOOKING NW, 8389
US NAVAL HOSPITAL CONTAGIOUS WARD E SIDE N END LOOKING NW, 8390
US NAVAL HOSPITAL CONTAGIOUS WARD W SIDE CTR PART OF SIDE LOOKING SE, 8391
US NAVAL HOSPITAL CONTAGIOUS WARD W SIDE N END LOOKING SE, 8392
US NAVAL HOSPITAL CONTAGIOUS WARD BACK (N) END LOOKING SW, 8393
US NAVAL HOSPITAL CONTAGIOUS WARD W SIDE s END LOOKING SE, 8394
US NAVAL HOSPITAL CONTAGIOUS WARD FRONT (S) END LOOKING NE, 8395
NAVAL HOSPITAL NEW LABORATORY FIRST FLOOR LOOKING NE, 8396
NAVAL HOSPITAL NEW LABORATORY LOOKING NE, 8397
PEARL HARBOR DRY DOCK, 8398
USS NEW MEXICO PORT FORWARD QUARTER, 8399
DETAILS OF BREAK – BROW – NEW MEXICO, 8400
DETAILS OF BREAK – BROW – NEW MEXICO, 8401
DETAILS OF BREAK – BROW – NEW MEXICO, 8402
DETAILS OF BREAK – BROW – NEW MEXICO, 8403
DETAILS OF BREAK – BROW – NEW MEXICO, 8404
USS NEW MEXICO VIEW OF BOW, 8405
USS NEW MEXICO MAIN DECK LOOKING FORWARD, 8406
USS NEW MEXICO UPPER & MAIN DECKS LOOKING AFT, 8407
USS NEW MEXICO VIEW FROM FORWARD, 8408
USS NEW MEXICO VIEW FROM STARBOARD QUARTER, 8409
USS PENNSYLVANIA 50' STEAMER NO 1 WITH TALBOT BOILER GENERAL VIEW, 8410
USS PENNSYLVANIA 50 FT STEAMER NO 1 WITH TALBOT BOILER GENERAL VIEW, 8411
USS PENNSYLVANIA 50' STEAMER NO 1 WITH TALBOT BOILER GENERAL VIEW, 8412
USS WYOMING IN DRY DOCK NO 4, 8415
USS WYOMING IN DRY DOCK NO 4, 8416
USS WYOMING IN DRY DOCK NO 4, 8417
USS WYOMING IN DRY DOCK NO 4, 8418
INCLINING EXPERIMENTS OF USS WORDEN, 8419
INCLINING EXPERIMENTS OF USS WORDEN, 8420
INCLINING EXPERIMENTS OF USS WORDEN, 8421
INCLINING EXPERIMENTS OF USS WORDEN, 8422
INCLINING EXPERIMENTS OF USS WORDEN, 8423
USS OCTOPUS, 8425
USS OCTOPUS, 8426
USS OCTOPUS, 8427
USS OCTOPUS, 8428
HAWSE PIPE CASTING FOR USS UTAH, 8433
USS LOUISIANA, 8434
USS COLORADO IN DRY DOCK 3 ON BLOCKS, 8435
USS COLORADO ENTERING DRY DOCK 3, 8436
FLOATING MACHINE SHOP ON WAYS, 8438
USS PONTIAC VIEW OF DERRICK AND BOOM STARBOARD SIDE, 8439
USS PONTIAC VIEW OF DERRICK AND BOOM FROM AFTER END, 8440
SS SLAVONIA FROM CAISSON DD3, 8441
SS CALORIA ARMED GUARD QUARTERS OP-24-D, 8442
SS SLAVONIA FROM HEAD DD3, 8443
USS ALABAMA ARRANGEMENT OF HULL ZINCS ON STARBOARD SIDE, 8444
USS ALABAMA ARRANGEMENT OF HULL ZINCS ON PORT SIDE, 8445
USS ALABAMA MASSACHUSETTS & INDIANA IN WHITNEY BASIN, 8446
USS Connecticut (BB-18), 8447
PLACING STACK ABOARD USS NEW YORK, 8448
USS KEARSARGE ENTERING DRY DOCK NO 3, 8455

UNTITLED, 8456
UNTITLED, 8457
SUBMARINE, 8458
SUBMARINE, 8459
SUBSURFACE SURVEY US NAVAL HOSPITAL, 8470
USS PENSACOLA, 8474
USS PENSACOLA, 8475
USS PENSACOLA, 8476
USS PENSACOLA, 8477
USS PENSACOLA, 8478
USS PENSACOLA VIEW FROM FORWARD FIRE CONTROL STATION LOOKING FORWARD AND DOWN SHOWING TRIPLE AND DOUBLE GUN MOUNT ARRANGEMENT OF FORECASTLE SHOWING ANCHOR CHAIN WITH STOPPERS ETC MAST SPREADER AND NETTING AT LEFT, 8479
USS PENSACOLA VIEW FROM FORWARD FIRE CONTROL STATION LOOKING AFT AND DOWN ON MAIN AND SUPERSTRUCTURE DECKS, 8480
POWER HOUSE ON US NAVAL HOSPITAL GROUNDS, 8481
POWER HOUSE ON US NAVAL HOSPITAL GROUNDS, 8482
EMERGENCY HOSPITAL GROUNDS OF US NAVAL HOSPITAL, 8483
EMERGENCY HOSPITAL GROUNDS OF US NAVAL HOSPITAL, 8484
POWER HOUSE ON US NAVAL HOSPITAL GROUNDS, 8485
POWER HOUSE ON US NAVAL HOSPITAL GROUNDS, 8486
EMERGENCY HOSPITAL GROUNDS OF US NAVAL HOSPITAL, 8487
POWER HOUSE ON NAVAL HOSPITAL GROUNDS, 8488
EMERGENCY HOSPITAL GROUNDS OF US NAVAL HOSPITAL, 8489
POWER HOUSE ON US NAVAL HOSPITAL GROUND, 8490
POWER HOUSE ON US NAVAL HOSPITAL GROUNDS, 8491
EMERGENCY HOSPITAL ON US NAVAL HOSPITAL GROUNDS, 8492
EMERGENCY HOSPITAL ON US NAVAL HOSPITAL GROUNDS, 8493
POWER HOUSE ON US NAVAL HOSPITAL GROUNDS, 8494
POWER HOUSE ON US NAVAL HOSPITAL GROUNDS, 8495
EMERGENCY HOSPITAL ON US NAVAL HOSPITAL GROUNDS, 8496
EMERGENCY HOSPITAL ON US NAVAL HOSPITAL GROUNDS, 8497
POWER HOUSE LOOKING E ON US NAVAL HOSPITAL GROUNDS, 8498
EMERGENCY HOSPITAL ON US NAVAL HOSPITAL GROUNDS, 8499
MK 17 GUN DIRECTOR 270° POSITION, 8500
MK 17 GUN DIRECTOR 90° POSITION, 8501
NAVAL HOSPITAL BROOKLYN NY BLDG 'B' EXTENSION PHOTOGRAPH OF ROOF AND CORNICE TAKEN FROM CORRIDOR ROOF (SPEC 8477) 3-10-121, 8504
NAVAL HOSPITAL BROOKLYN NY BLDG 'B' SHOWING CORNICE PANELLED PARAPET ROOF AND CUPOLA TAKEN FROM ROOF OF CORRIDOR (SPEC 8477) 3-HO-120, 8505
NAVAL HOSPITAL BROOKLYN NY BLDG 'B' DETAIL OF CORNICE PANELLED PARAPET ROOF AND CUPOLA TAKEN FROM ROOF OF SUN CORRIDOR (SPEC 8477) 3-HO-119, 8506
CONSTRUCTION OF DRY DOCKS NOS 5 & 6 PRELIMINARY WORK DEMOLITION OF PIER 3 VIEW LOOKING EAST FROM CLINTON AVE EXTENSION CONTRACT NOY 4720, 8507
CONSTRUCTION OF DRY DOCKS NOS 5 & 6 PRELIMINARY WORK VIEW LOOKING EAST FROM CLINTON AVE EXTENSION SHOWING DEMOLITION OF PIER 5 CONTRACT NOY 4720, 8508
CONSTRUCTION OF DRY DOCKS NOS 5 & 6 PRELIMINARY WORK DEMOLITION OF PARCEL G VIEW LOOKING EAST FROM METZ ST CONTRACT NOY 4720, 8509
TRANSFORMERS FOR POWER BLDG 23 ALLOT 71124-1 YARD LABOR 110/220 V 3 PHASE, 8510
ENLARGED MANHOLE NO 78 3RD ST AND WARRINGTON AVE IN CONNECTION WITH INSTALLATION OF CIRCUIT "S" ALLOT 71201-26 YARD LABOR, 8511
TRANSFORMER PLATFORM AND TRANSFORMERS ON CHAUNCEY AVE OUTSIDE BLDG # 12 ALLOT 71124-1 YARD LABOR, 8512
TRANSFORMER PLATFORM AND TRANSFORMER ON WARRINGTON AVE OUTSIDE BLDG # 22 ALLOT 71201-6 YARD LABOR, 8513
TRANSFORMER PLATFORM ON CHAUNCEY AVE OUTSIDE BLDG # 23 ALLOT 71124-1 YARD LABOR, 8514
ELECTRIC MANHOLE BET DRY DOCK # 2 AND 3 YARD LABOR, 8516
ELECTRIC MANHOLE ON ORDNANCE DOCK NEAR COAL PIER, 8517
BLG 41 COMPRESSOR ROOM LOOKING SW MONTHLY PROGRESS PHOTO, 8518
COMPRESSOR ROOM BLG 41 LOOKING SW MONTHLY PROGRESS PHOTO, 8519
COMPRESSOR ROOM BLG 41 LOOKING SW MONTHLY PROGRESS PHOTO, 8520
BUILDING 41 COMPRESSOR ROOM LOOKING WEST EVANS ALMIRALL CO CONTRACTOR MONTHLY PROGRESS PHOTO, 8521
BLG 41 COMPRESSOR ROOM LOOKING W MONTHLY PROGRESS PHOTO EVANS ALMIRAL CO CONTRACTOR, 8522
MONTHLY PROGRESS PHOTO NEW LAMP POSTS ON HIGH ST LOOKING N YARD LABOR, 8523

MONTHLY PROGRESS PHOTO NEW ELECTRIC LAMP POSTS ALONG HIGH ST LOOKING N YARD LABOR, 8524
LOOKING NW FROM BLDG NO 18 SHOWING STEEL STORAGE YARD T & E SHOP BUILDING & ACC ALLOT 17X1218-42-21
YARD LABOR, 8526
CONSTRUCTION OF DRY DOCKS NOS 5 & 6 WASHINGTON AVE SEWER VIEW LOOKING SOUTH SHOWING SHEETING
BRACING AND PILING CONTRACT NOY 4720, 8527
GENERAL VIEW LOOKING NORTHWEST FROM BLD NO 4 SHOWING TRANSVERSE CRANE RUNWAY AND COVERING F
STEEL STORAGE RACKS CONTRACT 4243, 8528
IMPROVEMENT TO SHIPBUILDING AREA VIEW LOOKING NW ON DOCK ST SHOWING SALT WATER LINE NEAR 2ND ST AT
BLDG NO 10 FOR NEW FIRE HYDRANT RNY (C&M) ALLOT 17X0609 YARD LABOR, 8529
IMPROVEMENTS TO SHIPBUILDING AREA LOOKING NW FROM BLDG NO 18 SHOWING FOUNDATIONS FOR ANGLE
RACKS ALLOT 17X1218-42-41 YARD LABOR, 8530
VIEW LOOKING N SHOWING THE COVERING OF STEEL STORAGE RACKS ON THE W SIDE OF SHIPWAYS NO 2
CONTRACT NOY 4243, 8531
VIEW LOOKING NE SHOWING THE COVERING ON STEEL STORAGE RACKS IN THE W SIDE OF SHIPWAYS NO 2
CONTRACT NO 4243, 8532
RECONSTRUCTION OF SHIPWAYS NO 1 LOOKING NORTH AT POSTS AND BRACES FOR WORKING PLATFORM
CONTRACT NOY 4206, 8533
RECONSTRUCTION ON SHIPWAYS NO 1 INSTALLING FRESH AND SALT WATER LINES AND AIR LINE ON EAST SIDE ON
WAYS VIEW LOOKING SOUTH CONTRACT NOY 4206, 8534
RECONSTRUCTION OF SHIPWAYS NO 1 INSTALLING DUCT LINES FOR 70 V DC WELDING LINES ON EAST SIDE OF WAYS
VIEW LOOKING NORTH CONTRACT NOY 4206, 8535
TRANSVERSE CRANE RUNWAY VIEW LOOKING NE SHOWING NEW ACCESS LADDER AND HANDRAIL TO CRANES ON
THE EAST END OF THE RUNWAY CONTRACT NOY 4243, 8536
VIEW LOOKING WEST SHOWING BORING NO 16 NEAR BLDG NO 43 CONTRACT NOY 4445, 8538
TRANSVERSE CRANE RUNWAY COLUMN FOOTINGS AND 12" AIR LINE ON NORTH SIDE OF BLDG NO 4 CONTRACT NOY
4243, 8539
TRANSVERSE CRANE RUNWAY STEAM LINE TO SERVE PICKLING TANKS NORTH SIDE OF BLDG NO 4 IN BACKGROUND
CONTRACT NOY 4243, 8540
TRANSVERSE CRANE RUNWAY VIEW LOOKING NORTH FROM BLDG NO 4 SHOWING TUNNEL FOR WATER AIR AND
STEAM LINES ON THEN WEST SIDE OF THE TRANSVERSE CRANE RUNWAY CONTRACT NOY 4243, 8541
REINFORCEMENT FOR TOP OF VALVE MANHOLE AT THE SE CORNER OF BLDG NO 18 CONTRACT NOY 4243, 8542
TRANSVERSE CRANE RUNWAY DRAINAGE LINE UNDER STEEL STORAGE RACKS ON THE NORTH SIDE OF
TRANSVERSE CRANE RUNWAY CONTRACT NOY 4243, 8543
COFFERDAMS FOR SHIPWAYS NO 2 INTERIOR VIEW OF BOX COFFERDAM SHOWING PLACING OF REINFORCING WELL
POINT IN LEFT CENTER CONTRACT NOY 3352, 8545
COFFERDAM FOR SHIPWAYS NO 2 GENERAL VIEW OF WORK TAKEN FROM EAST SIDE OF WAYS NO 2 CONTRACT NOY
3352, 8546
IMPROVEMENT TO DISTRIBUTING SYSTEMS INSTALLATION OF NEW SLAT WATER HYDRANT NO OF BLDG 214 ALLOT
7X218-35 YARD LABOR, 8548
ELECTRICAL TRANSFORMERS PERRY AVE AT BLDG 14 APPROPRIATION C AND R YARD LABOR, 8549
ADDITION TO STRUCTURAL SHOP BLDG 4 ELECTRIC DUCT FOR NEW AC FEEDERS CLOSURE AT 4TH ST AND MORRIS
AVE ALLOT 7X218-35-1 YARD LABOR, 8552
EXTENSION OF CRANE RUNWAYS SHIPWAYS 1 AND 2 VIEW LOOKING EASTWARD SHOWING WOOD WALKWAY IN
CANTILEVER TRUSS AT TOWER 27 – 26 – AND 25 CONTRACT NOY 3242, 8553
EXTENSION OF CRANE RUNWAYS SHIPWAYS 1 AND 2 GENERAL VIEW OF NEW EXTENSION TO SHIPWAYS SHOWING
WOOD WALKWAYS CONTRACT 3242, 8554
EXTENSION OF CRANE RUNWAYS SHIPWAYS NO 1 AND 2 VIEW OF CRANEWAYS FROM TOWER 25 SHOWING WOOD
WALKWAY S IN TRANSVERSE TRUSS CENTERLINE OF WAY NO 1 AND BRIDGE TRUSS BETWEEN TOWER 16-26
CONTRACT NOY 3242, 8555
COFFERDAM FOR SHIPWAYS NO 2 DRIVING SHEET PILING FOR OPEN COFFERDAM COMPLETED BOX COFFERDAM ON
OUTBOARD END CONTRACT NOY 3352, 8557
COFFERDAM FOR SHIPWAYS NO 2 VIEW LOOKING INBOARD FROM EAST SIDE OF WAYS '2' SHOWING SHEET PILING
FOR OPEN COFFERDAM WITH ADDED CROSSWALL AT STA 9 + 61 CONTRACT NOY 3352, 8558
IMPROVEMENT TO DISTRIBUTION SYSTEMS REPLACEMENT OF SALT WATER HYDRANT AT NORTH EAST CORNER OF
4TH ST AND PERRY AVE ALLOT 7X218-35-1 YARD LABOR, 8559
IMPROVEMENT TO DISTRIBUTION SYSTEMS VIEW LOOKING EAST ON 4TH ST SHOWING REPLACEMENT OF STEAM AND
RETURN LINES BETWEEN BUILDINGS NOS 41 AND 131 ALLOT 7X218-35-1 YARD LABOR, 8560
IMPROVEMENT TO DISTRIBUTION SYSTEMS VIEW LOOKING EAST ON 4TH ST SHOWING REPLACEMENT OF STEAM AND
RETURN LINES BETWEEN BUILDINGS NOS 41 AND 131 ALLOT 7X218-35-1 YARD LABOR, 8561
IMPROVEMENT TO DISTRIBUTION SYSTEMS VIEW LOOKING NO ON MORRIS AVE FROM 4TH ST SHOWING NEW
ELECTRIC DUCTS AND MANHOLES FOR POWER DISTRIBUTION TO EXTENSION OF STRUCTURAL SHOP AND ALSO
RECONSTRUCTION OF STEAM LINES BLDGS NOS 41 TO 131 ALLOT 7X218-35-1 YARD LABOR, 8562
IMPROVEMENT TO DISTRIBUTION SYSTEMS VIEW LOOKING SOUTH ACROSS DOCK ST SHOWING NEW STEAM LINES
AND TRENCHES CONNECTING BUILDINGS NOS 41 AND 131 ALLOT 7X218-35-1 YARD LABOR, 8563
EXTENSION OF CRANE RUNWAYS SHIPWAYS 1 AND 2 GENERAL VIEW AT INBOARD END OF SHIPWAYS SHOWING

RELOCATED AND NEW WALKWAYS IN THE EXTENDED PORTIONS CONTRACT NOY 3242, 8564
COFFERDAMS FOR SHIPWAYS NO 2 INNER SECTION OF COFFERDAM BRACING ASSEMBLED AND READY FOR LAUNCHING CONTRACT NOY 3352, 8566
IMPROVEMENT OF DISTRIBUTING SYSTEMS INSTALLATION NEW SALT WATER HYDRANT NEAR BLDG 214 ALLOT 7X218-35-1A YARD LABOR, 8567
ADDITION TO STRUCTURAL SHOP BLDG 4 ELECTRIC AND MANHOLE MORRIS AVE BETWEEN 2ND AND 3RD ST ELECTRIC SERVICE TO STRUCTURAL SHOP ALLOTT 7X218-31-4 YARD LABOR, 8568
ADDITION TO STRUCTURAL SHOP BLDG NO 4 ELECTRIC MANHOLE MORRIS AVE AND 4TH ST FOR ELECTRIC SERVICE TO STRUCTURAL SHOP, 8569
IMPROVEMENT OF DISTRIBUTING SYSTEMS REPLACEMENT OF STEAM LINES BETWEEN C P PLANT AND BLDG 131 NEW DUCTS AND PIPE LINES SO OF BLDG 20 ON 4TH ST ALLOT 7X218-35-1A YARD LABOR_, 8570
IMPROVEMENT OF DISTRIBUTING SYSTEMS REPLACEMENT OF STEAM LINES BETWEEN C P PLANT AND BLDG NO 131 NEW DUCTS BETWEEN BLDG 20 AND 131 ON DOCK ST, 8571
IMPROVEMENT OF DISTRIBUTING SYSTEMS REMOVAL OF 4 INCH AIR LINE BETWEEN PIER G AND H ALLOT 7X218-35-1A YARD LABOR, 8572
IMPROVEMENT OF DISTRIBUTING SYSTEMS REMOVAL OF AIR LINES AND IMPROVEMENT OF CONCRETE TRENCH ON PIER 'G' ALSO INSTALLATION OF AC SYSTEM ON PIER ALLOT 7X218-35-1A, 8573
EXTENSION OF CRANE RUNWAYS SHIPWAYS 1 AND 2 NEW AND OLD STEEL ERECTION BETWEEN TOWER NO 26-25-24, 8576
EXTENSION OF CRANE RUNWAYS SHIPWAYS 1 AND 2 BETWEEN TOWER NO 26-27-15 OF WAYS NO 2 CONTRACT NOY 3242, 8577
IMPROVEMENT OF DISTRIBUTING SYSTEMS REPLACEMENT OF STEAM LINE TO BLDG 131 VIEW LOOKING TOWARD WEST END OF BLDG 131 APPN 7X218-35 YARD LABOR PROJECT, 8578
IMPROVEMENT OF DISTRIBUTING SYSTEMS REPLACEMENT OF STEAM LINE TO BLDG 131 VIEW LOOKING TOWARD SO EAST END OF BLDG 20 APPN 7X218-35 YARD LABOR PROJECT, 8579
IMPROVEMENT OF DISTRIBUTING SYSTEMS REPLACEMENT OF STEAM HEATING SERVICE TO BLDG NO 115 PIPE DUCT FOR HEATING RETURN AT NO END OF BLDG NO 6 APPN 7X218-35 YARD LABOR PROJECT, 8580
IMPROVEMENT OF DISTRIBUTING SYSTEMS REPLACEMENT OF STEAM HEATING SERVICE TO BLDG NO 115 PIPE DUCT FOR HEATING RETURN NORTH WEST CORNER OF BLDG 115 APPN 7X218-35 YARD LABOR PROJECT, 8581
EXTENSION OF ELECTRIC LINES TO WATER FRONT TELEPHONE DUCT ON PIER "G" LOOKING INBOARD APPN 7X218-35 YARD LABOR PROJECT, 8583
COFFERDAMS FOR SHIPWAYS NO 2 PARTIALLY FABRICATED TRUSS FOR BRACING COFFERDAM CONTRACT NOY 3352, 8584
COFFERDAMS FOR SHIPWAYS NO 2 VIEW SHOWING DRIVING IN OUTER COFFERDAM AND AND [sic] FLOATING CRANE REMOVING OLD TIMBER WAYS CONTRACT NOY 3352, 8585
EXTENSION OF CRANE RUNWAYS SHIPWAYS 1 AND 2 VIEW LOOKING EAST FROM WAYS NO 2 SHOWING ERECTION OF NEW AND REUSED STEELWORK ON TOWER NO 24 AND 26 FOREGROUND TOWER 24 AND 25 IN BACKGROUND CONTRACT NOY 3242, 8586
EXTENSION OF CRANE RUNWAYS SHIPWAYS 1 AND 2 ERECTION OF NEW AND REUSED STEEL WORK ON TOWER NO 15 AND 27 CONTRACT NOY 3242, 8587
EXTENSION OF CRANE RUNWAYS SHIPWAYS 1 AND 2 VIEW SHOWING ASSEMBLY OF TRANSVERSE TRUSS OVER PLATE RACKS AND ERECTION OF NEW AND REUSED STEEL WORK ON TOWER NO 24 AND 25 CONTRACT NOY 3242, 8588
EXTENSION OF CRANE RUNWAYS SHIPWAYS 1 AND 2 DAMAGE TO NORTH TRANSVERSE TRUSS – BROKEN WEST END CONTRACT NOY 3242, 8589
DREDGING NEAR BERTH 12 CONTRACT NOY 3362, 8591
CONSTRUCTION OF ELECTRIC MANHOLE EAST END OF FIFTH ST APPROPRIATION 7X218-32-3 YARD LABOR, 8592
IMPROVEMENT OF DISTRIBUTING SYSTEM APPROPRIATION 7X128-35-1A INSTALLATION OF STEAM AND CONDENSATION LINES BETWEEN BLDG 6 AND 115 VIEW LOOKING EAST ON 2ND ST FROM SO EAST CORNER OF BLDG NO 6 YARD LABOR, 8593
IMPROVEMENT OF DISTRIBUTING SYSTEM INSTALLATION STEAM AND CONDENSATION LINES AT BLDG 115 VIEW LOOKING EAST ON SECOND ST FROM SO WEST CORNER OF BLDG NO 115 APPN 7X218-35-1 YARD LABOR, 8594
IMPROVEMENT OF DISTRIBUTING SYSTEM APPROPRIATION 7X128-35-1A REMOVAL OF STEAM AND CONDENSATION LINES BETWEEN BUILDINGS 41 AND 131 VIEW SHOWS EXCAVATION FOR NEW STEAM TRENCH SOUTH OF BUILDING NO 120 YARD LABOR, 8595
DEMOLISHING GATE HOUSE BLDG NO 535 ON FLUSHING AVE AT BLDG NO 3 YARD LABOR, 8596
DREDGE AT BERTH 13 CONTRACT NOY 3362, 8597
COFFERDAM FOR SHIPWAYS NO 2 VIEW SHOWING PARTIAL FABRICATION OF LONGITUDINAL TRUSS CONTRACT NOY 3352, 8598
COFFERDAMS FOR SHIPWAYS NO 2 EXCVATING UNDERWATER AT END OF OLD SHIPWAYS CONTRACT NOY 3352, 8599
EXTENSION OF CRANE RUNWAYS SHIPWAYS NO 1 AND 2 VIEW OF NEW TOWER NO 21 AND CONVERSION OF B H WAYS CRANE WAY CONTRACT NOY 3242, 8601
EXTENSION OF CRANE RUNWAYS SHIPWAYS NO 1 AND 2 ERECTION OF NEW AND OLD STEELWORK BETWEEN TOWERS 24 AND 25 CONTRACT NOY 3242, 8603
EXTENSION OF CRANE RUNWAYS AND SHIPWAYS 1 AND 2 PREPARATION FOR REMOVAL OF CANTILEVER TRUSSES

AT CENTER OF WAYS NO 1 CONTRACT NOY 3242, 8604
VIEW SHOWING DEMOLITION OF BYUILDING 223 FORMER SUBSTATION NO 13 NEAR PIER G BY WPA LABOR, 8605
PEDESTALS FOR REMOVABLE ROOF OF NEW STRESS RELIEVING FURNACE BETWEEN DRY DOCKS 2 AND 3
FOUNDATIONS AND SERVICES BY YARD LABOR APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M FURNACE AND
EQUIPMENT BY CONTRACT 61000, 8606
GENERAL VIEW OF NEW WELDING SHED AT SEAWALL BETWEEN DRY DOCKS 1 AND 4 ALLOT 7X127-4-10 YARD LABOR,
8607
REPAIRS TO ELEVATOR NO 36 BLDG WAYS NO 2 CONTRACT NOY 3163, 8608
EXTENSION OF CRANERUNWAYS – SHIPWAYS 1 AN 2 VIEW OF B H HANDLING WAYS NO 2 TROLLEY WIRES CUT FOR
REMOVAL OF TRUSS BETWEEN TOWERS 15 AND 27 CONTACT [SIC] NOY 3242, 8609
EXTENSION OF CRANE RUNWAYS – SHIPWAYS NO 1 AND 2 – REMOVAL OF CANTILEVER TRUSSES EAST AND CENTER
LINE OF WAYS NO 1 CONTRACT NOY 3242, 8610
EXTENSION OF CRANE RUNWAYS – SHIPWAYS NO 1 AND 2 MONORAIL AND TRUSS REMOVED BETWEEN TOWERS NO
16 AND 26 LOW RUNWAY BENT USED AS TEMPORARY SUPPORT PENDING CONVERSION OF B H WAYS TRUSS AT
TOWER NO 26 CONTRACT NOY 3242, 8611
EXTENSION OF CRANE RUNWAYS – SHIPWAYS 1 AND 2 VIEW AT TOWERS NO 24 AND 25 SHOWING TRUSS REMOVED
NEW STEEL BENT IN PLACE AND TRUSS CONVERSION BETWEEN TOWERS NO 25 AND NO 30 CONTRACT NOY 3242,
8612
COLUMN FOUNDATIONS BLDGWAYS NO 1 ALLOT 7X218-34-7 YARD LABOR, 8613
REPAIRS TO ELEVATOR NO 36 BLDGWAYS NO 2 CONTRACT NOY 3163, 8614
NEW STRESS RELIEVING FURNACE NEAR SEAWALL BETWEEN DRY DOCKS 2 AND 3 FOUNDATIONS AND SERVICES BY
YARD LABOR APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M FURNACE EQUIPMENT BY CONTRACT 61000, 8615
NEW STRESS RELIEVING FURNACE NEW SEAWALL BETWEEN DRY DOCKS 2 AND 3 FOUNDATIONS AND SERVICES BY
YARD LABOR APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M FURNACE AND EQUIPMENT BY CONTRACT 61000,
8616
NEW STRESS RELIEVING FURNACE NEW SEAWALL BETWEEN DRY DOCKS 2 AND 3 FOUNDATIONS AND SERVICES BY
YARD LABOR APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M FURNACE AND EQUIPMENT BY CONTRACT 61000,
8617
ROLLER TRACK WELDMENT HOUSE NEAR HEAD END OF DRY DOCK # 2 ALLOT 7X127-4-10 YARD LABOR, 8618
ROLLER TRACK WELDMENT HOUSE NEAR HEAD END OF DRY DOCK 2 VIEW SHOWING TRANSFORMERS IN PLACE
ALLOT 7X127-4-10 YARD LABOR, 8620
VIEW OF ROLLER TRACK WELDMENT HOUSE NEAR HEAD END OF DRY DOCK 2 ALLOT 7X127-4-10 YARD LABOR, 8621
NEW STRESS RELIEVING FURNACE NEAR SEAWALL BETWEEN DRY DOCKS 2 AND 3 FOUNDATIONS AND SERVICES Y
YARD LABOR APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M FURNACE AND EQUIPMENT BY CONTRACT 61000
(VIEW SHOWING ELECTRIC FEED LINES), 8622
GENERAL VIEW OF FOOTINGS FOR WELDING SHED AT SEAWALL BETWEEN DRY DOCKS 1 AND 4 ALLOT 7X127-4-10
YARD LABOR, 8623
IMPROVEMENTS TO BLDG WAYS NO 1 GENERAL VIEW OF NEW WELDING PLATFORM EAST SIDE OF BLDG WAYS NO 1
ALLOT 7X127-1-9 YARD LABOR (LOOKING OUTBOARD), 8624
IMPROVEMENTS TO BLDG WAY NO 1 GENERAL VIEW OF NEW WELDING PLATFORM EAST SIDE OF BLDG WAYS NO 1
ALLOT 7X127-1-9 (LOOKING INBOARD), 8625
IMPROVEMENTS TO BLDG WAYS NO 1 GANTRY CRANE AT NEW WELDING PLATFORM EAST SIDE OF BLDG WAYS NO 1
ALLOT 7X127-1-9 YARD LABOR, 8626
FOOTINGS FOR ROLLER TRACK WELDMENT HOUSE NEAR HEAD END OF DRY DOCK NO 2 ALLOT 7X127-4-10 YARD
LABOR, 8627
GENERAL VIEW OF LOCATION OF NEW INCINERATOR WALLABOUT BASIN EAST SIDE OF TERMINAL BRIDGE ALLOT
78201-28 MATERIAL BY YARD LABOR BY WORKS PROGRESS ADMINISTRATION, 8629
FOUNDATION FORMS FOR NEW INCINERATOR EAST SIDE OF TERMINAL BRIDGE AT WALLABOUT BASIN ALLOT 78201-
28 MATERIAL BY YARD – LABOR BY WORKS PROGRESS ADMINISTRATION, 8630
TURRET FOUNDATIONS AT SEAWALL BETWEEN DRY DOCKS 1 AND 4 ALLOT 7X127-1-4 YARD LABOR, 8631
IMPROVEMENT TO BLDGWAYS NO 1 VIEW AT HEAD END EAST SIDE ALLOT 7X127 – A – 0400 – 7X127 – 3 – 3 YARD
LABOR, 8632
IMPROVEMENTS TO BLDGWAYS NO 1 NEW EXTENSION AT HEAD END ALLOT 7X127 – A – 0400 YARD LABOR, 8633
IMPROVEMENTS TO BLDGWAYS NO 1 GENERAL VIEW OF NEW WELDING PLATFORM EAST SIDE OF BLDGWAYS NO 1
ALLOT 7X127 – 1 – 9 YARD LABOR (VIEW LOOKING INBOARD), 8635
IMPROVEMENT BLDGWAYS NO 1 GENERAL VIEW OF NEW WELDING PLATFORM EAST SIDE OF BLDGWAYS NO 1 ALLOT
7X127 – 1 – 9 YARD LABOR (LOOKING OUTBOARD), 8636
REPAIRS TO SEAWALL BETWEEN PIERS G AND H ALLOT 78201 – 30 MATERIAL BY YARD – LABOR BY WORKS
PROGRESS ADMINISTRATION, 8637
REPAIRS TO SEAWALL BETWEEN PIERS G AND H ALLOT 78201 – 30 MATERIAL BY YARD – LABOR BY WORKS
PROGRESS ADMINISTRATION (VIEW LOOKING OUTBOARD), 8638
REPAIRS TO SEAWALL BETWEEN PIERS G AND H ALLOT 78201 – 30 MATERIAL BY YARD – LABOR BY WORKS
PROGRESS ADMINISTRATION (VIEW LOOKING SO WEST), 8639
REPAIRS TO SEAWALL BETWEEN PIERS G AND H ALLOT 78201 – 30 MATERIAL BY YARD – LABOR BY WORKS
PROGRESS ADMINISTRATION (VIEW LOOKING SO EAST), 8640

IMPROVEMENTS TO BLDGWAYS GENERAL VIEW OF WELDING PLATFORM LOCATION EAST SIDE OF BLDGWAYS NO 1 ALLOT 7X127 – 1 – 8 YARD LABOR, 8642

IMPROVEMENTS TO BLDGWAYS NO WIDENING OF WORKING PLATFORM EAST SIDE OF BLDGWAYS ALLOT 7X127 – 3 – 3 YARD LABOR, 8643

TURRET FOUNDATIONS BETWEEN DRY DOCKS 1 AND 4 NEAR SEA WALL ALLOT 7X127 – 1 – 4 YARD LABOR, 8644

GENERAL VIEW OF TURRET FOUNDATIONS AT SEA WALL BETWEEN DRY DOCK NO 1 AND 4 ALLOT 7X127 – 1 – 4 YARD LABOR (VIEW LOOKING INBOARD), 8645

NEW STRESS RELIEVING FURNACE NEAR SEAWALL BETWEEN DRY DOCK 2 AND 3 INTERIOR VIEW FOUNDATIONS AND SERVICES BY YARD LABOR APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M FURNACE AND EQUIPMENT BY CONTRACT 61000, 8646

NEW STRESS RELIEVING FURNACE NEAR SEAWALL BETWEEN DRY DOCK 2 AND 3 INTERIOR VIEW FOUNDATIONS AND SERVICES BY YARD LABOR APPN 7X127 REPLACEMENT NAVAL VESSELS C AND M FURNACE AND EQUIPMENT BY CONTRACT 61000, 8647

GENERAL VIEW OF NEW WELDING SHED AT SEAWALL BETWEEN DRY DOCKS 1 AND 4 LOOKING NO WEST ALLOT 7X127-4-10 YARD LABOR, 8648

STEE [SIC] FRAMEWORK AND SIDING OF NEW WELDING SHED AT SEAWALL BETWEEN DRY DOCKS 1 AND 4 ALLOT 7X127 – 4 – 10 YARD LABOR, 8649

VIEW OF ROLLER TRACK WELDMENT HOUSE NEAR HEAD END OF DRY DOCK NO 2 ALLOT 7X127 – 4 – 10 YARD LABOR, 8650

REPAINTING 250 FOOT RADIO TOWERS THIS TOWER AT EAST END OF BLDG NO 5 AND 8TH ST VIEW LOOKING NO ON 8TH ST ALLOT 79601 – 2 – 12 YARD LABOR, 8651

NEW STRESS RELIEVING FURNACE NEAR SEAWALL BETWEEN DRY DOCKS 2 AND 4 FOUNDATIONS AND SERVICES BY YARD LABOR APPN – 7X127 REPLACEMENT NAVAL VESSELS C AND M FURNACE AND EQUIPMENT BY CONTRACT 61000, 8653

STEEL FRAMEWORK AND SIDEING [SIC] OF NEW WELDING SHED AT SEAWALL BETWEEN DRY DOCKS NO 1 AND 4 ALLOT 7X127 – 4 – 10 YARD LABOR, 8654

INTERIOR OF ROLLER TRACK WELDMENT HOUSE NEAR HEAD END OF DRY DOCK 2 ALLOT 7X127 – 4 – 10 YARD LABOR, 8655

VIEW OF ROLLER TRACK WELDMENT HOUSE NEAR HEAD END OF DRY DOCK 2 A LOT 7X127 – 4 – 10 YARD LABOR, 8656

MOTOR GENERATOR HOUSE AND SUPPORTING STRUCTURE BETWEEN BLDGWAYS 1 AND 2 GENERAL VIEW CONTRACT NOY 3059, 8657

MOTOR GENERATOR HOUSE AND SUPPORTING STRUCTURE BETWEEN BLDGWAYS 1 AND 2 INTERIOR VIEW LOOKING WEST CONTRACT NOY 3059, 8658

EXTENSION TO DRY DOCK 4 GENERAL VIEW LOOKING NORTH ON MORRIS AVE ALLOT 7X218 – 1 YARD LABOR, 8659

EXTENSION TO DRY DOCK 4 GENERAL VIEW LOOKING SO ON MORRIS AVE ALLOT 7X218 – 1 YARD LABOR, 8661

GENERAL VIEW OF STEEL FRAME WORK FOR WELDING SHED AT SEA WALL BET DRY DOCKS 1 AND 4 ALLOT 7X127 – 4 – 10 YARD LABOR, 8665

PAINTING RADIO TOWERS VIEW ON FLUSHING AVE BET BLDGS NO 30 - 92, 8666

TURRET ANNEALING PLANT NEAR SEA WALL BETWEEN DRY DOCKS 2 AND 3 GENERAL VIEW AND DRIVING PILES YARD LABOR, 8667

EXTENSION OF DRY DOCK 4 GENERAL VIEW ON MORRIS AVE LOOKING WEST ALLOT 7X218 – 29 – 1 YARD LABOR, 8669

RELOCATING ELECTRIC CABLES ON MORRIS AVE IN WAY OF DRY DOCK 4 EXTENSION ALLOT 7X218 – 29 – 1 YARD LABOR, 8670

EXTENSION OF DRY DOCK 4 RELOCATING ELECTRIC CABLES ON MORRIS AVE THAT ARE IN THE WAY ALLOT 7X218 – 29 – 1 YARD LABOR, 8671

GENERAL VIEW OF FOUNDATIONS FOR WELDING SHED AT SEA WALL BETWEEN DRY DOCKS 1 AND 4 ALLOT 7X127 – 4 – 10 YARD LABOR, 8672

EXTENSION OF ELECTRIC DISTRIBUTING SYSTEM TO WATER FRONT VIEW LOOKING EAST BERTH 6 ALLOT 7X351 – 2 – 2 – A YARD LABOR, 8674

EXTENSION OF ELECTRIC DISTRIBUTING SYSTEM TO WATER FRONT VIEW OF PIER 'H' ALLOT 7X351 – 2 – 2 – A YARD LABOR, 8675

EXTENSION OF ELECTRIC DISTRIBUTING SYSTEM TO WATER FRONT VIEW LOOKING OUTBOARD PIER G ALLOT 7X351 – 2 – 2A YARD LABOR, 8676

STEEL FRAME AND SIDING FOR ROLLER TRACK WELDMENT HOUSE NEAR HEAD END OF DRY DOCK 2 ALLOT 7X127 – 4 – 10 YARD LABOR, 8677

STEEL FRAME AND SIDING FOR ROLLER TRACK WELDMENT HOUSE NEAR HEAD END OF DRY DOCK 2 ALLOT 7X127 – 4 – 10 YARD LABOR, 8678

ADDITIONAL WELDING FACILITIES ELECTRIC CABLES TO NEW MOTOR GENERATOR HOUSE ON SHIPWAYS ALLOT 7X127 – 1 – 9 YARD LABOR, 8679

MOTOR GENERATOR HOUSE AND SUPPORTING STRUCTURE VIEW LOOKING NORTH SHOWING PLACING OF CORRUGATED ROOFING CONTRACT NOY 3058, 8680

MOTOR GENERATOR HOUSE AND SUPPORTING STRUCTURE BETWEEN BLDGWAYS 1 AND 2 VIEW LOOKING UP SHOWING REMOVAL OF FORMWORK OF FLOOR ARCHES CONTRACT NOY 3058, 8681

MOTOR GENERATOR HOUSE AND SUPPORTING STRUCTURE BETWEEN [SIC] BLDGWAYS 1 AND 2 GENERAL VIEW

LOOKING EAST CONTRACT NOY 3058, 8682
EXTENSION TO DRY DOCK NO 4 EXCAVATING ON MORRIS AVE AT BLDG 41 ALLOT 7X218 – 29 – 1 YARD LABOR, 8683
TURRET ANNEALING PLANT NEAR SEA WALL BETWEEN DRY DOCKS 2 AND 3 VIEW LOOKING INBOARD (YARD LABOR), 8684
IMPROVEMENTS TO BLDGWAYS NO 1 GANTRY CRANE CRANE [SIC] AT NEW WELDING PLATFORM EAST SIDE OF BLDGWAYS NO 1 ALLOT 7X127 – 1 – 9 YARD LABOR, 8685
MOTOR GENERATOR HOUSE AND SUPPORTING STRUCTURE BETWEEN BLDGWAYS 1 AND 2 VIEW SHOWING STEEL FRAMING INCLUDING INCLUDING [SIC] GENERATOR HOUSE CONTRACT NOY 3058, 8687
MOTOR GENERATOR HOUSE AND SUPPORTING STRUCTURE BETWEEN BLDGWAYS 1 AND 2 VIEW SHOWING TYPICAL CONECTION [SIC] BETWEEN NEW COLUMN AND EXISTING TOWER COLUMN CONTRACT NOY 3058, 8688
MOTOR GENERATOR HOUSE AND SUPPORTING STRUCTURE BETWEEN BLDGWAYS 1 AND 2 VIEW SHOWING WOOD RAMP AND RAILING CONTRACT NOY 3058, 8689
MOTOR GENERATOR HOUSE AND SUPPORTING STRUCTURE VIEW FROM PLATFORM OF NO 1 WAYS FOOTINGS FOR STEEL COLUMNS AT TOWER NO 5 BETWEEN SHIPWAYS 1 AND 2 CONTRACT NOY 3058, 8690
CLOSE UP VIEW OF REINFORCEMENT OF FOOTINGS FOR WELDING SHED AT SEAWALL BETWEEN DRY DOCKS 1 AND 4 ALLOT 7X127 – 4 – 10 YARD LABOR, 8691
DRIVING PILES AND FORM WORK FOR TURRET FOUNDATIONS AT SEA WALL BET DRY DOCKS 1 AND 4 ALLOT 7X127-1-4 YARD LABOR, 8692
ADDITION TO STRUCTURAL SHOP BLDG NO 4 VIEW SHOWING EXCAVATION FOR ARMOR PIT PLANER AND ELEVATION OF GROUND WATER AT SITE ALLOT 17X1218 031-2 YARD LABOR, 8694
ADDITION TO STRUCTURAL AND ACCESSORIES BLDG NO 4 EXCAVATION FOR ARMOR PIT PLANER FOUNDATION ALLOT 17X1218 031-1 YARD LABOR, 8695
ADDITION TO STRUCTURAL SHOP AND ACCESSORIES ARMOR PIT PLANER FOUNDATION SHOWING PENETRATION OF 25' FLUTED PILES FOR MIN CAP 35 KIPS YARD LABOR ALLOT 17X1218 031-2, 8696
ADDITION TO STRUCTURAL + ACCESSORIES ARMOR PIT PLANER FOUNDATION BLDG NO 4 ALLOT 17X1218 031-1 YARD LABOR, 8697
EXTENSION TO STRUCTURAL SHOP BLDG # 4 AND FOUNDRY ROOF AND PENTHOUSE BLDG # 4 EXT CONTRACT NOY 4731, 8698
ADDITION TO STRUCTURAL SHOP BLDG NO 4 VIEW LOOKING SOUTHEAST OF SECOND FLOOR FRAMING AND BRACING CONTRACT NOY 4731, 8699
ADDITION TO STRUCTURAL SHOP BLDG NO 4 GENERAL VIEW LOOKING SOUTHEAST CONTRACT NOY 4731, 8701
ANNEX TO BUILDING NO 4 VIEW LOOKING SW OF EXCAVATION ON SITE CONTRACT NOY 4731, 8702
ADDITIONS TO STRUCTURAL SHOP + ACCESSORIES BLDG NO 4 REPAIRS TO ROLLING DOOR E SIDE N CORNER ALLOT 17X 1218 031-2, 8703
STRUCTURAL SHOP BLDG NO 4 REPAIR OF ROLLING DOOR AT NORTHWEST CORNER ALLOT 1711201-1A YARD LABOR, 8704
ADDITION OF STRUCTURAL SHOP AND ACCESSORIES REPAIRS TO RETAINING WALL AND BUTTRESSES W SIDE OF 4 BLDG NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8705
PAVING IN BLDG NO 4 NEAR PLANER FOUNDATION ALLOT 7X218-31-2 YARD LABOR, 8706
ADDITION OF STRUCTURAL SHOP AND ACCESSORIES REPAIRS TO RETAINING WALL AND BUTTRESSES W SIDE OF 4 BLDG EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8707
EXTENSION STRUCTURAL SHOP AND MOLD LOFT BLDG COMPLETED IN 1939 EQUIPMENT IN PROGRESS, 8708
NEW SCALE IN NEW ADDITION OF STRUCTURAL SHOP BLDG NO 4 BU C AND R YARD LABOR, 8709
ADDITION OF STRUCTURAL SHOP BLDG NO 4 AND ACCESSORIES REPAIRS TO RETAINING WALL AND BUTTRESSES WEST SIDE OF NEW ADDITION, 8711
ADDITION OF STRUCTURAL SHOP BLDG NO 4 AND ACCESSORIES SIDEWALKS – PAVING AND TRACK WORK SO SIDE OF NEW ADDITION ALLOT 7X218-31-2 YARD LABOR, 8712
ADDITION OF STRUCTURAL SHOP AND ACCESSORIES PAVING AND TRACK WORK WEST SIDE OF NEW ADDITION TO BLDG NO 4 ALLOT 7X218-31-2, 8713
ADDITION OF STRUCTURAL SHOP AND ACCESSORIES RR TRACK WORK SO SIDE OF NEW EXTENSION OF BLDG NO 4 ALLOT 7X218-31-2 YARD LABOR, 8714
ADDITION OF STRUCTURAL SHOP AND ACCESSORIES PAVING AND TRACK WORK SOUTH SIDE OF NEW ADDITION TO BLDG NO 4 ALLOT 7X218-31-2, 8715
ADDITION OF STRUCTURAL SHOP AND ACCESSORIES PAVING SIDEWALK ON SOUTH SIDE OF NEW EXTENSION OF BLDG NO 4 ALLOT 7X218-31-2 YARD LABOR, 8718
ADDITION OF STRUCTURAL SHOP LAYING PAVING BLOCKS IN NEW ADDITION OF BLDG NO 4 – ALLOT 7X218-31-2 YARD LABOR, 8719
ADDITION OF STRUCTURAL SHOP AND ACCESSORIES MACHINE FOUNDATION IN NEW ADDITION TO BLDG NO 4 ALLOT 7X218-31-2 YARD LABOR, 8720
ADDITION OF STRUCTURAL SHOP BLDG NO 4 AND ACCESSORIES UNDERPINING [SIC] AND BRACING OF RETAINING WALL WEST SIDE OF NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8721
ADDITION OF STRUCTURAL SHOP BLDG NO 4 AND ACCESSORIES PAVING OUTSIDE NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8722
ADDITION OF STRUCTURAL SHOP BLDG NO 4 AND ACCESSORIES LAYING RAILROAD TRACK OUTSIDE OF NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8723

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES BUILDING FORMS FOR MACHINE FOUNDATION IN NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8724

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES BLOCK PAVING INSIDE NEW EXTENSION OF 4 BLDG ALLOT 7X218-31-2 YARD LABOR, 8725

ADDITION OF STRUCTURAL SHOP BLDG NO 4 AND ACCESSORIES POURING CONCRETE PAVING IN NEW EXTENSION TO BLDG NO 4 ALLOT 7X218-31-2 YARD LABOR, 8726

ADDITION OF STRUCTURAL SHOP BLDG NO 4 AND ACCESSORIES RETAINING WALL AND BUTTRESSES WEST OF NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8727

NEW EXTENSION TO BLDG NO 4 NEW FREIGHT ELEVATOR CAR COMPACTY [SIC] 10000 LBS CONTRACT NOY 3429 (COMPLETE), 8728

NEW EXTENSION TO BLDG NO 4 NEW FREIGHT AND PASANGER [SIC] ELEVATOR CAR CAPACITY 6000 LBS CONTRACT NOY 3429 (COMPLETE), 8729

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES PAVING ON PARK AVE NEAR BLDG NO 15 ALLOT 7X218-31-2 YARD LABOR, 8730

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES NEW RETAINING WALL AND BUTTRESSES ALLOT 7X218-31-2 YARD LABOR, 8731

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES LAYING OF NEW DRAIN LINES ON 1ST STREET OUTSIDE OF BLDG NO 4 ALLOT 7X218-31-2 YARD LABOR, 8733

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES LAYING RR TRACK INSIDE NEW EXTENSION OF BLDG NO 4 ALLOT 7X218-31-2 YARD LABOR, 8734

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES FOUNDATION FOR BENDING SLAB IN NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8735

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES CONSTRUCTION OF R ROAD AND PAVING SO SIDE OF NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8736

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES PAVING AND DRAINS SO SIDE OF NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8737

EXTENSION TO BLDG NO 4 25 AND 40 TON BRIDGE CRANES ON RAILS CONTRACT NOY 3426, 8738

EXTENSION TO BLDG NO 4 RAISING BRIDGE GIRDERS OF 40 TON BRIDGE CRANE ALLOT 7X218-31-2 YARD LABOR, 8739

EXTENSION TO BLDG NO 4 RAISING BRIDGE GIRDER OF 25 TON BRIDGE CRANE ALLOT 7X218-31-2 YARD LABOR, 8740

EXTENSION TO BLDG NO 4 VIEW OF ENTRY TO TRIANGLE BUILDING ON 2ND STREET CONTRACT NOY 3272, 8741

EXTENSION TO BLDG NO 4 VIEW OF SECOND FLOOR SHOWING FISSURES IN CONCRETE TOPPING FINISH CONTRACT NOY 3272, 8742

EXTENSION TO BLDG NO 4 VIEW OF HOT WATER HEATER AND PIPING WORK INCLUDING FRESH WATER RISER CONTRACT NOY 3272, 8743

EXTENSION TO BLDG NO 4 SOUTH ELEVATION AS VIEWED LOOKING EASTWARD ON 2ND ST CONTRACT NOY 3272, 8744

EXTENSION TO BLDG NO 4 VIEW IN TOILET ON 2ND FLOOR SHOWING CONDUIT RUNS FOR ELECTRICAL DISTRIBUTION CONTRACT NOY 3272, 8745

EXTENSION TO BLDG NO 4 VIEW OF LOW TENSION POWER AND LIGHTING SWITCHBOARD CONTRACT NOY 3272, 8746

EXTENSION TO BLDG NO 4 VIEW OF TRANSFORMERS AND CUBICLES CONTRACT NOY 3272, 8747

EXTENSION TO BLDG NO 4 VIEW SHOWING SLIDING DOOR OPERATING MECHANISM FOR DOOR NO D-8 CONTRACT NOY 3272, 8748

EXTENSION TO BLDG NO 4 VIEW ON 5TH FLOOR LOOKING WEST CONTRACT NOY 3272, 8749

EXTENSION TO BLDG NO 4 GENERAL VIEW IN MOLD – LOFT LOOKING WEST CONTRACT NOY 3272, 8750

EXTENSION TO BLDG NO 4 VIEW ON 4TH FLOOR LOOKING SO WEST CONTRACT NOY 3272, 8751

EXTENSION TO BLDG NO 4 URINAL FIXTURES AND WASH FOUNTAIN IN SECOND FLOOR TOILET ROOM CONTRACT NOY 3272, 8752

ADDITION OF STRUCTURAL SHOP NEW RETAINING WALL AND BUTTRESSES ALLOT 7X218-31-2 YARD LABOR, 8753

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES PAVING ON SOUTHSIDE OF NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8754

ADDITION OF STRUCTURAL SHOP MACHINE FOUNDATIONS INSIDE NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8755

REPAIRS TO DOOR 'F' BUILDING NO 4 ALLOT 70201-1 YARD LABOR, 8757

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES – TRACK WORK IN NEW NEW [SIC] EXTENSION – ALLOT 7X218-31-2 YARD LABOR, 8758

ADDITION TO STRUCTURAL SHOP ACCESSORIES MACHINE FOUNDATIONS INSIDE NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8759

ADDITION OF STRUCTURAL SHOP AND ACCESSORIES MACHINE FOUNDATION INSIDE OF NEW EXTENSION ALLOT 7X218-31-2 YARD LABOR, 8760

EXTENSION TO BLDG NO 4 NEW FINISHED FLOOR IN MOLD LOFT CONTRACT NOY 3272, 8761

EXTENSION TO BLDG NO 4 VIEW SHOWING MOLD LOFT FLOORING AND WOOD BASE AT NORTH WALL CONTRACT NOY 3272, 8762

EXTENSION TO BLDG O 4 VIEW AT STEAM PIT SHOWING VACUUM PUMP (RIGHT) AND CONTROL PANEL (LEFT) CONTRACT NOY 3272, 8763

EXTENSION TO BLDG NO 4 VIEW SHOWING INSTALLATION OF TRANSFORMERS AND BUS CONNECTIONS CONTRACT NOY 3272, 8764

EXTENSION TO BLDG O 4 VIEW AT NO WEST CORNER SHOWING FIRST FLOOR TOILET AND ENTRANCE TO FREIGHT ELEVATOR CONTRACT NOY 3272, 8765
EXTENSION TO BLDG NO 4 VIEW OF SOUTH ELEVATION FROM 2ND STREET CONTRACT NOY 3272, 8766
EXTENSION TO BLDG O 4 VIEW SHOWING STEEL SLIDING DOORS AT 2ND STREET LOOKING NORTHWARD CONTRACT NOY 3272, 8767
EXTENSION TO BLDG NO 4 LOW TENSION AND LIGHTING SWITCHBOARD CONTRACT NOY 3272, 8768
EXTENSION TO BLDG O 4 VIEW OF SOUTH AND EAST ELEVATION LOOKING EAST ON 2ND ST CONTRACT NOY 3272, 8769
EXTENSION TO BLDG 4 VIEW AT WEST ELEVATION SHOWING VERTICAL LIFT DOORS D – 2 AND D – 3 CONTRACT NOY 3272, 8770
EXTENSION TO BLDG 4 SUBSURFACE STEAM LINES TO NEW EXTENSION LOOKING SOUTH ON 2ND ST CONTRACT NOY 3272, 8771
EXTENSION TO BLDG 4 VIEW FINISH FLOORING IN MOLD LOFT LOOKING SO EAST FROM LINEE CONTRACT NOY , 8772
EXTENSION TO BLDG 4 VIEW AT WEST ELEVATION SHOWING VERTICAL LIFT DOOR D – 3 CONTRACT NOY 3272, 8774
EXTENSION TO BLDG NO 4 INTERIOR OF TOILET ROOM FIRST FLOOR CONTRACT NOY 3272, 8775
EXTENSION TO BLDG 4 TOILET ROOM 2ND FLOOR AT NO WEST CORNER CORNER [SIC] CONTRACT NOY 3272, 8776
EXTENSION TO BLDG NO 4 VIEW SHOWING THE PLACING OF STEEL SLIDING DOOR D – 8 CONTRACT NOY 3272, 8777
EXTENSION TO BLDG 4 VIEW OF TOILET ON 6TH FLOOR NO EAST CORNER CONTRACT NOY 3272, 8779
EXTENSION TO BLDG 4 NEW MACHINE FOUNDATIONS ALLOT 7X218 – 31 – 2 YARD LABOR, 8780
IMPROVEMENTS CENTRAL POWER PLANT NEW 5000 CFM AIR COMPRESSOR FOUNDATIONS FLOOR CHANGES AND MODIFICATION OF PIPING ALLOT 7X218 - 30 - 7 YARD LABOR , 8783
EXTENSION TO BLDG NO 4 FOUNDATION FOR BENDING PLATFORM IN NEW EXTENSION ALLOT 7X218 – 31 – 2 YARD LABOR, 8784
EXTENSION OF BLDG NO 4 FORM FOR PLANER FOUNDATION ALLOT 7X218 – 31 – 2 YARD LABOR, 8785
EXTENSION OF BLDG NO 4 PLACING OF STEEL FOR WELDING SLAB IN NEW EXTENSION ALLOT 218 – 31 – 2 YARD LABOR, 8786
EXTENSION TO BLDG NO 4 VIEW OF ROOF LOOKING EAST SHOWING ROOF VENTILATORS AND SKYLIGHTS CONTRACT NOY 3272, 8787
EXTENSION OF BLDG NO 4 VIEW SHOWING INSTALLATION ON URINAL FIXTURES IN FIRST FLOOR TOILET ROOM CONTRACT NOY 3272, 8788
EXTENSION OF BLDG NO 4 MACHINE ROOM OF ELEVATOR NO 1 CONTRACT NOY 2429, 8789
EXTENSION OF BLDG NO 4 VIEW OF SOUTH AND EAST ELEVATION LOOKING EAST ON SECOND ST CONTRACT NOY 3272, 8791
EXTENSION OF BLDG NO 4 INSTALLATION OF UNIT HEATERS ON LINE “E” CONTRACT NOY 3272, 8792
EXTENSION OF BLDG NO 4 VIEW LOOKING SOUTH SHOWING OUTSIDE STEAM TRENCH CONTRACT NOY 3272, 8793
EXTENSION OF BLDG NO 4 VIEW LOOKING WEST IN 2ND FLOOR TOILET SHOWING METAL PARTITIONS AND CONDUIT RUNS FOR ELECTRICAL POWER DISTRIBUTION CONTRACT NOY 3272, 8794
EXTENSION OF BLDG NO 4 VIEW OF INSTALLATION OF STAND PIPE AND SPRINKLER SYSTEM RISER PIPING ADJACENT TO DOOR “D” 7 CONTRACT NOY 3272, 8796
EXTENSION OF BLDG 4 VIEW OF HOT WATER HEATER FRESH WATER METER AND PIPING FOR STAND PIPE AND SPRINKLER SYSTEMS ON FIRST FLOOR OF TRIANGLE BLDG CONTRACT NOY 3272, 8797
EXTENSION OF BLDG NO 4 VIEW ON 6TH FLOOR OF TRIANGLE BLDG AT S EAST CORNER CONTRACT NOY 3272, 8798
EXTENSION OF BLDG NO 4 VIEW N 2ND FLOOR OD TRIANGLE BUILDING SHOWING INSTALLATION OF URINAL FIXTURES ON WEST WALL WITH WASH FOUNTAIN IN THE FOREGROUND CONTRACT NOY 3272, 8799
EXTENSION TO BLDG 4 FREIGHT ELEVATOR – ELEVATOR MACHINE – LEVELING PANEL AND CONTROL BOARD ON PLACE CONTRACT NOY 3429, 8800
EXTENSION TO BLDG 4 PASSENGER ELEVATOR – ELEVATOR MACHINE – SELECTOR LEVELING PANEL AND CONTROL BOARD N PLACE CONTRACT NOY 3429, 8801
ADDITION TO STRUCTURAL SHOP BLDG 4 FOUNDATION OF BENDING SLAB N NEW EXTENSION VIEW LOOKING NORTH ALLOT 7X218 – 31 – 2 YARD LABOR, 8802
ADDITION TO STRUCTURAL SHOP BLDG 4 FOUNDATION FOR 35’ HEAVY DUTY PLANER VIEW LOOKING SO EAST ALLOT 7X218 – 31 – 2 YARD LABOR, 8803
ADDITION TO STRUCTURAL SHOP BLDG 4 FOUNDATION OF WELDING SLAB IN NEW EXTENSION VIEW LOOKING NO EAST ALLOT 7X218 – 31 – 2 YARD LABOR, 8804
ADDITION TO STRUCTURAL SHOP BLDG 4 FOUNDATION OF LEVELING TABLE IN NEW EXTENSION VIEW LOOKING SO WEST ALLOT 7X218 – 31 – 2 YARD LABOR, 8805
EXTENSION TO BLDG 4 VIEW OF FIRE PROOF STEEL CLAD DOORS AR CROSSOVER BRIDGE IN MOLD LOFT CONTRACT NOY 3272, 8806
EXTENSION OF BUILDING 4 VIEW AT SOUTH WALL WINDOWS IN MOLD LOFT SHOWING SASH OPERATOR GLAZING AND LIGHTING INSTALLATION CONTRACT NOY 3272, 8807
EXTENSION OF BUILDING NO 4 VIEW SHOWING GLAZED TILE WORK AND PLUMBING FIXTURES IN 2ND FLOOR TOILET ROOM CONTRACT NOY 3272, 8808
EXTENSION TO BUILDING 4 LOOKING WEST BETWEEN LINES D AND E FROM THE 5TH FLOOR OF TRIANGLE BUILDING SHOWING CONDUITS PIPING WORK AND VENTILATOR DUCT INSTALLATION IN LOWER TRUSSES CONTRACT NOY 3272, 8809

EXTENSION TO BUILDING NO 4 VIEW ON ROOF LOOKING NO EASTWARD SHOWING BUILT UP ROOFING ON PITCH AND DECK ROOFS CONTRACT NOY 3272, 8810

EXTENSION TO BUILDING NO 4 VIEW ON ROOF AT VALLEY BETWEEN GABLES SHOWING THE PLACING OF SLAG AROUND SKYLIGHTS CONTRACT NOY 3272, 8811

EXTENSION TO BUILDING NO 4 VIEW OF GABLE WALL AT NO WEST CORNER OF NEW EXTENSION CONTRACT NOY 3272, 8812

EXTENSION TO BUILDING NO 4 EAST ELEVATION LOOKING SOUTH ON 2ND ST CONTRACT NOY 3272, 8813

EXTENSION TO BUILDING NO 4 VIEW IN 2ND FLOOR TOILET ROOM SHOWING CONDUIT RUN FOR POWER DISTRIBUTION THROUGH FLOOR AND WEST WALL CONTRACT NOY 3272, 8814

EXTENSION TO BUILDING NO 4 TRENCH EXCAV FOR STEAM LINE TO NEW EXTENSION SHOWING PLACING OF FORM WORK FOR THE CONCRETE MATTRESS CONTRACT NOY 3272, 8815

US...ARINE "THE INTELLIGENT WHALE", 8816

BLDG #4 EXT TOILET – SHOWING WC PARTITIONS FOUNTAIN – VENTILATING SYSTEM CONTRACT NOY 4731, 8818

MISCELLANEOUS SHIPBUILDING FACILITIES OIL TANK AND HOUSING AT OUTBOARD END OF PIER C ALLOT 17X1375 - 5, 8819

MATERIAL TESTING LABORATORY – BLDG #291 LOOKING NE FROM FLUSHING & WASHINGTON AVES SHOWING PILE CAPS & DRIVERS CONTRACT NOY 4731, 8820

BLDG #4 EXT 1ST FL GENERAL OFFICE SHOWING VENT DUCT SYSTEM CONTRACT NOY 4731, 8821

EXTENSION TO BLDG NO 4 VIEW OF NORTH WALL BRICK WORK FROM ROOF OF EXISTING BUILDING CONTRACT NOY 3272, 8822

EXTENSION TO BLDG NO 4 VIEW LOOKING WEST FROM 3RD FLOOR OF TRIANGLE BUILDING BEWTEEN LINES D AND E CONTRACT NOY 3272, 8823

EXTENSION TO BLDG NO 4 CONCRETE FLOOR ARCHES AND BRICK ENCLOSING WALL OF TRIANGLE BUILDING AS VIEWED LOOKING WEST ON SECOND ST CONTRACT NOY 3272, 8824

EXTENSION TO BLDG NO 4 ERECTION OF NEW STEELWORK ROLLING DOORS REMOVED AT BENTS 21 – 22 – 23 ONLINE "F" CONTRACT NOY 3272, 8826

EXTENSION TO BLDG NO 4 VIEW OF TRIANGLE BUILDING ADJOINING EXISTING STRUCTURAL SHOP AT SOUTH ELEVATION CONTRACT NOY 3272, 8828

EXTENSION TO BLDG NO 4 ERECTION OF TRIANGLE BUILDING STEELWORK INSTALLATION OF STAIRS AND FORMWORK FOR CONCRETE FLOOR SLABS CONTRACT NOY 3272, 8829

EXTENSION TO BLDG NO 4 VIEW OF TRIANGLE SECTION AT SO WEST OF EXISTING BUILDING CONTRACT NOY 3272, 8830

EXTENSION TO BLDG NO 4 TRIANGLE AECTION STEEL WORK ERECTION AS VIEWED FROM CHAUNCEY AVE AT SECOND ST CONTRACT NOY 3272, 8831

EXTENSION TO BLDG NO 4 VIEW OF ERECTION OF 1ST DIVISION STEEL WORK FOR THE TRIANGULAR BUILDING CONTRACT NOY 3272, 8832

EXTENSION TO BLDG NO 4 VIEW OF ERECTION OF 1ST DIVISION STEEL WORK FOR THE TRIANGULAR BUILDING CONTRACT NOY 3272, 8833

EXTENSION TO BLDG NO 4 VIEW SHOWING ERECTION OF 1ST DIVISION STEEL WORK FOR THE TRIANGULAR BUILDING CONTRACT NOY 3272, 8834

PRINTING AND REPAIRING WINDOW FRAMES AND DOORS EXTERIOR OF STRUCTURAL SHOP BLDG NO 4 ALLOT 77201 – 20 YARD LABOR, 8836

EXTENSION TO BLDG 4 STEEL SUPPORTING MEMBERS FOR BENDING SLAB ALLOT 703 / 5640 1 – 33 - 5 YARD LABOR, 8837

STORMDOORS TO BLDG 4 ALLOT 74201 - 1 YARD LABOR, 8838

REPAIRING STUCCO ON WALLS OF BLDG NO 4 ALLOT 72201 – 46 YARD LABOR, 8839

REPAIRS TO STUCCO WORK BLDG 4 ALLOT 79201 - -12 YARD LABOR, 8840

REPAIRS TO CEMENT ON WALLS OF BUILDING # 4 ALLOT 78201 -12 YARD LABOR, 8841

REPAIRS TO STUCCO WORK BLDG 4 ALLOT 79201 - 12 YARD LABOR, 8842

REPAIRS TO STUCCO WORK BLDG 4 ALLOT 79201 - 12 YARD LABOR, 8843

HOLES IN TILE NORTH WALL BLDG 4, 8844

STEAL ROLLING DOORS BLDG # 4 CONTRACT NO 9162 CORNELL IRION WORKS, 8845

CONTROL ROOM SPRINKLE SYSTEM BLDG 4 EXTENSION ON CONTRACT NO 9231 HG VOGEL CO, 8846

REPAIRS TO CEMENT ON WALLS OF BUILDING # 4 ALLOT 78201-12 YARD LABOR, 8847

INSTALATION OF NEW SPRINKLER SYSTEM IN BLDG # 4 MOLD LOFT CENT # 5090, 8848

INSTALLATION OF SPRINKLER SYSTEM IN MOLD LEFT OF BLDG # 4 CENT BU Y AND D # 5059, 8849

INSTALATION OF NEW SPRINKLER SYSTEM MO [SIC] MOLD LAFT [SIC] BLDG # 4 CONT BU AND D, 8850

INSTALATION OF NEW SPRINKLER SYSTEM IN MOLD LOFT BLDG # 4 CONT BU Y & D #5090 , 8852

UNTITLED, 8853

UNTITLED, 8854

UNTITLED, 8855

UNTITLED [USS NEW ORLEANS CA – 32 PLAQUE], 8856

USS New Orleans - Captain Stafford H.R. Doyle representing the Navy Yard Commandant Delivering the Ship to its Commanding Officer, Captain Allen B. Reed at the Commissioning Ceremony, 8857

USS NEW ORLEANS FOREMAST FROM PORT SIDE, 8861

USS NEW ORLEANS VIEW OF MASTS FROM STARBOARD SIDE, 8862
USS NEW ORLEANS VIEW OF MASTS FROM PORT SIDE, 8863
USS NEW ORLEANS FOREMAST - AT FIRE CONTROL PLATFORM PORTION OF WEDGING IN PLACE, 8864
USS NEW ORLEANS FOREMAST – UNDERSIDE OF FIRE CONTROL PLATFORM, 8865
USS NEW ORLEANS FOREMAST – VIEW AT MACHINE GUN PLATFORM, 8866
USS NEW ORLEANS – FOREMAST UNDERSIDE OF MACHINE GUN PLATFORM, 8867
USS NEW ORLEANS FOREMOST VIEW AT NAVIGATING BRIDGE BEFORE WATERSHED WAS INSTALLED, 8868
USS NEW ORLEANS FOREMAST VIEW UNDER NAVIGATING BRIDGE, 8869
USS NEW ORLEANS FOREMAST SECURING OF BASE ON SIGNAL BRIDGE, 8870
USS NEW ORLEANS, 8871
SUPPLY SYSTEM # 2 – 113 USS NEW ORLEANS CA 32, 8872
SUPPLY SYSTEM # 2 – 113 USS NEW ORLEANS CA 32, 8873
USS NEW ORLEANS, 8874
USS NEW ORLEANS VIEW SHOWING C R S MASTS, 8875
USS NEW ORLEANS VIEW SHOWING C R S MASTS, 8876
USS NEW ORLEANS STARBOARD SIDE LOOKING FORWARD, 8877
USS NEW ORLEANS CA 32, 8878
USS NEW ORLEANS PORT SIDE AFT, 8879
USS NEW ORLEANS CA 32 SHIPS BELL (ORIGINALLY INSTALLED ON EX NEW ORLEANS COMMISSIONED 1898)
RECEIVED FROM LOUISIANA STATE MUSEUM, 8880
USS NEW ORLEANS CA 32 SHIPS BELL (ORIGINALLY INSTALLED ON EX NEW ORLEANS COMMISSIONED 1898)
RECEIVED FROM LOUISIANA STATE MUSEUM, 8881
USS NEW ORLEANS, 8882
USS NEW ORLEANS, 8883
USS NEW ORLEANS, 8884
USS NEW ORLEANS, 8885
USS NEW ORLEANS, 8886
USS NEW ORLEANS, 8887
USS NEW ORLEANS LAYING SECTION OF WOODDECK (UPPERDK), 8888
USS NEW ORLEANS, 8889
USS NEW ORLEANS, 8890
USS NEW ORLEANS, 8891
USS NEW ORLEANS, 8892
USS NEW ORLEANS, 8893
USS NEW ORLEANS VIEW LOOKING FORWARD STARBOARD SIDE, 8894
USS NEW ORLEANS VIEW LOOKING FORWARD, 8895
USS NEW ORLEANS BOW VIEW AND SPONSORS PLATFORM, 8896
USS NEW ORLEANS VIEW SHOWING STARBOARD SIDE AND SPONSORS PLATFORM, 8897
USS NEW ORLEANS VIEW SHOWING STARBOARD SIDE AND SPONSORS PLATFORM, 8898
USS NEW ORLEANS IMMEDIATELY AFTER LAUNCHING, 8902
USS NEW ORLEANS ENTERING DD4 TO DROP FOREPOPPETS SLIDE WAYS AND PACKING, 8903
USS NEW ORLEANS JACKS FOR GIVING SHIP A START IN POSITION, 8904
USS NEW ORLEANS EXTREME FORWARD POPPET PORT SIDE WITH TRICING LINE, 8905
USS NEW ORLEANS AFTER POPPETS AND STERN SUPPORTS, 8906
USS NEW ORLEANS AFTER POPPETS PORT SIDE, 8908
USS NEW ORLEANS TRIGGER FOR RELEASING SHIP, 8909
USS NEW ORLEANS TRIGGER FOR RELEASING SHIP, 8910
USS NEW ORLEANS MAIN CONTROL STATION FOR RELEASING TRIGGERS IN PIT BENEATH SHIP, 8911
USS NEW ORLEANS FORE POPPET LOOKING AFT IN DRY DOCK 4, 8912
USS NEW ORLEANS GENERAL VIEW OF CRADLE IN DD4 AFTER PUMPING DOWN VIEW LOOKING FORWARD, 8913
USS NEW ORLEANS AFTER SOLID PACKING AND FORWARD AFTER POPPET DD4, 8914
USS NEW ORLEANS MAIN PACKING AFT OF FORWARD POPPETS IN DD4, 8915
USS NEW ORLEANS BROKEN SPREADER AND WEDGE RIDER IN MAIN PACKING AFT OF FORWARD POPPET, 8916
USS NEW ORLEANS BROKEN WEDGE RIDER AND WAYS PARTED PORT SIDE AFTER OF FORWARD POPPETS IN MAIN
PACKING, 8917
USS NEW ORLEANS AFTER MOST POPPET RAISED BY SLING CAST ADRIFT FROM SHIP 1ST POSITION, 8918
USS New Orleans After Most Poppet Washing Off Mud, 8919
USS NEW ORLEANS AFTER MOST POPPET LANDED ON DECK OF 150 TON CRANE FOR DISEMBLING, 8921
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FR 10, 8922
USS NEW ORLEANS ORLEANS VIEW LOOKING AFT FROM ABOUT FR 44, 8923
USS NEW ORLEANS ORLEANS VIEW FROM PORT SIDE LOOKING AFT FROM ABOUT FR 69, 8924
USS NEW ORLEANS ORLEANS VIEW LOOKING FORWARD FROM NO 2 TURRET, 8926
USS NEW ORLEANS ORLEANS VIEW LOOKING AFT FROM ABOUT FR 69, 8928
USS NEW ORLEANS ORLEANS VIEW LOOKING FORWARD FROM UPPER BRIDGE STRUCTURE, 8929
USS NEW ORLEANS ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8930

USS NEW ORLEANS ORLEANS VIEW LOOKING FORWARD FROM UPPER BRIDGE STRUCTURE, 8931
USS NEW ORLEANS ORLEANS VIEW SHOWING FORWARD BRIDGE AND FIRE CONTROL TUBES, 8932
USS NEW ORLEANS ORLEANS VIEW ON MAIN DK LOOKING FORWARD, 8933
USS NEW ORLEANS ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8934
USS NEW ORLEANS ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8935
USS NEW ORLEANS ORLEANS VIEW LOOKING AFT FROM ABOUT FR 69, 8936
USS NEW ORLEANS ORLEANS VIEW ON MAIN DK LOOKING FORWARD, 8937
USS NEW ORLEANS OF MAIN DK FROM NAVIGATION BRIDGE LOOKING FORWARD, 8938
USS NEW ORLEANS VIEW ON UPPER DECK LOOKING FORWARD AT BRIDGE, 8939
USS NEW ORLEANS VIEW FROM NAVIGATING BRIDGE LOOK AFT, 8940
USS NEW ORLEANS VIEW FROM STERN ON MAIN DK LOOK FORWARD, 8941
USS NEW ORLEANS LOOKING AFT FROM ABOUT FR 72, 8942
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8943
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8944
USS NEW ORLEANS VIEW LOOKING AFT FROM FR 69, 8945
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8946
USS NEW ORLEANS LOOKING AFT FROM ABOUT FR 69, 8947
USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF BLDG WAYS, 8948
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8949
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FRAME 69, 8950
USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF BLDG WAYS, 8951
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8952
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8953
USS NEW ORLEANS VIEW LOOKING FROM ABOUT FR 68, 8954
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FR 69, 8955
USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF BLDG WAYS, 8956
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 68, 8957
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FR 67, 8958
USS NEW ORLEANS VIEW LOOKING FORWARD FROM FR 68, 8959
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FR 73, 8960
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 78, 8961
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FR 67, 8962
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FR 69, 8964
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 69, 8965
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FR 65, 8966
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 76, 8967
USS NEW ORLEANS VIEW OF ASSEMBLE SECTION AT HEAD OF BLDG WAYS, 8968
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FR 70, 8969
USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT AFT 69, 8971
USS NEW ORLEANS VIEW LOOKING FROM ABOUT FR 70, 8972
USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF WAYS, 8973
USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF WAYS, 8974
USS NEW ORLEANS VIEW LOOKING FROM ABOUT FR 70, 8975
USS NEW ORLEANS VIEW LOOKING FROM ABOUT FR 70, 8976
USS NEW ORLEANS VIEW LOOKING FROM ABOUT FR 70, 8977
USS NEW ORLEANS VIEW LOOKING FROM ABOUT FR 70, 8978
USS NEW ORLEANS VIEW LOOKING FROM ABOUT FR 70, 8979
USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF BLDG WAYS, 8980
USS NEW ORLEANS VIEW LOOKING FOR'D FROM ABOUT FR 70, 8981
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FR 70, 8982
USS NEW ORLEANS ASSEMBLE SECTION AT HEAD OF BLDG WAYS, 9002
USS NEW ORLEANS VIEW FROM MIDSHIPS TO STERN, 9003
USS NEW ORLEANS VIEW FROM ABOUT MIDSHIPS TO BOW, 9004
USS NEW ORLEANS BUILT UP WELDED STEM ASSEMBLY BELOW SECOND DECK LOOKING DOWN, 9005
USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF BLDG WAYS, 9006
USS NEW ORLEANS VIEW LOOKING TO STERN, 9007
USS NEW ORLEANS VIEW FROM ABOUT MIDSHIPS, 9008
USS NEW ORLEANS VIEW FROM ABOUT MIDSHIPS TO STERN, 9009
USS NEW ORLEANS VIEW LOOKING AFT TO BULKHEAD NO 60 SHOWING ERECTION 2ND BEAMS FORD, 9010
USS NEW ORLEANS VIEW LOOKING FORWARD FROM FR 53 TO FR 22 SHOWING TRANS. S.T.S AND LONG ARMOR BULKHEADS, 9011
USS NEW ORLEANS VIEW LOOKING FORWARD FROM BULKHEAD 103 SHOWING SECURITY OF 2ND DECK AND ERECTION OF SHELL TO MAIN DECK, 9012
USS NEW ORLEANS VIEW LOOKING FORWARD TO BULKHEAD NO 103 SHOWING ERECTION OF STERN CASTING, 9013
USS NEW ORLEANS VIEW LOOKING AFT, 9014

USS NEW ORLEANS ASSEMBLE SECTION AT HEAD OF BLDG WAYS, 9015
USS NEW ORLEANS VIEW SHOWING KEEL LOOKING AFT TO BULKHEAD NO 53, 9016
USS NEW ORLEANS VIEW LOOKING FORWARD TO BULKHEAD NO 103, 9018
USS NEW ORLEANS ASSEMBLIE SECTION AT HEAD OF BLDG WAYS, 9019
USS NEW ORLEANS VIEW LOOKING AFT TO BULKHEAD NO 60, 9020
USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FRAME NO 20 TO BULKHEAD NO 60, 9021
USS NEW ORLEANS VIEW FROM STERN LOOKING FORWARD, 9022
USS NEW ORLEANS ASSEMBLIE SECTION AT HEAD OF BLDG WAYS, 9023
USS NEW ORLEANS VIEW LOOKING FORWARD, 9024
USS NEW ORLEANS VIEW LOOKING AFT TO BUILDING NO 6, 9025
USS NEW ORLEANS VIEW LOOKING AFT ABOUT FR 20 TO BULKHEAD NO 60, 9026
USS NEW ORLEANS VIEW MIDSHIP FROM BHD 53 TO BHD 74, 9027
USS NEW ORLEANS VIEW MIDSHIPS FROM BHD 74 TO BHD 92, 9028
USS NEW ORLEANS VIEW MIDSHIPS FROM BHD 92 TO BHD 103, 9029
USS NEW ORLEANS VIEW LOOKING FORWARD TO FRAME 10, 9030
USS NEW ORLEANS BULKHEAD ASSEMBLIES IN FIELD AT HEAD OF BUILDING WAYS, 9031
USS NEW ORLEANS VIEW LOOKING AFT BULKHEAD NO 6, 9032
USS NEW ORLEANS VIEW MIDSHIP FROM BKD B1 TO 103, 9034
USS NEW ORLEANS VIEW MIDSHIPS FROM BULKHEAD NO 60 TO 81, 9035
USS NEW ORLEANS VIEW LOOKING FORWARD TO BULKHEAD NO 92, 9036
USS NEW ORLEANS BULKHEAD ASSEMBLIES IN FIELD AT HEAD OF BUILDING WAYS, 9037
USS NEW ORLEANS VIEW LOOKING AFT TO BULKHEAD NO 60, 9038
USS NEW ORLEANS VIEW MIDSHIPS FROM BULKHEAD 81 TO 69, 9039
USS NEW ORLEANS VIEW LOOKING FORWARD TO NO 81 BULKHEAD, 9040
USS NEW ORLEANS BULKHEAD ASSEMBLIES IN FIRLD AT HEAD OF BUILDING WAYS, 9041
USS NEW ORLEANS VIEW LOOKING AFT TO BULKHEAD NO 74, 9042
USS NEW ORLEANS VIEW MIDSHIPS FROM BULKHEAD 81 TO NO 74 LOOKING FORWARD, 9043
USS NEW ORLEANS VIEW MIDSHIPS FROM BULKHEAD 81 TO NO 74 LOOKING FORWARD, 9044
USS NEW ORLEANS BULKHEAD ASSEMBLIES IN FIELD AT HEAD OF BUILDING WAYS, 9045
USS NEW ORLEANS VIEW LOOKING AFT TO BULKHEAD NO 74, 9046
USS NEW ORLEANS VIEW MIDSHIP FROM BHD NO 74 TO BHD 81, 9047
USS NEW ORLEANS VIEW LOOKING FORWARD TO BULKHEAD NO 81, 9048
USS NEW ORLEANS BULKHEAD ASSEMBLIES IN FIELD AT HEAD OF BLDG WAYS, 9051
USS NEW ORLEANS VIEW AT BOW LOOKING AFT, 9052
USS NEW ORLEANS VIEW AT STERN LOOK FORWARD, 9053
USS NEW ORLEANS VIEW AT BOW LOOKING AFT, 9054
USS NEW ORLEANS VIEW AT STERN LOOKING FORWARD, 9055
USS NEW ORLEANS VIEW ABOUT MIDSHIPS LOOKING AFT, 9056
USS NEW ORLEANS BULKHEAD ASSEMBLIES IN FIELD AT BLDG WAYS, 9057
USS NEW ORLEANS VIEW ABOUT ADMIDSHIPS LOOKING FORWARD, 9059
USS NEW ORLEANS VIEW ABOUT ADMIDSHIPS LOOKING AFT, 9060
USS NEW ORLEANS BULKHEAD ASSEMBLIES IN FIELD AT BLDG WAYS, 9061
USS NEW ORLEANS VIEW FROM BOW LOOK AFT, 9062
USS NEW ORLEANS VIEW ABOUT ADMIDSHIPS LOOKING FORWARD, 9063
USS NEW ORLEANS VIEW ABOUT ADMIDSHIPS LOOKING AFT, 9064
USS NEW ORLEANS VIEW FROM BOW LOOK AFT, 9066
USS NEW ORLEANS VIEW ABOUT MIDSHIPS LOOKING FORWARD, 9068
USS NEW ORLEANS SPECIAL DESIGNED CUTTING MACHINE FOR STS HATCHES SHOWING POSITION OF CUTTING TORCH AND LAYOUT OF TRACKS AND METHOD OF CUTTING RADIUS PRIOR TO CUTTING OF STS PLATING AND RANGING FROM 30 TO 90, 9069
USS NEW ORLEANS SPECIAL DESIGNED CUTTING MACHINE FOR STS HATCHES SHOWING POSITION OF CUTTING TORCH AND LAYOUT OF TRACKS AND METHOD OF CUTTING RADIUS PRIOR TO CUTTING OF STS PLATING AND RANGING FROM 30 TO 90, 9070
USS NEW VIEW LOOKING FORWARD TO BULKHEAD 92, 9071
USS NEW IMPACT HAND END WELDING $\frac{1}{4}$ TO $\frac{1}{2}$ DIG STUDS SCREWS ETC THRU DECK PLANKING AND TO VERTICAL BULKHEADS AND OVERHEAD PLATING (HAND SIZE) SHOWING WELDER IN PLACE FOR WELDING STUDS TO SECURE DECK PLANKING, 9072
USS NEW ORLEANS IMPACT POWER WELDING APPARATUS $\frac{3}{8}$ – $\frac{7}{16}$ – $\frac{1}{2}$ DIG ETC STUDS THRU DECK PLANKING (HEAVY DUTY) SJOWING WELDER RAISED BY AIR PISTONS PREPARATORY TO INSERTING STUD INHOLE, 9073
USS NEW ORLEANS IMPACT POWER END WELDING APPARATUS END WELDING $\frac{3}{8}$ – $\frac{7}{16}$ – $\frac{1}{2}$ DIG ETC STUDS THRU DECK PLANKING (HEAVY DUTY) SHOWING WELDER IN PLACE, 9074
USS NEW SPECIAL DESIGN CUTTING MACHINE STS HATCHES SHOWING POSITION OF CUTTING TORCH AND LAYOUT OF TRACKS AND METHOD OF CUTTING RADIUS PRIOR TO CUTTING OF STS PLATING RANGING FROM 30 TO 90, 9075
USS NEW ORLEANS SPECIAL GAS CUTTING MACHINE FOR CUTTING 45 BEVELS IN STS PLATING (SIDE VIEW), 9076
USS NEW ORLEANS SPECIAL GAS CUTTING MACHINE FOR CUTTING 45 BEVELS IN STS PLATING (FRONT VIEW), 9077

USS NEW ORLEANS SPECIAL GAS CUTTING MACHINE FOR CUTTING 45 BEVELS IN STS PLATING SHOWING GENERAL VIEW OF PIVOTING CENTER, 9078
PIPE WELDING MACHINE THREE PIECE ASSEMBLY, 9079
PIPE WELDING MACHINE (FRONT VIEW), 9080
PIPE WELDING MACHINE (SIDE VIEW), 9081
USS NEW ORLEANS METHOD OF CUTTING 1ST PLDK WT ARMOR COVERS FOR VENT OF OPENINGS FRAMES 45 TO 47, 9082
USS NEW ORLEANS METHOD OF CUTTING 1ST PLDK WT ARMOR COVERS FOR VENT OF OPENINGS FRAMES 45 TO 47, 9083
USS NEW ORLEANS FIXTURE FOR CUTTING DUY OBLONG SCUPPER HOLES THRY SIDE ARMOR AFT OF FRAME 48 AND 1ST PLATFORM, 9084
USS NEW ORLEANS FIXTURE FOR CUTTING DUY OBLONG SCUPPER HOLES THRU SIDE ARMOR AFT OF FRAME 48 AND 1ST PLATFORM , 9085
USS NEW ORLEANS CUTTING SCUPPER HOLES THRU SIDE ARMOR AFT OF FRAME 48 AND 1ST PLATFRORM, 9086
USS NEW ORLEANS PLAIN VIEW OF SAMPLE CUTS IN STS PLATING 5TH THICK BY THE OXY- ACETYLENE MACHINE CUTTING METHOD, 9087
USS NEW HATCHING CUT IN THE STS PLATING FOR THE SECOND DECK OF THE CA32, 9088
USS NEW ORLEANS NEW HATCHING CUT IN THE STS PLATING FOR THE SECOND DECK OF THE CA32, 9089
USS NEW ORLEANS GRINDING 45 BEVEL OXYACETYLENE CUT ON STS HATCH COVER, 9090
USS NEW ORLEANS HATCH CUT OUT FROM STS PLATING 2ND DK FIG 12, 9091
USS NEW ORLEANS HATCH CUT OUT FROM STS PLATING 2ND DK FIG 13, 9092
USS NEW ORLEANS HATCH CUT IN STS PLATING 2ND DK FIG 14, 9093
USS NEW ORLEANS HATCH CUT IN STS PLATING 2ND DK FIG 15, 9094
USS NEW ORLEANS PEEP HOLE SAMPLE MADE BY SPECIAL LAYOUT AND CUTTING TECHNIQUE MADE IN 90 STS PLATING, 9095
USS NEW ORLEANS PEEP HOLE SAMPLE MADE BY SPECIAL LAYOUT AND CUTTING TECHNIQUE MADE IN 90 STS PLATING, 9096
USS NEW ORLEANS HATCH CUT IN STS PLATING 2ND DK FIG 14, 9097
CIRCULAR BEVEL CUT MADE IN 90 STS PLATING – SAMPLE CUT, 9098
USS NEW ORLEANS BUILT UP WELDED STEM ASSEMBLY ABOVE SECOND DECK LOOKING UP, 9099
USS NEW ORLEANS BUILT UP WELDED STEM VIEW FROM 2ND DECK LOOKING DOWN, 9100
USS NEW ORLEANS BUILT UP WELDED STEM ASSEMBLY BELOW SECOND DECK LOOKING DOWN, 9101
USS NEW ORLEANS ASSEMBLY BELOW SECOND DECK LOOKING UP, 9102
USS NEW ORLEANS ASSEMBLY OF LOWER SECTION OF STEM AND STEM CASTING LOOKING OUTBOARD PRIOR TO WELDING, 9103
USS NEW ORLEANS ASSEMBLY OF LOWER SECTION OF STEM AND STEM CASTING PRIOR TO WELDING, 9104
USS NEW ORLEANS UPPER SECTION OF WELDED STEM SHOWING WELDING OF WEB BRACKETS TO STEM PLATES AND PIPING, 9105
USS NEW ORLEANS ASSEMBLY UPPER SECTION OF WELDED STEM SHOWING WELDING OF THE STEM PLATES AND PIPING, 9106
USS NEW ORLEANS STEM ASSEMBLY PRIOR TO WELDING INSIDE OF STEM PLATES AND ASSEMBLY OF STEM CASTING, 9107
USS NEW ORLEANS STEM ASSEMBLY PRIOR TO ASSEMBLY OF STEM CASTING AND WELDING OF BOTH ON THE EXTERIOR, 9108
WELDING BOTTOM CHAMBER ON THE EXTERIOR OF THE ALL WELDED RESCUE CHAMBER, 9109
WELDING ON THE INTERIOR SECTION OF THE ALL WELDED RESCUE CHAMBER, 9110
FINISHED ALL WELDED RESCUE CHAMBER, 9111
FINISHED ALL WELDED RESCUE CHAMBER PRIOR TO PRINTING, 9112
SPECIAL DESIGNED ALL WELDED STEPS ON THE EXTERIOR OF RESCUE CHAMBER, 9113
USS NEW ORLEANS SHOWING STS SHELL WELDED SEAM, 9114
USS NEW ORLEANS WELDING OF ARMOR PLATING STARBOARD SECTION 5FT ABOVE INNER BOTTOM IN THE SHAFT ALLEY AT BULKHEAD 103, 9115
USS NEW ORLEANS WELDED ALTERATION TO ENGINE FOUNDATION ADJESENT TO BULKHEAD 103, 9116
USS NEW ORLEANS STARBOARD SIDE OF INNER BOTTOM OF BULKHEAD 60 SHOWING THE JUNCTION OF RIVETED AND WELDED SEAMS, 9117
USS NEW ORLEANS , 9118
USS NEW ORLEANS WELDING FOR STIFFNERS FOR TURRET FOUNDATION ON BULKHEAD 38, 9119
USS NEW ORLEANS FULLET WELDS ON STIFFNERS OF BULKHEAD 36, 9120
USS NEW ORLEANS , 9121
USS NEW ORLEANS , 9122
USS NEW ORLEANS TEST SPECIMEN FOR FINDING SHRINKAGE STRESSES IN STRAPPED BUTT CONTINOUS AND INTERMITENT WELDS AS WELDED ON USS NEW ORLEANS, 9123
USS NEW ORLEANS TEST SPECIMEN FOR FINDING SHRINKAGE STRESSES IN STRAPPED BUTT CONTINOUS AND INTERMITENT WELDS AS WELDED ON USS NEW ORLEANS, 9124
USS NEW ORLEANS STAR I.B. STRUCTURE CASTING SHOWING METHOD USED TO STRAIGHTEN, 9125

USS NEW ORLEANS VIEW OF CROSS HEAD AFTER WELDING , 9129
 USS NEW ORLEANS VIEW OF CROSS HEAD AFTER WELDING , 9130
 USS NEW ORLEANS SET UP OF STRUCT FOR THE WELDING OF INTERIOR BRACING RINGS, 9131
 USS NEW ORLEANS SET UP OF STRUCT FOR THE WELDING OF INTERIOR BRACING RINGS, 9132
 USS NEW ORLEANS, 9133
 USS NEW ORLEANS STRUCT SET UP FOR THE WELDING OF INTERIOR BRACING RINGS, 9134
 USS NEW ORLEANS STERN TUBE CASTING PORT O.B. F.E. VED OUT READY FOR WELDING, 9135
 USS NEW ORLEANS VIEW SHOWING PORT O.B. STERN TUBE CASTING VED OUT BEFORE WELDING AFTER ANNEALING, 9136
 USS NEW ORLEANS VIEW SHOWING PORT O.B. STERN TUBE CASTING AFTER WELD HAD CRACKED AND HAD BEEN RECUT OUT READY TO BE REWELDED, 9137
 USS NEW ORLEANS VIEW SHOWING PORT O.B. STERN TUBE CASTING AFTER WELD HAD CRACKED AND HAD BEEN RECUT OUT READY TO BE REWELDED, 9138
 USS NEW ORLEANS VIEW SHOWING O.B. PORT STERN TUBE CASTING REWELDING, 9139
 USS NEW ORLEANS VIEW SHOWING O.B. PORT STERN TUBE CASTING AFTER WELDING, 9140
 USS NEW ORLEANS 14" ALL WELDED BITS, 9144
 USS NEW ORLEANS 14" ALL WELDED BITS, 9145
 USS NEW ORLEANS 14" ALL WELDED BITS, 9146
 USS NEW ORLEANS 14" OPEN AND CLOSED ALL WELDED FORGED SWALLOW CHOCKS, 9147
 USS NEW ORLEANS 14" OPEN AND CLOSED ALL WELDED FORGED SWALLOW CHOCKS, 9148
 TESTS SPECIMEN FOR FINDINGS CRINKAGESTRESSES IN STRAPPED BUTT CONTINIOUS AND INTERMENT AS WELDED ON USS NEW ORLEANS, 9149
 TESTS SPECIMEN FOR FINDINGS CRINKAGE STRESSES IN STRAPPED BUTT CONTINIOUS AND INTERMENT AS WELDED ON USS NEW ORLEANS, 9150
 USS NEW ORLEANS UPPER DECK SHOWING WARPAGE OF DECK PLATING AFTER WELDING, 9151
 USS NEW ORLEANS UPPER DECK LOOKING AFT, 9152
 USS NEW ORLEANS UPPER DECK LOOKING FORWARD, 9153
 USS NEW ORLEANS FRAME 14 LOOKING FORWARD UP UNDER UPPER DECK, 9154
 USS NEW ORLEANS BOW SHOWING AMOUNT LIFTED OFF KEEL BLOCKS, 9155
 USS NEW ORLEANS PULLING BOW OVER TO TRUE CENTER LINE, 9156
 USS NEW ORLEANS UPPER DK SHOWING WEIGHTS ON BOW, 9158
 USS NEW ORLEANS ALL WELDED RUDDER, 9159
 USS NEW ORLEANS RUDDER CLOSING INPLATE AND WELDING , 9162
 USS NEW ORLEANS WELDED FRAME AT STERN UNDER MAIN DK , 9163
 USS NEW ORLEANS CRACK WELDED IN I-B UPPER DK FRAM 76 PORT, 9165
 USS NEW ORLEANS METHOD OF ELIMINATING BUCKELING UPPER DK FRAME 76 PORT, 9166
 USS NEW ORLEANS ALUMENIUM FOIL INSTULATION 5 MAGAZINE O.B SHAFT ALLEY BHD FRAM 104 TO 107 PORT, 9167
 USS NEW ORLEANS ALUMENIUM FOIL INSTULATION 5 MAGAZINE O.B SHAFT ALLEY BHD FRAM 104 TO 107 PORT, 9168
 USS NEW FORWARD END OF DK HOUSE PORT SIDE ON UPPER DK, 9169
 USS NEW ORLEANS FOUNDATION FOR WINDLESS FRS 18 TO 22, 9170
 USS NEW ORLEANS LOWER BOW, 9171
 USS NEW ORLEANS LOWER BOW, 9172
 USS NEW Y.S.D. 221 VIEW SHOWING WELDING OF SHELL AND STERN POST, 9173
 USS NEW ORLEANS VIEW SHOWING WELDING OF SHELL AND STERN POST, 9174
 USS NEW ORLEANS Y.F.221 VIEW SHOWING UPPER SECTION OF WELDED RUDDER AND SECTION OF SHELL, 9175
 USS NEW ORLEANS Y.F. 221 VIEW SHOWING WELDED RUDDER LOWER SECTION AND LOWER BEARING, 9176
 USS NEW ORLEANS Y.F. 221 VIEW SHOWING WELDED SHELL AT KEEL AND STERN STRAKES A&B, 9177
 USS NEW ORLEANS Y.F. 221 VIEW SHOWING PORT SHAFT TUBE WELDED TO SHELL, 9178
 USS NEW ORLEANS Y.F. 221 VIEW SHOWING ALL WELDED SHELL STRAKES A&B FRS 2 TO 7 PORT SIDE AT KEEL, 9179
 USS NEW ORLEANS PORTABLE TAPPING MACHINE FOR TAPPING HOLES IN BACK OF ARMOR, 9181
 USS NEW ORLEANS COUNTERBORE FOR FACING BOTTOM OF HOLE AND COUNTERBORING FOR BODY OF BOLT, 9183
 USS NEW ORLEANS PORTABLE TAPPING MACHINE FOR TAPPING HOLES FOR LIFTING PADS, 9184
 USS NEW ORLEANS PORTABLE TAPPING MACHINE FOR TAPPING HOLES FOR LIFTING PAD, 9185
 USS NEW ORLEANS PORTABLE TAPPING MACHINE ARMOR BOLT HOLES IN BACK FACE OF ARMOR, 9186
 USS NEW ORLEANS MAKING ALONG SCARF ON A 90 STS DECK PLATE SHIPFITTER SHOP, 9187
 USS NEW ORLEANS MAKING ALONG SCARF ON A 90 STS 2ND DECK PLATE SHIPFITTER SHOP, 9188
 USS NEW ORLEANS MAKING ALONG SCARF ON A 90 STS 2ND DECK PLATE SHIPFITTER SHOP, 9189
 USS NEW ORLEANS MAKING ALONG SCARF ON A 90 STS 2ND DECK PLATE SHIPFITTER SHOP, 9190
 USS HELENA LOOKING DOWN AT SHELF PLATES PLAN 7201 CHC C50 FIGURE N0 6 OF WELDING SEQUENCE, 9191
 USS HELENA CIRCULAR BHD ON PLAN 7201. CHC. – C.50 FIGURE N0 5 OF WELDING SEQUENCE, 9192
 USS HELENA WELDED STIFFENERS LOWER ROLLER TRACKS, 9193
 USS HELENA WELDED FILLER BLOCKS LOWER ROLLER TRACKS, 9194
 USS HELENA CL 50 – ASSEMBLY OF LONGLGRIDERS AND FOUNDATION RING SEGMENTS AS SHOWN ON FIGURE NO 3 OF WELDING PROCEDURE FOR GUN GRIDERS FOR 6" TURRETS (VIEW LOOKING TOWARD BACK), 9195
 USS HELENA CL 50 – ASSEMBLY OF LONG'L GIRDERS AND RING SEGMENTS AS SHOWN IN FIGURE NO 3 OF WELDING

PROCEDURE FOR GUN GRIDERS FOR 6" TURRETS (VIEW LOOKING TOWARD BACK FROM RIGHT SIDE), 9196
 USS HELENA CL 50 – ERECTION OF DECK LUGS IN PAIRS AS SHOWN IN WELDING PROCEDURE FOR GUN GRIDERS FOR 6" TURRETS FIGURE NO 7 RIGHT HAND DECK LUG SHOWING, 9197
 USS HELENA CL 50 – ERECTION OF DECK LUGS IN PAIRS AS SHOWN IN FIGURE NO 7 OF WELDING PROCEDURE FOR GUN GRIDERS FOR 6" TURRETS FRONT OF DECK LUGS SHOWING , 9198
 USS HELENA CL 50 INSTALATION OF UPPER TRACK TO GUN PAN INC. WELDING FIGURE 40F WELDING SEQUENCE, 9199
 USS HELENA CL 50 TURRET WELDMENTS INSTALATION AND WELDING OF DECK LUGS TO WELDMENTS FIGURE 7 OF WELDING SEQUENCE , 9200
 USS HELENA CIRCULAR BHD ON PLAN 7201. C.H.C – C.50 FIGURE NO 5 OF WELDING SEQUENCE , 9201
 USS HELENA LOOKING DOWN AT SHELF PLATES PLAN 7201 CHC C50 FIGURE NO 6 OF WELDING SEQUENCE , 9202
 USS HELENA ERECTION OF DECK LUGS IN PAIRS AS SHOWN IN FIGURE NO 7 WELDING PROCEDURE FOR GUN GRIDERS FOR 6" TURRETS BACKS OF DECK LUGS SHOWING , 9203
 USS HELENA 6" TURRET WELDMENT PAN, PLATE AND STIFFNERS – PORT ASSEMBLY , 9204
 USS HELENA 6" TURRET LOWER ROLLER RACK ON SPIDER FOR WELDING, 9205
 USS HELENA LONG ARMOR PLATE SHOWING DEFECTIVE SECTION S.T.S PLATE 5946-1 MILL MARK CL-50-1303 CHB SL/1 , 9206
 USS HELENA LONG ARMOR PLATE SHOWING DEFECTIVE SECTION S.T.S PLATE 5946-1 MILL MARK CL-50-1303 CHB SL/1, 9207
 H.P. CASING FOR CL 50 , 9208
 H.P. CASING FOR CL 50 , 9209
 H.P. CASING FOR CL 50 , 9210
 H.P. CASING FOR CL 50 , 9211
 H.P. CASING FOR CL 50 , 9212
 H.P. CASING FOR CL 50 , 9213
 H.P. CASING FOR CL 50 , 9214
 H.P. CASING FOR CL 50 , 9215
 H.P. CASING FOR CL 50 , 9216
 H.P. CASING FOR CL 50 , 9217
 H.P. CASING FOR CL 50 , 9218
 U.S.S. HELENA, 9219
 U.S.S. HELENA 1.5 UPPER HANDLING ROOM REAR VIEW CREW STATIONED, 9220
 U.S.S. HELENA 1.5 UPPER HANDLING ROOM REAR VIEW CREW STATIONED, 9221
 U.S.S. HELENA 1.5 UPPER HANDLING ROOM LEFT SIDE INSTALLED FOR MANUAL OPERATION, 9222
 U.S.S. HELENA 1.5 UPPER HANDLING ROOM LEFT SIDE CARTRIDGE IN TRAY, 9223
 U.S.S. HELENA 1.5 UPPER HANDLING ROOM LEFT SIDE POWER PASSERS STATIONED, 9224
 U.S.S. HELENA 1.5 UPPER HANDLING ROOM REAR VIEW CREW STATIONED_, 9225
 U.S.S. HELENA 1.5 UPPER HANDLING ROOM REAR VIEW CREW STATIONED_, 9226
 U.S.S. HELENA 1.5 UPPER HANDLING ROOM REAR VIEW CREW STATIONED, 9227
 U.S.S. HELENA 1.5 UPPER HANDLING ROOM RIGHT SIDE POWDER PASSERS STATIONED, 9228
 U.S.S. HELENA COMMISSIONING CEREMONY L. TO R. CAPT L.M. STEVENS REAR ADMIRAL C.H. WOODWARD CAPT M.B. DE MOTT, 9229
 U.S.S. HELENA COMMISSIONING CEREMONY L. TO R. CAPT L.M. STEVENS REAR ADMIRAL C.H. WOODWARD CAPT M.B. DE MOTT, 9230
 U.S.S. HELENA COMMISSIONING CEREMONY, 9231
 U.S.S. HELENA COMMISSIONING CEREMONY, 9232
 U.S.S. HELENA COMMISSIONING CEREMONY, 9233
 U.S.S. HELENA COMMISSIONING CEREMONY, 9234
 USS BROOKLYN LOWER TURRET ROLLER PATH RING SET UP O BORING MILL FOR WELDING, 9250
 USS BROOKLYN LOWER TURRET ROLLER PATH RING SET UP ON BORING MILL FOR WELDING SHOWING ARRANGEMENT OF GAGES, 9251
 USS BROOKLYN BOTTOM HALF OF LOWER ROLLER PATH AFTER WELDING OF INTERNAL WEBS SHOWING MICROMETER GAUGE FOR MEASURING DIAMETRICAL DISTORTION DUE TO WELDING, 9252
 USS BROOKLYN BOTTOM HALF OF LOWER ROLLER PATH CASTING AFTER WELDING OF INTERNAL WEBS, 9253
 USS BROOKLYN LOWER TRACK ASSEMBLY READY FOR WELDING SHOWING MOUNTING ON SPIDER, 9254
 USS BROOKLYN LOWER ROLLER TRACK ASSEMBLY, 9255
 USS BROOKLYN LOWER TRACK ASSEMBLY SHOWING METHOD OF CONNECTION TO SPIDER, 9256
 BROOKLYN CRUISING TURBINE CASING # 259 LOWER HALF, 9257
 USS BROOKLYN CL 40 VIEW LOOKING FORWARD, 9265
 USS BROOKLYN CL 40 VIEW LOOKING AFT, 9266
 USS BROOKLYN TURRET WELDMENT TRANSOM BRACE FOR DECK LUGS, 9267
 USS BROOKLYN STERN PORT WELDMENT – SHOWING WELDMENT AFTER STRESS RELIEF, 9268
 USS BROOKLYN CL 40, 9269
 USS BROOKLYN CL 40, 9270
 USS BROOKLYN SHOWING OUTLETS IN THE INNER BOTTOM PLATING AND READY FOR THE FINISH WELDING

OPERATION ON THE UNDER SIDE, 9271
 USS BROOKLYN SHOWING THE FLOOR AND LONGITUDINAL ASSEMBLY WELDED TO THE SHELL PLATING – PRIOR TO THE ASSEMBLY OF THE INNER BOTTOM, 9272
 USS BROOKLYN WELDED 6" GUN TURRET (INVERTED) PRIOR TO ASSEMBLING OF CIRCULAR BULKHEAD AND GUN GIRDER, 9273
 USS BROOKLYN – ALL WELDED 6" GUN TURRET, 9274
 USS BROOKLYN FIELD WELDING SLAB USED FOR THE ERECTION AND WELDING OF LARGE WELDMENTS AND THE ASSEMBLY OF THE STS PLATING FOR DECKING, 9275
 USS BROOKLYN SHOWING THE NEAT SHIP FITTING BETWEEN THE TRANVERSE FRAME AND THE SHELL PLATING FORWARD OF FRAME 45 AND READY FOR WELDING, 9276
 USS BROOKLYN 6" GUN TURRET CLOSE – UP OF DECK LUG WELDMENT, 9277
 USS BROOKLYN WELDED BOW FRAMING ASSEMBLY – FORWARD OF FRAME # 4 BELOW BREAST HOOK FR 9 1/4, 9278
 USS BROOKLYN ALL WELDED RUDDER INBOARD PROFILE LOOKING STARBOARD, 9279
 USS BROOKLYN ALL WELDED RUDDER BOW VIEW, 9280
 USS BROOKLYN STERN POST WELDMENT IN POSITION, 9281
 USS BROOKLYN ALL WELDED RUDDER PORT SIDE, 9282
 USS BROOKLYN WELDED BOW ASSEMBLY FORWARD OF FRAME #4 BELOW 3rd DECK, 9283
 USS BROOKLYN WELDED BOW ASSEMBLY FORWARD OF FRAME #4 BELOW 3RD DECK, 9284
 USS BROOKLYN AFT END, 9285
 USS BROOKLYN FORWARD END, 9286
 USS BROOKLYN CL 40, 9287
 USS BROOKLYN CL, 9288
 USS BROOKLYN PORT OUTBOARD AFTER STRUT – AFTER BENDING LOWER ARM, 9289
 USS BROOKLYN PORT OUTBOARD AFTER STRUT BEFORE BENDING UPPER PALM, 9290
 USS BROOKLYN PORT OUTBOARD AFTER STRUT (BEFORE BENDING) TOP VIEW SHOWING STOPS AND FURNACE, 9291
 USS BROOKLYN PORT OUTBOARD AFTER STRUT UPPER PALM 2ND OPERATION – DRAWBACK DUE TO COOLING SHOWING REMOVAL OF BEND AND TWISTIN, 9292
 USS BROOKLYN STARBOARD INBOARD AFTER STRUT SHOWING FURNACE AND METHOD OD BENDING, 9293
 USS BROOKLYN STRUT, 9294
 USS BROOKLYN STARBOARD INBOARD AFTER STRUT BEFORE BENDING, 9295
 USS BROOKLYN STARBOARD INBOARD AFTER STRUT AFTER BENDING, 9296
 USS BROOKLYN CL 40 VIEW FROM MIDSHIPS LOOKING FORWARD, 9297
 USS BROOKLYN CL 40 VIEW LOOKING AFTER FROM MIDSHIPS , 9298
 USS BROOKLYN MICROMETER GAUGE FOR CHECKING UPPER ROLLER PATH, 9299
 USS BROOKLYN MICROMETER GAUGE FOR CHECKING UPPER ROLLER PATH, 9300
 USS BROOKLYN (CL 40) VIEW LOOKING AFT, 9301
 USS BROOKLYN (CL 40) VIEW LOOKING FORWARD, 9302
 USS BROOKLYN (CL 40) VIEW BACK # V TURRET, 9303
 USS BROOKLYN (CL 40) VIEW FRONT # V TURRET, 9304
 USS BROOKLYN CL NO 40, 9305
 USS BROOKLYN CL 40, 9306
 USS BROOKLYN (CL 40) VIEW SHOWING TURRETS UNDER CONSTRUCTION, 9307
 USS BROOKLYN, 9308
 USS BROOKLYN, 9309
 USS BROOKLYN, 9310
 USS BROOKLYN, 9311
 USS BROOKLYN, 9312
 USS BROOKLYN, 9313
 USS New Orleans, View Looking Forward from About Frame 67, 9327
 USS New Orleans - General View Looking Foward, 9345
 USS Helena, No. 1-5" Upper Handling Room, Rear View of Crew Stationed, 9388
 USS NEW ORLEANS VIEW LOOKING FROM ABOUT FRAME 69, 9389
 USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FRAME 67, 9391
 USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FRAME 67, 9392
 USS NEW ORLEANS VIEW LOOKING FORWARD TO STEM, 9394
 USS NEW ORLEANS VIEW LOOKING AFT TO STERN, 9395
 USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF BLDG WAYS, 9396
 USS NEW ORLEANS VIEW LOOKING FORWARD TO STERN, 9397
 USS NEW ORLEANS VIEW LOOKING AFT TO STERN, 9398
 USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF BLDG WAYS, 9399
 USS NEW ORLEANS VIEW LOOKING FORWARD TO STERN, 9400
 USS BROOKLYN, 9405
 USS BROOKLYN, 9408
 USS BROOKLYN, 9409
 USS BROOKLYN, 9410

USS BROOKLYN, 9411
USS BROOKLYN SPONSORS PLATFORM, 9412
USS BROOKLYN PHOTOGRAPHERS PLATFORM, 9413
USS BROOKLYN PHOTOGRAPHERS PLATFORM, 9414
USS BROOKLYN, 9415
USS BROOKLYN, 9416
USS BROOKLYN FORE POPPETS, 9417
USS BROOKLYN STARBOARD AND FORWARD POPPET FRAME, 9418
USS BROOKLYN TYPICAL MIDSHIP CRADLE, 9419
USS BROOKLYN AFTER STARBOARD POPPET SHORES AND CRIBBING, 9420
USS BROOKLYN AFTER POPPET, 9421
USS BROOKLYN, 9422
USS BROOKLYN, 9423
USS BROOKLYN, 9424
USS BROOKLYN, 9425
USS BROOKLYN C A 40, 9426
USS BROOKLYN C L NO 40 TURRET NO 5 SKIDDED TO POSITION FOR MAKING LIFT, 9427
USS BROOKLYN, 9428
USS BROOKLYN C L NO 40 'SHIPPING TURRET NO 5', 9432
Commissioning Ceremony USS Brooklyn, 9441
NO 3 USS BROOKLYN (TEST OF TURRET BUFFER) OSCILLOGRAPH MAKES RECORD OF MOTION OF TURRET N STEPS OF 1/16 INCH ON TIME SCALE OF 300 CYCLES/SECOND, 9447
[UNTITLED PLAQUE] USS BROOKLYN LIGHT CRUISER NAMED FOR CITY OF BROOKLYN NY BUILT AT THE NAVY YARD NY AUTHORIZED FEBRUARY 13 1929 KEEL LAID MARCH 12 1935 LAUNCHED NOVEMBER 30 1936 FIRST COMMISSIONED SEPTEMBER 30 1937, 9448
USS BROOKLYN #1 UNIT STAR H P TURBINE ROTATOR, 9449
USS BROOKLYN #1 UNIT STAR H P TURBINE ROTATOR, 9450
USS BROOKLYN, 9451
Dry Dock 4 - Yard Labor Renewing the Floor, View from Caisson, 9454
Dry Dock 4 - Yard Labor Renewing Floor, View from Caisson, 9455
DISINTEGRATION OF CONCRETE IN BED OF DD NO 4, 9460
DISINTEGRATION OF CONCRETE IN BED OF DD NO 4, 9461
DISINTEGRATION OF CONCRETE IN BED OF DD NO 4, 9462
DISINTEGRATION OF CONCRETE IN BED OF DD NO 4, 9463
DISINTEGRATION OF CONCRETE IN BED OF DD NO 4, 9464
DISINTEGRATION OF CONCRETE IN BED OF DD NO 4, 9465
DETAIL OF GASKET SHOWING METHOD OF FASTENING TO KEEL, 9466
PROGRESS SHEET SHOWING CRACKS SETTLEMENT OF BANK & RESULT ON SHEET PILING PHOTO OF F544S95, 9467
COURT MAP DD4 BOTTOM RIGHT, 9468
COURT MAP DD4 BOTTOM CENTER, 9469
COURT MAP DD4 BOTTOM LEFT, 9470
COURT MAP DD4 TOP RIGHT, 9471
COURT MAP DD4 TOP CENTER, 9472
COURT MAP DD4 TOP LEFT, 9473
PHOTO OF F544S177 DD 4 E SIDE ENTRANCE END, 9474
PHOTO OF F544S177 DD 4 E SIDE CENTER, 9475
PHOTO OF F544S177 DD 4 E SIDE HEAD END, 9476
PHOTO OF F544S177 DD 4 E SIDE ENTRANCE END, 9477
PHOTO OF F544S178 DD 4 W SIDE CENTER, 9478
PHOTO OF F544S178 DD 4 E SIDE ENTRANCE END, 9479
PHOTO OF F544S177 DD 4 W SIDE HEAD END, 9480
PHOTO OF F544S177 DD 4 E SIDE CENTER, 9481
PHOTO OF F544S177 DD 4 E SIDE HEAD END, 9482
PHOTO OF F544S178 DD 4 W SIDE ENTRANCE END, 9483
PHOTO OF F544S178 DD 4 W SIDE CENTER, 9484
PHOTO OF F544S178 DD 4 W SIDE HEAD END, 9485
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO, 9486
DD4 LOOKING NW, 9487
SITE OF DD 4 FROM ROOF BLG 41, 9488
MODEL OF DRY DOCK NO 4 GENERAL VIEW FROM ENTRANCE END, 9489
MODEL OF DRY DOCK 4 PUMP WELL SECTION, 9490
MONTHLY PROGRESS PHOTO DD4 NEW VENTILATORS ON PUMP WELL LOOKING NW YARD LABOR, 9491
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO RELOCATION OF GUARD CHAINS HEAD END LOOKING LITTLE W OF S YARD LABOR, 9492
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO RELOCATION OF GUARD CHAINS HEAD END LOOKING LITTLE W OF S

YARD LABOR, 9493
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO NEW BOLLARDS E SIDE LOOKING NE YARD LABOR, 9494
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO DURAX PAVEMENT LOOKING E FROM BDG 41 (58) UVALDE ASPHALT CO CONTRACTOR, 9495
Dry Dock 4 Monthly Progress Photo Durax Pavement Looking NE from Building 41 (58) Uvalde Asphalt Co Contractor, 9496
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO NEW HAND RAIL STAIRS AT HEAD LOOKING SE YARD LABOR, 9499
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO FOUNDATION FOR BOLLARD W SIDE LOOKING W YARD LABOR, 9500
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO RELOCATION OF GUARD CHAINS HEAD END LOOKING W YARD LABOR, 9502
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING & PAVING AROUND DOCK LOOKING NE YARD LABOR UVALDE ASPHALT CO CTR, 9503
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING & PAVING AROUND DOCK LOOKING N (USS ARK) YARD LABOR UVALDE ASPT CO CTR, 9504
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING & PAVING AROUND DOCK LOOKING NW YARD LABOR UVALDE ASPHALT CO CTR, 9505
DRY DOCK NO 4 FORMS AT HEAD OF DOCK FOR NEW BRACKET FOR RELOCATED GUARD CHAINS YARD LABOR, 9506
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO FOR NEW RAILING LOOKING NW YARD LABOR, 9507
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO NEW HAND RAILS LOOKING E AT HEAD YARD LABOR, 9508
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO NEW HAND RAILS LOOKING SE YARD LABOR, 9509
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO RR TRACK AROUND HEAD LOOKING E YARD LABOR, 9510
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING ETC AROUND DOCK LOOKING NE YARD LABOR, 9511
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO LOOKING N FROM BLG 41 (58) USS ARKANSAS YARD LABOR, 9512
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO TRACK ETC AT HEAD LOOKING NW YARD LABOR, 9513
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PAVING & GRADING LOOKING N YARD LABOR, 9514
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING & PAVING LOOKING NW YARD LABOR, 9515
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING & PAVING LOOKING E YARD LABOR, 9516
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING & PAVING LOOKING NE YARD LABOR, 9517
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING & PAVING LOOKING N YARD LABOR, 9518
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING & PAVING LOOKING NW YARD LABOR, 9519
DRY DOCK NO 4 PUMP WELL CENTER AND NORTH PUMPS, 9520
DRY DOCK NO 4 PUMP WELL LOOKING SW OVER TOPS OF CENTER AND SOUTH PUMPS, 9521
DRY DOCK NO 4 PUMP WELL LOOKING NE OVER CENTER AND NORTH PUMPS, 9522
DRY DOCK NO 4 PUMP WELL LOOKING SW ALONG MAIN GALLERY, 9523
DRY DOCK NO 4 PUMP WELL SOUTH PUMP, 9524
DRY DOCK NO 4 PUMP WELL LOOKING NE ALONG MAIN GALLERY, 9525
DRY DOCK NO 4 PUMP WELL MOTOR FLOOR LOOKING NE, 9526
DRY DOCK NO 4 SHOWING HOUSING FOR PAWL CAPSTAN NO 3, 9527
DRY DOCK NO 4 FAILURE OF CAPSTAN NO 2 SHOWING RUPTURE OF HOUSING FOR PAWL, 9528
DRY DOCK NO 4 FAILURE OF CAPSTAN NO 2 SHOWING RUPTURE OF HOUSING FOR PAWL, 9529
DRY DOCK NO 4 FAILURE OF CAPSTAN NO 2 SHOWING RUPTURE OF HOUSING FOR PAWL, 9530
DRY DOCK NO 4 FAILURE OF CAPSTAN NO 2 SHOWING BROKEN HEAD, 9531
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING ETC LOOKING E YARD LABOR, 9532
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING ETC LOOKING NE YARD LABOR, 9533
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING ETC LOOKING N YARD LABOR, 9534
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING ETC LOOKING NW YARD LABOR, 9535
DRY DOCK NO 4 ISOMETRIC HEAD END, 9536
DRY DOCK NO 4 ISOMETRIC ENTRANCE END, 9537
DRY DOCK NO 4 ISOMETRIC HEAD END, 9538
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING ETC YARD LABOR LOOKING E, 9539
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING ETC LOOKING NE YARD LABOR, 9540
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING ETC LOOKING N YARD LABOR, 9541
MONTHLY PROGRESS PHOTO DRY DOCK NO 4 GRADING ETC LOOKING NW YARD LABOR, 9542
DRY DOCK NO 4 INVERTED STALACTITES STA 5+65.5 CTR W HALF OF DOCK, 9543
DRY DOCK NO 4 INVERTED STALACTITES STA 1+86 ALONGSIDE BLOCKING, 9544
DRY DOCK NO 4 INVERTED STALACTITES STA 1+47 ABUTMENT JOINT E SIDE, 9545
DRY DOCK NO 4 INVERTED STALACTITES STA 1+31 LOOKING W, 9546
DRY DOCK NO 4 INVERTED STALACTITES STA 1+47 ABUTMENT JOINT E SIDE, 9547
DRY DOCK NO 4 INVERTED STALACTITES STAS 1 + 31 NEAR E SIDE, 9548
DRY DOCK NO 4 INVERTED STALACTITES STAS 1 + 31 & 1 + 41 LOOKING NW, 9549
DRY DOCK NO 4 INVERTED STALACTITES STAS 1 + 31 & 1 + 41 LOOKING NW, 9550
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING LOOKING E YARD LABOR, 9551
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING LOOKING EN YARD LABOR, 9553
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING LOOKING NE YARD LABOR, 9554
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING LOOKING NE YARD LABOR, 9555
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING LOOKING N YARD LABOR, 9556

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GRADING LOOKING NW YARD LABOR, 9557
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO AUG MONTHLY PROGRESS MAP HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9558
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO W APPROACH WALL LOOKING W HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9561
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO W APPROACH WALL LOOKING NE HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9568
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO LOOKING N FROM W END OF CAISSON GRADING YARD LABOR, 9569
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO LOOKING W FROM W END OF CAISSON GRADING YARD LABOR, 9571
Dry Dock 4 monthly progress photo looking northeast from Building 41, 9575
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO JULY MONTHLY PROGRESS MAP HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9577
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PROGRESS MAP FOR JUNE HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9591
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GENERAL VIEW LOOKING SOUTH HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9592
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO MONTHLY PROGRESS MAP FOR MAY HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9594
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO E APPROACH WALL – LOOKING W HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9595
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO W APPROACH WALL – LOOKING NW HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9596
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PUMP WELL ROOF & ENTRANCE HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9599
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GENERAL VIEW LOOKING SOUTH HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9600
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GENERAL VIEW LOOKING NORTH HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9601
USS UTAH FIRST DOCKING IN DRY DOCK NO 4, 9604
USS UTAH FIRST DOCKING IN DRY DOCK NO 4, 9605
USS UTAH FIRST DOCKING IN DRY DOCK NO 4, 9606
USS UTAH FIRST DOCKING IN DRY DOCK NO 4, 9607
DRY DOCK NO 4 LOCATION OF SHEET PILING AND MEASUREMENTS ACROSS DOCK, 9608
CROSS SECTIONS STATIONS 15 + 00 TO 17 + 00 SHOWING EXCAVATION IN DRY DOCK NO 4, 9609
CROSS SECTIONS STATIONS 12 + 50 TO 14 + 50 SHOWING EXCAVATION IN DRY DOCK NO 4, 9610
Dry Dock 4 - First vessel docked, USS Utah, 9634
CROSS SECTION AND ISOMETRIC VIEW OF DRY DOCK NO 4 US NAVY YARD NEWYORK SHOWING HEAD OF DOCK FROM STA 6+31.00 TO STA 8+25.75, 9641
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PUMP WELL CTR & N PUMP CASINGS ALBERGER PUMP CO CONTRACTOR, 9642
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PUMP WELL – MAIN GALLERY – LOOKING NE, 9643
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PUMP WELL – MOTOR FLOOR LOOKING N ALBERGER PUMP CO CONTRACTOR, 9644
USS PENSACOLA 53 SUPPLY OFFICE LOOKING FORWARD SHOWING FORM LOCKER AT LEFT KEY LOCKER WITH MAIL TRAY UNDER FOREMAST STRUT IN BACKGROUND BOOK RACK IN BACK OF STRUT FILING CABINETS AND TYPEWRITER DESKS AT RIGHT WITH BOOK RACKS AND PIGEON HOLE RACKS ETC OVER, 9659
USS PENSACOLA 54 CPO MESS ROOM LOOKING TO STARBOARD SHOWING ALUMINUM ALLOY BULKHEAD AND STIFFENERS AT LEFT ALUMINUM ALLOY PANTRY BULKHEADS IN BACKGROUND ALUMINUM ALLOY CHAIRS AIR SUPPLY TERMINALS OVERHEAD, 9660
USS PENSACOLA 55 CPO QUARTERS LOOKING FORWARD SHOWING ARRANGEMENT OF BERTHS TRANSOM LOCKERS AND CLEAN CLOTHES LOCKERS W T DOOR WITH SCREEN DOOR FRAME IN BACKGROUND FORE AND AFT DECK BEANS AND WELDED STIFFENERS UNDER MINE TRACKS OVERHEAD, 9661
USS PENSACOLA 56 CPO WATER CLOSET AND WASHROOM SHOWING AT LEFT ALUMINUM ALLOY WATER CLOSET JOINER DOOR INTO WATER CLOSET ARCHWAY SHOWER WATER CLOSET AND ALLUMINUM ALLOY WATER CLOSET JOINER DOORS LAVATORIES AT RIGHT AIR BLOWER AND VENTILATION PIPES ABOVE, 9662
USS PENSACOLA 57 SCUTTLE BUTT 2ND DECK FRAME 104 SHOWING FROM LEFT TO RIGHT MAIN MAST STRUT HAMMOCK HOOK GENERAL ANNOUNCING TELEPHONE REPRODUCER WITH “UNIFORM OF THE DAY” BOARD UNDER SCUTTLE BUTT WITH W T VENT PIPE AND COVER THROUGH BULKHEAD ABOVE AND GENERAL ALARM GONG IN BACK SUPPLY VENT TERMINAL CHAPLAINS PULPIT WITH LIGHTING DISTRIBUTION BOX AND TABLE STOWAGE OVER SOUNDING TUBE COVER WRENCH STOWED ON BULKHEAD LOWER LEFT NOTE HIGH COAMING AROUND TILING, 9663
USS PENSACOLA 58 INCLINED LADDER AND CREWS SPACE 1ST PLATFORM FRAME 113 LOOKING FORWARD AND TO STARBOARD SHOWING LOCKERS PEA COAT STOWAGE CENTER BACKGROUND HAMMOCK BERTHING AT RIGHT WITH LIFE JACKET RACKS OVER MESS TABLES AT LOWER LEFT AND RIGHT AIR SCOOP STOWAGE ON WEB FRAME FLUSH OILTIGHT MANHOLES TO FUEL OIL TANKS IN CENTER AND HINGED BENCHES ON NETTINGS AT RIGHT HAMMOCK HOOKS SHOWN WELDED ON FRAME OF H BARS CUT DOWN TO T BARS EXCEPT WERE WELDED TO OVERHEAD, 9664

USS PENSACOLA 59 SHIPS SERVICE STORE LOOKING FORWARD AND TO STARBOARD SHOWING ALUMINUM ALLOY SHELVING AT LEFT SODA FOUNTAIN AT RIGHT AND WIRE MESH ENCLOSURE BARBER SHOP BEYOND, 9665

USS PENSACOLA 60 MAIN ISSUING ROOM 1S PLATFORM PORT SIDE LOOKING FORWARD SHOWING STANDING DESK LOWER LEFT WITH TELEPHONE OVER AND ARRANGEMENT OF BINS ALL BINS AND DESK ALUMINUM ALLOY, 9666

USS PENSACOLA 61 DOCTORS OFFICE AND DISPENSARY LOOKING TO PORT SHOWING FROM LEFT TO RIGHT FLAT TOP DESK CORRESPONDENCE UNIT BOOKRACK TYPEWRITER DESK HIGH TOP DESK WITH SAFE LOCKER UNDER HINGED BERTH DRUG CABINET WITH SCALES ETC AND BOTTLE RACKS OVER, 9667

USS PENSACOLA 62 OPERATING ROOM LOOKING TO STARBOARD SHOWING INSTRUMENT STAND AND HINGED BOWLS AT LEFT OPERATING TABLE AND LIGHTS OVER STERILIZERS ETC IN BACKGROUND WATER STERILIZERS LAVATORY RIGHT FOREGROUND BULKHEAD IN BACKGROUND 2 1/2 # STEEL PLATE WELDED, 9668

USS PENSACOLA 64 2 1/2 # PLATE STEEL INBOARD OPERATING ROOM BULKHEAD LOOKING TO PORT SHOWING INTERMITTENT WELDING AT HEEL OF STIFFENING FLANGE OF BULKHEAD PLATING FASTENINGS OF ELECTRIC LEADS ETC AND PART OF DOOR FRAM AND DOOR (SAME LOCATION AS PREVIOUS PICTURE EXCEPT OTHER SIDE OF BULKHEAD DUE TO COSTLY TEMPORARY STIFFENING NECESSARY TO PREVENT WARPING DURING WELDING OTHER 2 1/2 # BULKHEADS WERE RIVETED USING TAR FELT BETWEEN SURFACES FOR AIRTIGHTNESS, 9669

USS PENSACOLA 65 DENTAL OFFICE LOOKING TO STARBOARD LAVATORY LOWER LEFT X-RAY DEVELOPING TANK LEFT X-RAY MACHINE ABOVE DENTAL CHAIR AND PEDESTAL TYPE DENTAL UNIT BEYOND DEVELOPING TANK DENTAL ILLUMINATOR ABOVE CHAIR DENTAL CABINET AT RIGHT WITH VENTILATING DEAD LIGHT ABOVE SAFE LOCKER EXTREME RIGHT DRAINAGE PIPING WITH CANVAS COVERED LAGGING ABOVE AND AIR-SCOOP AND SCREEN IN UPPER RIGHT CORNER OF ROOM, 9670

USS PENSACOLA 66 SICK BAY LOOKING TO STARBOARD SHOWING LAVATORY AT LEFT BERTHS LOCKERS VENTILATION TERMINALS ELECTRIC REFRIGERATOR AT RIGHT AND FLAT TOP DESK IN BACK OF REFRIGERATOR, 9671

USS PENSACOLA 68 8" MAGAZINE SHOWING ALUMINUM ALLOY PORTABLE STANCHIONS DECK FASTENING TOP AND BOTTOM NATURAL EXHAUST WITH W T COVER AND CHECK VALVE W T DOOR WITH 8" POWDER PASSING SCUTTLE AND THERMOSTAT WITH GUARD IN UPPER RIGHT HAND CORNER, 9673

USS PENSACOLA 69 8" MAGAZINE SHOWING ALUMINUM ALLOY STANCHION AND METHODS OF FASTENING SAME TOP AND BOTTOM THERMOMETER BOARD PORTABLE METAL STAGE FLOODING VALVE CORK INSULATION UNDER SIDE OF DECK ABOVE AND ALUMINUM ALLOY SPRINKLING PIPES ABOVE, 9674

USS PENSACOLA 70 8" MAGAZINE SHOWING ALUMINUM ALLOY STANCHIONS AND 8" – 55 CALIBER POWDER TANKS NESTED, 9675

USS PENSACOLA 71 8" POWDER HANDLING ROOM SHOWING FROM LEFT TO RIGHT W T ELECTRIC PANEL BOX W T DOOR WITH POWDER PASSING SCUTTLE POWDER HOIST POWDER HOIST MOTOR AND VOICE TUBE MAGAZINE SPRINKLING CONTACT MAKER AND LIGHT BOX AT UPPER RIGHT ALUMINUM ALLOY HANDWHEEL AT UPPER RIGHT SPRINKLING PIPES HOIST FLIGHTS AND HOIST DOOR ARE ALUMINUM ALLOY CASTINGS, 9676

USS PENSACOLA 72 NATURAL EXHAUST IN MAGAZINE SHOWING ALUMINUM ALLOY W T COVER WITH CHECK VALVE AND WIRE MESH SCREEN NOTE WELDING OF TUBE AND DOG BOLT PADS, 9677

USS PENSACOLA 73 WATER TIGHT BULKHEAD FRAME 72 LOOKING TO PORT AND FORWARD SHOWING VENTILATION DUCT WITH PORTABLE SECTION THROUGH BULKHEAD W T ALUMINUM ALLOY COVER FOR SAME NOT SHOWN BUT STOWED NEARBY NOT WELDING ON DUCT AND BULKHEAD BOLTS AND WING NUTS ARE CORROSION-RESISTING STEEL, 9678

USS PENSACOLA 74 VENTILATION PIPES 1ST PLATFORM FRAME 111 LOOKING TO PORT AND FORWARD SHOWING SUPPLY TERMINAL AT LEFT W T EXHAUST FROM 8" POWDER MAGAZINE IN CENTER W T SUPPLY CORK PAINTED TO 8" POWDER MAGAZINE AT RIGHT NOTE WELDING ON EXHAUST PIPE, 9679

USS PENSACOLA 75 RAISED W T HATCH WITH ESCAPE SCUTTLE 1ST PLATFORM FRAME 98 LOOKING FORWARD GENERAL ANNOUNCING TELEPHONE REPRODUCER UPPER LEFT CLOCK WRENCH STOWAGES ON BULKHEAD STIFFENER VENTILATION PIPES AT RIGHT STANCHIONS AND GUARD CHAIN NOTE WELDING ON HATCH AND COAMING FITTINGS NOTE ELBOWS WELDED IN HALVES ON VENTILATION PIPES ALSO WELDED TO PIPES AT ENDS OF ELBOWS, 9680

USS PENSACOLA 76 W T HATCH AND INCLINED LADDER LEADING TO BRIG WITH GUARD CHAIN AND STANCHIONS FIRE EXTINGUISHER WITH BASKET AND MAIN MAST STRUT, 9681

USS PENSACOLA 77 BALANCED ARMOR HATCH SHOWING CASING OVER SPRING ETC SUPPORT ON BULKHEAD FOR CATCH AND METAL GRATING IN BACK OF HATCH NOTE VERTICAL AND INCLINED LADDERS IN BACKGROUND, 9682

USS PENSACOLA 78 BULKHEAD STIFFENER BRACKET TO DECK CLIP SHOWING INSERTED PLATE WELDED AND LIGHTENED NOTE AIR SUPPLY PIPE N BACKGROUND CORK PAINTED, 9683

USS PENSACOLA 79 TRANSVERSE DECK BEAM FRAME 75 SECOND DECK STARBOARD SIDE LOOKING TO PORT AND AFT SHOWING BEAM CONNECTION TO W T LONGITUDINAL BULKHEAD NOTE WELDING, 9684

USS PENSACOLA 80 WELDING COMPOSITION CLEAT RIVETED TO STEEL PLATE PLATE WELDED TO STANCHION CATCH CLIPS WELDED TO STANCHION, 9685

USS PENSACOLA 81 BULKHEAD STIFFENER BRACKET TO LONGITUDINAL DECK BEAM 2ND DECK FRAME 109 LOOKING TO PORT AND FORWARD NOTE SMALL INSERTED PLATE WELDED AIR SCOOP STOWAGE AT LEFT HAMMOCK HOOK WELDED TO BULKHEAD AT RIGHT EMBOSSED ALUMINUM ALLOY LABEL PLATE SECURED WITH DRIVE SCREWS NOTE CORK INSULATION ON OVERHEAD ABOVE AIRSCOOP, 9686

USS PENSACOLA 82 INCLINED AND VERTICAL LADDER LEADING TO MAIN DECK AFT SHOWING LANDING OF LADDER ON COAMING OF COMPANION HATCH AND NON-SLIP TREAD ON DECK LADDER TREADS ARE CLASS #4 ALUMINUM

ALLOY AND NON-SLIP TREAD IS ALLUMINUM [sic] ALLOY WITH CARBORUNDUM CAST INTO SURFACE NOTE CLIPS FROM TREADS TO LADDER SCREEN (ALUMINUM ALLOY) TO PREVENT NOISY VIBRATION OF SCREEN, 9687

USS PENSACOLA 83 COMPANION AND VERTICAL LADDERS LEADING TO COMMUNICATION PLATFORM LADDER TREADS ARE CLASS #4 ALUMINUM ALLOY LADDER SCREEN ALUMINUM ALLOY NOTE CLIPS FROM TREADS TO SCREEN, 9688

USS PENSACOLA 84 WINDLASS MACHINERY ROOM LOOKING FORWARD AND TO PORT SHOWING WILDCAT SHAFT AND LOCKING HEAD HAND RAIL IN FOREGROUND WITH CAPSTAN SHAFTING BEHIND CHAIN PIPE IN BACKGROUND WATERBURY VARIABLE SPEED GEAR B-END IN VERTICAL POSITION AND OIL PIPING AT RIGHT NOTE SHELL AND STIFFENERS AT LEFT, 9689

USS PENSACOLA 85 STEERING GEAR MOTOR ROOM LOOKING AFT SHOWING INCLINED LADDER AND STARBOARD DRIVING MOTOR AT LEFT TRICK WHEEL COMPASS WITH RUDDER ANGLE INDICATOR OVER IN CENTER PORT DRIVING MOTOR WITH OIL PIPING IN BACKGROUND AT RIGHT STARBOARD A END HYDRAULIC SPEED GEAR WITH TILTING BOX CONTROL IN CENTER BACKGROUND AND SUPPLY VENTILATION PIPING OVERHEAD NOTE NO-SLIP TREADS ON DECK, 9690

USS PENSACOLA 86 HELMSMANS STATION IN CENTRAL STATION LOOKING FORWARD AND TO STARBOARD SHOWING WHEEL ENGINE ROOM TELEGRAPHS COURSE INDICATORS NATURAL EXHAUST TERMINAL WITH W T COVER AT UPPER RIGHT AIR COOLER AND PURIFIER SUPPLY TERMINAL AT UPPER LEFT STEERING CONTROL TRANSFER SWITCH IN BACKGROUND AT CENTER AND GENERAL ANNOUNCING EQUIPMENT AND COURSE COMPONENT RECORDER IN BACKGROUND AT RIGHT, 9691

USS PENSACOLA 87 AFTER END OF FORWARD BOILER ROOM LOOKING TO PORT N FLOOR PLATE LEVEL SHOWING OIL BURNERS AND FUEL OIL PIPING AT RIGHT ALUMINUM ALLOY HANDWHEELS EXCEPT ON BURNER PIPING, 9692

USS PENSACOLA 88 FORWARD END OF FORWARD ENGINE ROOM LOOKING TO PORT ON WORKING PLATFORM SHOWING MAIN CONDENSERS AT LEFT PORT CONTROL PANEL IN BACKGROUND MAIN STEAM PIPE OVERHEAD ALUMINUM ALLOY "TRILOCK" GRATING AND HANDRAILS, 9693

USS PENSACOLA 89 AIRPORT-CLOSED BATTLE COVER DOWN CORK INSULATION ON BULKHEAD AND SHEETMETAL BINDING STRIPS FOR 1" CORK AROUND DOOR AND AIRPORT BATTLE COVER IS CLASS #2 ALLOY DROP BOLTS AND NUTS ARE CORROSION RESISTING STEEL, 9694

USS PENSACOLA 90 AIRPORT OPEN BATTLE COVER UP, 9695

USS PENSACOLA 91 AIRPORT CLOSED BATTLE COVER UP, 9696

USS PENSACOLA 92 NON-WATER TIGHT PRESSED PANEL DOORS MAIN DECK LOOKING AFT OPEN DOOR TO DECK OFFICE CLOSED DOOR TO ATHLETIC GEAR LOCKER – BULKHEAD PERFORATED AT TOP FOR VENTILATION, 9697

USS PENSACOLA 93 WASH DECK GEAR LOCKER STARBOARD SIDE MAIN DECK FRAME 31 LOOKING INBOARD SHOWING RACKS ETC W T DOOR OPEN PART OF PARAVANE STOWAGE DOOR LEVER AND CLEAT FOR PARAVANE HANDLING AT LEFT WATER SHED WELDED TO DECK HOUSE, 9698

USS PENSACOLA 94 WATER TIGHT PRESSED PANEL DOOR STARBOARD SIDE MAIN DECK FRAME 31 SHOWING DOOR CLOSED AND DOGGED PIPE LEVER RIGHT AND LEFT DOOR HOOK AT RIGHT CENTERING WEDGE BELOW AND WATER SHED ABOVE AND COMPARTMENT TEST CONNECTION WITH CAP AT CENTER OF DOOR, 9699

USS PENSACOLA 95 INSIDE OF W T PRESSED PANEL DOOR STARBOARD SIDE MAIN DECK FRAME 31 SHOWING RUBBER GASKET DOOR STIFFENER AND BRACKETS WELDED TO DOOR, 9700

USS PENSACOLA 96 ALUMINUM ALLOY JOINER DOOR FRAME 40 LOOKING AFT SHOWING LAGGED VENTILATION PIPES OVERHEAD DOOR WITH HYDRAULIC DOOR CHACK DOOR STOP AND HOOK AT RIGHT NON-SLIP TREAD OF ALUMINUM ALLOY WITH CARBORUNDUM CAST INTO SURFACE ALUMINUM ALLOY BULKHEADS WITH PILASTERS AT RIGHT AND LEFT, 9701

USS PENSACOLA 97 ALUMINUM ALLOY SLIDING JOINER DOOR 2ND DECK FRAME 20 LOOKING AFT WITH LOWER PANEL LOUVERED AND CURTAIN DAVIT STEP FROM HATCH ABOVE AND VENTILATION SCREENS ABOVE BULKHEAD ALUMINUM ALLOY, 9702

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO HEAD OF DOCK FROM SCAFFOLD AT SLIDE 8 HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9703

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO N END E WALL LOOKING S HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9704

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO N END E WALL LOOKING S HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9705

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO BACKING E WALL & SHOWING CRANE RAIL FNDN HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9706

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO FDN PILES ADDITION BLG 41 YARD LABOR, 9707

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO HEAD OF DOCK FROM SCAFFOLD AT SLIDE 8 HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9708

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO EL DUTCH CHANGE AROUND HEAD W END LOOKING SW HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9717

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PUMP WELL DISCHARGE CULVERT FORMS HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9718

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO HEAD OF DOCK FROM FLOOR HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9733

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PUMP WELL VALVES IN PLACE HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9736

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO LOOKING DOWN IN PUMP WELL HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9737
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO LOOKING NE IN PUMP WELL – SHOWING VALVES HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9738
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO COFFERDAM – LOOKING NW HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9739
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PROGRESS MAP FOR NOVEMBER HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9740
MONTHLY PROGRESS PHOTO ADDITION BUILDING NO 41 YARD LABOR, 9741
DRY DOCK NO 4 GENERAL VIEW – LOOKING NORTH HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9742
DRY DOCK NO 4 FLOODING DOCK – VIEW FROM ALTAR E SIDE HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9743
DRY DOCK NO 4 FLOODING DOCK – VIEW FROM FLOOR HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9744
DRY DOCK NO 4 FLOODING DOCK – VIEW FROM W COPING HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9745
DRY DOCK NO 4 FLOODING DOCK – VIEW FROM W COPING HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9746
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO DREDGING ENTRANCE HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9749
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAISSON PENN BRIDGE CO CONTRACTOR, 9750
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAISSON PENN BRIDGE CO CONTRACTOR, 9751
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAPSTAN AT HEAD OF DOCK YARD LABOR, 9752
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO ADDITION TO BUILDING 41 YARD LABOR, 9753
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO JUNCTION OF SEWERS HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9754
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PUMP CHAMBER IN PUMP WELL ALBERGER PUMP CO CONTRACTOR, 9755
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO N PUMP CASING ALBERGER PUMP CO CONTRACTOR, 9756
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO N & CENTER PUMP CASINGS ALBERGER PUMP CO CONTRACTOR, 9757
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PUMP CASINGS ALBERGER PUMP CO CONTRACTOR, 9758
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PROGRESS MAP FOR DEC HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9762
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO JUNCTION OF SEWERS E SIDE, 9763
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAPSTAN AT HEAD OF DOCK YARD LABOR, 9764
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO SUCTION PIPE TRENCH AT CORNER OF PUMP WELL HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9765
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO SUCTION PIPE TRENCH NEAR SEA WALL HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9766
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO DISCHARGE MAIN BLDG 41 HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9767
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO DISCHARGE MAIN BLDG 41 HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9768
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CRANE TRACK TURN OUT E SIDE LOOKING SW HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9769
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO ADDITION BLDG 41 CONDENSER SYSTEM PIPING YARD LABOR HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9770
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAISSON PENN BRIDGE CO CONTRACTOR, 9771
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO DREDGING ENTRANCE HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9772
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GENERAL VIEW LOOKING N HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9773
DRY DOCK NO 4 MONTHLY PROGRESS GENERAL VIEW LOOKING S HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9774
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO SWITCH BOARD & MOTOR CASING ALBERGER PUMP CO CONTRACTOR, 9775
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO UM WELL LOOKING S ALBERGER PUMP CO CONTRACTOR, 9776
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO UM WELL LOOKING S ALBERGER PUMP CO CONTRACTOR, 9777
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO N & CTR PUMP CASINGS LOOKING NE ALBERGER PUMP CO CONTRACTOR, 9778
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO MONTHLY PROGRESS MAP HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9779
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO SEWER JUNCTION LOOKING SW HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9782
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO SEWER JUNCTION LOOKING N HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9783
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAPSTAN IN BLDG 41 LOOKING SE YARD LABOR, 9784
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAISSON PENN BRIDGE CO CONTRACTOR, 9786

DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PUMP WELL LKG SE OVER CTR & S PUMP CASING ALBERGER PUMP CO CONTRACTOR, 9788
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO LOOKING NW FROM E SIDE OF ENTRANCE HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9820
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO MONTHLY PROGRESS MAP HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9821
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO GENERAL VIEW LOOKING NE HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9822
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAISSON PENN BRIDGE CO CONTRACTOR, 9825
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAISSON PENN BRIDGE CO CONTRACTOR, 9826
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO MARCH MONTHLY PROGRESS MA HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9836
Dry Dock 4 monthly progress photo – Caisson in place looking northeast , 9839
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAPSTAN IN BLG 41 LOOKING W YARD LABOR, 9843
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAPSTAN IN BLG 41 LOOKING SE YARD LABOR, 9844
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO APRIL MONTHLY PROGRESS MAP HOLBROOK CABOT & ROLLINS CORP CONTRACTOR , 9847
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO TRENCH FOR CONDENSER PIPES HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9850
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO N END W WALL FROM E WALL HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9852
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO EL DUCT CHANGE AROUND HEAD W END LOOKING SW HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9857
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO FDN PILES ADDITION BDG 41 YARD LABOR, 9866
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO BACKING E WALL & SHOWING CRANE RAIL FNDN HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9867
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO S END W WALL LOOKING NW HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9892
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO S END E WALL LOOKING NE HOLBROOK CBOT & ROLLINS CORP CONTRACTOR, 9894
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO CAPSTAN HEAD OF DOCK LOOKING S ALONG \sphericalangle YARD LABOR, 9896
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO OCTOBER PROGRESS MAP HOLBROOK CABOT & ROLLINS CORP CONTRACTOR, 9903
DRY DOCK NO 4 WATER FLOWING FROM 8" PIPE THROUGH DOCK FLOOR PIPE TOP 14'-7" ABOVE FLOOR SURFACE H C & R CORP CONTRACTOR, 9908
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO C I MAIN TO CONDENSER HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 9916
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PROGRESS MAP HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 9917
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO PROGRESS MAP HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 9918
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO WATER FLOWING FROM PIPE FLOOR HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 9921
DRY DOCK NO 4 MONTHLY PROGRESS PHOTO S END W WALL LOOKING NW HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 9927
MONTHLY PROGRESS PHOTO ADDITION TO BUILDING 131 FOR LATRINE FOR DRY DOCK NO 4 LOOKING NW YARD LABOR, 10109
DRY DOCK 4 CONTRACTORS STORAGE YARD GRANITE FOR CAISSON SEATS LOOKING N HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10110
DRY DOCK 4 OLD SHEET PILING ELE 60 PANEL 31 HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10111
DRY DOCK 4 OLD SHEET PILING PANEL 31 EL 60, 10112
DRAINAGE TRENCH , 10114
DRY DOCK 4 SHEET PILING PANEL 31 EL HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10115
DRY DOCK NO 4 BOTTOM REINFORCEMENT COFFERDAM EL 51 HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10116
DRY DOCK 4 FORMS & REINFORCEMENT FOR CENTRE SECTION OF COFFERDAM LOOKING WEST HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10117
DRY DOCK NO 4 FORMS AND REINFORCEMENT FOR CENTER SECTION OF COFFERDAM LOOKING EAST, 10118
DRY DOCK NO 4 BEAM B & GIRDER C PUMP WELL LOOKING WEST, 10119
DRY DOCK NO 4 BEAM B & GIRDER C PUMP WELL LOOKING WEST, 10120
DRY DOCK NO 4 PANEL 18 FROM WEST SIDE HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10121
FROM DERRICK NO 7 GENERAL VIEW HEAD END, 10122
DRY DOCK 4 PROGRESS MAP, 10125
PANEL 34 FROM W, 10126
PANEL 33 FROM NE, 10127

PANEL 33 FROM SE, 10128
DRY DOCK 4 PUMP WELL LOOKING NE SHOWING SPECIAL CASTINGS HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10130
Dry Dock 4 Pumpwell Looking Southwest, 10131
DRY DOCK 4 PANEL 27 FLOOR LAID HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10132
DRY DOCK 4 PANEL 38 FROM WEST HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10133
DRY DOCK 4 PANEL 34 LAYING BRICK LOOKING EAST HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10134
DRY DOCK 4 PANEL 32 FROM NE HOLBROOK CABOT & ROLLINS CORP CONTRACTORS, 10135
DD 4 PARTS OF SPEARIN WILLIAMS, THE HOLBROOK CABOT AND ROLLINS CORP, 11012
DD 4 PARTS OF SPEARIN WILLIAMS THE HOLBROOK CABOT AND ROLLINS CORP, 11013
DD 4 MONTHLY PROGRESS PHOTO CRACK AT SOUTH END OF CAISSON QQ LOKING WEST THE HOLBROOK CABOT AND ROLLINS CORP, 11014
DD 4 MONTHLY PROGRESS PHOTO CRACK IN CAISSON LOOKING WEST THE HOLBROOK CABOT AND ROLLINS CORP, 11015
DD 4 MONTHLY PROGRESS PHOTO MOVEMENT CAISSON_ THE HOLBROOK CABOT AND ROLLINS CORP, 11016
DD 4 MONTHLY PROGRESS PHOTO TO CAISSON WEST SIDE CAISSONS KK JJ LOOKING WEST THE HOLBROOK CABOT AND ROLLINS CORP, 11017
DRY DOCK 4 SINKING DIAGRAMS FOR ARCH PUMP WELL AND COFFERDAM CAISSONS, 11018
DRY DOCK 4 SINKING DIAGRAMS FOR CAISSONS WEST INTERMEDIATE ROW, 11019
DRY DOCK 4 SINKING DIAGRAMS FOR CAISSONS CENTER AND EAST INTERMEDIATE ROWS, 11020
DRY DOCK 4 SINKING DIAGRAMS FOR CAISSONS, 11021
DRY DOCK 4 STATUS THE HOLBROOK CABOT AND ROLLINS CORP, 11022
DD 4 MONTHLY PROGRESS PHOTO GENERAL VIEW OF NORTH END LOOKING NORTH THE HOLBROOK CABOT AND ROLLINS CORP, 11023
DD 4 MONTHLY PROGRESS PHOTO GENERAL VIEW CAISSON BRACING WEST SIDE LOOKING SOUTH THE HOLBROOK CABOT AND ROLLINS CORP, 11024
Dry Dock 4 Monthly Progress Photo General View Looking North the Holbrook Cabot and Rollins Corp, 11025
DD 4 MONTHLY PROGRESS PHOTO GENERAL VIEW LOOKING SOUTH THE HOLBROOK CABOT AND ROLLINS CORP, 11026
DD 4 MONTHLY PROGRESS PHOTO CAISSON BRACING LOOKING SOUTH EAST_ THE HOLBROOK CABOT AND ROLLINS CORP , 11027
DD 4 SOUTH END LOOKING SOUTHWEST THE HOLDBROOK CABOT AND ROLLINS CORP, 11028
DD 4 EXAMPLE OF METAL SHEET PILING UNCOVERED AT S. END OF DOCK THE HOLBROOK CABOT AND ROLLINS CORP, 11029
DRY DOCK 4 PUMP WELL PLAN, 11030
DRY DOCK 4 CROSS-SECTIONS THROUGH PUMP WELL AND DISCHARGE CULVERT, 11031
DRY DOCK #4 DETAILS OF INTERMEDIATE CASSONS WITH PLUMB SIDE, 11032
USS Ohion, Barge Fashion, 11047
USS Ohion, Barge Fashion, 11048
GOWANUS RESERVE COAL STATION, 11050
GOWANUS RESERVE COAL STATION, 11051
GOWANUS RESERVE COAL STATION, 11052
GOWANUS RESERVE COAL STATION, 11054
GOWANUS RESERVE COAL STATION, 11055
INTERIOR OF BARGE 94 PELHAM BAY, 11056
[Food carriers with stackable pots], 11057
[Food carriers with stackable pots], 11058
[Food carriers with stackable pots], 11059
[Article in the engineering record Fire Streams from Small Hose and Nozzles], 11060
[Article in the engineering record Fire Streams from Small Hose and Nozzles], 11061
[Article in the engineering record Fire Streams from Small Hose and Nozzles], 11062
NAVY RESCUE BREATHING APPARATUS WITH DRAEGER AUTOMATIC VALVE FRONT VIEW ON MODEL, 11063
NAVY RESCUE BREATHING APPARATUS WITH DRAEGER AUTOMATIC VALVE BACK VIEW ON MODEL, 11064
NAVY RESCUE BREATHING APPARATUS WITH DRAEGER AUTOMATIC VALVE FRONT VIEW ON MODEL, 11065
[Machine], 11066
[Machine], 11067
[World Map], 11068
LYSHOLN TABLE FURNISHED BY NORBOURN ENG. CO, 11069
LYSHOLN TABLE FURNISHED BY NORBOUN NEG CO, 11070
LYSHOLN TABLE FURNISHED BY NORBOUN NEG CO, 11071
[Machine part detail], 11072
[Machine part detail], 11073
[Machine part detail], 11074
TEST OF STANDARD MANHOLE MOUNTING, 11075
CHALKING TOOLS LEAD PACKING FOR LEAD PACKED STUFFING BOXES, 11076

[World Map], 11077
 [Untitled Object], 11154
 [Untitled Object], 11156
 [Untitled Object], 11157
 [Untitled Object], 11158
 [Untitled Object], 11159
 [Untitled Object], 11160
 OFFICE OF INSPECTOR OF ENGINEERING MATERIALS 44 COURT STREET TEMPLE BAR BUILDING, 11161
 PERSONNEL OFFICE OF INSPECTOR OF ENGINEERING MATERIALS 44 COURT STREET MAIN OFFICE, 11164
 COLLAPSE OF STEEL STORAGE RACKS ON ORDANANCE DOCK LOOK E , 11165
 COLLAPSE OF STEEL STORAGE RACKS ON ORDANANCE DOCK LOOK E , 11168
 COLLAPSE OF STEEL STORAGE RACKS ON ORDANANCE DOCK LOOK W , 11169
 COLLAPSE OF STEEL STORAGE RACKS ON ORDANANCE DOCK LOOK W , 11170
 COLLAPSE OF STEEL STORAGE RACKS ON ORDANANCE DOCK LOOK W , 11171
 TEST OF STANDARD MANHOLE MOUNTING A, 11172
 [Untitled Object], 11173
 [Untitled Object], 11174
 [Untitled Object], 11175
 [Untitled Object], 11176
 [Untitled Object], 11177
 BOTTOM ROLL FOR SHIP LINER ROLLS, 11178
 BOTTOM ROLL FOR SHIP LINER ROLLS, 11179
 BOTTOM ROLL FOR SHIP LINER ROLLS, 11180
 TEST OF LEAD PACKED STUFFING BOX, 11181
 SAMPLE WELD FOR FUEL OIL PIPING. NEW STRUCTURAL SHOP BLDG #4, 11182
 SAMPLE WELD FOR FUEL OIL PIPING. NEW STRUCTURAL SHOP BLDG #4, 11183
 SAMPLE WELD FOR FUEL OIL PIPING. NEW STRUCTURAL SHOP BLDG #4, 11184
 SAMPLE WELD FOR FUEL OIL PIPING. NEW STRUCTURAL SHOP BLDG #4, 11185
 CONT # BUS 45968 REQ C AND R 53'-18. DEL ON CAR PL 800154_GENERAL VIEW SHOWING MACHINE AS SHIFTED ON
 CAR IN TRANSIT SHOWING BREAKAGE, 11186
 3 INCH 50 CALIBER MARKED 6, 11187
 3 INCH 50 CALIBER MARKED 6, 11188
 CONT # BU 45968 DATED 01/29/1919 REQ 53 NSA 1919_DELIVERED ON CAR PL 853126 03/10/1919_SIDE VIEW SHOWING
 BROKEN BEARINGS, 11189
 CONT # BU 45968 DATED 01/29/1919 REQ 53 NSA 1919_DELIVERED [ILLEGIBLE], 11190
 CONT # BU 45968 dated 01/29/1919 REQ 53 NSA 1919 delivered on car PL 853126 detail view showing broken bearings , 11227
 CONT # BUREAU 45968 DATED 01/29/1919 REQ 53 NSA 1919 ON CAR PL 853126 03/10/1919 GENERAL VIEW SHOWING
 MACHINE AS SHIFTED ON CAR IN TRANSIT CAUSING BREAK, 11229
 TEST 1809A FUGURE E3 DREADNAUGHT SAFETY SUIT COMPLETELY DONNED, 11230
 HD TEST # 1769 A LADDER TREADS UNIVERSAL TREAD SHOWING METHOD OF TEST, 11235
 HD TEST # 1769 A LADDER TREADS NAVY STANDARD SHOWING METHOD OF TEST, 11236
 HD TEST #1769 A LADDER TREADS UNIVERSAL TREAD LATERAL BENDING, 11237
 HD TEST #1769 A LADDER TREADS NAVY STANDARD LATERAL BENDING, 11238
 HD TEST #1769 A LADDER TREAD NAVY STANDARD SHOWING BROKEN WOOD, 11239
 HD TEST #1769 A LADDER TREADS UNIVERSAL TREAD SHOWING FAILURE AT RIVET HOLE, 11240
 [Untitled], 11241
 SHIPS IN PORT OF NEW YORK THAT ARE BEING REPAIRED UNDER THE JURISDICTION OF THE INDUSTRIAL MANAGER
 EXCEPT THOSE VESSELS UNDER REPAIR AT MARINE BASIN, 11242
 CONT # BU 45968 DATED 01/29/1919 REQ 53 NSA 1919_DELIVERED [ILLEGIBLE], 11243
 CONT # BU 45968 DATED 01/29/1919 REQ 53 NSA 1919 DELIVERED ON CAR PL 853126 03/10/1919 SIDE VIEW SHOWING
 BROKEN BEARINGS, 11244
 3 INCH 50 CALIBER MARKED 6, 11245
 3 INCH 50 CALIBER MARKED 6, 11246
 LAND PRODUCTS CO NEW YORK ENGINEERING DEPARTMENT, 11248
 LAND PRODUCTS CO NEW YORK ENGINEERING DEPARTMENT, 11249
 LAND PRODUCTS CO NEW YORK ENGINEERING DEPARTMENT, 11250
 ACCIDENT TO LOCOMOTIVE CRANE NO 28 DETAIL VIEW OF FORWARD TRUCK RIGHT SIDE, 11251
 ACCIDENT TO LOCOMOTIVE CRANE NO 28 GENERAL VIEW RIGHT SIDE, 11252
 ACCIDENT TO LOCOMOTIVE CRANE NO 28 IRREGULARITY OF TRACKS UPON WHICH ACCIDENT OCCURRED LOOKING
 WEST, 11253
 ACCIDENT TO LOCOMOTIVE CRANE NO 28 GENERAL VIEW LEFT SIDE, 11254
 ACCIDENT TO LOCOMOTIVE CRANE NO 28 DETAIL VIEW OF DAMAGE RIGHT SIDE, 11255
 [Untitled], 11256
 [Untitled], 11257
 TEST OF LEAD PACKED STUFFING BOX, 11258

BOTTOM ROLL FOR SHIP LINER ROLLS, 11259
 BOTTOM ROLL FOR SHIP LINER ROLLS, 11260
 Storehouse and accessories - Laying new saltwater pipe at north end of new non-commissioned officers' quarters Building 58, between Buildings 130 and 152, 573
 Storehouse and Accessories, View Showing Completed Pile Caps – Non-commissioned Officers' Quarters Building 58 between Buildings 130 and 152, 575
 Building 58 Construction and Scaffolding, 594
 Storehouse and Accessories, Building No. 58 - View of East Face of Non-Commissioned Officers' Quarters, 599
 Remodeling Building 32 Sheathing Piling and Foundation Excavation, 623
 Remodeling of Building 32 Excavation Sheet Piling and Whalers, 625
 General View of Wall Foundation and Floor Support Forms Building 32, 629
 Removing Last of the Steel of the 2nd Floor of Building 10, View Looking South, 631
 Demolition of Wall on Stringham Avenue, East End of Building 214 for Outside Crossover Connection to Railroad Tracks, 632
 Repairs to Standard Gauge Railroad Tracks on Chauncey Avenue between Second and Third Streets at Building 14, 633
 Paving with asphalt block south end of Second Street, 634
 Preparing transformers for removal to platform adjacent to present position at Fifth Street and Morris Avenue Building 41, 637
 Skylight Cornice and Gutter Work on Lean-to and Remodeling of Building 10, 640
 Removing Old Monitors and Roof Sheathing of Building 11 on Second Street Side , 641
 General view of Interior of Building 11 Showing Roof Removed, 642
 Copper Forms and General Roof Work on Extension to Building 234, 643
 General View of Lean-to, Building 12, 645
 Remodeling of Buildin 92, View on 2nd Floor, East Side, 666
 Steam Main Duct to Building 92, 672
 Remodeling of Building 92, View in Basement Showing Gas, Water and Steam Intakes, 677
 Remodeling Building 92, Removing Rear Porch, 678
 Remodeling Building 92, View of New Concrete Foundation for Rear Porch, 684
 Remodeling Building 92, Repairing Exterior, South Side, 685
 Remodeling Building 92, Repairs to Exterior, East Side, 686
 Remodeling Building 92, Repairing Exterior of the West Side, 687
 Remodeling Building 92, Repairing Exterior, North Side, 688
 Remodeling Building 92, view of east side, 696
 Remodeling Building 92, view of north side, 697
 Remodeling Building 92, view of new rear porch, 699
 Remodeling Building 92, view of bathroom basement, 700
 Remodeling building view of laundry in basement, 701
 Marine Barracks Building 93, view looking northeast, 702
 Alterations to Building 93 for Marine Officers Quarters, Exterior View of West Side, 705
 Alterations to Building 93 for Marine Quarters, General View of Pipe Lines to Building, 708
 Alterations to Building 93 to Marine Officers Quarters, General Exterior View of West Side Looking East, 720
 Alterations to Building 93 for Marine Officers Quarters, General Exterior View of West Side Showing Keystone in Place above Arch, 721
 Alterations to Building 93 for Marine Officers Quarters, Exterior View of South and West Side, 726
 Alterations to Building 93 for Marine Officers Quarters, General View of West Side Looking East, 727
 Repairs to Sidewalks in Immediate Vicinity of Building 93, View Looking East, 738
 Interior Demolition of Floors in Building 10, 818
 Grouting Base of Flanging Machine in New Shop, Building 11, 983
 Elevator at Building Ways No. 1 for Accident to WPA Workmen, 988
 Field Supervisory Staff, 989
 Repairs to Standard Gauge Railroad Track at Dock and Second Streets , 991
 Building 32 Roof, 992
 General View of Building 32, Rear, 993
 Applying Insulation on Roof of Building 32, 994
 Elevator at building, Ways 1 , 998
 General View - Interior of Consolidation of Shops, 1003
 General Interior View - Consolidation of Shops Buildings 11 and 12, 1004
 Waterfront between Piers C and D, 1005
 Repairs to Wide Gauge Track Starboard Side of Dry Dock 4, 1007
 Repairs to Railroad Tracks at Third and Dock Streets, 1008
 Skylight Improvements - Roof of Forge Shop, Building 11, 1011
 Electrical Work in Transformer Room, Consolidation of Shops, 1013
 General View of Sheet Metal Shop from Roof of Pipe and Copper Office Showing Three Runway Monorail Crane, 1014
 Monorail Spur Tracks Leading to Crane, Building 11A, 1015
 Turntable Switch and Switches in Acid Room - Consolidation of Shops, 1017
 Improvements to Building 37, 1022
 Improvement to Building 37, View of West Wall, 1023

Demolition of Building 37, 1032
 General View on Chauncey Avenue from Second Street to Fifth Street , 1033
 Public Utilities Installing 8" Freshwater Main Showing Line on Chauncey Avenue Near Third Street, 1038
 Demolition of Marine Barracks Extension, South End of Building 13 and Excavation for Foundation, 1040
 Improvements to Marine Barracks - Excavation and Installation of 8" Freshwater Line, 1041
 Erecting Skylight Base Frames on Roof of the Forge Shop Building 11, Third Street Side, 1042
 Excavating - Driving Sheet Piling for Garage Foundation and Breaking Up Old Concrete Floor, 1043
 Railroad rolling stock - general repair to steam crane, 1044
 Demolition of Marine Barracks Extension, 1047
 Demolition of Marine Barracks - Excavations and Pile Driving, South End of Building, 1048
 Improvements to garage excavating and driving sheathing former site of Building 37, 1050
 Public Utilities - Excavating for installation of 8 inch fresh water line on Perry Avenue north of Second Street, 1051
 Demolition of Extension to Marine Barracks Driving Sheet Piling and Excavating for Foundations South of building, 1052
 Improvements to Garage Driving Piles, Excavating, and Building Forms for Foundation Work, 1053
 Remodeling Roof of Building 11, Forge Shop - Removing Old Monitors, Installing New Roof Sheeting, Skylights, and Ventilators, 1054
 Plumbing Installation of Waste and Drain Lines Building 204, 1055
 Improvements to Marine Barracks Driving Piles, Sheet Piling, Excavating and Removing Spoil, 1057
 Improvements to Marine Barracks - Driving Piles, Sheet Piling, Excavating and Removing Spoil, 1059
 Improvements to Marine Barracks Driving Piles, Sheet Piling, Excavating and Removing Spoil, 1061
 Asbestos Covering and Painting of Steam Lines, Boiler Room Power Plant, 1062
 Driving Pile for Foundation of New Garage Building 37, 1065
 Installation of 8" Fifth Street Freshwater Line on West Side of Dry Dock 2, 1068
 General Repairs to Rolling Stock at Roundhouse, 1069
 Receiving and laying concrete floor slab of Building 32, 1079
 Receiving and laying concrete floor slab Building 32, 1084
 Repaving Dock Street between Second and Third Street with Granite Blocks, 1091
 Improvements to Ramps, Platforms, and Catwalks Building Ways No. 1 and 2, 1093
 Improvements to Ramps Platforms and Catwalks Buildingways No. 1 and 2, 1094
 General view consolidation of shops looking north from resin platform, Building 11A, 1128
 Paving of parking lot at foot of Second Street, 1135
 General view of floor opening south end of Building 128 repairs to floor supports, 1142
 Excavation Work for Repairs to Floor Support in Building 128, 1146
 Standard Gauge Track Improvements East Side of Dry Dock 3, 1150
 Excavating Grading and Repaving Waterfront between Dry Dock 2 and 4, 1152
 Street Drainage to Sewer Connections South End of Dry Dock 4, 1153
 Improvements to Garage Building, Brick Partition between Buildings 32 and 37, 1154
 Public Utilities - Fire Hydrant Connection on Perry Avenue Near Third Street at Building 13, 1155
 Demolition of Hose House Building 138 for New Cumberland Street Gate Project, 1156
 Removing Coping from Top of Wall at Location for New Cumberland Street Gate, 1158
 Exterior View of Proposed Location of New Cumberland Street Gate, 1159
 Receiving and laying concrete floor slabs remodeling of Building 37, 1161
 Receiving and Laying Concrete for Floor Slabs Remodeling of Building 37, 1162
 Repairs to Standard Gauge Railroad Tracks near Berth 6, 1163
 View of Building 200, Building 15, and Sand Street Gate inside yard, 1164
 View of Building 200, Building 15, and Sand Street Gate, 1165
 Form work for crane track improvements in Pier C, 1166
 Form Work for Crane Track Improvements on Pier C, 1167
 Close-up View of Hammer Driving Tube Pile in Foundation Pit for New Guard House and Gate at Cumberland Street., 1169
 Erection of double quarters at main entrance of naval hospital, 1247
 Erecting double quarters at main entrance of Naval Hospital, view looking northwest , 1249
 Medical Staff and Patients in Ward, 1263
 Electrical Class, Radio Section, 2125
 Electrical Class, Armature Winding Section , 2126
 Electrical Class, Dynamo Section, 2131
 BLDG #41 COMP AIR INSTALL YARD LABOR, 3779
 SUBASSEMBLY SHOP IMPROVEMENTS OF SHOP BUILDINGS AND STEEL STORAGE RUNWAYS VIEW LOOKING WEST SHOWING EXCAVATING WORK ON SITE FOR BUILDING 62 NOY 4243, 3780
 SUBASSEMBLY SHOP IMPROVEMENTS OF SHOP BUILDINGS AND STEEL STORAGE RUNWAYS VIEW OF FIELD OFFICE ON 5TH STREET NEAR DD 2 CONTRACT NOY 4243 , 3781
 SUBASSEMBLY SHOP IMPROVEMENTS OF SHOP BUILDINGS AND STEEL STORAGE RUNWAYS VIEW LOOKING WEST SHOWING COLUMN FOOTINGS FOR PAINT SHOP BLDG NO 62 CONTRACT NOY 4243, 3782
 PAINT SHOP BLDG NO 62 VIEW OF EAST CORNER OF INTERIOR SHOWING STAIRWAY AND FINISHED ROUGH TILE CONTRACT NOY 4243, 3783
 PAINT SHOP BLDG 62 VIEW LOOKING WEST SHOWING CONDUIT FOR POWER CABLES LEADING INTO BLDG CONTRACT

NOY 4243, 3784
PAINT SHOP BLDG 62 GENERAL VIEW OF BLDG SHOWING THE PLACING OF BRICK ON THE WEST AND SOUTH FRONTS CONTRACT NOY 4243, 3785
PAINT SHOP BLDG 62 GENERAL VIEW LOOKING WEST OF SECOND FLOOR CONTRACT NOY 4243, 3786
PAINT SHOP BLDG NO 62 VIEW LOOKING NORTHEAST FROM 5TH ST SHOWING FRONT SOUTH SIDE OF PAINT SHOP CONTRACT NOY 4243, 3787
PAINT SHOP BLDG 62 VIEW LOOKING NORTHEAST FROM FIFTH ST SHOWING FRONT SOUTH ELEVATION CONTRACT NOY 4243, 3788
PAINT SHOP BLDG NO 62 VIEW OF SOUTH SIDE NOY 4243, 3789
Subassembly Shop - Improvements of Shop Buildings and Steel Storage Runaways, Looking East on Chauncey Avenue Showing Excavation Work for Footings of Building 63, 3793
[untitled], 3801
SUB ASSEMBLY SHOP NO2, BLDG 564 VIEW LOOKING EAST FROM DOCK ST SHOWING STEEL ERECTION NOY 4243, 3802
VIEW LOOKING SOUTHEAST ON CHAUNCEY AVE SHOWING NORTHWEST WALL OF BLDG 63 NOY 4243, 3803
VIEW LOOKING NORTH ON CHAUNCEY AVE SHOWING STEEL ERECTION ON BLDG NO 63 NOY 4243, 3805
VIEW OF 4TH ST SE END OF BLDG NO 63 NOY 4243, 3806
VIEW OF 3RD ST NW END OF BLDG NO 63 NOY 4243, 3807
VIEW OF REINFORCING FOR SLAB BEING PLACED IN N CORNER, 3RD ST END OF BLDG NO 63 NOY 4243, 3808
NORTHWEST, 3RD ST END OF BLDG NO 63 NOY 4243, 3809
VIEW OF SOUTHEAST 4TH ST END OF BLDG NO 63 NOY 4243, 3810
VIEW OF 2ND FLOOR OF BLDG NO 63 FROM SOUTHEAST 4TH ST END OF BLDG NOY 4243, 3811
IMPROVEMENTS TO SHOP BLDG 63 MEZZANINE N SIDE BLDG 63 NOY 4243, 3813
IMPROVEMENTS TO SHOP BLDG 63 MEZZANINE S SIDE BLDG 63 NOY 4243, 3814
RELOCATION OF STRESS RELIEVING FURNACE BLDG NO 68 LOOKING N FROM OUTBOARD END OF BLDG NO 18 SHOWING SECOND SECTION ON BARGE RNV C&M YARD LABOR, 3815
RELOCATION OF STRESS RELIEVING FURNACE BLDG NO 68 VIEW LOOKING SE SHOWING FIRST SECTION RELOCATED AT NORTH END OF BLDG 18 RNV C&M YARD LABOR, 3816
RELOCATION OF STRESS RELIEVING FURNACE BLDG NO 68 VIEW LOOKING NW SHOWING DISMANTLING RNV C&M YARD LABOR, 3817
VIEW LOOKING SE SHOWING RELOCATED STRESS RELIEVING FURNACE BLDG NO 68 RNV 7X191439/X266-575 YARD LABOR, 3818
BLDG 69 SUB STATION 4, 3819
REPAIRING ROOF AND METAL WORK OF BLDG 69 ALLOT 7X218-23-1, 3820
FOR THE EXTENSION TO ROOF OF TURRET WELDMENT HOUSE BLDG NO 72 NEAR BLDG 131 REPLACEMENT NAVAL VESSELS C & M YARD LABOR, 3821
FOR THE EXTENSION TO ROOF OF TURRET WELDMENT HOUSE BLDG NO 72 AT SEA WALL NEAR BLDG 131 REPLACEMENT NAVAL VESSELS C & M YARD LABOR, 3822
EXTENSION OF ROOF OF TURRET WELDMENT HOUSE BLDG 72 AT SEA WALL NEAR BLDG 131 REPLACEMENT NAVAL VESSELS C & M YARD LABOR, 3823
ALTERATION TO BLDG 74 FOR FIRE ENGINE HOUSE VIEW LOOKING SW YARD LABOR ALLOT 7201-4, 3824
ALTERATION TO BLDG 74 FOR FIRE ENGINE HOUSE VIEW LOOKING NW YARD LABOR ALLOT 7201-4, 3825
ALTERATIONS TO BLDG 74 FOR FIRE ENGINE HOUSE COMPLETED YARD LABOR ALLOT 7201-4, 3826
REPAIRS TO BLDG 87 ALLOT 74201-46 YARD LABOR FRONT VIEW, 3827
REPAIRS TO BLDG 87 ALLOT 74201-46 YARD LABOR, 3828
ALTERATIONS TO BLDG 88 FOR MARINE OFFICERS GARAGE ALLOT 6201-12, 3829
ALTERATIONS TO BLDG 93 FOR MARINE OFFICERS QUARTERS ENTRANCE TO PORCH AND STAIRS YARD LABOR, 3830
MONTHLY PROGRESS PHOTO BLDG 114 TROLLEY TRACKS LOOKING SW LARD YAVOR, 3831
MONTHLY PROGRESS PHOTO BLDG 114 136 NEW TROLLEY TRACKS LOOKING SW YARD LABOR, 3832
TRANSVERSE CRANE RUNWAY START OF DEMOLITION OF BLDG 115 CONTRACT NOY 4243, 3833
TRANSVERSE CRANE RUNWAY BLDG NO 115 DEMOLITION CONTRACT NOY 4243, 3834
STOREHOUSE AND ACCESSORIES, VIEW TAKEN FROM TOP OF HAMMERHEAD CRANE SHOWING NORTH PART OF NEW SCRAP METAL PLANT BLDG 118 SHOWING BIN WALLS CONSTRUCTED ON ATHLETIC FIELD CONTRACT NOY 4163, 3835
STOREHOUSE AND ACCESSORIES BLDG 77 VIEW TAKEN FROM WEST SIDE OF NEW SCRAP METAL PLANT SITE LOOKING EAST SHOWING EXCAVATION WORK CONTRACT NOY 4163, 3836
STOREHOUSE AND ACCESSORIES BLDG 77 VIEW TAKEN FROM TOP OF HAMMERHEAD CRANE SHOWING SOUTH PART OF NEW SCRAP METAL PLANT ERECTION OF BIN WALLS BUILDING NO 118 BEING CONSTRUCTED ON ATHLETIC FIELD CONTRACT NOY 4163, 3837
STOREHOUSE AND ACCESSORIES, VIEW SHOWING OFFICE FOUNDATION AND BIN WALLS OF NEW SCRAP METAL PLANT BLDG 118 CONSTRUCTED ON ATHLETIC FIELD CONTRACT NOY 4163, 3838
STOREHOUSE AND ACCESSORIES, VIEW LOOKING SOUTHEAST SHOWING STEAM DUCT IN FRONT OF BLDG 87 FOR NEW SCRAP METAL PLANT BLDG 118 CONT NOY 4163, 3839
STOREHOUSE AND ACCESSORIES VIEW LOOKING NORTHWEST FROM FRONT OF BLDG 87 SHOWING STEAM DUCT FOR NEW SCRAP METAL PLANT BLDG 118 CONT NOY 4163, 3840
STOREHOUSE AND ACCESSORIES VIEW LOOKING NORTH SHOWING OFFICE BLDG AND SCALE PIT WORK AT NEW

SCRAP METAL PLANT BLDG 118 CONT NOY 4163, 3841
 STOREHOUSE AND ACCESSORIES VIEW LOOKING NORTH SHOWING WORK ON TRACK TO THE NEW SCRAP METAL PLANT BLDG 118 CONT NOY 4163, 3842
 STOREHOUSE AND ACCESSORIES VIEW FROM HAMMERHEAD CRANE SHOWING NEW SCRAP METAL PLANT BLDG 118 CONT NOY 4163, 3843
 STOREHOUSE AND ACCESSORIES NEW SCRAP METAL PLANT BLDG 118 VIEW AT SOUTH END CONT NOY 4163, 3844
 STOREHOUSE AND ACCESSORIES, NEW SCRAP METAL PLANT BLDG 118 VIEW OF TRACK WORK AT SOUTH END CONT NOY 4163, 3845
 STOREHOUSE AND ACCESSORIES NEW SCRAP METAL PLANT BLDG 118 VIEW OF EAST SIDE OF DISMANTLING HOUSE CONT NOY 4163, 3846
 PAINT STORAGE PAINTING INTERIOR_ ALLOT 79201-30 YARD LABOR, 3847
 VIEW 3 OF 6 OF OLD PILE HEADS REMOVED FROM SE CORNER OF BLDG 120, 3850
 BLDG 120_(4 OF 6)_VIEW OF STEEL SHORING IN PLACE UNDER SE CORNER OF BLDG 120- NOTE USE OF TWO PLATES ON BOTTOM BETWEEN WHICH THIN STEEL WEDGES WERE DRIVEN AND STEEL PLATE COVERING CONCRETE AND GROUT PLACED IN SOCKET INTO WHICH OLD PILE HEADS FITTED, 3851
 BLDG 120_(5 OF 6)_VIEW OF STEEL SHORING IN PLACE UNDER SE CORNER OF BLDG 120- NOTE USE OF TWO PLATES ON BOTTOM BETWEEN WHICH THIN STEEL WEDGES WERE DRIVEN AND STEEL PLATE COVERING CONCRETE AND GROUT PLACED IN SOCKET INTO WHICH OLD PILE HEADS FITTED, 3852
 BLDG 120_(6 OF 6)_DETAIL OF METHOD OF GROUTING BETWEEN OLD CONCRETE FOOTING AND NEW CUT OFF OF PILES, 3853
 BLDG 120_REPAIRS TO CORNICE AND BRICK WORK_ ALLOT 7X218-23-1_YARD LABOR_12-01-1932, 3854
 BLDG 120_OIL HOUSE, CONDITION OF RR TRACK BEFORE REPAIRS, 3855
 BLDG 120_OIL HOUSE, CONDITION OF RR TRACK BEFORE REPAIRS, 3856
 BLDG 120_2ND FL VIEW LOOKING S FROM N END OF BLDG, SHOWING DAMAGE TO ALCOHOL CAGE ON LEFT, 3857
 BLDG 120_PAINT STORAGE, PAINTING INTERIOR_ ALLOT 79201-30_YARD LABOR, 3858
 BLDG 120_IMPROVEMENT TO DISTRIBUTING SYSTEMS RELOCATION OF STEAM HEATING AND RETURN LINES TO BLDG_ ALLOT 7X218-35_YARD LABOR, 3859
 REPAIRS TO PAINT STORAGE BLDG 120 ALLOT 79201-30_YARD LABOR, 3860
 REPAIRS TO PAINT STORAGE BLDG 120 ALLOT 79201-1 YARD LABOR, 3861
 PAINT STORAGE_REPAIRS TO ROOF OF BLDG 120 NEW TRUSSES INSTALLED_ ALLOT 79201-30 YARD LABOR, 3862
 REPAIRS TO ROOF OF BLDG 120 ALLOT 79201-30 YARD LABOR, 3863
 REPAIRS TO ROOF OF BLDG 120 ALLOT 79201-30 YARD LABOR, 3864
 REPAIRS TO ROOF OF PAINT STORAGE BLDG 120 ALLOT 79201-30 YARD LABOR, 3865
 REPAIRS TO ROOF OF PAINT STORAGE BLDG 120 ALLOT 79201-30 YARD LABOR, 3866
 REPAIRS TO ROOF OF PAINT STORAGE BLDG 120 ALLOT 79201-1 YARD LABOR, 3867
 PAINTING INTERIOR OF PAINT STORAGE BLDG 120 ALLOT 79201-30 YARD LABOR, 3868
 PROTECTIVE SCREEN INSTALLED IN DISBURSING OFFICE BLDG 121, 3869
 YARD DISPENSARY EXCAVATING FOR EXTENSION TO BLDG 122 ALLOT 7X218-15-1 YARD LABOR, 3870
 YARD DISPENSARY EXCAVATING FOR EXTENSION TO BLDG 122 ALLOT 7X218-15-1 YARD LABOR, 3871
 PAY CAR TRAILER, 3872
 YARD DISPENSARY EXCAVATING FOR EXTENSION TO BLDG 122 ALLOT 7X218-15-1 YARD LABOR, 3873
 YARD DISPENSARY FOUNDATION FOR ADDITION TO BLDG 122 CONTRACT NOY 1050, 3874
 YARD DISPENSARY FOUNDATION FOR ADDITION TO BLDG 122 CONTRACT NOY 1050, 3875
 YARD DISPENSARY ADDITION TO BLDG 122 VIEW LOOKING EAST CONTRACT NOY 1050, 3876
 YARD DISPENSARY ADDITION TO BLDG 122 WEST END CONTRACT NOY 1050, 3877
 YARD DISPENSARY ADDITION TO BLDG 122 NORTH SID CONTRACT NOY 1050, 3878
 YARD DISPENSARY ADDITION TO BLDG 122 VIEW OF 2ND FL CONTRACT NOY 1050, 3879
 YARD DISPENSARY ADDITION TO BLDG 122 VIEW OF 1ST FL CONTRACT NOY 1050, 3880
 DDITION TO YARD DISPENSARY DOOR ADJOINING PRESENT BLDG CONTRACT NOY 1050, 3881
 ADDITION TO YARD DISPENSARY WEST END CONTRACT NOY 1050, 3882
 ADDITION TO YARD DISPENSARY NORTH SIDE CONTRACT NOY 1050, 3883
 ADDITION TO YARD DESPENSARY VIEW LOOKING EAST CONTRACT NOY 1050, 3884
 ADDITION TO YARD DISPENSARY VIEW OF 2ND FL CONTRACT NOY 1050, 3885
 ADDITION TO YARD DISPENSARY VIEW OF TOP FLOOR CONTRACT NOY 1050, 3886
 ADDITION TO YARD DISPENSARY VIEW OF FIRST FLOOR CONTRACT NOY 1050, 3887
 ADDITION TO YARD DISPENSARY NORTH SIDE_ CONTRACT NOY 1050, 3888
 ADDITION TO YARD DISPENSARY VIEW LOOKING SO EAST CONTRACT NOY 1050, 3889
 ADDITION TO YARD DISPENSARY CORRIDOR FIRST FLOOR CONTRACT NOY 1050, 3891
 ADDITION TO YARD DISPENSARY CORRIDOR FIRST FLOOR CONTRACT NOY 1050, 3892
 ADDITION TO YARD DISPENSARY CORRIDOR SECOND FLOOR CONTRACT NOY 1050, 3893
 ADDITION TO YARD DISPENSARY VIEW ON TOP FLOOR CONTRACT NOY 1050, 3894
 ADDITION TO YARD DISPENSARY VIEW OF NORTH SIDE CONTRACT NOY 1050, 3895
 RED BRASS EXHAUST PIPE CORRODED SECTION, 3896
 RED BRASS EXHAUST PIPE CORRODED SECTION NEAR FLANGE FIG 2 180° AWAY GROW FIG 1, 3897
 SAFETY ACID HANDLING DEVICE EXHIBIT A, 3898

STAIR ENCLOSURE ON THE SE CORNER OF BLDG 123 RNV CM ALLOT 17X0603 YARD LABOR, 3899
STAIR ENCLOSURE ON THE SOUTHEAST CORNER OF BLDG NO 123 RNV CM ALLOT 17X0603 YARD LABOR, 3900
REPAIRS TO PUMPWELL BETWEEN DD 2 & 3 REPAIRING BLDG EXTERIOR VIEW ALLOT 73201-35 YARD LABOR, 3903
REPAIRS TO PUMPWELL DD 2 AND 3 ALLOT 73201-35 YARD LABOR, 3904
REPAIRING PUMPWELL BETWEEN DD 2 & 3 ALLOT 73201-35 YARD LABOR, 3905
REPAIRING PUMPWELL BETWEEN DRYDOCKS 2 AND 3 ALLOT 73201-35 YARD LABOR, 3906
REPAIRING PUMPWELL DD 2 AND 3 ALLOT 73201-35 YARD LABOR, 3909
REPAIRING PUMPWELL DD 2 AND 3 ALLOT 73201 35 YARD LABOR, 3910
INTERIOR OF BLDG NO 125 PUMPWELL DRYDOCKS 2 AND 3, 3911
INTERIOR OF BLDG NO 125 PUMPWELL DD 2 AND 3, 3912
BUILDING NO 126, 3913
BUILDING NO 126, 3917
BUILDING NO 126, 3918
BUILDING NO 126, 3919
BUILDING NO 126, 3920
BUILDING NO 126, 3921
BUILDING NO 126, 3922
BUILDING NO 126, 3923
BUILDING NO 126, 3924
BUILDING NO 126, 3925
LOOKING EAST ON 1ST FLOOR OF BUILDING 126, 3926
CONT 2485 DEMOLITION OF BUILDING 126 FOR STRUCTUAL SHOP MAIN STREET AND CHAUNCEY AVE LOOK NE FROM
1ST STREET DEG NON CO CONTR, 3927
SMALL BOAT AND SHIP, 3928
SMALL BOATS AND SHIP LAUNCHING WAYS IN BACKGROUND, 3929
SMALL BOATS LAUNCHING WAYS IN BACKGROUND, 3930
REPAIRS TO ROOF OF BLDG 127 YARD LABOR VIEW LOOKING SOUTH, 3931
SAMPLE SKYLIGHT FOR BLDG 127, 3932
SAMPLE SKYLIGHT FOR BUILDING 127, 3933
REPAIRS TO ROOF OF BLDG 127 ALLOT 7X218-13-5 YARD LABOR, 3934
BUILDING NO 127, 3935
BUILDING NO 127, 3936
ELEVATORIN NORTH EAST CORNER BUILDING NO 127, 3937
BLDG NO 127 3RD FLOOR OFFICES, 3938
BLDG 127 ENLARGING SW HOISTWAY, 3939
PANE RUNWAY 1ST FL W SIDE LOOKING S YARD LABOR, 3940
ENLARGED DOORWAY IN S CORNER LOOKING NW YARD LABOR, 3941
NEW STEEL DOOR IN SW CORNER LOOKING NW YARD LABOR, 3942
NEW CRANE RUNWAY ON SW SIDE LOOKING NW YARD LABOR, 3943
AMBULANCE BOAT NO 6448 FOR USS HAVANA, 3944
AMBULANCE BOAT NO 6448 FOR USS HAVANA, 3945
BLDG 128 REPAIRING SLATE BROKEN BY SKYLIGHT WORK UNDER CONTRACT 44857, 3946
SANDER VIBRATION DE ENENERGIZER ON CAM SHIFT OF V6 PORT ENGINE, 3947
VIEW OF 1ST FLOOR BLDG 130 LOOK WEST, 3951
REPAIRS TO ROOF OF BLDG PATTERN SHOP VIEW FROM ROOF OF BLDG 27 YARD LABOR ALLOT 7201 6, 3952
BLDG 130, 3953
BLDG 130, 3954
BLDG 130, 3955
BLDG 130 LOOKING NE, 3956
BLDG 130 LOOKING EAST, 3957
BLDG 130 LOOKING N, 3958
BLDG 130 LOOKING NE, 3959
BLDG 130 LOOKING E, 3960
ROOF REPAIRS BLDG 131 ALLOT 7920 12 YARD LABOR, 3961
REPAIRS TO ROOF BLDG 131 ALLOT 79201 2 YARD LABOR, 3962
ROOF REPAIRS BLD 131 ALLOT 79201 2 YARD LABOR, 3963
REPAIRS TO ROOF BLDG 131 ALLOT 79201 2 YARD LABOR, 3964
REPAIRS TO ROOF BLDG 131 ALLOT 79201 2 YARD LABOR, 3965
REPAIRS TO ROOF BLDG 131 79201 2 YRAD LABOR, 3966
FIRE ESCAPE ERECTED ON NO SIDE OF PRISON BLDG 215 CONTRACT 479, 3967
FIBRE DUCT AND MAN HOLE SUB STATION 6 ALLOT 7 X 218 8 9 YARD LABOR, 3968
REMODELING SUB STATION 6 EXTERIOR VIEW ALLOT 7 X 218 8 5 YARD LABOR, 3969
VESSELS ALONG SIDE PIER F LOOKING NW, 3971
VIEW OF WATERFRONT LOOKING NW FROM CANTILEUER CRANE TRACK, 3972
VIEW OF WATER FRONT LOOKING N FROM CANTILEVER CRANE TRACK, 3973

VIEW OF WATER FRONT LOOKING NE FROM CANTILEVER CRANE TRACK, 3974
VIEW OF WATERFRONT LOOKING SE FROM CANTILEVER CRANE TRACK, 3975
VIEW OF THE WATER FRONT LOOKING E FORM CANTILEVER CRANE TRACK, 3976
CARGO MAT HULL DIV, 3977
CARGO MAT HULL DIV, 3978
CARGO MAT HULL DIV, 3979
HULL DIV TEST AIR TANK 27, 3980
OIL BURNING RANGES IN CREWS GALLEY OF USS FULTON, 3981
METHOD OF TESTING BULKHEAD STIFFENER BRACKET, 3982
FOUNDATION FOR PROPELLER SHAFTS MCDONOUGH AV NEAR BLDG 2 (18) YD L, 3983
HULL DIV OIL BURNING BAKE OVEN FOR PEARL HARBOR, 3984
FOUNDATION FOR PROPELLER SHAFTS MC D NEAR BLDG 25, 3985
WATER FRONT LOOKING NW FROM OUTER END OF CANTILEVER CRANE TRACK, 3986
WATER FRONT LOOKING NE FROM OUT END CANTILEVER CRANE TRACK, 3987
WATER FRONT LOOKING E FROM OUT END CANTILEVER CRANE TRACK, 3988
WATER FRONT LOOKING SE FROM OUT END CANTILEVER CRANE TRACK, 3989
WATER FRONT LOOKING S FROM OUT END CANTILEVER CRANE TRACK, 3990
WATER FRONT LOOKING N FROM IN SHORE END OF LOCAL PLANT, 3991
WATER FRONT LOOKING NE FROM INNER END OF COAL PLANT, 3992
WATER FRONT LOOKING SE FROM INNER END OF LOCAL COAL PLANT, 3993
WATER FRONT LOOKING SE FROM OUT END OF COAL PLANT, 3994
WATER FRONT LOOKING S FROM OUT END COAL PLANT, 3995
WATER FRONT LOOKING W FROM OUT END COAL PLANT, 3996
WATER FRONT LOOKING NW FROM TOP FWD MAST USS FLORIDA LYING ALONG S SIDE OF PIER F, 3998
WATER FRONT LOOKING NE FROM S SIDE PIER F, 3999
WATER FRONT LOOKING S FROM S SIDE PIER F, 4001
TEST SUBMARINE SECTION EXTERIOR VIEW, 4003
TEST SUBMARINE SECTION INTERIOR VIEW NO 1, 4004
TEST SUBMARINE SECTION INTERIOR VIEW NO 3, 4006
MONTHLY PROGRESS PHOTO OIL STORAGE SHED IN REAR OF BLG 120 LOOKING E YARD LABOR, 4007
SCALES FOR EXPERIMENTAL PURPOSES ABOARD SHIP LOADING POSITION, 4008
SCALES FOR EXPERIMENTAL PURPOSES ABOARD SHIP WEIGHING POSITION, 4009
GENERAL ROUTING OF PLATES AND BARS MANUFACTURING DEPT HULL DIV, 4010
OIL STORAGE SHED IN REAR OF BLDG 120 LOOKING E YARD LABOR, 4011
EXPERIMENTAL FLOOR NO 10, 4013
EXPERIMENTAL FLOOR NO 10, 4014
LOOKING SE FROM BETWEEN BLDGS 87 AND 215, 4015
LOOKING SE AT PARK AND PERRY AVS, 4016
LOOKING N FROM E OF PEAR OF BLDG 120, 4017
SCRAP HEAP W OF BLDG 120 LOOKING NW, 4018
STEEL RACK W OF DDI REINFORCED CONCRETE WORK BY PUB WKS LOOKING N YARD LABOR, 4019
[untitled], 4020
[untitled], 4021
[untitled], 4022
[untitled], 4023
[untitled], 4024
[untitled], 4025
TEMP STORAGE SHED CHAUNCEY AVE BTWN 4 & 3 STS LOOKING NW FROM SW SIDE LOCO SHED CHAS MEADS & CO
CONTR, 4026
TEMP STORAGE SHED CHAUNCEY AV BTWN 3 & 2 STS LOOKING NW FROM CHAUNCEY NEAR 3RD CHAS MEADS & CO
CONTR, 4027
USS SUBMARINE G 2, 4029
VIEW INSIDE JOINER SHOP, 4030
TIMBER PILES SE OF TEAK SHED, 4031
TEAK SHED, 4032
ASH MESS BENCHES, 4033
OAK BOAT LUMBER, 4034
OAK LUMBER ON 2ND FLOOR OF LUMBER SHED, 4035
SPRUCE INSIDE LUMBER SHED, 4036
SPRUCE WHITE PINE AND THICK MAPLE IN LUMBER SHED, 4037
[untitled], 4038
[untitled], 4039
[untitled], 4040
[untitled], 4041
[untitled], 4042

CLINTON AVE STORE HOUSE LOOKING S CHAS MEADS & CO CONTRACTOR, 4043
CITY PARK PAVILION, 4045
CITY PARK COMFORT STATION FROM SOUTH, 4046
CITY PARK PERGOLA & COMFORT STATION FROM ST EDWARDS PLACE, 4047
WORKS PROGRESS ADMINISTRATION - TEMPORARY SHORING UNDER FOOTING OF COLUMNS 9 AND 10 MACHINE SHOP BLDG 128 YARD PROJ 11 (B) OFFICIAL PROJ 209 - 2021 , 4052
ELEVATOR AND BLDG WAYS NO 1, 4053
WORKS PROGRESS ADMINISTRATION PILE TEST UNDER FOOTINGS OF COLUMNS 5 AND 6 MACHINE SHOP BLDG 128 YARD POST 11 (B) OFFICIAL PROJECT 209-2021, 4056
WORKS PROGRESS ADMINISTRATION PAVING OPERATIONS ON DOCK ST BET 3RD AND 4TH STS NEAR BLDG 131 YARD PROJECT (11B) OFFICIAL PROJECT 209-2021, 4059
WORKS PROGRESS ADMINISTRATION GENERAL VIEW OF NEW GATE AND GUARD HOUSE AT CUMBERLAND ST YARD PROJ 11(B) OFFICIAL PROJ 209- 2021, 4061
WORKS PROGRESS ADMINISTRATION VIEW SHOWING MACHINES CROWDED CLOSE TO COLUMNS BEING UNDER PINNED (BUILDING NO 128)_YARD PROJECT 12, OFFICIAL PROJECT 209-4019, 4063
WORKS PROGRESS ADMINISTRATION VIEW SHOWING MAACHINES CROWDED CLOSE TO COLUMBUS BEING UNDERPINNED IN BUILDONG NO 128 YARD PROJECT 12, OFFICIAL PROJECT 209-4019, 4064
WORKS PROGRESS ADMINISTRATION VIEW SHOWING MACHINES CROWDED CLOSE TO COLUMNS BEING UNDERPINNED IN BUILDING 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4065
WORKS PROGRESS ADMINISTRATION VIEW SHOWING MACHINES CLOSE TO COLUMNS BEING UNDERPINNED IN BUILDING 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4066
WORKS PROGRESS ADMINISTRATION VIEW SHOWING MACHINES CLOSE TO COLUMNS BEING UNDERPINNED IN BLDG 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4067
WORKS PROGRESS ADMINISTRATION VIEW SHOWING MACHINES CROWDED CLOSE TO COLUMNS BEING UNDERPINNED IN BLDG 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4069
WORKS PROGRESS ADMINISTRATION VIEW SHOWING MACHINES CROWDED CLOSE TO COLUMNS BEING UNDERPINNED IN BLDG 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4070
WORKS PROGRESS ADMINISTRATION VIEW SHOWING CROWDED CLOSE TO COLUMNS BEING UNDERPINNED IN BLDG 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4071
View Showing Machines Crowded Close to Columns Being Underpinned in Building 128, 4072
WORKS PROGRESS ADMINISTRATION VIEW SHOWING MACHINES CROWDED CLOSE TO COLUMNS BEING UNDERPINNED IN BLDG 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4073
WORKS PROGRESS ADMINISTRATION VIEW SHOWING MACHINES CROWDED CLOSE TO COLUMNS BEING UNDERPINNED IN BLDG 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4074
WORKS PROGRESS ADMINISTRATION GENERAL VIEW OF COLUMNS IN BOILER SHOP BLDG 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4075
WORKS PROGRESS ADMINISTRATION GENERAL VIEW OF COLUMNS IN BOILER SHOP BLDG 128 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4076
WORKS PROGRESS ADMINISTRATION PIT EXCAVATION AT FOOTING TO COLUMNS 19 - 20 MACHINE SHOP BLDG 128 YARD PROJECT 11 'B' OFFICIAL PROJECT 209-4019, 4078
WORKS PROGRESS ADMINISTRATION TEST PIT BOILER SHOP BLDG YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4080
WORKS PROGRESS ADMINISTRATION BRICK SUPPORT TO WALL COLUMN IN FOUNDRY BLDG 29 YARD PROJECT 11(A) OFFICIAL PROJECT 209-2021, 4090
WORKS PROGRESS ADMINISTRATION GARAGE EXTESNSION WALL AND STEEL ERECTION YARD PROJECT 11 OFFICIAL PROJECT 209-2021, 4099
WALL AND STEEL ERECTION GARAGE EXTENSION BLDG 37 YARD PROJECT 11 OFFICIAL PROJECT 209-2021, 4100
WORKS PROGRESS ADMINISTRATION (BLDG 37) WALL AND STEEL ERECTION FOR GARAGE EXTENSION _YARD PROJECT 11 OFFICIAL PROJECT 209-2021, 4101
MARINE BARRACKS EXTENSIO BLDG NO 13 WORKS PROGRESS ADMINISTRATION BRICKING UP EXTENSION WALLS AND SETTING STEEL WITH USE OF SPEED CRANE YARD PROJECT 11 OFFICIAL PROJECT 209-2021, 4103
WORKS PROGRESS ADMINISTRATION MARINE BARRACKS EXTENSION BLDG NO 13 38 1/2 TON TEST ON PORCH PILE NO 8 PERRY AVE AND 3RD ST YARD PROJECT NO 11 OFFICIAL PROJECT 209-2021, 4104
MARINE BARRACKS EXTENSION, PERRY AVE AND 3RD ST 38 1/2 TON TEST ON PORCH PILE NO 8 WORKS PROGRESS ADMINISTRATION_YARD PROJECT 11 OFFICIAL PROJECT 209-2021, 4105
WORKS PROGRESS ADMINISTRATION GENERAL VIEW OF NEW EXTENSION TO MARINE BARRACKS BLDG 13 YARD PROJECT 11 OFFICIAL PROJECT 209-2021, 4108
WORKS PROGRESS ADMINISTRATION UNDERPINNING OF PATTERN RACKS AND NEW SECTION OF FLOORING IN BUILDING NO 132 YARD PROJECT 11B OFFICIAL PROJECT 209-2021, 4111
WORKS PROGRESS ADMINISTRATION UNDERPINNING OF PATTERN RACKS AND REINFORCING STEEL FOR CONCRETE FLOOR SLABS YARD PROJECT 11B OFFICIAL PROJECT 209-2021, 4112
WORKS PROGRESS ADMINISTRATION INSTALLATION OF WASTE LINES FOR TOILETS IN BLDG NO 23 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4113
WORKS PROGRESS ADMINISTRATION IMPROVEMENTS TO GARAGE FRONT ELEVATION OF BLDG 37 YARD PROJECT 11 OFFICIAL PROJECT 209-2021, 4114

WORKS PROGRESS ADMINISTRATION INSTALLING COPPER GUTTERS BLDG NO 11 - 3RD ST SIDE OF BLDG YARD PROJECT 2 A SUB PROJECT 2 OFFICIAL PROJECT 09 - 12, NEC 612, 4115
WORKS PROGRESS ADMINISTRATION IMPROVEMENTS TO GARAGE BLDG 37 REAR ELEVATION YARD PROJECT 11 OFFICIAL PROJECT 209-2021, 4116
WORKS PROGRESS ADMINISTRATION STANDARD GAUGE TRACK IMPROVEMENTS WEST SIDE OF BLDG WAYS NO 1 YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4117
WORKS PROGRESS ADMINISTRATION INSTALLATION OF 8" FRESH WATER LINE ON 3RD ST AND CHAUNCEY AVE YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4118
WORKS PROGRESS ADMINISTRATION INTERIOR VIEW OF IMPROVEMENT TO GARAGE BLDG NO 37 YARD PROJECT 11 OFFICIAL PROJECT 209-2021, 4119
WORKS PROGRESS ADMINISTRATION STANDARD GAUGE RR TRACK IMPROVEMENTS 3RD ST AND PERRY AVE YARD PROJECT 12 OFFICIAL PROJECT 209-4019, 4120
WORKS PROGRESS ADMINISTRATION STONE SHED (AT ARMOR PLATE STORAGE YARD) CUTTING GRANITE FOR BLDG 13 AND CUMBERLAND ST GATE YARD PROJECT 13 OFFICIAL PROJECT 209-8007, 4121
WORKS PROGRESS ADMINISTRATION EXCAVATING AROUND UNDERPINNING TO FOOTINGS OF COLUMNS NO 3 AND 4 IN MACHINE SHOP BLDG 128 YARD PROJECT 11'B' OFFICIAL PROJECT 209-2021, 4122
WORKS PROGRESS ADMINISTRATION EXCAVATING AROUND UNDERPINNING TO FOOTINGS OF COLUMNS NO 31 AND 32 EXTERIOR VIEW OF BLDG 128 YARD PROJECT 11'B' OFFICIAL PROJECT 209-2021, 4123
WORKS PROGRESS ADMINISTRATION GRADING - CURBING AND GATE COLUMN REINFORCING FOR NEW CUMBERLAND ST GATE YARD PROJECT 11 B OFFICIAL PROJECT 209-2021, 4124
WORKS PROGRESS ADMINISTRATION GRADING - CURBING AND GATE COLUMN REINFORCING FOR NEW CUMBERLAND ST GATE YARD PROJECT 11 B OFFICIAL PROJECT 209-2021, 4125
IMPROVEMENT TO DISTURBING SYSTEMS VIEW LOOKING OUTBOARD ON PIER 'G' SHOWING COMPLETION NEW AIR TENCH AND TELEPHONE DUCTS ALLOT 7X218 - 53 - 1 YARD LABOR, 4126
350 TON HAMMERHEAD CRANE NEAR BERTH 12 - 50 AND 175 TON HOISTING DRUMS CONTRACT NOY 3341, 4127
350 TON HAMMERHEAD CRANE NEAR BERTH 12 - 50 AND 175 TON HOISTING DRUMS CONTRACT NOY 3341, 4128
FOUNDATION FOR NEW TRANSFORMER OUTSIDE OF BLDG NO 43 ALLOT 7X218 - 32 - 3 YARD LABOR, 4130
EXTENSION OF BLDG WAYS NO 2 VIEW LOOKING SO EAST SHOWING THE CHICAGO BOOMS IN PLACE AT TOP OF VARIOUS TOWERS CONTRACT NOY 3590, 4131
EXTENSION OF BLDG WAYS NO 2 VIEW LOOKING NO EAST SHOWING THE COMPLETED STEEL WORK IN SHORE END CONTRACT NOY 3590, 4132
IMPROVEMENTS OF BERTHS NO 11 AND 12 VIEW SHOWING EXCAVATION OF SEA WALL VIEW LOOKING INBOARD CONTRACT NOY 3742, 4133
IMPROVEMENTS TO BERTHS NO 11 AND 12 VIEW LOOKING OUT BOARD SHOWING EXCAVATION CONTRACT NOY 3742, 4134
350 TON HAMMERHEAD CRANE VIEW SHOWING ADDITIONAL STEEL (TOWER) UNDER CHANGE ORDER CPNTRACT NOY 3341, 4135
350 TON HAMMERHEAD CRANE NEAR BERTHS 11 AND 12 VIEW SHOWING ROOF AND TROLLEY WIRE UPPORTS FOR 15 TONE CRANE CONTRACT NOY 3341, 4136
IMPROVEMENTS OF BERTHS 11 AND 12 IEW SHOWING THE RODS CONTRACT NOY 3742 LOOKING IN BOARD, 4138
IMPROVEMENTS OF BERTHS 11 AND 12 VIEW SHOWING RODS AND WALL EXCAVATION LOOKING IN BOARD CONTRACT NOY 3742, 4139
FOUNDATION FOR NEW TRANSFORMER OUTSIDE OF BUILDING NO 43 ALLOT 7X218 - 32 - 3 YARD LABOR, 4140
TEST BORING AT HAMMERHEAD CRANE HOLE - 2 - H CONTRACT NOY 3809, 4141
IMPROVEMENTS TO SHIPWAYS NO 2 VIEW LOOKING EAST FROM 11 + 7 SHOWING PLACING OF PREFABRICATED BENTS FOR WORKING PLATFORM CONTRACT NOY 3643, 4142
IMPROVEMENTS TO SHIPWAYS NO 2 VIEW OF CENTER COFFERDAM LOOKING NORTH FROM STA 9 + 90, 4143
IMPROVEMENTS TO SHIPWAYS NO 2 VIEW LOOKING EAST FROM WAYS NO 2 SHOWING PLIES FOR TOWER FOUNDATION NO 41 AND PIER EXTENSION CONTRACT NOY 3643, 4144
IMPROVEMENTS TO SHIPWAYS NO 2 GENERAL VIEW OF CENTER AND BOX COFFERDAM FROM FROM EAST SIDE OF WAYS NO 2 CONTRACT NOY 3643, 4145
IMPROVEMENTS TO SHIPWAYS NO 2 VIEW IN CENTER OF COFFERDAM LOOKING INBOARD FROM STATIONS 11 + 37 SHOWING REMOVAL OF OLD AND PLACING OF NEW CONSTRUCTION CONTRACT NOY 3643, 4146
POWER HOUSE ON US NAVAL HOSPITAL GROUNDS, 4147
USN RECEIVING SHIP BARRACKS - BAY RIDGE - BKLYN - MESS HALL LOOK N, 4148
INTERIOR OF EMERG HOSPITAL, 4149
US NAVAL HOSPITAL NURSES QUARTERS, 4150
US NAVAL HOSPITAL NURSES BUILDING LOOKING N, 4151
SHRAPNEL WOUND LEFT BUTTOCKS CAUSING DISPLACEMENT UPWARDS OF HEAD OF FEMUR WITH BONE LOSS BONE LOSS BODY OF ISCHIUM AND ACETABALUM WITH SUBSEQUENT ANKYLOSIS TWO OPERATIONS RESECTION OF SCAR TISSUE AND SCIATIC NERVE INCLUSION AND CURRETAGE OF NECROTIC BONE - DAKINIZED - SPONTANEOUS CLOSURE AIDED BY STRAPPING, 4152
5 PHYSIO - THERAPY - FIRST - PLANT - B - 1, 4153
GUSTAFSON - AMPUTATION 12 - 18 - 19 UP ON TEMPORY HOSPITAL PEG LEG 1 - 4 - 20 UP ON PERMANENT ARTIFICIAL LIMB 3 - 3 - 20, 4154

BLDG 1 CONTR 3892 TYPICAL WARD FIRST FLOOR, 4156
USS New York Stern View Starboard, 4241
USS New York - The President and Secretary of the Navy at the sponsors stand, 4242
USS New York - Breaking the bottle, 4243
USS New York leaving the ways, bow view , 4244
USS New York Leaving the Ways, 4245
SS Slavonia from Dry Dock 3, 4249
SS Slavonia from Head of Dry Dock 2, 4250
USS Pontiac (YT-20) - View of derrick and boom from after, 4251
USS Pontiac (YT-20) View of Derrick and Boom on Starboard Side, 4252
USS West Virginia Range and Deflection Indicator MK IX MOD 1, 4278
USS West Virginia Torpedo Battle Order Transmitter and Repeat Back Indicator MK III MOD 1, 4283
USS Arkansas in Dry Dock 4 for Repairs to Bottom, 4321
House A Alterations Looking Southeast - Monthly Progress Photo, 4386
HOUSE A (10) PARLOR, 4429
House A (10) Reseeding Lawn, Looking Northwest, 4444
Nurse, 4558
Medical Staff and Nurses, 4561
Nurses and patient, 4562
EXTENSION TO BLDG 4 VIEW OF NORTH WALL AND SHOWING BRIDGE CROSSOVER LOOKING WESTWARD FROM ROOF OF EXISTING BLDG 4 CONTRACT NOY 3272, 4592
EXTENSION TO BLDG 4 GENERAL VIEW OF ROOF AS VIEWED FROM EAST END OF NEW STRUCTURE CONTRACT NOY 3272, 4593
EXTENSION TO BLDG 4 VIEW LOOKING EAST FROM SOUTHWEST CORNER OF STRUCTURE SHOWING BRICK WORK OF WEST WALL CONTRACT NOY 3272, 4594
EXTENSION TO BLDG 4 VIEW OF SOUTH WALL FROM INTERIOR LOOKING WESTWARD SHOWING INSTALLATION OF STEEL SUB-FRAMES FOR WINDOW SASH CONTRACT NOY 3272, 4595
EXTENSION TO BLDG 4 VIEW OF NEW EXTENSION LOOKING SOUTH ON SECOND ST CONTRACT NOY 3272, 4596
EXTENSION TO BLDG 4 VIEW SHOWING SOUTH ELEVATION CONTRACT NOY 3272, 4597
EXTENSION TO BLDG 4 MOLD LOFT FLOOR BEAMS – NORTH WALL BRICK WORK AND NEW BRIDGE CROSSOVERS AS VIEWED FROM 6TH FLOOR OF TRIANGLE BUILDING CONTRACT NOY 3272, 4598
EXTENSION TO BLDG 4 VIEW SHOWING CONCRETE WALLS ON SOUTH AND EAST ELEVATIONS CONTRACT NOY 3272, 4599
EXTENSION TO BLDG 4 VIEW OF PENTHOUSE AND EAST GABLE BRICKWORK FROM ROOF OF TRIANGLE BLDG CONTRACT NOY 3272, 4600
EXTENSION TO BLDG 4 VIEW OF WEST AND SOUTH CONCRETE WALLS FROM LINE D AT GRADE CONTRACT NOY 3272, 4601
EXTENSION TO BLDG 4 VIEW SHOWING BRICKWORK ABOVE OFFSET AT DOOR MARKED D – 8 CONCRETE WALLS BRICK PIERS AND DOOR FRAME TO BE PLACES AS SUBSEQUENT WORK CONTRACT NOY 3272, 4602
EXTENSION TO BLDG 4 VIEW AT SOUTH WEST CORNER SHOWING INSTALLATION OF STEEL SUB – FRAMES FOR WINDOW SASH CONTRACT NOY 3272, 4603
EXTENSION TO BLDG 4 INSTALLATION OF VACUUM RETURN LINE STEAM PIT AND HOUSE TRAP PIT CONTRACT NOY 3272, 4604
EXTENSION TO BLDG 4 VIEW AT DOOR D - 8 SHOWING WORK OF PLACING VACUUM RETURN TRENCH CONTRACT NOY 3272, 4605
EXTENSION TO BLDG 4 VIEW OF OLD CONCRETE SLAB ENCOUNTERED IN EXCAVATION FOR VACUUM RETURN TRENCH BETWEEN DOOR D – 8 AND TRIANGLE BUILDING CONTRACT NOY 3272, 4606
EXTENSION TO BLDG 4 INSTALLATION OF HOUSE TRAP PIT AND VACUUM RETURN TRENCH AS VIEWED FROM CRANE RUNWAY ON LINE 'E' CONTRACT NOY 3272, 4607
EXTENSION TO BLDG 4 ELEVATOR MACHINE AND CAR SLING – ELEVATOR NO 2 CONTRACT NOY 3429, 4608
EXTENSION TO BLDG NO 4 VIEW LOOKING WESTERLY FROM 6TH FLOOR OF TRIANGLE BUILDING SHOWING MOLD LOFT UNDER FLOORING CONTRACT NOY 3272, 4609
EXTENSION TO BLDG 4 VIEW OF CROSSOVER BRIDGE FROM BLDG NO 4 TO NEW EXTENSION CONTRACT NOY 3272, 4610
EXTENSION TO BLDG NO 4 VIEW OF ROOF AND SKYLIGHT FRAMING CONTRACT NOY 3272, 4611
EXTENSION TO BLDG NO 4 VIEW AT 5TH FLOOR LOOKING WEST SHOWING PIPING WORK IN TRUSSES UNDER MOLD LOFT UNDER FLOORING CONTRACT NOY 3272, 4612
EXTENSION TO BLDG NO 4 SOUTH ELEVATION CONTRACT NOY 3272, 4613
EXTENSION TO BLDG NO 4 VIEW OF ROOF AND SKYLIGHT FRAMING CONTRACT NOY 3272, 4614
EXTENSION TO BLDG 4 ELEVATION ON 2ND STREET LOOKING SOUTH CONTRACT NOY 3272, 4615
EXTENSION TO BLDG NO 4 ELEVATOR MACHINE AND ACCESSORIES ELEVATOR NO 1 CONTRACT NOY 3429, 4616
EXTENSION TO BLDG NO 4 VIEW OF ELEVATION LOOKING EAST ON SECOND ST CONTRACT NOY 3272, 4617
EXTENSION TO BLDG NO 4 VIEW AT COLUMN E 13 SHOWING MOUNTING OF TYPICAL POWER SWITCH PANEL CONTRACT NOY 3272, 4618
EXTENSION TO BLDG NO 4 VIE [SIC] ON LINE 'D' SHOWING STEEL SASH AND DOORS REMOVED DOOR OPENINGS

FILLED WITH CONCRETE CONTRACT NOY 3272, 4619
 EXTENSION TO BLDG NO 4 VENTILATOR DUCT INSTALLATION IN TRUSSES UNDER MOULD [SIC] LOFT FLOOR – SASH
 AND DOOR REMOVAL DOOR OPENINGS FILLED WITH CONCRETE CONTRACT NOY 3272, 4620
 EXTENSION TO BLDG NO 4 VIEW SHOWING F P S C DOOR #1 WITH 6” STANDPIPE REMOVED IN ORDER TO PERMIT
 PLACING OF SAME CONTRACT NOY 3272, 4621
 STOREHOUSE AND ACCESSORIES EXCAVATION FOR NEW NON-COMMISSIONED OFFICERS QUARTERS, BETWEEN
 BLDGS NO 130 AND 152, 5888
 PAINTING AND SCRAPING OF SWITCH BOARDS MOTORS AND FLOOR, 5891
 FOUNDATION PIERS 31, BLDG 32, 5893
 FOUNDATION PIERS, BLDG 32, 5894
 INTERIOR PAINTING OF POWER PLANT, BLDG 41, 5896
 HEATING UNITS IN TRUSSES, BLDG 127, 5897
 REPAIRS TO DUMPERS IN ROUNDHOUSE, BLDG 530, 5898
 Building 11 - Sectional View of Ventilators, Consolidation of Shops, 5899
 Building 10 - General View of the Interior, 5900
 Building 10 - General View Morris Avenue Side, 5901
 REMOVING OLD PAVEMENT, 2ND ST BET MORRIS AND CHAUNCEY AVES_, 5902
 Building 10 - General Interior View Showing Crane Piers and Crane Run, 5903
 Building 10 - General View of Remodeled Building, 5904
 GATE FOR NEW OUTSIDE RR CONNECTION ON STRINGHAM AVE, 5905
 NEW GATE FOR OUTSIDE RR CONNECTION ON STRINGHAM AVE, 5906
 RECEIVING STEEL FOR ERECTION ON BLDG 32, 5907
 SHOE REPAIR SHOP FOR WPA WORKERS, 5908
 STEEL FRAMING WITH SECTION OF EAST WALL, FRONT VIEW BLDG 32, 5909
 STANDARD GAUGE RR TRACK IMPROVEMENTS PAULDING AVE YARD, 5910
 PAVING OPERATIONS STRINGHAM AVE SHOWING ELEVATION OF STREET, 5911
 Building 11 - Installation of New Skylights, Roof Sheathing and Ventilators, 2nd St Side, 5912
 NEW GATE IN WALL ON STRINGHAM AVE FOR OUTSIDE RR CONNECTIONS, 5913
 TIE BOLTS AND FOUNDATION FOR RAIL PLATE AND WIDE GAUGE RR TRACKS, 5917
 REPAIRS TO STANDARD GAUGE RR TRACKS, 2ND ST WEST OF MORRIS AVE, 5918
 PAVING WITH ASPHALT BLOCK AT 2ND ST BET MORRIS AND CHAUCEY AVES, 5919
 GENERAL VIEW OF NEW GARAGE BLDG 32 UNDER CONSTRUCTION, 5922
 NEW SIDEWALK ON MORRIS AVE BET 2ND AND 3RD STS, 5925
 NEW FOUNDATIONS UNDER MACHINES IN SHEETMETAL SHOP, BLDG 12, 5926
 Building 11 - View of Northeast Corner of Consolidation of Shops, 5927
 INSTALLATION OF INTAKE AND EXHAUST VENTILATION DUCTS IN SHEETMETAL SHOP, BLDG 12, 5930
 SIDEWALK AND STREET IMPROVEMENT AT 2ND ST AND MORRIS AVE, 5931
 STANDARD GAUGE RR TRACK IMPROVEMENT ON MORRIS AVE BET 1ST AND 2ND STS, 5932
 REPAIRS TO CATWALKS AND CRANE STRUCTURE OVER BLDG WAYS 1, 5933
 GENERAL VIEW OF CONSTRUCTION OPERATION OF GARAGE BLDG 32, 5935
 EXTENSION TO TRANSFORMER ROOM BLDG 41, POWER PLANT, AT 5TH ST, 5937
 Building 10 - General Interior Painting, 5938
 MILL AND CARPENTER SHOP WORK BLDG 6, INSTRUMENT CABINET FOR BLDG 41, 5939
 SHEET METAL SHOP_ ASPHALT BLOCK PAVING IN BLDG 12, 5940
 BLDG 11A, NEW PIPE SHOP_ TRANSFERRING MACHINERY AND EQUIPMENT INTO NEW PIPE SHOP, 5941
 ASPHALT BLOCK PAVING IN SHEET METAL SHOP, BLDG 12, 5958
 TRANSFERRING MACHINERY AND EQUIPMENT INTO NEW PIPE SHOP, BLDG 11A, CONSOLIDATION OF SHOPS, 5959
 TRANSFERRING MACHINERY AND EQUIPMENT INTO NEW PIPE SHOP, BLDG 11A, CONSOLIDATION OF SHOPS, 5960
 TRANSPORTATION DEPT, BLDG 14, 5961
 PAVING OF INTERSECTION WITH ASPHALT BLOCK AT MORRIS AVE AND 2ND ST, 5962
 UNTITLED, 9314
 USS NEW ORLEANS BULKHEAD ASSEMBLIES IN FIELD AT HEAD OF BLDG WAYS, 9318
 USS NEW ORLEANS VIEW LOOKING FORWARD TO BULKHEAD NO 32, 9319
 USS NEW ORLEANS ASSEMBLIE SECTION AT HEAD OF BLDG WAYS, 9320
 USS NEW ORLEANS START IB STRUCT CASTING SHOWING METHOD USED TO STRAIGHTEN, 9321
 USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FRAME 103, 9322
 USS NEW ORLEANS VIEW LOOKING FORWARD FROM FRAME 53, 9323
 USS NEW ORLEANS VIEW LOOKING FORWARD ABOUT FR 103 TO 53, 9324
 USS NEW ORLEANS ASSEMBLIE SECTION AT HEAD OF BLDG WAYS, 9325
 USS NEW ORLEANS VIEW LOOKING FORWARD TO STEM, 9326
 USS NEW ORLEANS VIEW LOOKING AFT FROM ABOUT FRAME 67, 9328
 USS NEW ORLEANS ASSEMBLY SECTION AT HEAD OF BLDG WAYS, 9329
 USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FRAME 69, 9330
 USS NEW ORLEANS VIEW LOOKING FORWARD FROM ABOUT FR 70, 9331
 YF 221 VIEW SHOWING WELDED STEM AT KEEL SHELL STRAKES A & B, 9332

USS NEW ORLEANS MAIN CONTROL STATION FOR RELEASING TRIGGERS IN PIT BENEATH SHIP, 9333
USS NEW ORLEANS TRIGGER FOR RELEASING SHIP, 9334
USS NEW ORLEANS TRIGGER FOR RELEASING SHIP, 9335
USS NEW ORLEANS, 9336
USS NEW ORLEANS, 9337
USS NEW ORLEANS, 9338
USS NEW ORLEANS SHIP SERVICE STORE, 9339
USS NEW ORLEANS SHIP SERVICE STORE ROOM LOOKING TO STARBOARD, 9340
USS NEW ORLEANS SILVER SERVICE, 9341
USS NEW ORLEANS GENERAL VIEW LOOKING FOR SIGNAL BRIDGE, 9342
USS NEW ORLEANS GENERAL VIEW LOOKING AFT FROM MACHINE GUN PLATFORM, 9343
USS NEW ORLEANS BROADSIDE VIEW OF PORT SIDE LOOKING FORWARD SHOWING OUTREACH OF BOAT AND AIRPLANE CRANE BOOM BOOM CARRYING TEST LOAD OF 32000# AT BOAT HOIST, 9344
USS NEW ORLEANS GENERAL VIEW LOOKING FORWARD, 9346
USS NEW ORLEANS BROADSIDE OF PORT SIDE LOOKING FORWARD SHOWING AFTER END OF BRIDGES SEARCHLIGHT PLATFORMS AND 5" A A GUNS, 9347
USS NEW ORLEANS VIEW OF STARBOARD SIDE LOOKING AFT SHOWING BOAT AND AIRPLANE CRANE SECONDARY CONNING STATION PART OF BOAT STOWAGE AND CATAPULT, 9348
USS NEW ORLEANS GENERAL VIEW STARBOARD SIDE LOOKING AFT, 9349
USS NEW ORLEANS DECK OVER HANGER LOOKING AFT SHOWING BOAT STOWAGE BOAT AND AIRPLANE CRANES SECONDARY CONNING STATION AND ETC, 9350
USS NEW ORLEANS LOOKING FORWARD FROM DIRECTOR AND MACHINE GUN PLATFORM AFT, 9351
USS NEW ORLEANS BOW LOOKING AFT SHOWING BRIDGES GUNPORT BUCKLERS #1 AND #2 - 8" TURRETS AND MISCELLANEOUS RIGGING, 9352
USS NEW ORLEANS BROADSIDE PORT SIDE LOOKING AFT SHOWING BRIDGES MISCELLANEOUS STOWAGES 5" A A GUNS SEARCHLIGHT PLATFORMS BOAT AND AIRPLANE CRANE AND MISCELLANEOUS RIGGING, 9353
USS NEW ORLEANS NAVIGATING BRIDGE STARBOARD SIDE LOOKING AFT SHOWING SELF SYNCHRONOUS ALIDADE 24" SEARCHLIGHT SPEED FLAG LOCKER DECK MATS AND ALUMINUM WINDSHIELD, 9354
USS NEW ORLEANS ARRANGEMENT STARBOARD SIDE LOOKING AFT SHOWING 5" A A GUNS SEARCHLIGHT PLATFORMS BRIDGES VENTURI TYPE WINDSHIELDS AND CATAPULT FOUNDATION, 9355
USS NEW ORLEANS NAVIGATING BRIDGE PILOT HOUSE STARBOARD LOOKING TO PORT AND FORWARD SHOWING RADIO KEY SOUNDER ENGINE REVOLUTION TRANSMITTER AND INDICATOR AUXILIARY TELEGRAPH TO ENGINE ROOM ENGINE ORDER TRANSMITTER AND INDICATOR STEERING TELEGRAPH AND ANGLE INDICATOR STEERING STAND STARBOARD COMPASS HELMSMAN GRAFTING WHISTLE AND SIREN PULLS SLIDING WINDOWS WITH CORY - KENT CLEAR VISION SCREENS AND VOICE TUBES, 9356
USS NEW ORLEANS NAVIGATING BRIDGE PORTSIDE LOOKING TO STARBOARD SHOWING RADIO DIRECTION FINDER STATION STARBOARD COMPASS RUBBER DECK MATS AND WINDSHIELD, 9357
USS NEW ORLEANS SIGNAL BRIDGE AFT LOOKING FORWARD STARBOARD SIDE SHOWING 12" SIGNAL SEARCHLIGHTS RUBBER DECK MATS AND VENTURI WINDSHIELD, 9358
USS NEW ORLEANS SIGNAL BRIDGE STARBOARD SIDE LOOKING AFT SHOWING SIGNAL FLAG BOX 12" SIGNAL SEARCHLIGHT RUBBER DECK MATS AND #1 SMOKE STACK, 9359
USS NEW ORLEANS FORWARD BATTLE LOOKOUT AND MACHINE GUN PLATFORM STARBOARD LOOKING TO PORT SHOWING AFTER 50 CALIBRE A A MACHINE GUN MOUNT READY SERVICE BOX AND FOREMAST, 9360
USS NEW ORLEANS UPPER DECK LOOKING AFT FROM BOW SHOWING SECTION OF HAWSE PIPE ANCHOR CHAINS STOPPERS WILDCATS CHAIN PIPES ETC, 9361
USS NEW ORLEANS UPPER DECK LOOKING AFT FROM BOW SHOWING SECTION OF HAWSE PIPE GRATING ANCHOR CHAIN STOPPERS WILDCAT CHAIN PIPE ETC, 9362
USS NEW ORLEANS FORWARD BATTLE LOOKOUT AND MACHINE GUN PLATFORM PORT SIDE LOOKING FORWARD SHOWING FORWARD 50 CALIBRE A A MACHINE GUN MOUNT AND READY SERVICE BOX, 9363
USS NEW ORLEANS NAVIGATING BRIDGE CHART TABLE TRACKING TABLE PITOMETER LOG CHRONOMETER BOX CALL BELL ANNUNCIATOR ELECTRICAL PAN JACK BOX FOR TIME TICK CLINOMETER ANNUNCIATOR FOR DEAD RECKONING TRACER AND GYRO COMPASS SYSTEMS LATITUDE AND LONGITUDE INDICATOR SHAFT REVOLUTION INDICATOR AVERAGE R P M FOUR SHAFTS SHAFT REVOLUTION INDICATOR MILAGE ONE SHAFT BEARING INDICATOR DESK LIGHTS SHIPS SERVICE TELEPHONE CLOCK A C SELF SYNCHRONOUS COURSE RECORDER ANEMOMETER AND HATCH TO NAVIGATORS STORES, 9364
USS NEW ORLEANS RADIO CENTRAL LOOKING TO STARBOARD AND AFT SHOWING RADIO RECEIVER CLASS II A C TYPE "RAB" WITH OPERATORS TABLE FILE CABINET HETRODYNE FREQUENCY METER TELEPHONE SUPERVISORS TABLE CLOCK RECEIVER POWER REMOTE CONTROL PANEL RECEIVER EXTENSION PLUG BOARD TYPE SE2458 TRANSMITTER REMOTE CONTROL PLUG BOARD TYPE SE3260, 9365
USS NEW ORLEANS RADIO CENTRAL LOOKING TO PORT AND AFT SHOWING RADIO RECEIVER CLASS II A C TYPE "RAB" WITH OPERATORS TABLE RADIO RECEIVER CLASS I A C TYPE "RAA" WITH OPERATORS TABLE FUSED SWITCH BOX TRUMBULL #5791 FIRE EXTINGUISHER FIRST AID CABINET AND RADIO RECEIVER CLASS I A C TYPE "RAA" WITH OPERATORS TABLES, 9366
USS NEW ORLEANS RADIO CENTRAL LOOKING TO PORT AND FORWARD SHOWING RADIO RECEIVER CLASS I A C TYPE "RAA" WITH OPERATORS TABLE THREE RADIO RECEIVERS CLASS II A C TYPE "RAB" WITH OPERATORS TABLES

RADIO RECIEVER CLASS I A C TYPE "RAA" ELECTRICAL FAN CLOCK FUSED SWITCH BOX TRUMBALL #5791 AND FIRST AID CABINET, 9367
 USS NEW ORLEANS RADIO TRANSMITTER ROOM LOOKING FORWARD TO STARBOARD SHOWING TRANSMITTER CLASS "3C" MODEL "TAU" TRANSMITTER CLASS "2J" MODEL "TAQ-3" TRANSMITTER CLASS "4C" MODEL "TBF" RADIO RECEIVER CLASS II A C TYPE "RAB" WITH OPERATORS TABLE RADIO RECEIVER CLASS I A C TYPE "RAA" WITH OPERATORS TABLE TRANSMITTER CLASS "5H" MODEL "TBA" AND SUPERVISORS TABLE, 9368
 USS NEW ORLEANS GENERAL VIEW OF SIDE LADDER LOOKING FORWARD, 9369
 USS HULL NO 350 WATER TIGHT BULKHEAD NO 105, 9370
 USS HULL NO 350 METHOD OF HOLDING DOWN BULKHEAD WHILE WELDING N THE SHOP - WATER TIGHT BULKHEAD NO 93, 9371
 USS HULL NO 350 METHOD OF HOLDING DOWN BULKHEAD WHILE WELDING N THE SHOP - WATER TIGHT BULKHEAD NO 1054, 9372
 USS 350 - 353 EXHAUST SYSTEM FOR EXTRACTING FUEMS [SIC] FROM THE ELECT WELDING OF GALV SURFACES, 9373
 USS 350 - 353 METHOD OF HOLDING DOWN WATER TIGHT BHDS IN PLACE ALSO SHOWING EXHAUST HOSE FOR CARRING OFF FUEMS [SIC] IN WAY OF GALV ELECTRIC WELDNG, 9374
 USS 350 - 353 METHOD OF HOLDING DOWN WATER TIGHT BHDS IN PLACE FOR ELECTRIC WELDING ALSO SHOWING EXHAUST HOSE FOR CARRING OFF FUEMS [SIC] IN WAY OF GALV ELECT WELDING, 9375
 USS HULL 350 ALL WELDED BLKD # 127, 9381
 USS HULL 350 ALL WELDED BLKD # 127, 9382
 USS HULL 350 ALL WELDED BLKD # 127, 9383
 USS HULL 350 ALL WELDED BLKD # 127, 9384
 USS HULL # 350, 9385
 USS HULL # 350, 9386
 USS HULL 350, 9387
 Remodeling Building 92, view of west side, 698
 Applying Insulation on Roof of Building 32, 995
 Receiving and laying concrete floors slabs remodeling Building 37, 1160
 NURSES HAT SIDE VIEW, 4165
 NURSES HAT FRONT VIEW, 4167
 PEARL HARBOR DRY DOCK, 4168
 AMMUNITION DEPOT IONA ISLAND NEW YORK 'L' FILLING HOUSE 5, 4169
 NAVAL AMMUNITION DEPOT IONA ISLAND NEW YORK POWER HOUSE INTERIOR VIEW, 4170
 US NAVAL AMMUNITION DEPOT IONA ISLAND NEW YORK TEST HOUSE, 4171
 US NAVAL AMMUNITION DEPOT IONA ISLAND NEW YORK INSPECTOR OF ORDNANCE HOUSE, 4172
 S NAVAL AMMUNITION DEPOT IONA ISLAND NEW YORK PUMPHOUSE, 4173
 US NAVAL AMMUNITION DEPOT IONA ISLAND NEW YORK NORTH DOCK AND LIGHTERS, 4174
 US NAVAL AMMUNITION DEPOT IONA ISLAND NEW YORK QUILTING HOUSE, 4175
 US NAVAL AMMUNITION DEPOT DETONATOR HOUSE, 4176
 US NAVAL AMMUNITION DEPOT IONA NEW YORK ADMINISTRATION BUILDING, 4177
 US NAVAL AMMUNITION DEPOT IONA NEW YORK STOREHOUSE 2, 4178
 US NAVAL AMMUNITION DEPOT IONA ISLAND NEW YORK OFFICER'S QUARTERS 1, 4179
 US NAVAL AMMUNITION DEPOT IONA ISLAND NEW YORK OFFICER'S QUARTERS 4 BLDG 301, 4180
 US NAVAL AMMUNITION DEPOT IONA ISLAND NEW YORK RESERVOIR, 4181
 US NAVAL AMMUNITION DEPOT IONA ISLAND NEW YOK PAINT STORAGE HOUSE BLDG 103, 4182
 REPAVING STREETS IN NAVAL HOSPITAL IN RESERVATION BROADWAY BETWEEN BLDG "A" AND "E" LOOKING WEST, 4183
 RADIO MAST ERECTED ON ROOF OF BLDG 5 SOUTH EAST END YARD LABOR, 4186
 RADIO MAST ERECTED ON EAST SIDE OF ROOF OF BLDG 3 YARD LABOR, 4187
 RADIO MAST BEING ERECTED ON WEST SIDE OF ROOF OF BLDG 3 YARD LABOR, 4188
 USS ALABAMA ARRANGEMENT OF HULL ZINCS ON PORT SIDE, 4247
 USS ALABAMA ARRANGEMENT OF HULL ZINCS ON STARBOARD SIDE, 4248
 FLOATING MACHINE SHOP ON WAYS, 4263
 USS LOUISIANA, 4299
 HAWSE PIPE CASTING FOR USS UTAH, 4300
 USS DELAWARE ENTERING DRY DOCK NO 4 LOOKING S, 4301
 USS OCTOPUS, 4302
 USS OCTOPUS, 4303
 USS OCTOPUS, 4304
 USS OCTOPUS, 4305
 USS ARKANSAS ANCHOR STOWAGE, 4306
 USS ARKANSAS ANCHOR STOWAGE, 4307
 USS ARKANSAS ANCHOR STOWAGE, 4308
 USS ARKANSAS BOTTOM SURFACE OF PORT SIDE AFT AS PREPARED FOR REPAINTING, 4309
 USS ARKANSAS BOTTOM SURFACE OF PORT SIDE AFT PAINT USED AS ANTI-CORROSIVE, 4310
 USS ARKANSAS IN DD 4 PORTSIDE VIEW LOOKING AFT, 4311

USS ARKANSAS SURFACES ON BOTTOM OF PORTSIDE AS PREPARED FOR REPAINTING LOOKING FORWARD, 4312
USS SANDS, 4313
USS SANDS, 4314
USS SANDS, 4315
USS SANDS, 4316
USS ARKANSAS FLAG BRIDGE PORTSIDE LOOKING ACROSS THE BOW FROM PORT DIRECTOR TOWER, 4317
USS ARKANSAS FLAG BRIDGE LOOKING AFT FROM RANGE FINDER ON TOP OF TURRET #2, 4318
USS ARKANSAS FLAG BRIDGE PORTSIDE LOOKING FORWARD FROM BOAT CRANE MAST, 4319
USS ARKANSAS IN DD NO 4 FOR REPAIRS TO BOTTOM, 4320
[untitled], 4322
untitled, 4323
untitled, 4324
untitled, 4325
untitled, 4326
untitled, 4327
untitled, 4328
untitled, 4329
untitled, 4330
untitled, 4331
untitled, 4332
GUN DIRECTOR MK 17, 0° POSITION 03/16/1926, 4333
GUN DIRECTOR MK 17, 90° POSITION, 4334
GUN DIRECTOR MK 17 270° POSITION, 4335
MK 17 GUN DIRECTOR 90 DEGREE POSITION, 4336
GUN DIRECTOR 270 DEGREE POSITION, 4337
[untitled], 4338
QUARTERS 'A' REPAIRS INSTALLATION OF NEW ROOF ON GREEN HOUSE ON COMMANDANT'S HILL, 4340
QUARTERS 'A' REPAIRS WATER SUPPLY LOOKING NW ALLOTMENT 78201-28, 4341
QUARTERS 'A' REPAIRS BASEMENT ALLOTMENT 78201-28, 4342
QUARTERS 'A' REPAIRS CEILING 2ND FLOOR HALL LEVELED UP ALLOTMENT 8201-28 YARD LABOR, 4343
QUARTERS 'A' REPAIRS 2ND FLOOR SETTLEMENT PARTITIONS ALLOTMENT 78201-28 YARD LABOR, 4344
QUARTERS 'A' REPAIRS KNEE BRACE IN ATTIC ALLOTMENT 78201-28 YARD LABOR, 4347
QUARTERS 'A' REPAIRS CEILING 1ST FL HALL LEVELED UP ALLOTMENT 8201-28 YARD LABOR, 4348
QUARTERS 'A' REPAIRS KNEE BRACE IN ATTIC ALLOTMENT 78201-28, 4349
QUARTERS 'A' REPAIRS NEW STUDS IN BASEMENT FLOORS LEVELED UP ALLOTMENT 8201-28, 4350
QUARTERS 'A' REPAIRS SETTLEMENT OF PARTITIONS 1ST FLOOR ALLOTMENT 78201-28, 4351
QUARTERS 'A' REPAIRS NEW STUDS IN BASEMENT FLOORS LEVELED UP LOOK S ALLOTMENT 8201-28, 4352
QUARTERS 'A' REPAIRS TO BASEMENT ALLOTMENT 78201-28, 4353
QUARTERS 'A' REPAIRS 1ST FL HALL ALLOTMENT 78201-28, 4354
QUARTERS 'A' REPAIRS 2ND FL HALL SETTLEMENT OF PARTITIONS ALLOTMENT 78201-28, 4355
QUARTERS 'A' REPAIRS TO WATER SUPPLY LOOK NW ALLOTMENT 78201-28, 4356
QUARTERS 'A' REPAIRS VIEW OF DINING ROOM COMPLETED ALLOT 78201-1, 4357
QUARTERS 'A' REPAIRS TO ROADWAY ALLOT 8201-28_YARD LABOR, 4358
QUARTERS 'A' REPAIRS UNDERPINNING COMPLETED ALLOT 8201-28 YARD LABOR, 4359
QUARTERS 'A' REPAIRS NEW BRICK FIREPLACE IN PARLOR ALLOT 8201-28 YARD LABOR, 4360
QUARTERS 'A' REPAIRS TO ROADWAY ALLOT 8201-28 YARD LABOR, 4361
QUARTERS 'A' REPAIRS RENEWED ROADWAY LOOK SW ALLOT 78201-1 YARD LABOR, 4362
QUARTERS 'A' REPAIRS RENEWED ROADWAY LOOK EAST ALLOT 78201-1 YARD LABOR, 4363
QUARTERS 'A' REPAIRS RENEWED ROADWAY LOOK EAST ALLOT 78201-1 YARD LABOR, 4364
QUARTERS 'A' REPAIRS EAST BEDROOM REFINISHED & FURNISHED 2ND FLOOR ALLOT 78201-1 YARD LABOR, 4365
QUARTERS 'A' REPAIRS EAST BEDROOM REFINISHED & FURNISHED 2ND FLOOR ALLOT 78201-1, 4366
QUARTERS 'A' REPAIRS TO LIBRARY ALLOT 78201-1 YARD LABOR, 4367
QUARTERS 'A' REPAIRS KITCHEN REFINISHED ALLOT 78201-1 YARD LABOR, 4368
LOOKING SW FROM HOUSE A (10), 4369
LOOKING SW FROM HOUSE A (10), 4370
QUARTERS 'A' REPAIRS FIRE ESCAPE BUILT ON S SIDE 201-14, 4371
OAK FLOORING QUARTERS (A) CONDITION OF EXISTING FLOOR PRIOR TO CONTRACT START CONTRACT NOY 2559, 4372
QUARTERS A COMMANDANT'S HOUSE, 4373
BLDG A LOOKING NW, 4374
BLDG A PARLOR MANTEL, 4375
BLDG A LOOKING NW, 4376
BLDG A LOOKING W, 4377
HOUSE A LOOKING W, 4378
HOUSE A LOOKING NW, 4379

HOUSE A LOOKING NW, 4380
HOUSE A LOOKING NW, 4381
HOUSE A FRONT DOOR OF ADDITION LIBRARY MANTEL, 4382
HOUSE A ADDITION LIBRARY MANTEL, 4384
HOUSE A LOOKING NW, 4385
HOUSE A ALTERATIONS LOOKING N MONTHLY PROGRESS PHOTO JOS BAUER CONTRACTOR, 4387
HOUSE A REPAIRS LOOKING NE JOS BAUER CONTRACTOR, 4388
HOUSE A LOOKING NW, 4390
HOUSE A LOOKING SW FROM W END OF PORCH, 4391
HOUSE A LOOKING SW FROM W END OF PORCH, 4392
NEW CONCRETE STAIRWAY BETWEEN BLDG 1 (11) AND HOUSE A (10) N SIDE LOOKING W YARD LABOR, 4394
REINFORCED CONCRETE STAIRWAY BETWEEN BLDG 1 (11) AND HOUSE A (10) S SIDE LOOKING SW YARD LABOR, 4395
LOOKING SW TOWARDS HOUSE A (10), 4397
HOUSE A CONSERVATORY AND GREENHOUSE LOOKING N, 4461
QUARTERS B D C H K L LOOKING NW, 4464
HOUSE B (52) LOOKING NW REPAIRS, 4465
HOUSE B (52) LOOKING W REPAIRS, 4466
HOUSE B (52) LOOKING NW REPAIRS, 4467
REPAIRS TO QUARTERS - HOUSE C - PS SIMMONS CONTR AM - DIAMOND BLASTCO SUB - CONTR FOR STUCCO, 4470
HOUSES C & H (51) LOOKING NW REPAIRS PS SIMMONS, C'R. AM. DIAMOND BLAST CO., SUBCONTRACTOR FOR STUCCO, 4478
EXTENSION QUARTERS 'D' ALLOT 70201-21 YARD LABOR, 4479
EXTENSION QUARTERS 'D' COMPLETED ALLOT 70201-31 YARD LABOR, 4480
HOUSE D (53) REPAIRS LOOKING NW PS SIMMONS, C'R. AM. DIAMOND BLAST CO., SUBCONTRACTOR FOR STUCCO, 4483
HOUSE D (53) LOOKING NW REPAIRS PS SIMMONS, C'R. AM. DIAMOND BLAST CO., SUBCONTRACTOR FOR STUCCO, 4484
NEW FLOOR IN QUARTERS 'F' ALLOT 70201-16 CONTRACT NOY 702, 4492
ALTERATIONS AND REPAIRS TO QUARTERS G ALLOT 74201 - 48 YARD LABOR, 4495
ALTERATIONS AND REPAIRS TO QUARTERS 'G' VIEW OF EAST SIDE ALLOT 74201 - 48 YARD LABOR, 4502
ALTERATIONS AND REPAIRS TO QUARTERS 'G' ALLOT 74201 - 48 YARD LABOR, 4504
ALTERATIONS AND REPAIRS TO QUARTERS 'G' ALLOT 74201 - 48 YARD LABOR, 4506
HOUSE I (55) REPAIRS LOOKING NW PS SIMMONS, C'R. AM. DIAMOND BLAST CO., SUBCONTRACTOR FOR STUCCO, 4519
HOUSE I (55) REPAIRS LOOKING NW PS SIMMONS, C'R. AM. DIAMOND BLAST CO., SUBCONTRACTOR FOR STUCCO, 4520
EXCAVATIONS & RR TRACK FOR ROUNDHOUSE LOOKING SW ALONG 5TH ST YARD LABOR, 4526
EXCAVATIONS & RR TRACK FOR ROUNDHOUSE LOOKING SW ALONG 5TH ST YARD LABOR, 4527
ROUNDHOUSE GENERAL VIEW OF SITE LOOKING SW FROM 5TH ST YARD LABOR, 4528
ROUNDHOUSE GENERAL VIEW OF SITE LOOKING NE YARD LABOR, 4529
ROUNDHOUSE SW FLUSHING AVE SIDE OF SITE LOOKING SW YARD LABOR, 4530
ROUNDHOUSE NW POLICE STATION SIDE OF SITE LOOKING SW YARD LABOR, 4531
ROUNDHOUSE CONCRETE FOUNDATION FOR WALL ON SW SIDE LOOKING NW YARD LABOR, 4532
ROUNDHOUSE LAYING CONCRETE BLOCKS AT 5TH ST COR LOOKING W YARD LABOR, 4533
ROUNDHOUSE TURN TABLE PIT, LOOKING N YARD LABOR, 4534
ROUNDHOUSE SW FLUSHING AVE SIDE OF SITE LOOKING SW YARD LABOR, 4535
ROUNDHOUSE NW SIDE OF SITE POLICE STATION LOOKING SW YARD LABOR, 4536
ROUNDHOUSE EXTERIOR LOOKING N YARD LABOR, 4537
ROUNDHOUSE EXTERIOR LOOKING NE YARD LABOR, 4538
ROUNDHOUSE SHOWING INSIDE LOOKING SE YARD LABOR, 4539
ROUNDHOUSE SHOWING INSIDE LOOKING S YARD LABOR, 4540
ROUNDHOUSE GENERAL VIEW LOOKING SW YARD LABOR, 4541
ROUNDHOUSE INTERIOR VIEW S SIDE LOOKING SE YARD LABOR, 4546
ROUNDHOUSE GENERAL VIEW LOOKING SW YARD LABOR, 4548
ROUNDHOUSE LOOKING SW YARD LABOR, 4549
ROUNDHOUSE LOOKING SW YARD LABOR, 4550
ROUNDHOUSE LOOKING SW YARD LABOR, 4551
ROUNDHOUSE LOOKING S YARD LABOR, 4552
ROUNDHOUSE DOORS INSTALLED LOOKING SW YARD LABOR, 4553
EXTENSION TO ROUNDHOUSE LOOKING SW YARD LABOR, 4555
REPAVING STREETS IN NAVAL HOSP RESERVATION ROADWAY BETWEEN BLDGS "A" AND "E" LOOKING WEST
WALLABOUT MARKET IN BACKGROUND CONT 4953-A, 4556
untitled, 4557
untitled, 4559
untitled, 4560

Naval Chaplains, 4563
 BLDG 127 REPAIRS TO ROOF OF BLDG VIEW LOOKING NORTH YARD LABOR, 4564
 REPAIRS TO ROOF OF BLDG 127 ALLOT 7X218 - 13 - 5, 4566
 BLDG 127 REPAIRS TO ROOF OF BLDG ALLOT 7X218-13-5 YARD LABOR, 4567
 BLDG 127 REPAIRS TO ROOF OF BLDG ALLOT 7X218-13-5 YARD LABOR, 4568
 BLDG 127 REPAIRS TO BRICKWORK OF BLDG NORTH END CONTRACT NOY 1824, 4569
 untitled, 4570
 BLDG 130, 4571
 LOOKING NO FROM CANTILEVER CRANE TRACK, 4573
 50 TON HAMMERHEAD CRANE NEAR BERTH 12 175 TON TROLLEYS IN POSITION CONTRACT NOY 3341, 4576
 50 TON HAMMERHEAD CRANE NEAR BERTH 12 175 TON TROLLEYS IN POSITION CONTRACT NOY 3341, 4577
 GUN DIRECTOR MK 17 180 DEGREE POSITION, 4623
 USS Rijnland (ID-2718), Naval Overseas Transportation Service [NOTS], Port Side View at Navy Yard New York, 5610
 Commissioning Ceremony of USS Oriskany (CVA-34) at the New York Naval Shipyard, Brooklyn, 5873
 Cornice for Quarters E, F, and G, 4488
 Alterations to Building 93 for Marine Officers Quarters, Interior View Showing Mantle in Place for One of the Rooms, 731
 Argentine Battleship Rivadavia Entering Whitney Basin, 2054
 Demolition of Building 75 Looking Southeast from 4th Street Contract Noy 4243, 3184
 Remodeling Building 92, View in Basement, West Side, 674
 Photo of Frontispiece Standard Boats of the U.S. Navy, 1900 Edition, 2081
 Waterfront Looking West from Out at the End Coal Plant, 3997
 Remodeling Building 32 - General View of Excavating and Pile Driving Operations, 628
 Naval Hospital Brooklyn NY Building 'F' Detail of Gutter Cornice and Flashing of Extension Taken from Cupola Building 95 Annex (Spec 8477) 3-HO-122, 8503
 Handling Salvaged Granite for Reuse on Lean-to Building 10 and Quarters A, 621
 Excavation and Driving Piles for Pickling Tank Foundation - Steel Storage Yard C and R Allotment Yard Labor, 3626
 EXCAVATION FOR ELECTRIC DUCTS AT HEAD OF PIER G, ALLOT, 7X218-41-4, YARD LABOR, 8040
 Remodeling Building 32 - Pile Driving Operations, 626
 Remodeling Building 32 - Excavating and Sheet Piling for Foundation, 627
 Excavating and Driving Piles for Picking Tank Foundation Steel Storage Yard C and R Allot Yard Labor, 3627
 U.S. Naval Hospital New York, Concrete Walk from Main Building to Receiving Door Building F, 5942
 Erection of Accumulator Tank Compressed Air Line View East of Building Ways 1, 5915
 Wallabout Market , 1986
 Jib Cranes Southeast Side Building 116 (27) Looking East, Monthly Progress Photo, 7371
 USS Brooklyn (CL-40), 9433
 Demolition of Existing Building 78, Looking Southwest from a Point in Building 41 Contract Noy 4243, 3183
 Investigation of Site for New Annealing Furnace Between Dry Dock 1 and 4 , 3623
 Investigation of Site for New Annealing Furnace Between Dry Docks 1 and 4 Near Seawall, 3624
 Investigation of Site for New Annealing Furnace Between Dry Docks 1 and 2 Near Seawall, 3625
 Kaiser Wilhelm II Clearance Between Stern and Head of Dock, 6687
 Kaiser Wilhelm II View Under Point of Stern Looking Directly Aft at Guard on Caisson, 6688
 Kaiser Wilhelm II Looking Down from Caisson on Point of Stern, 6690
 Kaiser Wilhelm II Point of Stern Projecting Bet Braces on Caisson Rudder Swung 60 Degrees To Port to Clean Caisson, 6691
 Dry Dock 4 Renewing the Floor, Looking North Toward the Entrance, 9453
 Dry Dock 4, First Vessel Docked - USS Utah, 9615
 Dry Dock 4 Monthly Progress Photo – General View Looking Northeast, 9780
 Dry Dock 4 Granite Storage Yard, Looking Northeast, 10123
 Excavating Around Pumpwell Between Dry Dock 2 and 3 for Waterproofing, 3901
 Improvements to 2nd Floor, Building 14 - Court Martial Room, 648
 Foundation for Substation 6, 6953
 Erecting Elevator in Laundry at the Naval Hospital, 1103
 Erecting Shop Building 128 (63-C) Showing Congestion Looking Northeast, 6302
 Equipment, 1260
 Excavating Conduit for Steam Pipes, Long Side of Building 128 Looking East, 6287
 Excavation for Electric Ducts and Manholes in Building 217, 6973
 Excavation and Forms for Lumber Rack Foundations in Building 214 View Looking Southwest, 6979
 Excavating for Stem Lines Leading from Building 28 to Building 62 , 3188
 Old Anchor Excavated near Building No. 225, 2032
 Monthly Progress Photo - Building 116 (27), New Trolley Runway to Building 116 (26), Looking North, 7368
 Monthly Progress Photo - Trolley Runway Between Buildings 115 (26) and 116 (27), Looking Northwest, 7381
 Monthly Progress Photo - Trolley Runway Between Buildings 115 (26) and 116 (27), Looking Northwest, 7389
 Monthly Progress Photo - Crane Runway Between Buildings 115 (26) and 116 (27), Looking West, 7391
 Monthly Progress Photo - Crane Runway Between Buildings 115 (26) and 116 (27), Looking Northwest, 7392
 Monthly Progress Photo - Trolley Support Between Buildings 115 (26) and 116 (27), Looking Northwest, 7393
 Repairs to Roof of Building 16, Looking West, 7607

Naval Hospital Repairs to Quarters 4 Looking Northwest, 8345
 Erecting Double Quarters at Main Entrance of Naval Hospital, 1252
 Officers Quarters B, East Wall, 4462
 Officers Quarters C, South Wall, 4468
 Repairs to Cornice on Quarters E, F, and G, 4489
 Repairs to Officers Quarters E, F and G (54), Looking Northwest, 4490
 Officers Quarters E, F and G (54), Looking Northwest , 4491
 Quarters I, G, F, and E, Looking North, 4518
 Foam Fire Extinguisher, Still Working 1 1/4 Minutes Later Showing Use Over Head , 2019
 Foam Fire Extinguisher, Liquids Used "A" and "B" resultant Volume "C", 2021
 Underpinning of Columns to Pattern Racks, Building 132, 1075
 Front View Improvement to Building 37, 1131
 Naval Hospital - A.W. Shelby, Seaman 2nd Class, Ankylosis of the Knee, 4162
 Naval Hospital - A.W. Shelby, Seaman 2nd Class, Ankylosis of the Knee, 4163
 Naval Hospital Physiotherapy Department Staff, Without Chief Dr. Bainbridge, 5992
 Naval Hospital - Ptosis (Luetic), 6048
 Building E, Naval Emergency Ward, Looking North, 8150
 Naval Hospital Building E Emergency Ward, Looking East, 8151
 Naval Hospital Interior View of Mortuary Chapel, 8344
 Naval Hospital Brooklyn NY Building F Detail of Gutter and Cornice Taken from Cupola Building 95 Annex (SPEC 8477) 3-HO-123, 8502
 Repaving Streets in Naval Hospital Reservation between Buildings A and E Looking West, 1120
 Repaving Streets in Naval Hospital Reservation between Buildings A and E, Looking East, 1174
 Repaving Streets in Naval Hospital Reservation in Vicinity of Garage, Looking Northwest, 1176
 Repaving Roadway in Naval Hospital Reservation in Vicinity of Garage Looking Northwest, 1187
 Completed double quarters at main entrance, view looking Southeast, 1255
 Equipment, 1259
 People Playing Pool at the Naval Hospital, 1262
 Men and women reading and playing cards and checkers at the Naval Hospital, 1264
 Men Sitting and Standing Inside Hospital Ward, 1265
 Erecting Extension to Staff Garage, 1177
 Ice in Basin Looking Northwest from Pier D, 2134
 Ice in Basin Looking Northwest from Outer End of Pier D, 2137
 Ice in Basin Looking Northeast from Outer End of Pier D, 2143
 Clinton Avenue Storehouse, Looking North , 4044
 Alterations Completed to Building 60, 608
 Acid Handling Device for Emptying Carboys with Safety. , 3179
 Interior View of Building 50, 3576
 Building 131, Interior, 6188
 Repairs to Quarters I Bedroom, Top Floor Front , 4515
 Steam and Internal Combustion Engine Laboratory, 2129
 Flower Beds in Front of Public Works Building, 3182
 Kaiser Wilhelm II Clearance Between Stem Gauge of Face of Alter at Head of Dock, 6686
 Naval Hospital Mortuary Chapel Completed, 6089
 Naval Hospital Mortuary Autopsy Room, 6091
 Removing Last of Steel of 2nd Floor of Building 10, View Looking South, 630
 Erection of double quarters at main entrance of naval hospital, 1253
 Erection of double quarters at main entrance , 1254
 Present Cumberland Street Gate Entrance to the Navy Yard at Morris Avenue, 1046
 USS New Orleans Assembly Section at Head of Buildingways, 9390
 Ice on Down Spent at Southwest Corner of Building 6 (25), 2145
 Ice on Downspout at Center of Southwest Side of Building 6 (25), 2151
 Ice on the Downspout on the Southwest Side of Building 22 (43), 2158
 New Elevator Shaft in Building 127 Allot 77201-23 Yard Labor, 3178
 General View of Exposed Tile to Which Repairs are Being Made - Building 4 , 3538
 350 Ton Hammerhead Crane Near Berth 12, View Looking West Showing Alignment of Quay Wall at Berth 12, 3680
 Building 131, Top Floor, 6187
 Building 131, Interior, 6189
 Building 131, Interior, 6190
 Building 131, Interior, 6191
 Building 131, Interior, 6192
 Building 131, View from Dry Dock 1, 6194
 Building 131, View from Dry Dock 1, 6195
 Building 131, 6196
 Building 131, 6197

Building 131, Top Floor, 6198
 Building 131, 6199
 Building 131, 6200
 Building 131, 6201
 Building 131, 6202
 Building 131, 6203
 Building 131, 6204
 Building 131, 6205
 Building 131, 6207
 Building 131, 6208
 Building 131, 6209
 Building 131, 6210
 Building 131, 6211
 Building 131, 6212
 Building 131, 6213
 Building 131, 6214
 Building 131, 6216
 Building 131, 6217
 Building 129, Exterior, 6232
 Erecting Shop Building 128 (63-C) Showing Congestion Looking Northeast, 6301
 Building 11 - Former Steel Foundry Foundations for Drop Hammers, Looking South, 6474
 Kaiser Wilhelm II View Under Point of Stern Looking Aft, 6689
 14" Gun MV, Long Pointed Projectile, Detail, 6735
 14" Gun MV, Long Pointed Projectile, Detail, 6736
 Electrical Class, Dynamo Section, 6854
 Wallabout Market, 6926
 11'6" Planer Foundation, Building 128, View of Excavation Showing Piles Under Former Planer and Location of City Sewer, 7088
 Laying Sidewalk Along North End of Building 128, 7318
 Interior View Building 120 Sectional View of West Side Looking South, Showing Stowage of Varnishes, Paint and Oil House , 7345
 Building 116 (27), 7374
 Monthly Progress Photo - Building 115 (26) Extension of Trolley Track Out of Northwest End, Looking North, 7401
 Reconstruction of Shipways No.1 Looking North at Posts and Braces for Working Platform, 7939
 Reconstruction of Shipways No.1 Installing Duct Lines for 70V DC Welding Lines on East Side of the Ways, View Looking North, 7941
 Reconstruction of Buildingways No.1, View Looking Toward the Inshore End of the Ways Showing Timbers Being Removed at Stations 9 and 50, 7957
 Reconstruction of Buildingways No.1, View Looking South Showing Form Work of Top Slab at Inboard End, 7975
 Reconstruction of Shipbuildingways No.1, South End Looking Northwest, 8020
 Improvement to Shipways No.2, View of West Side of Pier 42 Taken from Pier 41 and Showing Decking Being Completed, 8061
 Improvement to Shipways No.2, View Looking Inboard from 11 and 37 Showing Platform Construction, 8082
 Improvements to Shipways No.2, Pile Driving for Pier Extension on East Side, 8083
 View Looking West Showing Enclosure for Photoelectric Detector for Yard Basin at Pier C, 8817
 USS New Orleans 16" Closed Swallow Chock All Welded with Foundation Plates Welded to the Chock, 9143
 USS Brooklyn (CL-40) at Buildingways No.2 CL 40 with Keel Blocks and Cribbing Ready to Receive Keel, 9261
 USS New Orleans, View Looking Aft from About Frame 78, 9402
 USS Brooklyn (CL-40) Turret No.5, 9429
 Dry Dock 4, First Vessel Docked - USS Utah, 9611
 Dry Dock 4, First Vessel Docked - USS Utah, 9613
 Dry Dock 4, First Vessel Docked - USS Utah, 9614
 Temporary Foundry, Sub-assembly No. 2, Building 269, View Looking East from Second and Dock Streets, 9652
 Temporary Foundry Sub-assembly No. 2, Building 269, Looking Southwest , 9653
 Temporary Foundry Sub-assembly No. 2, Building 269, Looking North of Sheds for Coke and Sand, 9654
 Temporary Foundry Sub-assembly No.2, Building 269, Looking North from Dock Street Showing Placing Forms for Lean-to Columns, 9655
 Temporary Foundry, Sub-Assembly No.2, Building 269, View Looking West from Dry Dock 1 of Core Shop, 9656
 Temporary Foundry, Sub-Assembly No.2, Building 269, General Exterior View from Dock Street Looking Northeast, 9657
 Temporary Foundry, Sub-Assembly No.2, Building 269, General Interior Looking Northeast from Dock Street End of Building, 9658
 Building 126, 3175
 Remodeling Building 88 for Maine Officers Garage Yard Labor, Allot 6202-1, 3180
 Fire Department and Apparati, 3185
 Quarters of Fire Department, 3186
 General View of Present and New Location of Gate at Cumberland Street, 3195
 Wall Cracks of Lean-To, Foundry Southwest Corner (Building 29), 3197
 View of Southeast Corner of Building 120 Showing Settlement Cracks, 3848
 View of Bearing Piles Under Southeast Corner of Building 120 Showing Decayed Portion of Pile Head, 3849

Building 126, 3914
 Building 126, 3915
 View of the 1st Floor Building 130, Looking Northwest, 3949
 Waterfront from South Side of Pier F Looking Southwest, 4002
 Installing New Railroad Tracks, 5889
 Repairs to Catwalks and Crane Structure Over Buildingways No.1, 5934
 Building 131, 6206
 Building 131, 6218
 Reconstruction of Buildingways No.1, General View from Center Looking North to Outboard End, 7974
 Improvement of Berths 11 and 12, 8008
 Alterations Completed to Building 60, View of South and East Walls, 611
 Alterations Completed to Building 60, View of North and East Walls, 612
 Repairs to Roof and Metal Work of Building 60, 615
 Blue Stone Curbing and Sub-Base for Paving Block at Turret Foundation Between Pier C and D, 622
 Remodeling Building 32 - Excavation for Foundations , 624
 Improvements to 2nd Floor, Building 14 - Court Martial Room, 647
 Gyro School Room, 5th Floor, Building 5, 652
 Bedroom and Furniture in Building 93, Marine Officers Quarters, 757
 Installation of Crocker-Wheeler and Westinghouse Generator Set, Building 234, 808
 General Interior Painting of Dry Dock 3 Pumpwell, 809
 General Interior Painting of Dry Dock 3 Pumpwell, 810
 Improvements to 2nd Floor of Building 14, View of Corridor to Court Martial Rooms, 812
 Demolition of Floors in Building 10, 819
 New Transformers Outside of Building 152, 996
 General View of Fifth Street, Side of Building 32, 997
 Interior View Erection of Garage Doors, Building 32, 999
 General View of Building 10, Looking Northwest, 1009
 View Showing Miles 15 Ton Cranes in Position, Building 10, 1010
 Rear Elevation of Building 37 Before Demolition, 1019
 Improvements to Garage - Removing Debris from Demolition of Building 37, 1035
 Ice House on Clinton Avenue, Dock, Built Against Navy Yard Wall, 1058
 Dumping Ramp of Carleton Construction Company Built Against the Navy Yard Wall, Clinton Avenue, 1060
 Dumping Ramp of Carleton Construction Company Built Against the Navy Yard Wall, Clinton Avenue, 1064
 Dumping Ramp of Carleton Construction Company at Clinton Avenue Dock, Against the Navy Yard Wall, 1066
 Improvements to Garage Building 37, 1067
 Erection of Mill Shed for Form Work Material Yard, 1070
 Public Utilities Building 152 - Installation of Transformers, 1071
 Navy Yard Wall, Clinton Avenue , 1072
 Under Pinning of Columns to Pattern Racks of Building 132, 1073
 Contractor's Dumping Ramps, Clinton Avenue Dock, 1074
 Stone Shed at Ordnance Dock, 1077
 Contractor's dumping ramps, Clinton Ave. dock, 1078
 U.S. Naval Hospital - New Doors on Garage , 1081
 U.S. Naval Hospital - Reconstruction of Garage Doors, 1082
 U.S. Naval Hospital, Open Drain for Storm Water Along North Wall, 1083
 U.S. Naval Hospital - Open Drain for Storm Water Along West Wall, 1085
 Setting Single Leg Steam Hammer 2500 lbs Capacity on New Foundation, 1086
 U.S. Naval Hospital Building C - Proposed Laundry, 1092
 U.S. Naval Hospital Building C - Proposed Laundry, 1096
 U.S. Naval Hospital Building C - Proposed Laundry, 1097
 Changes in Building C for Laundry, 1098
 Interior of Laundry, Building C, 1102
 Erecting Elevator in Laundry at the Naval Hospital, 1104
 Erecting Elevator Shaft in Laundry at the Naval Hospital, View from Inside Laundry, 1111
 Interior View of Double Quarters Showing Dining Room, 1118
 Erecting Elevator Shaft in Laundry at the Naval Hospital, View from Inside Laundry, 1124
 Erecting Elevator Shaft in Laundry at the Naval Hospital, View from Outside Laundry , 1125
 Construction of Bridge Connecting Buildings A and E - Detail View of Staging, 1126
 Erection of Monorail and Switches Under Mezzanine Floor in Sheet Metal Shop, Building 12, 1129
 West Elevation of Building 37 Before Demolition, 1130
 Raising Floor Tiers Due to Settlement of Building 132 - View on Ground Floor, 1134
 Reinforcing Steel Mat for Footings - New Addition to Building 13, 1138
 Steel Dowel Footing for Concrete Pier - New Addition to Building 13, 1139
 Reinforcing Steel Frame for Concrete Pier on Footing, Addition to Building 13, 1140
 General View of New Addition to Building 13 - Pouring Concrete Driving Piles, Also Concrete Wall Forms, 1141

Exposed Pile Under Footing of Column 5 and 6, Machine Shop, Building 128, 1143
 Exposed Footing and Pile Under Columns 5 and 6, Machine Shop, Building 128, 1144
 Pit at Base of Footings to Columns 7 and 8 Underpinning Operations, Machine Shop, Building 128, 1145
 Tunnel Entrance to Repairs of Floor Supports in Building 128, 1147
 Floor Opening for Removal of Spoil in Repairs to Floor Supports Also Showing Fresh Air Intake, Building 128, 1148
 Bricking Up Walls of Building 204, 1149
 Driving Tube Piling into Foundation Pit for New Guard House and Cumberland Street Gate, 1168
 Shoring of Foundation South End of Building 120, 1170
 Erecting Elevator in Laundry of Naval Hospital, View of Elevator Looking North, 1182
 Repairing Floor on 2nd Floor, Northern Extremity of Building D, 1183
 Repairs to Floor on 2nd Floor of Northern Extremity, East Wing of Building D, 1184
 Repaving Roadway in Naval Hospital Reservation in Vicinity of Powerhouse, Looking Northeast, 1186
 Repairs to Floor of 2nd Floor, Northern Extremity of Building D, 1202
 Repairs to 2nd Floor, Northern Extremity of Building D, 1203
 Sheath Piling and Form Work Under Footing of Columns 7 and 8, Machine Shop Building 128, 1206
 U.S.S. Pensacola Detail View of After Structure, 1275
 Wallabout Market , 1992
 Seamans Regulation Hat, 1999
 Photograph of a Photograph - 22 Evans Street, 2004
 Photograph of a Photograph - 22 Evans Street, 2013
 Photograph of a Photograph - Provoost Mansion, 2014
 Photograph of a Photograph - Provoost Mansion, 2015
 Anchor Excavated Near Building 225, 2035
 Old Anchor Excavated Near Building 225, 2038
 Anchor Excavated Near Building 225, 2039
 Anchor Excavated Near Building 225, 2040
 Anchor Excavated Near Building 225 , 2041
 South Side of Ordnance Dock Looking East from Coal Plant, 2047
 Painting of Yard Building 12 [33] Looking South, 2048
 Site of Tennis Court on Ordnance Dock Looking East, 2052
 Argentine Battleship Rivadavia in Dry Dock 4, Looking Northeast, 2068
 Argentine Battleship Rivadavia in Dry Dock 4 Looking North, 2070
 Argentine Battleship Rivadavia in Dry Dock 4 Looking Southwest, 2071
 Argentine Battleship Rivadavia in Dry Dock 4 Looking Southwest, 2072
 Argentine Battleship Rivadavia in Dry Dock 4 Looking Southwest, 2073
 Argentine Battleship Rivadavia in Dry Dock 4 Looking Northeast Showing Clearance Between Sides of Ship and Dock, 2074
 Fleet Trophies, 2075
 Fleet Trophies, 2076
 Fleet Trophy, 2077
 Fleet Trophy, 2078
 Fleet Trophy, 2079
 Fleet Trophy, 2080
 Pickling Tanks Near Launchingways, Looking East, 2085
 From Photo of S.S. Carpathia in Dry Dock 4 at Erie Basin, Brooklyn NY, 2101
 Electrical Class, Smithery Section, 2127
 Electrical Class, Engine Room , 2130
 Snow around house A (10) looking north from Main Street near Perry Street, 2192
 Repairs to Quarters D, 4481
 Officer Quarters E, South Wall, 4485
 Repairs to Cornice of Quarters E, F, and G, 4486
 Repairs to Quarters I Bedroom, 2nd Floor Rear, 4509
 Repairs to Quarters I Bedroom, Top Floor Front, 4511
 Repairs to Quarters I Bedroom, Top Floor Front, 4512
 Repairs to Quarters I Bedroom, Top Floor Front, 4513
 Repairs to Quarters I Bedroom, Top Floor Front, 4514
 Repairs to Quarters I Bedroom, Top Floor Front, 4517
 New Piling- Part of Foundation Work for New Addition to Building 13, 1137
 Erecting Extension to Staff Garage, 1179
 Repaving in Naval Hospital Reservation Cement Walk to Flagstaff Directly Opposite Main Entrance of Building A, Looking West, 1181
 Foam Fire Extinguisher, Operating on Fuel and Oil And Gasoline Fire. , 2017
 Repairs to Quarters I Bedroom, Top Floor Front, 4510
 Repairs to Quarters I Bedroom, Top Floor Front, 4516
 East Waterfront of Navy Yard, Looking East from Near the Commandant's Slip, 2100
 USS Pensacola 67 Shell Stowage in 8" Triple Gun Mount, 9672

USS West Virginia Gun Director MK XI MOD 2, 4293
 Naval Hospital - A.W. Shelby, Seaman 2nd Class, Ankylosis of the Knee, 4161
 Loosened Brick Paving on Avenue B, Looking East, 1099
 Courtyard End of Avenue A, Brick Paving Opened, Looking Southwest, 1100
 Street Between Main Building and Building C, Looking West - Brick Paving Opened, 1101
 Repaving Streets in the Naval Hospital Reservation - Roadway Between Building A and Building A Annex, Looking South, 1105
 Repaving Streets in the Naval Hospital Reservation - Roadway Between Building A and Building A Annex, View Looking South, 1121
 New Parking Lot Curbing and Paving Operations, East End of Building 5, 1151
 Excavating and Grading in Yard at Location of New Cumberland Street Gate, 1157
 Repairing Streets in Naval Hospital Reservation View of Approach and Porch of Main Nurses' Quarters, Looking North, 1193
 Repaving Streets - View of Roadway Between Building A and A Annex, Looking East, 1199
 U.S.S. Pensacola View Look Forward, 1266
 U.S.S. Pensacola View Look Aft, 1267
 Sink with Pipes and Drain, 1256
 Bathtub and Sink, 1257
 Close-up of Sink, 1258
 Various Pipes, 1261
 Excavation for Sewer Manhole West Side of Building 18, 7997
 Laying Pneumatic Messenger Tube System on Warrington Avenue North of Third Street, 6750
 10" Experimental C R S Airport - Lens and Battle Cover Open CDO Plan D D 3505-1203-15, 9376
 10" Experimental CRS Airport View at Shell Outside - CDO Plan 3505-1203-15, 9377
 10" Experimental CRS Airport Lens and Battle Cover in Place CDO Plan DD 3505-1203-5, 9378
 10" Experimental CRS Airport Lens in Place - Battle Cover Lined Up CDO Plan DD 3505-1203-15, 9379
 10" Experimental CRS Airport Lens Open - Battle Cover in Place CDO Plan DD 3505-1203-15, 9380
 Power House, U.S. Naval Hospital Grounds, 8139
 Naval Hospital Power House, 8143
 General Interior Painting of Power Plant Building 41, 1001
 General Interior Painting of Power House Building 41, 1002
 New Steel for Housing Coal Crusher in Rear of Building 41, 1006
 Power Improvements at Northeast Corner of Building 41, 1012
 Oil Brakers Electrical Installation, Power Plant Building 41, 1025
 Panel Board Installation, Power Plant Building 41, 1026
 New Housing of Coal Crusher at Power Plant Building 41, 1029
 Covering of Steam Lines in Power Plant Building 41, 1030
 Pipe Covering of Steam Lines in Power Plant Building 41, 1031
 Repaving Streets - View of Roadway in Vicinity of Powerhouse Looking East, 1198
 Construction of Incinerator at Powerhouse, 1241
 Erecting Chimney of Incinerator at Powerhouse, 1242
 Construction of Incinerator at Powerhouse, View of North Side, 1243
 Erection of Chimney for Incinerator at Powerhouse, View of South Side, 1244
 View Looking North at Third Street and Chauncey Avenue Showing Preparing of Track for Paving, 3187
 Repairs to Standard Gauge Railroad Tracks Near Annealing Plant, 813
 Front View of New Garage Building 32, Old Garage Building 37, 1018
 Railroad Track Improvements at Dock and Third Streets, 1056
 Remodeling Building 92, View of Hallway, 1st floor, Looking North, 660
 Remodeling Building 92, View on Top Floor, West Side Looking North, 661
 Remodeling Building 92, View of Room in Basement, 682
 Alterations to Building 93 for Marine Officers Quarters, General View in Hall on 2nd Floor, View Looking South, 711
 Paving Second Street at Perry Avenue with Asphalt Block, 638
 Grading Roadway in Immediate Vicinity of Building 93, View Looking West, 732
 Repaving Roadways in Naval Hospital Reservation in Vicinity of Powerhouse, View Looking East, 1185
 Repaving Roadway in Naval Hospital Reservation Between Buildings A and A Annex, 1189
 Paving Roadway in Naval Hospital Reservation Between Building C and Commanding Officer's Quarters, View Looking North, 1190
 Repaving Roadway in Naval Hospital Reservation Along East Side of Building F, Looking North, 1191
 Repaving Roadway in Naval Hospital Reservation Along East Side of Building F, Looking South, 1192
 Repaving Roadway in Naval Hospital Reservation Between Building A and E, Looking East, 1194
 Repaving Streets - View of Roadway Along North Side of Building F, View Looking East, 1195
 Repaving Streets - View of Roadway Between Buildings A and E, Looking West, 1196
 Repaving Streets - View of Roadway in Vicinity of Garage, Looking Northwest, 1197
 Monthly Progress Photo - Trolley Runway Between Buildings 115 (26) and 116 (27), Looking Northwest, 7388
 Floating and Finishing Concrete Standard Gauge Railroad Tracks on Perry Avenue at Third Street, 620
 Repaving Streets in the Naval Hospital Reservation In the Vicinity of the Garage, View Looking West, 1123
 Repaving Streets in Naval Hospital Reservation Between Buildings A and E, Looking East, 1173
 Ice on Downspouts of Buildings 22 (43) and 127 (44), 2162

Repaving Streets in the Naval Hospital Reservation Between Building A and E, Looking East, 1117
 Repaving Streets in Naval Hospital Reservation Between Buildings A and E, Looking South, 1175
 Repaving Streets in Naval Reservation in Vicinity of Powerhouse, Looking Northwest , 1178
 Repaving Streets in Naval Hospital Reservation in Vicinity of Powerhouse, View Looking Northeast, 1180
 Naval Hospital Road Repairs Looking North from Near Building 426, 6527
 Building 131, 6193
 Building 128, Repairing Slate Broken by Skylight, 7219
 Building 58 Construction Roof View, 585
 General View of Roof in Consolidation of Shops, View Looking North, 635
 General View of Roof in the Consolidation of Shops, View Looking North, 636
 Roof Parapet Coping Forms, Building 32, 990
 Holley Tower on Roof of Power Plant Building 41, 1027
 Junction of Building 128 and 28 on Fifth Street Looking Southwest from West End of Roof of Building 190, During Period of Glazing, 7233
 Monthly Progress Photo - Roundhouse Looking Southwest, 3199
 Transportation Repairs to Roundhouse Turntable, 1045
 Transportation Extension to Inspection Pit at Roundhouse, 1049
 Checking out at Noon at the Launchingways, 6808
 Electrical Class, Mechanical Section, 2119
 Electrical Class, Engine Section, 2128
 Erecting Shop Building 128 (63-C) Showing Congestion Looking Northeast, 6303
 USS Pensacola Midship Looking Aft, 9315
 USS New Orleans Assembly Section at Head of Buildingways, 9393
 USS New Orleans, View Looking Forward from About Frame 94, 9401
 USS Brooklyn (CL-40) Turret No.5, 9430
 U.S.S. Pensacola Bow View , 1269
 U.S.S. Pensacola View Looking Aft, 1270
 U.S.S. Pensacola view looking forward, 1271
 U.S.S. Pensacola View from Midships Looking Aft, 1273
 U.S.S. Pensacola general view looking forward, 1274
 U.S.S. Pensacola detail view of forward structure, 1276
 U.S.S. Pensacola General View Looking Aft , 1277
 U.S.S. Pensacola Main Deck, Looking Aft , 1278
 U.S.S. Pensacola, Midship Looking Aft, 1279
 U.S.S. Pensacola Midship Look Forward, 1280
 Discharge Head, 1281
 Pickling Tank Near Launchingways, Looking North, 2083
 Vessels on East Side of Whitney Basin, Looking Northeast from West of Dry Dock 1 Entrance, 2084
 Waterfront Near Entrance to Dry Docks 2 and 3, 2118
 U.S.S. Pensacola view looking forward, 1272
 Excavation Around Pump Well for Waterproofing Between Dry Docks 2 and 3. , 3902
 U.S.S. Pensacola View Looking Forward, 1268
 Present Wash Room and Showers, 2nd Floor, Building 41, 644
 Washroom and Shower Improvement, 2nd Floor, Building 41, 1133
 Interior of Altered Building 60, 614
 Repairs to Sidewalks in Immediate Vicinity of Building 93, View Looking North, 739
 Sidewalk Improvements on Sixth Street at Building 30, 1063
 Wallabout Market, 1984
 Wallabout Market, 1998
 Installing Hardware on Bradley Wash Basins, 2nd Floor Lean-to of Building 12, 817
 Removing Skylights and Monitor from Old Building 11 - Openings for New Skylights, 639
 Monorail Crane and Discharge Points, Copper Shop Building 11A, 1016
 Interior View of West Side of New Garage Showing East Wall of Building 37, 1020
 Interior View of East Side of New Garage Building 32, 1021
 Monitor Skylight Improvement to Power Plant Over Boiler Room, 1028
 General View of Building 10, View Looking Southeast, 1095
 View in New Pipe Shop, Painting Two Ton Motor Driven Monorail Crane, Building 11A, 1024
 Construction of Bridge Connecting Buildings A and E, General View of Span in Place , 1230
 Construction of Bridge Connecting Buildings A and E - Detail View of Staging at Building E, 1231
 Construction of Bridge Connecting Buildings A and E - General View of Span in Place, 1232
 Interior View of Bridge Being Constructed Connecting Buildings A and E, 1233
 Exterior View of Bridge Under Construction Connecting Buildings A and E, 1234
 Interior View of Bridge Being Constructed Connecting Buildings A and E, 1238
 Exterior View of Bridge Under Construction Connecting Buildings A and E, 1239
 Interior View of Bridge Between Buildings A and E, Looking East, 1240

12" Steam Feed and Return Lines Cast Iron Conduit on Fourth Street from Building 41 Powerhouse through Building 132, 5936
 Building 58 View Showing Steam Duct and Manhole South of Non-commissioned Officers' Quarters, 581
 Excavation for Steam Duct to Building 92, 670
 Relocating High Pressure Steam and Return Line Through Foundation Wall, South End of Building 13, 1076
 High Pressure Steam Line from Column to Pickling Tank, 1090
 U.S. Naval Hospital - New Street Lighting Units Along Main Roadway, 1087
 New Street Lighting System - Lighting Units at Main Building Entrance, 1089
 New Tennis Courts at Officers Quarters, Looking Northeast, 2042
 New Tennis Courts at Officers Quarters, Looking Northeast, 2045
 New Tennis Courts on Ordnance Dock, Looking Northeast, 2046
 Miscellaneous Improvements, 2nd Floor Bathroom, Building 14, 646
 Modernized Toilet of Building 128, 649
 Modernized Toilet and Plumbing Work, Building 226, 650
 Modernized Toilet and Plumbing Work, Building 226, 651
 Plumbing Improvement of Latrine, Building 205, 811
 Plumbing Improvements to Latrine in Building 205, 815
 Excavation for Air Lines West Side of Welding Platform, 3655
 Excavation for Electric Duct East Side of Building Ways 1, 8017
 New Electric Manhole at Third Street and Morris Avenue, 814
 Building 58 View Looking North Showing Steam Duct at Non-commissioned Officers' Quarters, 583
 City Park from Thompson & Norris Company's Building, 6695
 City Park from Thompson & Norris Company's Building, 6698
 City Park from Thompson & Norris Company's building, 6699
 City Park from Thompson & Norris Company's Building, 6704
 City Park from Thompson & Norris Company's Building, 6707
 View of East (Front) Face of Building 58, Non-Commissioned Officers Quarters, Completed, 3189
 Excavation for New Non-Commissioned Officers Quarters Between Buildings 130 and 152, 3190
 View of Non-Commissioned Officers' Quarters, Building No. 58, Showing Steel Erected, 577
 Building 58 View of Non-Commissioned Officers' Quarters, Looking Southwest, 579
 Building 58 Construction Roof View, 593
 Building 58 Construction Materials, 596
 Building 58 View Looking Northwest Showing Steam Duct to Non-Commissioned Officers' Quarters, 604
 Building 58 View of East Face (Front) of Building 58 Non-Commissioned Officers' Quarters Completed, 606
 Building 92, Front Corner of East Elevation, 653
 Building 92, East Elevation, 654
 Building 92, South Elevation, 655
 Building 92, North Elevation, 656
 Building 92, View Showing West Side of Front Stoop, 657
 Building 92, View Showing East Side of Front Stoop, 658
 Building 92, West Elevation, 659
 Remodeling Building 92, View Top Floor, East Side Looking South, 662
 Remodeling Building 92, View on 2nd Floor, East Side, 663
 Remodeling Building 92, View on 1st Floor, East Side Looking North, 664
 Remodeling of Building 92, View on 2nd Floor, West Side, 665
 Remodeling of Building 92, View in Corridor Between 2nd and 3rd Floors, 667
 Remodeling Building 92, View 1st Floor East Side, 668
 Remodeling of Building 92, View on 1st Floor, Front Corridor, 669
 Remodeling Building 92, View in Basement, 671
 Remodeling Building 92, View on 2nd Floor, East Side, 673
 Remodeling Building 92, Room in Basement, New Floor Laid, 675
 Remodeling of Building 92, Floor Part Laid in Basement, 676
 Remodeling Building 92, View of Basement Hall, 679
 Remodeling of Building 92, View of 1st Floor Hall Front Showing Walls with Brown Coat of Plaster, 680
 Remodeling Building 92, View of Room 1st Floor, Front, Showing Brown Coat of Plaster, 681
 Remodeling Building 92, View of Room, 1st Floor, Back, Showing Brown Coat of Plaster, 683
 Remodeling Building 92, View of Kitchen, 1st Floor, 689
 Remodeling Building 92, View of Bathroom in Basement, 690
 Remodeling of Building 92, View of Bathroom on 1st Floor, 691
 Remodeling of Building 92, View on 1st Floor, 692
 Remodeling Building 92, Constructing New Rear Porch, Also Showing New Window Sash, 693
 Remodeling Building 92, Side View of New Porch, 694
 Remodeling Building 92, View of South Side, 695
 Alterations to Building 93 for Marine Officers, 703
 Alterations to Building 93 for Marine Officers Quarters, Exterior View of South and East Sides, 704
 Alterations to Building 93 for Marine Officers Quarters, Exterior View of South and West Sides, 706

Alterations to Building 93 for Marine Officers Quarters, Exterior View of North and West Sides, 707
Alterations to Building 93 for Marine Officers Quarters, Interior View of North Extremity of Hall on 1st Floor, 709
Alterations to Building 93 for Marine Officers Quarters, General View of Stairway in Center of 1st Floor, 710
Alterations to Building 93 for Marine Officers Quarters, General View of Doorways in North Extremity of 2nd Floor, 712
Alteration to Building 93 for Marine Officer's Quarters, General Interior View Looking South Along Hallway in Basement, 713
Alterations to Building 93 for Marine Officer's Quarters, General View of Hallway Looking South on 1st Floor, 714
Alterations to Building 93 for Marine Officer's Quarters, General View of Hallway Looking South on 2nd Floor, 715
Alterations to Building 93 for Marine Officer's Quarters, General Interior View Looking South Along Hallway on Top Floor, 716
Alterations to Building 93 for Marine Officers Quarters, General View of Stairway on 1st Floor Looking East, 717
Alterations to Building 93 for Marine Officer's Quarters, General Exterior View of South and West Sides Looking Northeast, 718
Alterations to Building 93 for Marine Officers Quarters, General Exterior View of North and East Sides, Looking Southwest, 719
Alterations to Building for Marine Officer's Quarters, Detail View of Keystone in Place in Arch Over Central Window, West Side of Building Looking East, 722
Alterations to Building 93 for Marine Officers Quarters, General View of South Side and West Side Looking East, 723
Alterations to Building 93 for Marine Officers Quarters Exterior View of West Side, 724
Alterations to Building 93 for Marine Officers Quarters, Yard Labor, General View of North and West Sides Looking West, 725
Alterations to Building 93 for Marine Officers Quarters, Exterior View of North and East Sides, 728
Alterations to Building 93 for Marine Officers Quarters, Detail View of Entrance Under Construction in Center of West Wall, 729
Alterations to Building 93 for Marine Officers Quarters, Interior View of Top Floor, South Side, Showing Entrance to One of the Apartments, 730
Remodeling Building 93 for Marine Officers Quarters, Exterior View of North and East Sides, 733
Remodeling Building 93 for Marine Officers Quarters, Exterior View of West Side, 734
Remodeling Building 93 for Marine Officers Quarters, Exterior View of South and West Sides, 735
Remodeling Building 93 for Marine Officers Quarters, Interior View Showing Mantle in Place in One of the Rooms, 736
Remodeling Building 93 for Marine Officers Quarters, Interior View Showing Reflection of Bathtub in Bathroom through Mirror in Door, 737
Interior view of section of bathroom, 740
Alterations to Building 93 for Marine Officers Quarters, Entrance to Porch and Stairs, 741
Alterations to Building 93 for Marine Officers Quarters, Apartment Entrance, 742
Alterations to Building 93 for Marine Officers Quarters, Kitchen Cabinet, 743
Alterations to Building 93 for Marine Officers Quarters, Alcove from Hall, 744
Alterations to Building 93 for Marine Officers Quarters, Entrance to Porch, 745
Alterations to Building 93 for Marine Officers Quarters, Laundry Trays, 746
Alterations to Building 93 for Marine Officers Quarters - Kitchen, Stove and Closets, 747
Alterations to Building 93 for Marine Officers Quarters, Living Room Fire Place, 748
Alterations to Building 93 for Marine Officers Quarters, Interior Main Stairs, 749
Alterations to Building 93 for Marine Officers Quarters, Entrance Door from Inside, 750
Alterations to Building 93 for Marine Officers Quarters, Exterior View of South and West Walls Showing Awnings Lowered, 751
Alterations to Building 93 for Marine Officers Quarters, Exterior View of South and West Walls Showing Awnings Raised, 752
Alterations to Building 93 for Marine Officers Quarters, Exterior View of South and East Walls Showing Awnings Lowered, 753
Alterations to Building 93 for Marine Officers Quarters, Exterior View of South and East Walls Showing Awnings Raised, 754
Dining Furniture Installed in Dining Room of Building 93, Marine Officers Quarters, 755
Bedroom and Furniture in Building 93, Marine Officers Quarters, 756
Kitchen and Furniture in Building 93, Marine Officers Quarters, 758
Alcove and Furniture in Hall of Building 93, Marine Officers Quarters, 759
Hallway and Furnishings of Apartment of Building 93, Marine Officers Quarters, 760
Living Room and Furniture of Apartment in Building 93, Marine Officers Quarters, 761
Bathroom and Fittings of Apartment in Building 93, Marine Officers Quarters, 762
Exterior of Building 93, Marine Officers Quarters, 763
Fire Escape Erected on East Side of Building 93, 764
Fire Escape Erected on North Side of Building 93, 765
Printing Cornice and Fire Escapes, Building 93, 766
Outside Shell Enclosing Conservatory Under Construction at Quarters A, 816
Greenhouse of Salvaged Granite Constructed Under Temporary Enclosure at Quarters A, 1000
Erection of Temporary Kitchen for Use by Marine Barracks on Chauncey Avenue, 1036
Improvements to Marine Barracks Building 13 - Demolition Operations South End of Building, 1037
New Street Lighting System Lamp at Entrance to Nurses' Quarters, 1088
View of Double Quarters at Main Entrance, Looking South, 1106
View of Double Quarters at Main Entrance, Looking Northwest, 1107
View of Double Quarters at Main Entrance, Looking Southeast, 1108
Interior View of Double Quarters Showing Bedroom on 2nd Floor, 1109
Interior View of Double Quarters Showing Parlor on 1st Floor, 1110
Interior View of Double Quarters Showing Hall and Stairs to 2nd Floor, 1112
Interior View of Double Quarters Showing Stairs from 2nd Floor to Attic, 1113
Interior View of Double Quarters Showing Section of Kitchen, 1114

Interior View of Double Quarters Showing Bathroom on 2nd Floor, 1115
 Interior View of Double Quarters Showing Fireplace in Parlor , 1119
 Interior View of Double Quarters Showing Parlor on 1st Floor, 1122
 General View of Building 13 Showing Buildings a South End, 1132
 Repaving Streets - View of Approach to Nurse's Quarters, Looking East, 1200
 Repaving Streets - Construction of Steps Leading to Nurse's Quarters, Looking North, 1201
 Repairs to Floor on 2nd Floor of Nurses' Quarters - New Floor Just Laid, 1228
 Repairing Hallway on 2nd Floor of Nurses' Quarters, 1229
 Alterations to Rooms in Right Wing of Nurses' Quarters, 1235
 Installation of Drain Pipes in Right Wing of Nurses' Quarters Storeroom, 1236
 Installation of Drain Pipes in Right Wing on First Floor of Nurses' Quarters, 1237
 Site for Erection of Double Quarters at Main Entrance to Naval Hospital, View Looking East, 1245
 Laying the Foundation for Double Quarters Under Construction at the Main Entrance of the Naval Hospital, Looking North, 1246
 Laying Concrete Foundation for Double Quarters at Main Entrance at Naval Hospital, View Looking West, 1248
 Erecting Double Quarters at Main Entrance of Naval Hospital, View Looking Northwest , 1250
 Erecting Double Quarters at Main Entrance of Naval Hospital, Looking Northwest, 1251
 Snow Around House A Looking West from Main Street Opposite Building 2, 2163
 LOOKING SW TOWARDS HOUSE A (10), 4398
 LOOKING W TOWARDS HOUSE A (10), 4401
 LOOKING W TOWARDS HOUSE A (10), 4403
 LOOKING NE FROM HOUSE A (10), 4404
 LOOKING NE FROM HOUSE A (10), 4405
 LOOKING W FROM HOUSE A (10), 4406
 LOOKING W FROM HOUSE A (10), 4408
 LOOKING NW ALONG HIGH ST SHOWING HOUSE A (10), 4409
 LOOKING NW ALONG HIGH ST SHOWING HOUSE A (10), 4410
 LOOKING S FROM HOUSE A (10), 4411
 LOOKING SW FROM HOUSE A (10), 4412
 LOOKING SW FROM HOUSE A (10), 4414
 HOUSE A (10) N FIRST FLOOR ROOM, 4415
 HOUSE A (10) FIRST FLOOR ROOM, 4416
 HOUSE A (10) NE FIRST FLOOR ROOM, 4417
 HOUSE A (10) NE FIRST FLOOR ROOM, 4418
 HOUSE A (10), 4421
 HOUSE A (10) NE FIRST FLOOR ROOM, 4422
 HOUSE A (10) NW BEDROOM, 4423
 HOUSE A (10) NW BEDROOM, 4424
 HOUSE A (10) NW BEDROOM, 4425
 HOUSE A (10) FIRST FLOOR HALL, 4427
 HOUSE A (10) FIRST FLOOR HALL, 4428
 HOUSE A (10) PARLOR, 4432
 HOUSE A (10) DINING ROOM, 4433
 HOUSE A (10) DINING ROOM, 4435
 HOUSE A (10) PARLOR, 4436
 HOUSE A (10) SW BEDROOM, 4437
 HOUSE A (10) SW BEDROOM, 4439
 HOUSE A (10) NE BEDROOM, 4441
 HOUSE A (10) RESEEDING LAWN LOOKING N YARD LABOR, 4458
 HOUSE A (10) RESEEDED LAWN LOOKING N YARD LABOR, 4459
 HOUSE A (10) RESEEDED LAWN LOOKING N YARD LABOR, 4460
 Quarters B, D, C, H, K, and L, Looking Northwest, 4463
 Interior View of Double Quarters Showing Bedroom on 2nd Floor, 1116
 HOUSE A (10) SW BEDROOM, 4438
 U.S. Naval Ammunition Depot, Iona Island, New York - Inspector of Ordnance House, 3192
 U.S. Naval Ammunition Depot, Iona Island, New York - Pump House, 3193
 U.S. Naval Ammunition Depot, Iona Island, New York - Administration Building, 3194
 Engineering and Survey Department, Building 6, 984
 Payroll Department, Building 6, 985
 Payroll Department, Building 6, 986
 Method of Paying Employees on Payday, 987
 Stucco Repairs, Building 4 - Roofers Applying Plastic Finish to Exposed Tile, 3539
 Improvements to Garage Building 37 - Sheet Metal Workers Installing Skylight Frames and Flashing , 3540
 Improvements to Standard and Wide Gauge Tracks, Pier C, 3198
 Dry Dock 4, First Vessel Docked - USS Utah, 9612
 Excavation and Building Forms for New Curbing on Farragut Avenue, 3629

Excavation and Building Forms for New Curb on Farragut Avenue, 3628
 Argentine Battleship Rivadavia in Whitney Basin, Just before entering Dry Dock 4, Looking North, 2055
 Argentine Battleship Rivadavia in Dry Dock 4 Looking North, 2069
 USS West Virginia Removal of Plates, Key Bolts Broken - Key Protruding Through Shelf, 4254
 USS West Virginia Removal of Plates - Pile Drive in Operation, 4255
 USS West Virginia Removal of Plates - Plate #35 Breaking Away, 4256
 USS West Virginia Removal of Plates - Hoisting Away, 4257
 USS West Virginia Removal of Plates - Hoisting Away, 4258
 USS West Virginia Removal of Plates - Transporting Plate to End of Pier, 4259
 USS West Virginia Removal of Plates - Lowering Plate at End of Pier, 4260
 USS West Virginia Removal of Plates - Plate #35 Showing Key and Tops Used to Hold It in Place, 4261
 USS West Virginia Gun Train Indicator MK VIII, 4267
 USS West Virginia Torpedo Target Bearing Transmitter MK I MOD 1, 4268
 USS West Virginia Gun Director MK XI MOD 2, 4269
 USS West Virginia Train Indicator MK IV MOD 2, 4270
 USS West Virginia Gun Director MK XIV MOD 1, 4271
 USS West Virginia Gyro-Repeater in Battle Station #2, 4273
 USS West Virginia Train Indicator MK VII, 4275
 USS West Virginia, General View in Turret of Officer's Station, 4281
 USS Brooklyn (CL-40) Section of Keel as Fabricated Showing Shell Plates Connected Before Being Installed, 9260
 USS Pensacola - View of Navigating Bridge from Above Center Line of Ship About 30° from Vertical Side of Photo , 9452
 Dry Dock 4, First Vessel Docked - USS Utah, 9635
 USS West Virginia - Ship's Bearing Indicator MK IV MOD 4, 3191
 Waterfront Looking Southwest from South South of Pier F, 4000
 In the Trough of the Sea - USS Adams in Tow of the USS Yorktown, 2043
 Vessels Alongside Pier F Looking Northwest, 2088
 Looking Northwest Along Causeway, Showing Vessels at Piers E and F, 2089
 Vessels Alongside Pier D, Looking Southwest from Pier E, 2090
 Waterfront Southwest Side of Ordnance Dock, Looking North from Side of Entrance to Dry Dock 4, 2091
 Waterfront at Pier D and Mainland , 2102
 Waterfront Southwest Side of Ordnance Dock Showing End of Pier F, Looking North, 2109
 Waterfront Along Causeway Showing End of Pier E, Looking Northeast, 2111
 Waterfront from Dry Dock 3 Entrance to South Side of Pier E, Looking Northeast, 2117
 USS West Virginia Spalded Surface of Plate #40, 4262
 USS West Virginia Train Indicator MK VII, 4264
 USS West Virginia Gun Director MK XII MOD 1, 4265
 USS West Virginia Range Deflection Indicator MK IX, 4266
 USS West Virginia Elevation Indicator MK IV MOD 2, 4279
 USS West Virginia Train Indicator MK IV MOD 2, 4280
 USS West Virginia Danger Bearing Indicator and Alarm MK I, 4282
 USS West Virginia Ships Bearing Indicator MK XIII MOD 4, 4285
 USS West Virginia Periscope Mount MK III MOD 1, 4286
 USS West Virginia Torpedo Target Bearing Transmitter MK II MOD 1, 4287
 USS West Virginia Gun Train Indicator MK VIII, 4288
 USS West Virginia Periscope Mount MK III MOD 1, 4289
 USS West Virginia Gun Director MK XIV MOD 1, 4290
 USS West Virginia Torpedo Target Bearing Transmitter MK II MOD 1, 4291
 USS West Virginia Searchlight Train Indicator MK VI, 4292
 USS West Virginia Elevation Indicator and Junction Box, 4294
 USS West Virginia Range Delection Indicator MK IX, 4295
 USS West Virginia Multiple Turret Indicator MK IV, 4296
 USS West Virginia Multiple Turret Indicator MK IV MOD 1, 4297
 USS West Virginia Multiple Turret Indicator MK IV MOD 1, 4298
 Athletic Field, Looking Northeast Showing the North Goal, Spectator's Stands, Tennis Court, and Receiving Ship Washington, 2086
 Athletic Field, Looking Northeast Showing the North Goal, Spectator's Stands, Tennis Court and Receiving Ship Washington, 2087
 Improvements of Berths no 11 and 12 View Showing Excavation of Sea Wall View Showing Excavation of Sea Wall View Looking Inboard Contract Noy 3742., 3174
 Grading and Paving with Asphalt Block, Pier C, 1127
 East Waterfront Looking East from the West Side of the Commandant's Slip, 2132
 Relocating Freshwater, Saltwater, Air and Conduit Lines at Head of Dock C, also Repairs to Standard Gauge Tracks , 619
 Installation of Freshwater Line on Chauncey Avenue Between Third and Fourth Streets, 1034
 Public Utilities Section of 8 Inch Freshwater Pipe Which Failed - Removed by W.P.A. Labor at Morris Avenue and Fifth Street, 1039
 Photo of Plate 130 from Standard Boats of the U.S. Navy, 1900 Edition, 2082
 Wallabout Market , 1988
 Lacerated Buttock Wound, 8251

Lacerated Buttock Wound, 8252

Repair of Lacerated Buttock Wound, 8254

Repair of Lacerated Buttock Wound, 8255

USS New York and USS. Wyoming at Pier D, Looking West from Pier E, 2106

Sub-Assembly Shop Steel Erection looking NW showing cols in Line A and Bents #1 to #3 between lines B & E Plate #119, 5631